WORK INSTRUCTION

Document ID: DOC-0000767
Project: PRJ-002
Uploaded on: 2023-11-09
Uploaded by: user171
Export class: EAR99

Assembly of P-100957 at plant PLT02

Part Number: P-100957
Revision: A.1
Plant: PLT02
Station: ST-52
Torque (Nm): 20
Cycle time (s): 289

Step 1: Clean mating surface

Step 2: Inspect incoming part

Step 3: Torque to specification

Step 4: Clean mating surface

Step 5: Visual check

Step 6: Torque to specification