ITAR CONTROLLED - USML CATEGORY XIX

WORK INSTRUCTION

Document ID: DOC-0002563
Project: PRJ-025
Uploaded on: 2026-03-04
Uploaded by: user045
Export class: ITAR-USML-XIX

Assembly of P-102076 at plant PLT04

Part Number: P-102076
Revision: A.1
Plant: PLT04
Station: ST-42
Torque (Nm): 2.5
Cycle time (s): 294

Step 1: Move to next station

Step 2: Visual check

Step 3: Fit fasteners

Step 4: Clean mating surface

Step 5: Inspect incoming part

Step 6: Move to next station

Assembly of P-103474 at plant PLT01

Part Number: P-103474
Revision: A.1
Plant: PLT01
Station: ST-83
Torque (Nm): 5
Cycle time (s): 51

Step 1: Apply thread locker

Step 2: Clean mating surface

Step 3: Move to next station

Step 4: Visual check

Step 5: Visual check

Step 6: Visual check

Assembly of P-103345 at plant PLT04

Part Number: P-103345
Revision: A.1
Plant: PLT04
Station: ST-21
Torque (Nm): 5

Cycle time (s): 117

Step 1: Record result

Step 2: Torque to specification

Step 3: Fit fasteners

Step 4: Record result

Step 5: Fit fasteners

Step 6: Apply thread locker