WORK INSTRUCTION

Document ID: DOC-0000672
Project: PRJ-038
Uploaded on: 2023-09-15
Uploaded by: user055
Export class: EAR99

Assembly of P-100972 at plant PLT04

Part Number: P-100972
Revision: A.1
Plant: PLT04
Station: ST-62
Torque (Nm): 8
Cycle time (s): 126

Step 1: Torque to specification

Step 2: Fit fasteners

Step 3: Record result

Step 4: Record result

Step 5: Visual check

Step 6: Fit fasteners

Step 7: Fit fasteners

Assembly of P-100554 at plant PLT02

Part Number: P-100554
Revision: A.1
Plant: PLT02
Station: ST-56
Torque (Nm): 20
Cycle time (s): 236

Step 1: Clean mating surface

Step 2: Move to next station

Step 3: Visual check

Step 4: Record result

Step 5: Clean mating surface

Step 6: Inspect incoming part

Step 7: Visual check