WORK INSTRUCTION

Document ID: DOC-0001034
Project: PRJ-033
Uploaded on: 2024-03-26
Uploaded by: user072
Export class: EAR99

Assembly of P-101036 at plant PLT01

Part Number: P-101036
Revision: A.1
Plant: PLT01
Station: ST-79
Torque (Nm): 5
Cycle time (s): 203

Step 1: Inspect incoming part

Step 2: Inspect incoming part

Step 3: Apply thread locker

Step 4: Record result

Step 5: Clean mating surface