EXPORT CONTROLLED - ECCN 3A001

WORK INSTRUCTION

Document ID: DOC-0001044
Project: PRJ-007
Uploaded on: 2024-04-01
Uploaded by: user136
Export class: ECCN-3A001

Assembly of P-101509 at plant PLT01

Part Number: P-101509
Revision: A.1
Plant: PLT01
Station: ST-46
Torque (Nm): 8
Cycle time (s): 115

Step 1: Fit fasteners

Step 2: Clean mating surface

Step 3: Move to next station

Step 4: Torque to specification

Step 5: Record result