WORK INSTRUCTION

Document ID: DOC-0002260
Project: PRJ-017
Uploaded on: 2025-10-15
Uploaded by: user149
Export class: EAR99

Assembly of P-101541 at plant PLT03

Part Number: P-101541
Revision: A.1
Plant: PLT03
Station: ST-47
Torque (Nm): 2.5
Cycle time (s): 73

Step 1: Inspect incoming part

Step 2: Record result

Step 3: Record result

Step 4: Fit fasteners

Step 5: Inspect incoming part

Step 6: Apply thread locker

Step 7: Visual check

Step 8: Torque to specification

Assembly of P-101390 at plant PLT02

Part Number: P-101390
Revision: B.1
Plant: PLT02
Station: ST-38
Torque (Nm): 8
Cycle time (s): 236

Step 1: Visual check

Step 2: Record result

Step 3: Visual check

Step 4: Apply thread locker

Step 5: Apply thread locker

Step 6: Record result

Step 7: Fit fasteners