EXPORT CONTROLLED - ECCN 3A001

WORK INSTRUCTION

Document ID: DOC-0000813
Project: PRJ-010
Uploaded on: 2023-11-28
Uploaded by: user149
Export class: ECCN-3A001

Assembly of P-100425 at plant PLT03

Part Number: P-100425
Revision: A.1
Plant: PLT03
Station: ST-30
Torque (Nm): 20
Cycle time (s): 99

Step 1: Record result

Step 2: Inspect incoming part

Step 3: Clean mating surface

Step 4: Visual check

Step 5: Visual check

Assembly of P-101155 at plant PLT02

Part Number: P-101155
Revision: A.1
Plant: PLT02
Station: ST-58
Torque (Nm): 8
Cycle time (s): 212

Step 1: Record result

Step 2: Fit fasteners

Step 3: Apply thread locker

Step 4: Move to next station

Step 5: Move to next station