

New Work Order

Order #TVO-700003972

Dear Installer,

Thank you for accepting Tyres Vision Work Order #TVO-7000003972

Please find the details below:

Customer Details

Brandon Ronald Lourens

Vehicle Information

Plate No.: 55029

Make: Gmc

Model: Sierra-1500

Year: 2015

Installer Information

Tyre Rack Tyres

Near Emirates transport, M -5, Musaffah, Mussafah

Abu Dhabi

United Arab Emirates

Delivery Date/Time: 23-08-16 10:00am

Order Updates

The customer will come for the tire installation tomorrow at 3:00 PM--Customer will pay 2,688/- AED to Shop

ITEM	QTY
Bridgestone 275/55 R20 113V Alenza 001 2022	2
Bridgestone 275/55 R20 113V Alenza 001 2023	2

Please note the following,

- 1. The tyres supplied to you under this work order must be fitted ONLY to the Vehicle bearing the license plate number and description specified here. Please contact us if the customer insists on fitting these to another vehicle.
- 2. Please refuse to accept delivery if the tyres being delivered by the courier are not the exact same specifications and DOT as listed here
- 3. The customer has paid for new tyres, delivery, installation, balancing and disposal of old tyres. You will have to charges the customer directly for Alignment or any other service you provide.
- 4. The work order will not be considered complete unless the customer sign this work order and you email back a scanned copy to your Tyres Vision contact.

Please feel free to call us at or Write to us at customercare@tyresvision.com	
Job Complete (Y/N):	Remarks (if any):
Data & Time:	Customer Signature