

Pre-start - Mon 28 Sep 2026

Prefilled automatically Sun 27 Sep 2026 from the schedule and the carrier's list · supervisor: _____ · start time: _____

01 What is coming in

In (9): 4 portable buildings, 4 toilets & amenities, 1 generator
Where: S10 (2), S13 (1), S11 (1), S14 (1).

02 Hazards and controls talk each one through, then tick

- ☐ **Take 5 before every task.** Stop and do a Take 5 before each new task and again whenever the job or the conditions change - a new drop, a new spot, a new crew member, rain, a crowd. Two minutes, every time; it is the Coates risk assessment tool at the task.
- ☐ **Safety gear on.** Full PPE on before the gate and kept on: hi-vis, safety glasses, steel-cap boots, gloves for handling, and anything the SWMS adds for the task. Sun: hat, sunscreen, water.
- ☐ **Spotting trucks.** Trucks on site today: a dedicated spotter for every truck that moves or reverses - in the driver's mirror, eye contact before it moves, nobody behind it, the spotter does nothing else. The driver stops if they lose sight of the spotter.
- ☐ **Review the SWMS.** Read the SWMS for today's tasks together and sign on to it before work starts. If today's job is not in the SWMS, stop and review it before starting.
- ☐ **Unloading trucks.** Exclusion zone set up round the truck and the lift before the first strap comes off; nobody under a suspended load or between the load and the truck; loads checked for shift before straps are released; buildings lifted with tag lines on firm, level ground. Only licensed operators on the forklift, crane or Hiab.
- ☐ **Congested areas and low branches.** The precinct is busy - public, other contractors, event vehicles and the tram. Walk the route before the truck does, keep to walking pace, barricade the drop spot. Look up before every lift and every move: low branches, awnings, signs and wires. Do not drive through the park unescorted.
- ☐ **Tight spots.** Plan the placement before the unit arrives: measure the gap, clear the path, a spotter on every tight manoeuvre, hands clear of pinch points. If it does not fit as planned, stop and re-plan - do not force it; toilets placed clear of paths and doorways, level and stable; generators on level ground, cables run clear of walkways.
- ☐ **High communication at all times.** Radio or phone on and charged; say what you are about to do before you do it; one voice directs each lift and each reverse; any change to the plan goes to the whole crew straight away. Site contacts below.

03 Coates Life Saving Rules read out, every one, every day

- ☐ **Risk Assessment.** I will not commence any work that I am unfamiliar with, that is non-routine, potentially hazardous or impacted by changing conditions without first completing the appropriate Coates risk assessment tool to identify, assess and control risks.
- ☐ **High-Risk Work.** I will not commence any High-Risk Work without a risk assessment being completed and without having signed onto the applicable Safe Work Method Statement (SWMS).
- ☐ **Training and Competency.** I will be inducted, trained, competent and hold the required certification and licenses to conduct the task.
- ☐ **Fit for Work.** When I commence work, I will be physically fit, and not impaired by fatigue, injury, distraction, drugs or alcohol. I will wear the required personal protective equipment (PPE) as identified for the task or site rules.
- ☐ **Tools and Equipment.** I will only use tools and equipment that are fit for purpose and for which I am trained, competent and authorised. I will ensure that damaged or defective equipment is tagged out and removed from service.
- ☐ **Critical Risk Non-Negotiables.** When I commence a work activity related to a Coates Top 10 Critical Risk, I will always ensure that I review and strictly adhere to the non-negotiable rules and controls for that Critical Risk to protect me, my workmates and others from serious harm.

If you're unsure, ask the question. Everyone has the right to stop the job.

04 Site

Hours: 07:00-17:00 Monday to Friday - Unless otherwise approved by iEDM.
Contacts: Safety & Traffic Coordinator: Steve Haines 0407 734 398 · Site Manager: John Brett 0433 809 117
Added on the morning:

05 Sign-on

NAME	SIGNATURE	NAME	SIGNATURE

Coates Industrial Solutions · GC500 · Author: Andrew Fisher · Pre-start, prefilled · the day's record is the signed sheet