

DELIVER

GN18

1 × 50kva → Generator

DATE **Wed 07 Oct 2026**

LOAD TIME

CARRIER

ON SITE

After 07:00

LOAD

Own page · no shared load
recorded

ON THE TRUCK

WHAT	ASSET NO.	ALSO ON IT
1 × 50kva Generator · Generators	1276501	None on the schedule

WHERE IT GOES

LOCATION	Generator		
SECTOR		NEXT TO	GEM
BESIDE	P08, P51, WC38	NEAR	Gate 2 (~30 m), Commodore (~45 m)
FROM GATE	south, about 260 m		
WAY IN	Sundale Bridge → Tedder Ave Access Point, gate G10		
ESCORT	Do not drive through the park unescorted		



MASTER-PLAN POSITION
-27.983572, 153.424180
From master plan D001 · not a
phone pin
SCAN TO NAVIGATE


PHOTOS




Whole site



From the road



Close-up



Master plan

SAFETY

PPE: Hi-vis, Safety glasses, Steel-cap boots · Site hours 07:00–17:00 Monday to Friday

JSEA REQUIRED

The driver must complete a Job Safety and Environmental Analysis (JSEA) before unloading. This applies to every load. No JSEA, no unload.

TAKE 5

Take 5 before every new task. Stop, look, assess, control, then proceed — before each new task and again whenever the job or conditions change (a new unit, a new position, a new crew member, weather, the public).

COATES LIFE SAVING RULES — read and followed on every task

Risk Assessment	I will not commence any work that I am unfamiliar with, that is non-routine, potentially hazardous or impacted by changing conditions without first completing the appropriate Coates risk assessment tool to identify, assess and control risks.	High-Risk Work	I will not commence any High-Risk Work without a risk assessment being completed and without having signed onto the applicable Safe Work Method Statement (SWMS).	Training and Competency	I will be inducted, trained, competent and hold the required certification and licenses to conduct the task.
Fit for Work	When I commence work, I will be physically fit, and not impaired by fatigue, injury, distraction, drugs or alcohol. I will wear the required personal protective equipment (PPE) as identified for the task or site rules.	Tools and Equipment	I will only use tools and equipment that are fit for purpose and for which I am trained, competent and authorised. I will ensure that damaged or defective equipment is tagged out and removed from service.	Critical Risk Non-Negotiables	When I commence a work activity related to a Coates Top 10 Critical Risk, I will always ensure that I review and strictly adhere to the non-negotiable rules and controls for that Critical Risk to protect me, my workmates and others from serious harm.

DOCUMENTS



Loading and unloading at third party sites
SEQ-SWMS-009.01g
34 pages

CONTACTS

COATES SITE Andrew Fisher 0429 352 788 COATES OFFICE Ross Saxelby (07) 3299 9797 IEDM SAFETY & TRAFFIC Steve Haines 0407 734 398
IEDM SITE MANAGER John Brett 0433 809 117 EMERGENCY 000

DELIVER

P52

1 × Building 12m → Gate 1 Volunteer Check-In

DATE

Wed 07 Oct 2026

LOAD TIME

CARRIER

ON SITE

After 07:00

LOAD

Own page · no shared load recorded

ON THE TRUCK

WHAT	ASSET NO.	ALSO ON IT
1 × Building 12m Gate 1 Volunteer Check-In · Portable buildings	13227211	Fridge (Full Size)

WHERE IT GOES

LOCATION

Gate 1 Volunteer Check-In

SECTOR

S23

NEXT TO

SCA, iEDM

BESIDE

OP10, OP16, P53, P54, P56, WC67

NEAR

Breaker St (~30 m), S23 (~35 m), Gate 1 (~60 m), Helen (~30 m)

FROM GATE

west, about 50 m

WAY IN

Sundale Bridge → Tedder Ave Access Point, gate G10

ESCORT

Do not drive through the park unescorted

QR CODE

MASTER-PLAN POSITION
-27.981311, 153.424032
From master plan D001 · not a phone pin
SCAN TO NAVIGATE

PHOTOS

Whole site

From the road

Close-up

Master plan

SAFETY

PPE: Hi-vis, Safety glasses, Steel-cap boots · Site hours 07:00–17:00 Monday to Friday

JSEA REQUIRED

The driver must complete a Job Safety and Environmental Analysis (JSEA) before unloading. This applies to every load. No JSEA, no unload.

TAKE 5

Take 5 before every new task. Stop, look, assess, control, then proceed — before each new task and again whenever the job or conditions change (a new unit, a new position, a new crew member, weather, the public).

COATES LIFE SAVING RULES — read and followed on every task

Risk Assessment

I will not commence any work that I am unfamiliar with, that is non-routine, potentially hazardous or impacted by changing conditions without first completing the appropriate Coates risk assessment tool to identify, assess and control risks.

High-Risk Work

I will not commence any High-Risk Work without a risk assessment being completed and without having signed onto the applicable Safe Work Method Statement (SWMS).

Training and Competency

I will be inducted, trained, competent and hold the required certification and licenses to conduct the task.

Fit for Work

When I commence work, I will be physically fit, and not impaired by fatigue, injury, distraction, drugs or alcohol. I will wear the required personal protective equipment (PPE) as identified for the task or site rules.

Tools and Equipment

I will only use tools and equipment that are fit for purpose and for which I am trained, competent and authorised. I will ensure that damaged or defective equipment is tagged out and removed from service.

Critical Risk Non-Negotiables

When I commence a work activity related to a Coates Top 10 Critical Risk, I will always ensure that I review and strictly adhere to the non-negotiable rules and controls for that Critical Risk to protect me, my workmates and others from serious harm.

DOCUMENTS

QR CODE

Loading and unloading at third party sites
SEQ-SWMS-009.01g
34 pages

QR CODE

Safe Transport of Portable Buildings
SAF-PRO-075
6 pages

QR CODE

Pre-Transit Checklist — Site Accommodation Work Instruction
TRAN-WI-R1.2
10 pages

QR CODE

Guidance sheet for lifting portable buildings
Help Sheet 81
1 page

CONTACTS

COATES SITE Andrew Fisher 0429 352 788

COATES OFFICE Ross Saxelby (07) 3299 9797

IEDM SAFETY & TRAFFIC Steve Haines 0407 734 398

IEDM SITE MANAGER John Brett 0433 809 117

EMERGENCY 000

DELIVER

P54

1 × Building 6m → Accred Centre BOH

DATE

Wed 07 Oct 2026

LOAD TIME

CARRIER

ON SITE

After 07:00

LOAD

Own page · no shared load recorded

ON THE TRUCK

WHAT	ASSET NO.	ALSO ON IT
1 × Building 6m Accred Centre BOH · Portable buildings	1327219	None on the schedule

WHERE IT GOES

LOCATION

Accred Centre BOH

SECTOR

S23

NEXT TO

iEDM

BESIDE

OP10, OP16, P52, P53, P55, P56

NEAR

Breaker St (~25 m), S23 (~40 m), Gate 1 (~50 m), Helen (~20 m)

FROM GATE

west, about 60 m

WAY IN

Sundale Bridge → Tedder Ave Access Point, gate G10

ESCORT

Do not drive through the park unescorted



MASTER-PLAN POSITION

-27.981318, 153.423936

From master plan D001 · not a phone pin

SCAN TO NAVIGATE

PHOTOS



Whole site



From the road



Close-up



Master plan

SAFETY

PPE: Hi-vis, Safety glasses, Steel-cap boots · Site hours 07:00–17:00 Monday to Friday

JSEA REQUIRED

The driver must complete a Job Safety and Environmental Analysis (JSEA) before unloading. This applies to every load. No JSEA, no unload.

TAKE 5

Take 5 before every new task. Stop, look, assess, control, then proceed — before each new task and again whenever the job or conditions change (a new unit, a new position, a new crew member, weather, the public).

COATES LIFE SAVING RULES — read and followed on every task

Risk Assessment

I will not commence any work that I am unfamiliar with, that is non-routine, potentially hazardous or impacted by changing conditions without first completing the appropriate Coates risk assessment tool to identify, assess and control risks.

High-Risk Work

I will not commence any High-Risk Work without a risk assessment being completed and without having signed onto the applicable Safe Work Method Statement (SWMS).

Training and Competency

I will be inducted, trained, competent and hold the required certification and licenses to conduct the task.

Fit for Work

When I commence work, I will be physically fit, and not impaired by fatigue, injury, distraction, drugs or alcohol. I will wear the required personal protective equipment (PPE) as identified for the task or site rules.

Tools and Equipment

I will only use tools and equipment that are fit for purpose and for which I am trained, competent and authorised. I will ensure that damaged or defective equipment is tagged out and removed from service.

Critical Risk Non-Negotiables

When I commence a work activity related to a Coates Top 10 Critical Risk, I will always ensure that I review and strictly adhere to the non-negotiable rules and controls for that Critical Risk to protect me, my workmates and others from serious harm.

DOCUMENTS



Loading and unloading at third party sites

SEQ-SWMS-009.01g

34 pages



Safe Transport of Portable Buildings

SAF-PRO-075

6 pages



Pre-Transit Checklist — Site Accommodation Work Instruction

TRAN-WI-R1.2

10 pages



Guidance sheet for lifting portable buildings

Help Sheet 81

1 page

CONTACTS

COATES SITE Andrew Fisher 0429 352 788

COATES OFFICE Ross Saxelby (07) 3299 9797

IEDM SAFETY & TRAFFIC Steve Haines 0407 734 398

IEDM SITE MANAGER John Brett 0433 809 117

EMERGENCY 000

DELIVER

P55

1 × Ticket Box 6m → Gate 1 Ticket Box

Table with 2 columns: Field (DATE, LOAD TIME, CARRIER, ON SITE, LOAD) and Value (Wed 07 Oct 2026, After 07:00, Own page · no shared load recorded)

ON THE TRUCK

Table with 3 columns: WHAT, ASSET NO., ALSO ON IT. Row 1: 1 × Ticket Box 6m, 172114, None on the schedule.

WHERE IT GOES

Table with 4 columns: LOCATION, SECTOR, BESIDE, FROM GATE, WAY IN, ESCORT. Row 1: Gate 1 Ticket Box, S23, P54, P56, west, about 75 m, Sundale Bridge → Tedder Ave Access Point, gate G10, Do not drive through the park unescorted.



MASTER-PLAN POSITION
-27.981347, 153.423803
From master plan D001 · not a phone pin
SCAN TO NAVIGATE


PHOTOS



Whole site



From the road



Close-up



Master plan

SAFETY

PPE: Hi-vis, Safety glasses, Steel-cap boots · Site hours 07:00–17:00 Monday to Friday

JSEA REQUIRED

The driver must complete a Job Safety and Environmental Analysis (JSEA) before unloading. This applies to every load. No JSEA, no unload.

TAKE 5

Take 5 before every new task. Stop, look, assess, control, then proceed — before each new task and again whenever the job or conditions change (a new unit, a new position, a new crew member, weather, the public).

COATES LIFE SAVING RULES — read and followed on every task

Table with 4 columns: Risk Assessment, High-Risk Work, Training and Competency, Fit for Work. Each column contains specific safety rules and requirements.

DOCUMENTS



Loading and unloading at third party sites
SEQ-SWMS-009.01g
34 pages



Safe Transport of Portable Buildings
SAF-PRO-075
6 pages



Pre-Transit Checklist — Site Accommodation Work Instruction
TRAN-WI-R1.2
10 pages



Guidance sheet for lifting portable buildings
Help Sheet 81
1 page

CONTACTS

COATES SITE Andrew Fisher 0429 352 788 COATES OFFICE Ross Saxelby (07) 3299 9797 IEDM SAFETY & TRAFFIC Steve Haines 0407 734 398
IEDM SITE MANAGER John Brett 0433 809 117 EMERGENCY 000

DELIVER

P56

1 × Building 3.6m → Gate 1 Ticket BOH

DATE

Wed 07 Oct 2026

LOAD TIME

CARRIER

ON SITE

After 07:00

LOAD

Own page · no shared load recorded

ON THE TRUCK

WHAT	ASSET NO.	ALSO ON IT
1 × Building 3.6m Gate 1 Ticket BOH · Portable buildings	1268865	None on the schedule

WHERE IT GOES

LOCATION

Gate 1 Ticket BOH

SECTOR

S23

NEXT TO

iEDM

BESIDE

P52, P53, P54, P55

NEAR

Breaker St (~20 m), S23 (~45 m), Gate 1 (~50 m), Helen (~15 m)

FROM GATE

west, about 65 m

WAY IN

Sundale Bridge → Tedder Ave Access Point, gate G10

ESCORT

Do not drive through the park unescorted

QR CODE

MASTER-PLAN POSITION
-27.981305, 153.423889
From master plan D001 · not a phone pin
SCAN TO NAVIGATE

PHOTOS

Whole site

From the road

Close-up

Master plan

SAFETY

PPE: Hi-vis, Safety glasses, Steel-cap boots · Site hours 07:00–17:00 Monday to Friday

JSEA REQUIRED

The driver must complete a Job Safety and Environmental Analysis (JSEA) before unloading. This applies to every load. No JSEA, no unload.

TAKE 5

Take 5 before every new task. Stop, look, assess, control, then proceed — before each new task and again whenever the job or conditions change (a new unit, a new position, a new crew member, weather, the public).

COATES LIFE SAVING RULES — read and followed on every task

Risk Assessment

I will not commence any work that I am unfamiliar with, that is non-routine, potentially hazardous or impacted by changing conditions without first completing the appropriate Coates risk assessment tool to identify, assess and control risks.

High-Risk Work

I will not commence any High-Risk Work without a risk assessment being completed and without having signed onto the applicable Safe Work Method Statement (SWMS).

Training and Competency

I will be inducted, trained, competent and hold the required certification and licenses to conduct the task.

Fit for Work

When I commence work, I will be physically fit, and not impaired by fatigue, injury, distraction, drugs or alcohol. I will wear the required personal protective equipment (PPE) as identified for the task or site rules.

Tools and Equipment

I will only use tools and equipment that are fit for purpose and for which I am trained, competent and authorised. I will ensure that damaged or defective equipment is tagged out and removed from service.

Critical Risk Non-Negotiables

When I commence a work activity related to a Coates Top 10 Critical Risk, I will always ensure that I review and strictly adhere to the non-negotiable rules and controls for that Critical Risk to protect me, my workmates and others from serious harm.

DOCUMENTS

QR CODE

Loading and unloading at third party sites
SEQ-SWMS-009.01g
34 pages

QR CODE

Safe Transport of Portable Buildings
SAF-PRO-075
6 pages

QR CODE

Pre-Transit Checklist — Site Accommodation Work Instruction
TRAN-WI-R1.2
10 pages

QR CODE

Guidance sheet for lifting portable buildings
Help Sheet 81
1 page

CONTACTS

COATES SITE

Andrew Fisher 0429 352 788

COATES OFFICE

Ross Saxelby (07) 3299 9797

IEDM SAFETY & TRAFFIC

Steve Haines 0407 734 398

IEDM SITE MANAGER

John Brett 0433 809 117

EMERGENCY

000

DELIVER

P57

1 × Building 9.6m → Radio Distribution Office

Table with 2 columns: Field (DATE, LOAD TIME, CARRIER, ON SITE, LOAD) and Value (Wed 07 Oct 2026, After 07:00, Own page · no shared load recorded)

ON THE TRUCK

Table with 3 columns: WHAT, ASSET NO., ALSO ON IT. Row 1: 1 × Building 9.6m, 1268888, Fridge (Full Size)

WHERE IT GOES

Table with 4 columns: LOCATION, SECTOR, BESIDE, FROM GATE, WAY IN, ESCORT. Location: Radio Distribution Office. Sector: S23. Beside: OP10, WC67. From Gate: west, about 35 m. Way In: Sundale Bridge → Tedder Ave Access Point, gate G10. Escort: Do not drive through the park unescorted.



MASTER-PLAN POSITION
-27.981319, 153.424194
From master plan D001 · not a phone pin
SCAN TO NAVIGATE

PHOTOS

Four images: Whole site, From the road, Close-up, Master plan. Each image has a red circle highlighting the delivery location.

SAFETY

PPE: Hi-vis, Safety glasses, Steel-cap boots · Site hours 07:00–17:00 Monday to Friday

JSEA REQUIRED

The driver must complete a Job Safety and Environmental Analysis (JSEA) before unloading. This applies to every load. No JSEA, no unload.

TAKE 5

Take 5 before every new task. Stop, look, assess, control, then proceed — before each new task and again whenever the job or conditions change (a new unit, a new position, a new crew member, weather, the public).

COATES LIFE SAVING RULES — read and followed on every task

Grid of 8 safety rules: Risk Assessment, High-Risk Work, Training and Competency, Fit for Work, Tools and Equipment, Critical Risk Non-Negotiables.

DOCUMENTS



Loading and unloading at third party sites
SEQ-SWMS-009.01g
34 pages



Safe Transport of Portable Buildings
SAF-PRO-075
6 pages



Pre-Transit Checklist — Site Accommodation Work Instruction
TRAN-WI-R1.2
10 pages



Guidance sheet for lifting portable buildings
Help Sheet 81
1 page

CONTACTS

COATES SITE Andrew Fisher 0429 352 788 COATES OFFICE Ross Saxelby (07) 3299 9797 IEDM SAFETY & TRAFFIC Steve Haines 0407 734 398
IEDM SITE MANAGER John Brett 0433 809 117 EMERGENCY 000

DELIVER

T0258

1 x 3.0m Cont → Helen Park

DATE Wed 07 Oct 2026
LOAD TIME
CARRIER
ON SITE After 07:00
LOAD Own page · no shared load recorded

ON THE TRUCK

Table with 3 columns: WHAT, ASSET NO., ALSO ON IT. Row 1: 1 x 3.0m Cont, 3.0m Cont · Helen Park · Portable buildings, None on the schedule.

WHERE IT GOES

LOCATION Helen Park
SECTOR S23
BESIDE
FROM GATE west, about 80 m
WAY IN Sundale Bridge → Tedder Ave Access Point, gate G10
ESCORT Do not drive through the park unescorted



MASTER-PLAN AREA
-27.981235, 153.423761
Area only, from master plan D001 · not a phone pin
SCAN TO NAVIGATE


PHOTOS



Whole site



From the road



Close-up

SAFETY

PPE: Hi-vis, Safety glasses, Steel-cap boots · Site hours 07:00–17:00 Monday to Friday

JSEA REQUIRED

The driver must complete a Job Safety and Environmental Analysis (JSEA) before unloading. This applies to every load. No JSEA, no unload.

TAKE 5

Take 5 before every new task. Stop, look, assess, control, then proceed — before each new task and again whenever the job or conditions change (a new unit, a new position, a new crew member, weather, the public).

COATES LIFE SAVING RULES — read and followed on every task

Table with 4 columns: Risk Assessment, High-Risk Work, Training and Competency, Fit for Work. Each column contains specific safety rules and instructions.

DOCUMENTS



Loading and unloading at third party sites
SEQ-SWMS-009.01g
34 pages



Safe Transport of Portable Buildings
SAF-PRO-075
6 pages



Pre-Transit Checklist — Site Accommodation Work Instruction
TRAN-WI-R1.2
10 pages



Guidance sheet for lifting portable buildings
Help Sheet 81
1 page

CONTACTS

COATES SITE Andrew Fisher 0429 352 788 COATES OFFICE Ross Saxelby (07) 3299 9797 IEDM SAFETY & TRAFFIC Steve Haines 0407 734 398
IEDM SITE MANAGER John Brett 0433 809 117 EMERGENCY 000

DELIVER

WC20

2 × Toilet Block 6m · 2 × Waste tank → Toilets (Tank Mounted)

DATE Wed 07 Oct 2026

LOAD TIME

CARRIER

ON SITE After 07:00

LOAD Own page · no shared load recorded

ON THE TRUCK

WHAT	ASSET NO.	ALSO ON IT
2 × Toilet Block 6m · 2 × Waste tank Toilets (Tank Mounted) · Toilets & amenities	1327228 1327225	None on the schedule

WHERE IT GOES

LOCATION	Toilets (Tank Mounted)		
SECTOR	S04	NEXT TO	
BESIDE		NEAR	S04 (~40 m)
FROM GATE	south-east, about 780 m		
WAY IN	Sundale Bridge → Tedder Ave Access Point, gate G10		
ESCORT	Do not drive through the park unescorted		




MASTER-PLAN POSITION
-27.987468, 153.428179
From master plan D001 · not a phone pin
SCAN TO NAVIGATE

PHOTOS




Whole site



From the road



Close-up



Master plan

SAFETY

PPE: Hi-vis, Safety glasses, Steel-cap boots · Site hours 07:00–17:00 Monday to Friday

JSEA REQUIRED

The driver must complete a Job Safety and Environmental Analysis (JSEA) before unloading. This applies to every load. No JSEA, no unload.

TAKE 5

Take 5 before every new task. Stop, look, assess, control, then proceed — before each new task and again whenever the job or conditions change (a new unit, a new position, a new crew member, weather, the public).

COATES LIFE SAVING RULES — read and followed on every task

Risk Assessment

I will not commence any work that I am unfamiliar with, that is non-routine, potentially hazardous or impacted by changing conditions without first completing the appropriate Coates risk assessment tool to identify, assess and control risks.

High-Risk Work

I will not commence any High-Risk Work without a risk assessment being completed and without having signed onto the applicable Safe Work Method Statement (SWMS).

Training and Competency

I will be inducted, trained, competent and hold the required certification and licenses to conduct the task.

Fit for Work

When I commence work, I will be physically fit, and not impaired by fatigue, injury, distraction, drugs or alcohol. I will wear the required personal protective equipment (PPE) as identified for the task or site rules.

Tools and Equipment

I will only use tools and equipment that are fit for purpose and for which I am trained, competent and authorised. I will ensure that damaged or defective equipment is tagged out and removed from service.

Critical Risk Non-Negotiables

When I commence a work activity related to a Coates Top 10 Critical Risk, I will always ensure that I review and strictly adhere to the non-negotiable rules and controls for that Critical Risk to protect me, my workmates and others from serious harm.

DOCUMENTS



Loading and unloading at third party sites
SEQ-SWMS-009.01g
34 pages



Safe Transport of Portable Buildings
SAF-PRO-075
6 pages



Pre-Transit Checklist — Site Accommodation Work Instruction
TRAN-WI-R1.2
10 pages



Guidance sheet for lifting portable buildings
Help Sheet 81
1 page

CONTACTS

COATES SITE Andrew Fisher 0429 352 788 COATES OFFICE Ross Saxelby (07) 3299 9797 IEDM SAFETY & TRAFFIC Steve Haines 0407 734 398
IEDM SITE MANAGER John Brett 0433 809 117 EMERGENCY 000

DELIVER

WC38

1 × FWF → Toilet

DATE	Wed 07 Oct 2026
LOAD TIME	
CARRIER	
ON SITE	After 07:00
LOAD	Own page · no shared load recorded

ON THE TRUCK

WHAT	ASSET NO.	ALSO ON IT
1 × FWF Toilet · Toilets & amenities		None on the schedule

WHERE IT GOES

LOCATION	Toilet		
SECTOR	S10	NEXT TO	GEM
BESIDE	P08, P51	NEAR	Gate 2 (~30 m), Commodore (~55 m)
FROM GATE	south, about 265 m		
WAY IN	Sundale Bridge → Tedder Ave Access Point, gate G10		
ESCORT	Do not drive through the park unescorted		



MASTER-PLAN POSITION

-27.983631, 153.424238

From master plan D001 · not a phone pin

SCAN TO NAVIGATE


PHOTOS




Whole site



From the road



Close-up



Master plan

SAFETY

PPE: Hi-vis, Safety glasses, Steel-cap boots · Site hours 07:00–17:00 Monday to Friday

JSEA REQUIRED

The driver must complete a Job Safety and Environmental Analysis (JSEA) before unloading. This applies to every load. No JSEA, no unload.

TAKE 5

Take 5 before every new task. Stop, look, assess, control, then proceed — before each new task and again whenever the job or conditions change (a new unit, a new position, a new crew member, weather, the public).

COATES LIFE SAVING RULES — read and followed on every task

Risk Assessment	I will not commence any work that I am unfamiliar with, that is non-routine, potentially hazardous or impacted by changing conditions without first completing the appropriate Coates risk assessment tool to identify, assess and control risks.	High-Risk Work	I will not commence any High-Risk Work without a risk assessment being completed and without having signed onto the applicable Safe Work Method Statement (SWMS).	Training and Competency	I will be inducted, trained, competent and hold the required certification and licenses to conduct the task.
Fit for Work	When I commence work, I will be physically fit, and not impaired by fatigue, injury, distraction, drugs or alcohol. I will wear the required personal protective equipment (PPE) as identified for the task or site rules.	Tools and Equipment	I will only use tools and equipment that are fit for purpose and for which I am trained, competent and authorised. I will ensure that damaged or defective equipment is tagged out and removed from service.	Critical Risk Non-Negotiables	When I commence a work activity related to a Coates Top 10 Critical Risk, I will always ensure that I review and strictly adhere to the non-negotiable rules and controls for that Critical Risk to protect me, my workmates and others from serious harm.

DOCUMENTS



Loading and unloading at third party sites
SEQ-SWMS-009.01g
34 pages

CONTACTS

COATES SITE Andrew Fisher 0429 352 788 COATES OFFICE Ross Saxelby (07) 3299 9797 IEDM SAFETY & TRAFFIC Steve Haines 0407 734 398
IEDM SITE MANAGER John Brett 0433 809 117 EMERGENCY 000

DELIVER

WC39

2 × FWF → Toilets

DATE	Wed 07 Oct 2026
LOAD TIME	
CARRIER	
ON SITE	After 07:00
LOAD	Own page · no shared load recorded

ON THE TRUCK

WHAT	ASSET NO.	ALSO ON IT
2 × FWF Toilets · Toilets & amenities		None on the schedule

WHERE IT GOES

LOCATION	Toilets		
SECTOR		NEXT TO	COW, OPT
BESIDE	OP14, P46	NEAR	Gate 2 (~55 m), Park (~35 m)
FROM GATE	south, about 265 m		
WAY IN	Sundale Bridge → Tedder Ave Access Point, gate G10		
ESCORT	Do not drive through the park unescorted		



MASTER-PLAN POSITION
-27.983559, 153.423886
From master plan D001 · not a phone pin
SCAN TO NAVIGATE

PHOTOS




Whole site



From the road



Close-up



Master plan

SAFETY

PPE: Hi-vis, Safety glasses, Steel-cap boots · Site hours 07:00–17:00 Monday to Friday

JSEA REQUIRED

The driver must complete a Job Safety and Environmental Analysis (JSEA) before unloading. This applies to every load. No JSEA, no unload.

TAKE 5

Take 5 before every new task. Stop, look, assess, control, then proceed — before each new task and again whenever the job or conditions change (a new unit, a new position, a new crew member, weather, the public).

COATES LIFE SAVING RULES — read and followed on every task

Risk Assessment	I will not commence any work that I am unfamiliar with, that is non-routine, potentially hazardous or impacted by changing conditions without first completing the appropriate Coates risk assessment tool to identify, assess and control risks.	High-Risk Work	I will not commence any High-Risk Work without a risk assessment being completed and without having signed onto the applicable Safe Work Method Statement (SWMS).	Training and Competency	I will be inducted, trained, competent and hold the required certification and licenses to conduct the task.
Fit for Work	When I commence work, I will be physically fit, and not impaired by fatigue, injury, distraction, drugs or alcohol. I will wear the required personal protective equipment (PPE) as identified for the task or site rules.	Tools and Equipment	I will only use tools and equipment that are fit for purpose and for which I am trained, competent and authorised. I will ensure that damaged or defective equipment is tagged out and removed from service.	Critical Risk Non-Negotiables	When I commence a work activity related to a Coates Top 10 Critical Risk, I will always ensure that I review and strictly adhere to the non-negotiable rules and controls for that Critical Risk to protect me, my workmates and others from serious harm.

DOCUMENTS



Loading and unloading at third party sites
SEQ-SWMS-009.01g
34 pages

CONTACTS

COATES SITE Andrew Fisher 0429 352 788 COATES OFFICE Ross Saxelby (07) 3299 9797 IEDM SAFETY & TRAFFIC Steve Haines 0407 734 398
IEDM SITE MANAGER John Brett 0433 809 117 EMERGENCY 000

DELIVER

WC40

5 × FWF → Toilets

DATE

Wed 07 Oct 2026

LOAD TIME

CARRIER

ON SITE

After 07:00

LOAD

Own page · no shared load recorded

WHAT	ASSET NO.	ALSO ON IT
5 × FWF Toilets · Toilets & amenities		None on the schedule

WHERE IT GOES

LOCATION

Toilets

SECTOR

S10

NEXT TO

BESIDE

NEAR

S10 (~80 m), Gate 2 (~30 m), Commodore (~65 m)

FROM GATE

south, about 265 m

WAY IN

Sundale Bridge → Tedder Ave Access Point, gate G10

ESCORT

Do not drive through the park unescorted



MASTER-PLAN POSITION

-27.983644, 153.424458

From master plan D001 · not a phone pin

SCAN TO NAVIGATE


PHOTOS




Whole site



From the road



Close-up



Master plan

SAFETY

PPE: Hi-vis, Safety glasses, Steel-cap boots · Site hours 07:00–17:00 Monday to Friday

JSEA REQUIRED

The driver must complete a Job Safety and Environmental Analysis (JSEA) before unloading. This applies to every load. No JSEA, no unload.

TAKE 5

Take 5 before every new task. Stop, look, assess, control, then proceed — before each new task and again whenever the job or conditions change (a new unit, a new position, a new crew member, weather, the public).

COATES LIFE SAVING RULES — read and followed on every task

Risk Assessment

I will not commence any work that I am unfamiliar with, that is non-routine, potentially hazardous or impacted by changing conditions without first completing the appropriate Coates risk assessment tool to identify, assess and control risks.

High-Risk Work

I will not commence any High-Risk Work without a risk assessment being completed and without having signed onto the applicable Safe Work Method Statement (SWMS).

Training and Competency

I will be inducted, trained, competent and hold the required certification and licenses to conduct the task.

Fit for Work

When I commence work, I will be physically fit, and not impaired by fatigue, injury, distraction, drugs or alcohol. I will wear the required personal protective equipment (PPE) as identified for the task or site rules.

Tools and Equipment

I will only use tools and equipment that are fit for purpose and for which I am trained, competent and authorised. I will ensure that damaged or defective equipment is tagged out and removed from service.

Critical Risk Non-Negotiables

When I commence a work activity related to a Coates Top 10 Critical Risk, I will always ensure that I review and strictly adhere to the non-negotiable rules and controls for that Critical Risk to protect me, my workmates and others from serious harm.

DOCUMENTS



Loading and unloading at third party sites

SEQ-SWMS-009.01g

34 pages

CONTACTS

COATES SITE

Andrew Fisher 0429 352 788

COATES OFFICE

Ross Saxelby (07) 3299 9797

IEDM SAFETY & TRAFFIC

Steve Haines 0407 734 398

IEDM SITE MANAGER

John Brett 0433 809 117

EMERGENCY

000

Coates Industrial Solutions · GC500 2026 · Author: Andrew Fisher

From the GC500 record, 27 Sep 2026 19:06 AEST · A ruled line means not yet recorded

GC500-DRV-01 · Wed 07 Oct 2026 · Load 11 of 13

DELIVER

WC61

8 x FWF → Toilets

Table with 2 columns: Field, Value. Fields include DATE (Wed 07 Oct 2026), LOAD TIME, CARRIER, ON SITE (After 07:00), and LOAD (Own page · no shared load recorded).

ON THE TRUCK

Table with 3 columns: WHAT, ASSET NO., ALSO ON IT. Row 1: 8 x FWF, Toilets · Toilets & amenities, None on the schedule.

WHERE IT GOES

Table with 2 columns: LOCATION, DETAILS. Location: Toilets. Details include Sector (S22A), Next to (S22 (~50 m)), Beside, From gate (south-east, about 610 m), Way in (Sundale Bridge → Tedder Ave Access Point, gate G10), and Escort (Do not drive through the park unescorted).



MASTER-PLAN POSITION
-27.984129, 153.429805
From master plan D001 · not a phone pin
SCAN TO NAVIGATE

PHOTOS



Whole site



From the road



Close-up



Master plan

SAFETY

PPE: Hi-vis, Safety glasses, Steel-cap boots · Site hours 07:00–17:00 Monday to Friday

JSEA REQUIRED

The driver must complete a Job Safety and Environmental Analysis (JSEA) before unloading. This applies to every load. No JSEA, no unload.

TAKE 5

Take 5 before every new task. Stop, look, assess, control, then proceed — before each new task and again whenever the job or conditions change (a new unit, a new position, a new crew member, weather, the public).

COATES LIFE SAVING RULES — read and followed on every task

Table with 4 columns: Rule Category, Rule Description. Rules include Risk Assessment, High-Risk Work, Training and Competency, Fit for Work, Tools and Equipment, and Critical Risk Non-Negotiables.

DOCUMENTS



Loading and unloading at third party sites
SEQ-SWMS-009.01g
34 pages

CONTACTS

COATES SITE Andrew Fisher 0429 352 788 COATES OFFICE Ross Saxelby (07) 3299 9797 IEDM SAFETY & TRAFFIC Steve Haines 0407 734 398
IEDM SITE MANAGER John Brett 0433 809 117 EMERGENCY 000

DELIVER

WC86

1 × Accessible Toilet → Toilet

DATE	Wed 07 Oct 2026
LOAD TIME	
CARRIER	
ON SITE	After 07:00
LOAD	Own page · no shared load recorded

ON THE TRUCK

WHAT	ASSET NO.	ALSO ON IT
1 × Accessible Toilet Toilet · Toilets & amenities		None on the schedule

WHERE IT GOES

LOCATION	Toilet	
SECTOR	S04	NEXT TO
BESIDE		NEAR S04 (~20 m)
FROM GATE	south-east, about 800 m	
WAY IN	Sundale Bridge → Tedder Ave Access Point, gate G10	
ESCORT	Do not drive through the park unescorted	



MASTER-PLAN POSITION
-27.987660, 153.428216
From master plan D001 · not a phone pin
SCAN TO NAVIGATE

PHOTOS




Whole site



From the road



Close-up



Master plan

SAFETY

PPE: Hi-vis, Safety glasses, Steel-cap boots · Site hours 07:00–17:00 Monday to Friday

JSEA REQUIRED

The driver must complete a Job Safety and Environmental Analysis (JSEA) before unloading. This applies to every load. No JSEA, no unload.

TAKE 5

Take 5 before every new task. Stop, look, assess, control, then proceed — before each new task and again whenever the job or conditions change (a new unit, a new position, a new crew member, weather, the public).

COATES LIFE SAVING RULES — read and followed on every task

Risk Assessment I will not commence any work that I am unfamiliar with, that is non-routine, potentially hazardous or impacted by changing conditions without first completing the appropriate Coates risk assessment tool to identify, assess and control risks.	High-Risk Work I will not commence any High-Risk Work without a risk assessment being completed and without having signed onto the applicable Safe Work Method Statement (SWMS).	Training and Competency I will be inducted, trained, competent and hold the required certification and licenses to conduct the task.
Fit for Work When I commence work, I will be physically fit, and not impaired by fatigue, injury, distraction, drugs or alcohol. I will wear the required personal protective equipment (PPE) as identified for the task or site rules.	Tools and Equipment I will only use tools and equipment that are fit for purpose and for which I am trained, competent and authorised. I will ensure that damaged or defective equipment is tagged out and removed from service.	Critical Risk Non-Negotiables When I commence a work activity related to a Coates Top 10 Critical Risk, I will always ensure that I review and strictly adhere to the non-negotiable rules and controls for that Critical Risk to protect me, my workmates and others from serious harm.

DOCUMENTS



Loading and unloading at third party sites
SEQ-SWMS-009.01g
34 pages

CONTACTS

COATES SITE Andrew Fisher 0429 352 788 COATES OFFICE Ross Saxelby (07) 3299 9797 IEDM SAFETY & TRAFFIC Steve Haines 0407 734 398
IEDM SITE MANAGER John Brett 0433 809 117 EMERGENCY 000