



PRE DISPATCH INSPECTION CHECK SHEET ['MIDDLE']
RSB TRANSMISSIONS (I) LTD , LUCKNOW

DESCRIPTION-
Drg. No-

ASSY PROPSHAFT 590H JT 941 R

Shift
Mode No-

C

#

Part No:-

Invoice No.
4 Supply Date

FC320400

18/12/2024

Regular- Sample-

QTY:-

4 Sample Size

Actual Observations

4

5

Product Status

Remark

SR NO.	Characteristics	Specification	Mode Of Checking.	1	2	3	4	5	Product Status	Remark
1	Tube Length	As per Control Plan	Measuring Tape	941	942	942	943	Ok	All Shaft Found of ok	Checked in process/poka yoke Control
2	Matching of Tube Length in QR Code Sticker &	Match tube lengh with QR Sticket	Visual	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
3	QR Code Sticker Proper Scanning	Checked Part Number ,Drawing Modification no	Barcode/ QR Code Scanner	FEA32300111111111111111111111111111	FEA32300111111111111111111111111111	FEA32300111111111111111111111111111	FEA32300111111111111111111111111111	Ok	All Shaft Found of ok	
4	Total Flange to Flange Length In Closed	As per Control Plan	Measuring Tape	1516	943	942	944	Ok	All Shaft Found of ok	Checked in process/poka yoke Control
5	Type of Centre Bearing Kit	As per Control Plan	Visual	NA	NA	NA	NA	Ok	All Shaft Found of ok	
6	Rotary Movment Of Centre Bearing Kit	No jamming of center Brg.Rotation	Hand Feel	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
7	Coupling Flange Orientations (As per QA Alert)	As per Control Plan (checked Mounting hole	Visual	NA	NA	NA	NA	Ok	All Shaft Found of ok	
8	UJ Movement (Smooth)	Proper And Equal Free ness	Hand Feel	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
9	Circlip Seating/ Circlip Missing	No circlip missing ,proper setting and no crack	Visual	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
10	Paint Missing at Slip Area & UJ Area.	No paint missing at uj Area	Visual	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
11	Paint Condition	(No Run Down/Blisters/Patches,No paint allow in	Visual	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
12	Anti Rust Oil @ Machining Area	No anti rust oil missing in maching Area	Visual	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
13	Locking of Cheknuts	Hex Nut luck by punching	Visual	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
14	Proper Adhesion on Painted Surface (4B)	No Paint peel off Allow On Prop Shaft	Visual (As Per Standard)	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
15	Rust free	No Rust allow on prop shaft	Visual	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
16	No Welding Defect	No Blow hole ,porosity ,spatter ,under cut allow)	Visual	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
17	Proper Seating of Balancing Weight Condition On	proper setting	Visual Checked By hammer	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	
18	Grease Nipple Condition & Status	No free ness and loose	Visual	NON GREASABLE	NON GREASABLE	NON GREASABLE	NON GREASABLE	Ok	All Shaft Found of ok	
19	Mounting Hole Centre Distances	As per control plan	Vernier/ Checking Fixture	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	As per control plan
20	Mounting hole ID	As per control plan	Checking Pin /Round plug Gauge	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	As per control plan
21	Drill Hole (4 nos)	As per control plan	Checking Pin /Round plug Gauge	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	Incoming control (Checked on Sampling plan)
22	PCD	As per control plan	Checking Fixture	Ok	Ok	Ok	Ok	Ok	All Shaft Found of ok	Incoming control (Checked on Sampling plan)
23	Tube OD	As per control pla	Vernier /snap gauge	Ø103.9X4.5	Ø103.9X4.5	Ø103.9X4.5	Ø103.9X4.5	Ok	All Shaft Found of ok	Incoming control (Checked on Sampling plan)
24	Deadener available	AS per control plan	sound detect	No	No	No	No	Ok	All Shaft Found of ok	

Remarks :- (IF ANY)
CHECKED BY (SIGNTAURE):-
FORM NO :

Taufeek Ahmad
Date

18/12/2024

PASSED DISPATCH (SIGNATURE): SUDHIR