Самостоятельная работа 7


1. Вычислить вероятность безотказной работы (ВБР) следующей расчетно-логической схемы (см. рисунок), со следующими характеристиками элементов (см. таблицу).

	Элемент	ВБР
	S1	0,8
	S2	0,75
	\$3	0,8
S4 S6	S4	0,8
L S5 L	\$5	0,975
	\$6	0,8

S2 153:
$$P = (1-0.75)(1-0.8) = 0 - 0.25 \cdot 0.2 = 0.96$$

S18 (S2 153): $P = 0.8 \cdot 0.95 = 0.76$
S4155: $P = 1 - (1-0.8)(1-0.975) = 1 - 92 \cdot 0.015 = 0.995$
(S4155) &S6: $P = 0.995 \cdot 08 = 0.796$
 $Q = (1-0.76) - (1-0.796) = 0.24 \cdot 0.104 = 0.04896$
BBP: $P = 1 - Q = 0.95104$

2. Дана AADL-модель со следующей диаграммой:



Модель ошибок описана так (с незначительными сокращениями):

PROCESS Sens

error propagations

p : out propagation {NoService, HwErr, SwErr};

processor : in propagation {NoService, HwErr};

events

Failure : error event;

```
transitions
          all -[processor{NoService}]-> Fail;
     propagations
          Fail -[]-> p(NoService);
          all -[processor{HwErr}]-> p(HwErr);
          all -[Failure] -> p(SwErr);
     end component;
______
PROCESS Mon
     error propagations
         p : in propagation {NoService, HwErr, SwErr};
     transitions
          Op -[p{NoService}]-> SA;
          Op -[p{HwErr} or p{SwErr}]-> SB;
     end component;
PROCESSOR CPU
     error propagations
         pow : in propagation {NoService};
         bindings : out propagation {NoService, HwErr};
     events
          Failure : error event;
     transitions
          Op -[ pow{NoService} ]-> Fail;
     propagations
          Fail -[]-> bindings(NoService);
          all -[Failure] -> bindings(HwErr);
     end component;
DEVICE Bat
     error propagations
         pow : out propagation {NoService};
     events
          Failure : error event;
     transitions
         Op -[Failure]-> Fail;
    propagations
          Fail -[]-> pow_(NoService);
     end component;
```

Пусть все компоненты изначально находятся в состоянии **Op**. В какое состояние придет каждый из компонентов модели, если в компоненте **b** произойдет событие **Failure**?

Компонент	Состояние	
b	Fall	
cpu	Fail	
S	Fail	
m	SA	