

notes: ENC\_BUT is actually wrong on the original diagram, it was always on pin 24.

multiplexers numbers for notes only - # 3 was on pin A21, changed to pin A12. # 4 was on pin A22, changed to A13.