
FORMAT TO BE FOLLOWED FOR K-MAPS and Circuit Diagrams

K MAPS

- For k-map labelling, make proper pairs (no need to use coloring this is just for example) that are visible.
- After making pairs label the output on top by showing an arrow on each pair.



CIRCUIT DIAGRAMS

- Mention the output of every gate on top of it.
- Then also mention the final Output Q on the last gate.
 Label the bubbles (if any) in clear way. If they are dots and are not visible they will not be counted.

