Calibration  cal_date correction : dict
_
report_no

## DataReading equip\_id : NoneType measurements site\_id : NoneType correct()

readline from calibration table()

export to db()

get correction()

quantity: str raw: bool timestamp unit: str value: NoneType

new val()

Measurement