

cVAE + tính chỉnh
có kiểm soát

mục tiêu $(-0,75; -0,38)$



$(-0,74; -0,38)$

mục tiêu $(-0,57; -0,39)$



$(-0,57; -0,39)$

mục tiêu $(-0,53; -0,47)$



$(-0,53; -0,47)$

mục tiêu $(-0,41; -0,43)$



$(-0,41; -0,45)$

mục tiêu $(-0,28; -0,61)$



$(-0,28; -0,61)$

mục tiêu $(-0,02; -0,06)$



$(-0,02; -0,05)$

SIMP từ đầu
(tốt nhất 4 seed)



$(-0,75; -0,38)$



$(-0,57; -0,39)$



$(-0,52; -0,47)$



$(-0,42; -0,44)$



$(-0,28; -0,61)$



$(-0,02; -0,06)$