


cVAE, trong phân phối




$\nu = (-0,47; -0,50)$

cVAE, $\nu^* > 0$ (dấu chưa thấy)



$\nu = (0,55; 0,46)$

SIMP từ đầu



$\nu = (-0,47; -0,50)$