

HSE Golden Rules

Ten rules that keep us safe – on every site, vessel and in every office

Hannah Weber · 01 September 2025 · WE-HSE-STD-001



Pre-task check at Kestrel Ridge

#	Rule	What it means
1	Stop work when unsafe	Everyone has Stop Work Authority. No discussion, no blame.
2	Permit to work	Never start hazardous work without a valid permit and a toolbox talk.
3	Working at height	Use fall protection above 2 m; inspect your harness before each use.
4	Energy isolation	Lock out, tag out, test for dead – before touching electrical or hydraulic systems.
5	Lifting operations	Stay out of the exclusion zone; never stand under a suspended load.
6	Marine transfers	Transfer to and from vessels and structures only with approval, PFD and in the agreed sea state.
7	Driving	Wear a seat belt, no phone while driving, keep to the speed limit – also on site tracks.
8	Fit for work	No alcohol or drugs; tell your supervisor if you are tired, ill or on medication.
9	Confined spaces	Enter only with a permit, gas test

		and a standby person.
10	Report everything	Report every incident, near miss and unsafe condition within the shift.

The Golden Rules apply to employees, contractors and visitors. Breaking a Golden Rule on purpose leads to removal from site and can lead to dismissal or termination of the contract. Reporting a mistake never does.

Why we remind each other: on 3 June 2026 a dropped object near miss on MV Sea Atlas (HSE-INC-2026-018) could have caused a serious injury. The exclusion zone (rule 5) worked – nobody was hurt.

Signed: Dr. Amara Okafor (CEO) · Hannah Weber (HSE Manager). Version 3, 1 September 2025.