

Baltic Certification Services GmbH – Audit Report

Item	Details
Client	Weyland Energy GmbH
Certificate no.	BCS-OHS-ENV-4471
Audit type	2nd surveillance audit
Dates	17–20 November 2025
Sites audited	Hamburg HQ, Edinburgh office and control centre, Kestrel Ridge Wind Farm, Port of Eastholm (Harrow Bay onshore works)
Audit team	M. Lindholm (lead auditor), Dr. S. Ahrens (technical expert offshore wind)
Recommendation	Continued certification

1. Summary

The integrated management system is well implemented and actively led. Top management commitment was evident in interviews with the incoming CEO and the COO. The HSE statistics show a clear improvement over 2024. The audit team noted a strong reporting culture at Kestrel Ridge and good contractor engagement at the Port of Eastholm. Preparation for the offshore construction phase of Harrow Bay is the main challenge for the next certification cycle.

2. Findings

No.	Type	Clause	Finding
1	Minor NC	ISO 45001 8.1.4.2	Bridging documents for two marine contractors of Harrow Bay not yet finalised; contractor HSE requirements not fully transferred.
2	Minor NC	ISO 14001 9.1.1	Waste recycling rate at operating sites is reported but data from two German sites is estimated, not measured.
3	Observation	ISO 45001 7.2	GWO training matrix for office-based staff who visit turbines occasionally is not up to date.
4	Observation	ISO 14001 6.1.2	Aspects register should include SF ₆ in the offshore substation of Harrow Bay.
5	Good practice	ISO 45001 5.4	Safety representatives at Kestrel Ridge include O&M contractor staff – very good participation.

3. Next audit

3rd surveillance audit planned for November 2026, including a visit to an installation vessel at Harrow Bay. Corrective action plans for findings 1 and 2 to be submitted within 60 days.

M. Lindholm, Lead Auditor – 12 December 2025