

Toolbox Talk – Heat Stress in Nacelles

Toolbox talk – 10 minutes

Hannah Weber · 29 June 2026

Why this matters

On sunny summer days the temperature in a nacelle can exceed 40 °C. Combined with climbing, PPE and physical work this leads to heat exhaustion – and tired people make mistakes at height.

Signs to look for

- Headache, dizziness, nausea
- Heavy sweating or – worse – no sweating
- Confusion, irritability
- Cramps

What we do

- Start early – plan nacelle work for the morning in heat waves
- Take 1 litre of water per person per hour up the tower
- Use the service lift where available
- Breaks every 45 minutes in heat above 30 °C
- Buddy checks – look after each other

Discuss

What can we change in our planning this week to avoid the hottest hours in the nacelle?