

# Test GSE-HLR-6

" Status Final e Opção de Reinício


O sistema deve apresentar uma mensagem clara ao final do processo indicando se a transferência da imagem foi concluída com sucesso ou falha, e deve disponibilizar um botão para que o operador possa reiniciar o processo em caso de falha."

## Procedimento realizado

1. Com o arquivo em ambiente restrito(logado) e firmware válido já selecionado
2. Clicou-se em transferir

## Resultados obtidos

Após aguardar a transferência, foi exibida mensagem de sucesso, de forma clara e destacada



e interrompendo-se a transferência na metade, temos uma mensagem clara de erro na transferência

**PN:**

—

**Imagen:**

Nenhuma imagem selecionada

**Logs:**

```
File "C:\Dev\TCC_PES_end_sprint\gse_fls\gse\backend\protocols\arinc615a.py", line 279, in run_upload_flow
    self.tftp.serve_file_on_rrq()
File "C:\Dev\TCC_PES_end_sprint\gse_fls\gse\backend\protocols\tftp_client.py", line 642, in serve_file_on_rrq
    self._send_data_and_wait_ack(transfer_sock, block_num, chunk, rrq_addr)
File "C:\Dev\TCC_PES_end_sprint\gse_fls\gse\backend\protocols\tftp_client.py", line 719, in _send_data_and_wait_ack
    raise Exception()
Exception: Falha: ACK não recebido para bloco 301 após 1 tentativas

[erro] Transferência falhou.
[TFTP-OK] Socket principal fechado
[WORKER1 Thread encerrada e sockets limpos]
```

**Progresso:****Transferir****Selecionar Imagem****Sair**