My Report Title
My Report Title 2

11/26/2014

١	,	٨		ш	ı۸	_	1	$\overline{}$	A	Г
١		м	_	u	//-	١Т	ш	J	ľ	И

Valuation Number: ESTIMATE-0000002 Effective Date: 11/25/2014

Value Basis: New Construction Expiration Date: 11/26/2015

Estimate Expiration Date: 3/25/2015

Cost As Of: 09/2014

BUSINESS

GOLDEN SANDS SKATELAND

2003 PLOVER RD

PLOVER, WI 54467

USA

BUSINESS PROFILE

Report Primary Naics: 711219 - Other Spectator Sports

Gross Sales: \$170,000 USD Quality Factor: Average

Building Value: \$446,005 USD Number of Employees: 3

Sq Ft Occupied: 2,838 Year Started: 1978

CONTENTS

System Estimated Total: \$85,760 USD

5754 Business In Industry Peer Group Range

(Values in Thousands)

\$86



System Estimated Total Breakdown

 Inventory:
 \$44,120 USD
 Furniture:
 \$4,470 USD

 Equipment:
 \$31,890 USD
 Miscellaneous:
 \$3,910 USD

Computer: \$1,370 USD

LOCATION 00001 - GOLDEN SANDS SKATELAND - Headquarters

GOLDEN SANDS SKATELAND

2003 PLOVER RD

Building Value: \$446,005 USD

PLOVER, WI 54467

USA

Sq Ft Occupied: 2,838

Number of Employees: 3

Included in Contents Estimate: Yes

MSB costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

My Report Title
My Report Title 2

Policy: ESTIMATE-0000002 11/26/2014

Location Adjustments

Climatic Region: 1 - Cold

High Wind Region: 2 - Moderate Damage

Seismic Zone: 1 - No Damage

BUILDING 00001 - 00001

Section 1

SUPERSTRUCTURE

Occupancy: 100% Indoor Ice or Roller Rink Story Height: 20 ft.

Construction Type: 100% Steel Frame (ISO 4) Number of Stories: 1

Gross Floor Area: 2,838 sq.ft. Irregular Adjustment: None

Construction Quality: 2.0 - Average

Year Built: 1978

SUBSTRUCTURE Depth of Story Height: 10 ft.

Basement: Unfinished 500 sq.ft.

Construction Type: Masonry (ISO 2)

Adjustments

Depreciation: 10%

Hillside Construction: Degree of Slope: Level Site Accessibility: Excellent

Site Position: Unknown Soil Condition: Excellent

Fees

Architect Fees: 7% is included

Overhead and Profit: 20% is included

SUMMARY OF COSTS	User Specified	System Generated	Replacement Exclusion

SUPERSTRUCTURE

Site Preparation \$595

Foundations \$57,998

Foundation Wall

Interior Foundations

Slab On Ground

\$264,746

Framing

Exterior Wall 2% Wall Openings

MSB costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

My Report Title My Report Title 2

Policy: ESTIMATE-0000002 11/26/2014

SUMMARY OF COSTS	User Specified	System Generated	Replacement Exclusion
Exterior Wall		34% Brick on Masonry	
		33% Concrete, Precast Panels	
		33% Stucco on Masonry	
Structural Floor			
Roof			
Material		100% Single-Ply Membrane	
Pitch			
Interior			\$23,976
Floor Finish		10% Carpet	
		80% Concrete Sealer or Topping	
		10% Tile, Vinyl Composite	
Ceiling Finish		20% Drywall	
		100% Paint	
Partitions			
Length		28 ft.	
Structure			
Finish		100% Drywall	
		100% Paint	
Mechanicals			\$84,388
Heating		100% Gas, Oil, or Electric Suspended Unit Heater	
Cooling		20% Unit Air Conditioners, Air Cooled	
Fire Protection		100% Sprinkler System	
		100% Manual Fire Alarm System	
		100% Automatic Fire Alarm System	
Plumbing		3 Total Fixtures	
Electrical		100% Average Quality	

MSB costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

My Report Title My Report Title 2

Policy: ESTIMATE-0000002 11/26/2014

SUMMARY OF COSTS User Specified		System Generated	R	Replacement	Exclusion
Elevators		0 Passenger			
		0 Freight			
Built-ins				\$14,302	
TOTAL RC SECTION 1				\$446,005	
TOTAL ACV	Depreciated Cost (90%)			\$401,404	
TOTAL RC BUILDING 00	001 00001			\$446,005	
TOTAL ACV				\$401,404	
		Replacement	Sq.Ft.	\$/Sq.Ft.	Depreciated
LOCATION TOTAL, Loca	tion 00001	\$446,005	3,338	\$157	\$401,404
		Replacement	Sq.Ft.	\$/Sq.Ft.	Depreciated
VALUATION GRAND TO	TAL	\$446,005	3,338	\$134	\$401,404

MSB costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

My Report Title My Report Title 2

Policy: ESTIMATE-0000002 11/26/2014

V	A	ı	l	l	Δ	Т	ı	O	N	J
•	_	_	•	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	_		ш	v	ш	•

Valuation Number:ESTIMATE-0000002Effective Date:11/25/2014Value Basis:New ConstructionExpiration Date:11/26/2015Estimate Expiration Date:3/25/2015Cost As Of:09/2014

BUSINESS

GOLDEN SANDS SKATELAND

2003 PLOVER RD

PLOVER, WI 54467

USA

BUSINESS PROFILE

Report Primary Naics: 711219 - Other Spectator Sports

Gross Sales: \$170,000 USD Quality Factor: Average

Building Value: \$446,005 USD Number of Employees: 3

Sq Ft Occupied: 2,838 Year Started: 1978

CONTENTS

System Estimated Total: \$85,760 USD

5754 Business In Industry Peer Group Range

(Values in Thousands)

\$86



System Estimated Total Breakdown							
Inventory:	\$44,120 USD	Furniture:	\$4,470 USD				
Equipment:	\$31,890 USD	Miscellaneous:	\$3,910 USD				
Computer:	\$1,370 USD						

LOCATION 00001 - GOLDEN SANDS SKATELAND - Headquarters

GOLDEN SANDS SKATELAND

2003 PLOVER RD

Building Value: \$446,005 USD

PLOVER, WI 54467

USA

Sq Ft Occupied: 2,838

Number of Employees: 3

Included in Contents Estimate: Yes

MSB costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.

My Report Title My Report Title 2

Policy: ESTIMATE-0000002 11/26/2014

BUILDING 00001: SUPERSTRUCTURE	Replacement	Sq.Ft.	\$/Sq.Ft.	Depreciated
Section 1: 100% Indoor Ice or Roller Rink	\$446,005	2,838	\$157	\$401,404
BUILDING 00001: SUBSTRUCTURE	Replacement	Sq.Ft.	\$/Sq.Ft.	Depreciated
Section 1: 500 sq.ft. Basement, Unfinished	\$0	500	\$0	\$0
Section Totals	Replacement	Sq.Ft.	\$/Sq.Ft.	Depreciated
Section 1: 100% Indoor Ice or Roller Rink	\$446,005	3,338	\$157	\$0
BUILDING TOTAL, Building 00001	\$446,005	3,338	\$157	\$401,404
BUILDING INSURANCE SUMMARY		·		
Total Insured Amount	\$1			
Percent of Insurance to Value	0%			
100% Co-insurance Requirement	\$446,005			\$401,404
-100% Variance	(\$446,004)			
	Replacement	Sq.Ft.	\$/Sq.Ft.	Depreciated
LOCATION TOTAL, Location 00001	\$446,005	3,338	\$157	\$401,404
	Replacement	Sq.Ft.	\$/Sq.Ft.	Depreciated
VALUATION GRAND TOTAL	\$446,005	3,338	\$134	\$401,404

Report Footer

MSB costs include labor and material, normal profit and overhead as of date of report. Costs represent general estimates which are not to be considered a detailed quantity survey. These costs include generalities and assumptions that are common to the types of structures represented in the software.