September 12, 2022

Westwood Conservation Commission 50 Carby St. Westwood, MA 02090

Re: Dam Repair Protocol 42 Mill St., Westwood, MA (DEP #438-0706)

Dear Westwood Conservation Commission:

Goddard Consulting, LLC is pleased to submit this letter indicating that we will engage a Geotechnical Engineer to evaluate the existing conditions of the existing onsite dam and opine on repairs. We propose to limit dam repair costs to \$35,000.

Action items anticipated by Goddard Consulting to be included in the scope of work are as follows:

- Remove all large vegetation and roots from the dam.
- Clean existing spillway in disrepair, reform and repour the concrete.
- Place sandbags upgradient of the dam in the pond in the vicinity of the leak, drain water from this area, locate and repair the leak with bentonite clay or equivalent, then remove sandbags once repaired.

If there are any questions concerning this request, please do not hesitate to contact us.

Sincerely,

Goddard Consulting, LLC

LA HOLLY

Scott Goddard Principal & PWS