PROJECTS COMPLETED Updated November 15, 2019

2016

- 1. Drains were scoped and cleaned. City installed inspection chamber between Cypress ABCD and City lines. Jan. 2016
- 2. Property Line survey was completed by Olsen & Assoc. Feb. 2016
- 3. New aluminum railings were installed in Plaza AB and CD stairwells by Lindahl Aluminum \$1,300. Feb. 2016
- 4. Building B, 3rd floor re-levelled by fire door threshold so that it is more manageable for motorized scooters and wheelchairs (Southside Flooring and Rugs \$551.25). March 2016
- 5. The electrical upgrade project to power smart lighting was completed in March 2016.
- 6. Nine pole lights were replaced around pool and patio (Shared Facilities) April 2016
- 7. Skylights repaired or replaced as needed ongoing.
- Cracks were repaired on pool deck by Crack or Jack Concrete Repair. April 2016
- 9. Hallway next to lockers in Building B had new vinyl floor tiles laid and baseboards installed. September 2016
- 10. Levelling of the pavers along pathways around Cypress is ongoing.
- 11. Upgraded five flagpoles in pool area to provide a safer way of putting up flags at the beginning of the season and taking them down at the end. November 2016.

- 12. The 17 faulty roof vents were replaced on Building B (\$26,000). November 2016.
- 13. Games Room was cleaned out and restored. September December 2016. Reopened December 14th, 2016.

2017

- 1. Infrared scanning of all electrical panels was completed and any problems found were fixed. March 2017.
- 2. Fire lane between Buildings B & C was paved and the two post fixed. June 2017
- 3. The wooden door at the north entrance to the pool, facing Woodridge, was replaced with an aluminum one. September 2017
- 4. A bulge on the side edge of the roof on Building B was repaired along with re-caulking and re-sealing some areas on all three buildings. November 2017
- 5. The tile in the area around the pool and lounge was repaired or retiled as needed. November 2017

2018

- 1. New shelves were installed in the pool room to keep the room organized in accordance with recommendations of the Vancouver Coastal Health inspector. October 2018
- 2. The electrical panel in the pool room was replaced. October 2018

- 3. Worn out bearing plates were replaced in the overhead garage door in Building B. November 2018
- 4. Old exit signs were changed over to new green running person in Building A. November 2018
- 5. Suites damaged by the January 25th fire in Building B were refurbished, inspected and owners were allowed to move back in November and December 2018.
- 6. The fire panels in the lobbies of all three buildings were replaced along with the associated sensor connections. 2018

2019

- 1. The wooden entry door to the pool was replaced with an aluminum one by Lindahl Aluminum for \$1,497.00. 2019
- 2. The updating of the emergency exit signs to green running person has been completed. 2019
- 3. Telus installed wiring in all three buildings for their new fibre optic network built from flexible, glass fibre. October 2019
- 4. The final survey of the Building C slab was completed by Matson Peck and Topliss and we received a subsequent follow-up report by RJC stating that the slab is stable and needs no further attention. 2019