

RECORD RETENTION

The quality control department shall retain all batch records for five years.

SAMPLE HANDLING

Samples must be thoroughly mixed prior to analysis.

APPROVAL RESPONSIBILITY

The Production Supervisor shall verify equipment cleanliness before use.

REFERENCE DOCUMENT

Follow the cleaning procedure described in the Master Cleaning SOP.

PROCESS SEQUENCE

Calibrate the instrument, then perform the system suitability test, and finally begin sample analysis.

RESULT REPORTING

Report results to two decimal places after review.