

1.0 Scope

This procedure applies to all analytical testing performed in the QC laboratory.

3.0 Quality Review

The Quality Assurance reviewer shall check all raw data for transcription errors.

3.0 Quality Review

A supervisor shall countersign the quality review checklist prior to submission.

6.5 Documentation Review

A second analyst shall independently review all calculations before batch release.

7.0 Analytical Results Table

Results are summarized below.

Result: 10.5, 20.3, conforms

2.0 Sample Preparation

Dilute the sample to 100 mL with mobile phase before injection.

5.0 Qualifying the Equipment

All analytical balances shall be requalified annually by the metrology team.

8.0 Final Disposition

The QA Manager shall issue the final batch disposition after all reviews are complete.

9.0 Environmental Monitoring

Environmental monitoring of the manufacturing area shall be performed weekly using settle plates.

10.0 Long-Term Sample Retention

The stability chamber log shall be filed together with the batch record for long-term retention.