

RECORD RETENTION

The Quality Control department shall retain all batch records for five years.

SAMPLE HANDLING

Samples must be completely mixed prior to analysis.

APPROVAL RESPONSIBILITY

The Quality Assurance Officer shall verify equipment cleanliness before use.

REFERENCE DOCUMENT

Follow the cleaning procedure described in the Equipment Sanitation SOP.

PROCESS SEQUENCE

Perform the system suitability test, then calibrate the instrument, and finally begin sample analysis.

RESULT REPORTING

Report results to two decimal places after review and verification.