Linked procedure demo



Sub-task B5678 - Open the access port

- 1. Clean around the access port with isopropyl alcohol.
- 2. Ensure power has been locked out using procedure C33345.
- 3. Grasp the handle firmly, and turn.
- 4. Carefully swing the access port open.
- 5. Secure open port with 0.073 binding wire and duct tape.
- 6. Procedure complete.