TRI-COUNTY COLLISION ANALYSIS, LLC
Crash Reconstruction · Vehicle Data Retrieval · 2750 Foundry Rd, Unit 4, Riverton · (555) 010-8820

Report TCA-26-1187
Report date 10/20/2026

CRASH DATA RETRIEVAL REPORT

Event data recorder (restraint control module) · 2020 Ford Escape

CASE & RETRIEVAL INFORMATION			
REQUESTED BY LSH Law Group (Atty. Elijah Thone) · LSH-2026-MVA-770412		MATTER John Doe v. Robert Smith · Civil Action No. 26-CV-04417	
CRASH DATE 02/06/2026	POLICE REPORT RPD-26-018842	AUTHORITY FOR ACCESS Evidence preservation & inspection agreement, LSH / Harbor Point Insurance / Kevin Alvarez, dated 10/02/2026	
VEHICLE 2020 Ford Escape	VIN 1FMCU9G6XLUB•••417	OWNER Kevin Alvarez	INSURER / CLAIM Harbor Point · HP-26-7741
MODULE Restraint control module (RCM), removed during repair 03/2026; retained under Harbor Point evidence hold at Eastline Auto Body, Riverton		MODULE P/N · S/N LX6T-14B321-AC · 0S7Q4418	EVIDENCE SEAL (AS RECEIVED) HP-EH-2291 — intact
DOWNLOAD DATE 10/20/2026 (Tue)	TIME 10:05–10:48	METHOD Direct-to-module (bench)	RETRIEVAL TOOL / SOFTWARE CDR-class kit · software v. 24.3
RETRIEVED BY Daniel Reese, Crash Data Analyst / Reconstructionist		PRESENT Marcus Bell (Harbor Point Insurance); Case Manager, LSH Law Group	

Event summary

Event	Type	Locked	Ignition cycle at event / at download	Time from event 1	Max. lateral ΔV	Max. longitudinal ΔV
1 (most recent deployment)	Side impact, right — deployment	Yes	4,812 / 4,812	0 ms	−15.2 mph @ 78 ms	−1.9 mph @ 64 ms
2	Side, left — non-deployment	No	4,812 / 4,812	1,340 ms	+3.8 mph @ 52 ms	−0.6 mph @ 40 ms

Event 1 — pre-crash data (−5.0 to 0.0 s, 2 samples/s)

Time (s)	Vehicle speed (mph)	Accelerator pedal (%)	Service brake	Engine RPM	Steering input (deg)	ABS activity
−5.0	0	0	On	700	0	Off
−4.5	0	0	On	700	0	Off
−4.0	0	0	On	700	0	Off
−3.5	0	0	On	700	0	Off
−3.0	0	0	On	700	0	Off
−2.5	0	14	Off	1,100	0	Off
−2.0	2	22	Off	1,600	0	Off
−1.5	5	26	Off	2,000	−1	Off
−1.0	7	26	Off	2,200	−1	Off
−0.5	9	24	Off	2,300	−1	Off
0.0 (event)	**11**	**18**	**Off**	**2,200**	**0**	**Off**

Speed at impact (event trigger, t = 0.0 s): 11 mph.

Event 1 — occupant restraint data

DRIVER SEAT BELT BUCKLED	FRONT PASSENGER SEAT BELT BUCKLED	PASSENGER OCCUPANT CLASSIFICATION Adult · airbag enabled	DRIVER SEAT TRACK Not forward
DRIVER FRONT AIRBAG Not deployed	PASSENGER FRONT AIRBAG Not deployed	RIGHT FRONT SEAT SIDE AIRBAG Deployed · 9 ms	RIGHT SIDE CURTAIN Deployed · 11 ms
LEFT SIDE AIRBAGS / CURTAIN Not deployed	DRIVER BELT PRETENSIONER Not deployed	PASSENGER BELT PRETENSIONER Deployed · 10 ms	WARNING LAMP (SRS) AT EVENT Off

Data file & chain of custody

RETRIEVED DATA FILE TCA-26-1187_ESCAPE_RCM_20261020.cdrx	FILE SIZE 412,880 bytes	REPORT GENERATED 10/20/2026 11:02
SHA-256 OF DATA FILE f254d3e4b6223b6198b788df955e3262918acef7623a2d8f2e3a2378a3d6f37a		

Date / time	Action	By
10/20/2026 09:40	RCM received from Eastline Auto Body storage in Harbor Point evidence bag, seal HP-EH-2291 intact; photographed (12 images) before opening.	D. Reese; witnessed M. Bell
10/20/2026 10:05	Bench connection; module powered from regulated supply; read-only retrieval; no data written to the module.	D. Reese
10/20/2026 10:48	Retrieval complete; data file hashed; copies to Tri-County case drive and to write-once disc for LSH Law Group and Harbor Point.	D. Reese
10/20/2026 10:55	Module resealed in new bag, seal TCA-S-5530; returned to Harbor Point evidence hold.	D. Reese → M. Bell
10/20/2026 11:10	Disc copy (hash verified) and this report delivered.	D. Reese → Case Manager, LSH Law Group

Data limitations

Pre-crash data are recorded at 2 samples per second; values between samples are not recorded. Vehicle speed is the speed reported to the module by the vehicle's speed sensors and may differ from true ground speed during wheel slip, braking or lateral movement; reported speed accuracy is approximately ±1 mph. Time 0.0 is the module's algorithm-enable (event trigger) time. The module does not record calendar date or time of day; Event 1 is matched to the 02/06/2026 crash by the deployment record, the module's removal at repair in 03/2026 and the unchanged ignition-cycle count.

Certification

I retrieved the data described in this report personally, using the method and equipment stated, and this report is a true and complete printout of the data retrieved. I am trained and certified in the use of the retrieval system and have performed more than 300 event-data retrievals. I have no financial interest in the outcome of this matter.

Daniel Reese

Daniel Reese, Crash Data Analyst / Reconstructionist
Tri-County Collision Analysis, LLC · 10/20/2026

M. Bell

Witnessed: Marcus Bell, Harbor Point Insurance · 10/20/2026