RIVERTON COLLISION CENTER

Auto Body · Frame & Structural · Refinish · 1820 Foundry Rd, Riverton · (555) 010-6620

ESTIMATE OF RECORD
RO / Estimate No. RCC-26-0331
Written 02/16/2026

PRELIMINARY ESTIMATE

OWNER / CUSTOMER John Doe · (555) 010-2288		ADDRESS 2214 Maple Hollow Rd, Riverton		INSURER / CLAIM NO. Keystone Mutual · KM-26-440871-PD
VEHICLE 2019 Honda Civic LX 4D Sedan		VIN 2HGFC2F63KH548213		ADJUSTER (CLAIMANT) Leah Moran, PD
MILEAGE 52,300	PLATE PKW-3186	COLOR Lunar Silver	DATE OF LOSS 02/06/2026	POINT OF IMPACT 11 o'clock — left front
CONDITION Not drivable · in by tow 02/12/2026		ESTIMATOR Paul Diaz		INSPECTION 02/16/2026 at RCC, pre-teardown

Line	Oper.	Description	Part no.	Parts/sublet	Body	Paint	Mech	Struct
1	Repl	Front bumper cover, primed	04711-TBA-A00ZZ	412.00	2.4	3.2		
2	Repl	Front bumper reinforcement bar	71130-TBA-A00	198.00	0.8			
3	Repl	Front bumper energy absorber	71170-TBA-A00	46.00	0.2			
4	Repl	Front grille assy	71121-TBA-A01	168.00	0.4			
5	Repl	Headlamp assy, L (LED)	33150-TBA-A11	486.00	0.4			
6	Repl	Fender panel, L	60261-TBA-A90ZZ	264.00	1.8	2.4		
7	Repl	Fender liner, L	74151-TBA-A00	48.00	0.3			
8	Repl	Hood panel	60100-TBA-A90ZZ	498.00	1.0	3.0		
9	Repl	Front door shell, L	67050-TBA-A00ZZ	612.00	3.2	2.8		
10	Blnd	Rear door, L (blend)				1.2		
11	Repl	Lower radiator support (bolted)	60435-TBA-A00ZZ	132.00	1.2			
12	Repl	Radiator assy	19010-5BA-A51	214.00			1.0	
13	Repl	A/C condenser	80110-TBA-A01	286.00			0.8	
14	Subl	A/C evacuate & recharge		149.00				
15	Repl	Lower control arm, L front	51360-TBA-A01	188.00			0.9	
16	Repl	Tie rod end, L outer	53560-TBA-A01	64.00			0.4	
17	Repl	Wheel, alloy 16 in., L front	42800-TBA-A71	312.00			0.3	
18	Repl	Tire 215/55R16, L front		142.00				
19	Subl	Mount & balance; four-wheel alignment		118.32				
20	Misc	Cover car, corrosion protection, haz. waste		38.00	0.5			
Hours / parts subtotal				**4,375.32**	**12.2**	**12.6**	**3.4**	**0.0**

Estimate notes. Left-front impact; vehicle was parked at the curb when struck by another vehicle. Visual inspection only — hidden damage likely behind the L front door and at the L A-pillar/hinge area. Teardown authorized by Keystone (L. Moran) on 02/17/2026. A supplement will follow teardown if required.
Labor rates: body $58.00/h · paint $58.00/h · mechanical $96.00/h · structural $72.00/h · paint materials $38.00 per paint hour. Sales tax 7% on parts and materials; sublet not taxed.

Parts (taxable)	$4,108.00
Sublet	$267.32
Body labor 12.2 h @ $58.00	$707.60
Paint labor 12.6 h @ $58.00	$730.80
Mechanical labor 3.4 h @ $96.00	$326.40
Paint materials 12.6 h @ $38.00	$478.80
Sales tax 7% ($4,586.80)	$321.08
ESTIMATE TOTAL	**$6,940.00**

Paul Diaz

Paul Diaz, Estimator · Riverton Collision Center · 02/16/2026

RIVERTON COLLISION CENTER

Auto Body · Frame & Structural · Refinish · 1820 Foundry Rd, Riverton · (555) 010-6620

SUPPLEMENT 1 (teardown)
RO / Estimate No. RCC-26-0331
Written 03/02/2026

SUPPLEMENT 1 — TEARDOWN

Vehicle 2019 Honda Civic LX · VIN 2HGFC2F63KH548213 · owner John Doe
Insurer / claim Keystone Mutual Insurance · KM-26-440871-PD · Leah Moran
Estimator Paul Diaz · teardown completed 02/27/2026

Teardown findings. L door and fender removed: L front pillar (A-pillar) outer panel buckled at the upper hinge mount; L upper apron reinforcement kinked; L front pillar out of OEM dimensional tolerance. OEM procedure: section the outer pillar (windshield R&R and ADAS camera recalibration required). Structural repair. Photos uploaded to the claim file 03/02/2026.

Line	Oper.	Description	Part no.	Parts/sublet	Body	Paint	Mech	Struct
S1	Repl	Front pillar outer panel, L (A-pillar section)	64500-TBA-A00ZZ	286.00				9.0
S2	Repl	Apron reinforcement, L front (upper)	60810-TBA-A00ZZ	148.00				1.5
S3	Struct	Structural setup, pull & measure (pre/post)						3.0
S4	Repl	Upper hinge, L front door	67410-TBA-A01	54.00	0.6			
S5	R&I	A-pillar trim & headliner, L side			1.2			
S6	Rfn	Refinish A-pillar, L (outer)				1.8		
S7	Repl	Weld-through primer, seam sealer, cavity wax		46.00				
S8	Subl	Windshield R&R, urethane; ADAS camera recal.		489.63				
Hours / parts subtotal				**1,023.63**	**1.8**	**1.8**	**0.0**	**13.5**

Repair summary — RO RCC-26-0331	
Preliminary estimate (02/16/2026)	$6,940.00
Supplement 1 — teardown (03/02/2026)	$2,315.00
Total repair	**$9,255.00**
Deductible	N/A (third-party claim)
Paid by Keystone Mutual, EFT 04/24/2026	($9,255.00)
Balance due	**$0.00**

Parts (taxable)	$534.00
Sublet	$489.63
Body labor 1.8 h @ $58.00	$104.40
Paint labor 1.8 h @ $58.00	$104.40
Structural labor 13.5 h @ $72.00	$972.00
Paint materials 1.8 h @ $38.00	$68.40
Sales tax 7% ($602.40)	$42.17
SUPPLEMENT 1 TOTAL	**$2,315.00**

Date	Repair order status log
03/03/2026	Supplement 1 reviewed and approved by Keystone (L. Moran). All parts ordered from dealer.
03/06/2026	**PARTS BACKORDER:** 64500-TBA-A00ZZ (A-pillar outer panel) and 67050-TBA-A00ZZ (L front door shell) on manufacturer backorder — no ship date; dealer estimate 4–6 weeks. Vehicle held at RCC, not drivable. Owner and Keystone notified.
03/30/2026	Backorder status checked with dealer — still no ship date. Owner updated by phone.
04/14/2026	Backordered parts received. Structural repair started.
04/22/2026	Post-repair measurements within OEM tolerance; windshield installed; ADAS camera recalibrated (sublet report on file).
04/24/2026	**Repair completed.** Final invoice $9,255.00 paid by Keystone Mutual (EFT). Vehicle released to owner.

Paul Diaz
Paul Diaz, Estimator · Riverton Collision Center

John Doe
Vehicle received by owner · 04/24/2026

RIVERTON TOWING

24-Hour Towing & Recovery · Secure Storage Yard · 44 Depot St, Riverton · (555) 010-6650

INVOICE No. RT-260206-07
Invoice date 02/12/2026

TOW & STORAGE INVOICE

BILL TO Keystone Mutual Insurance · Claims, P.O. Box 4100, Riverton		CLAIM NO. KM-26-440871-PD	ADJUSTER Leah Moran
VEHICLE OWNER John Doe, 2214 Maple Hollow Rd, Riverton		VEHICLE 2019 Honda Civic LX · Lunar Silver · plate PKW-3186	
VIN 2HGFC2F63KH548213		CALL SOURCE Riverton PD rotation · Officer T. Garner #2217	
CALL RECEIVED 02/06/2026 07:26	HOOKED 02/06/2026 07:58	PICKUP LOCATION Birch Ave at Maple Hollow Rd, Riverton (parked, collision)	
DROP LOCATION Riverton Towing yard, 44 Depot St		TRUCK / DRIVER Flatbed #4 · D. Kowal	POLICE REPORT RPD-26-018842
RELEASED TO Riverton Collision Center (shop flatbed) · 02/12/2026 09:15			

Description	Qty	Rate	Amount
Tow — flatbed, accident scene to storage yard (hook-up, mileage, debris clean-up included)	1	$185.00	$185.00
Storage — outdoor secured, 02/06/2026 through 02/11/2026	6 days	$45.00	$270.00
INVOICE TOTAL			**$455.00**
Payment — Keystone Mutual Insurance, check no. 7120448, received 02/20/2026			($455.00)
BALANCE DUE			**$0.00**

Storage accrues at $45.00 per calendar day or part day from the day of tow until the vehicle is released. Personal property removed by owner 02/07/2026 (signed inventory on file). Vehicle released on owner's authorization to the repair facility named above.

PAID 02/20/2026

R. Vance

Rhonda Vance, Office · Riverton Towing