

Riverside Collision Center

Estimator: Dana Whitfield · (555) 455-0192
Supplement S1 · 09/29/2026

Supplement S1 — Teardown Findings

Crestline claim CMI-26-0918-4471 · RAV4 VIN TRNG4RAV4XLE22014 · 28,412 miles

Teardown found the **left rear frame rail buckled**, the **rear floor pan** pushed forward and the left quarter panel damaged beyond repair. OEM parts are requested for all structural and sensor-related parts on this 2022 vehicle.

Line	Type	Amount
Rear frame rail LH — OEM	Part	\$1,710.68
Rear floor pan — OEM	Part	\$912.75
Quarter panel LH — OEM	Part	\$1,148.60
Rear bumper reinforcement — OEM (replaces A/M)	Part	\$402.10
Credit: A/M bumper reinforcement removed	Part	-\$286.00
Rear bumper cover — OEM (replaces A/M)	Part	\$618.30
Credit: A/M bumper cover removed	Part	-\$412.00
Blind-spot radar bracket LH — OEM	Part	\$64.20
Seam sealer & corrosion protection	Materials	\$186.00
Body labor — structural (rail sectioning, floor pan, quarter panel) — 98.0 hrs @ \$72.00	Labor	\$7,056.00
Frame setup, measure & pull — 6.0 hrs @ \$95.00	Labor	\$570.00
Refinish labor (added panels) — 12.0 hrs @ \$72.00	Labor	\$864.00
Paint & materials (added) — 12.0 hrs @ \$42.00	Materials	\$504.00
Labor-rate difference on initial estimate — 63.0 hrs × (\$72 – \$58)	Labor	\$882.00
Sublet: pre-repair diagnostic scan	Sublet	\$95.00
Sublet: post-repair diagnostic scan	Sublet	\$95.00
Sublet: blind-spot / rear cross-traffic radar calibration	Sublet	\$385.00
Sublet: four-wheel alignment	Sublet	\$149.00
Shop supplies & hazardous waste disposal (supplement)	Misc	\$35.01

	Amount
Taxable parts & materials (net of credits)	\$4,848.63
Labor, sublet & non-taxable	\$10,131.01
Sales tax 8.25% on parts & materials	\$400.01
Supplement total	\$15,379.65
Preliminary estimate E-4471-01	\$9,480.35
Total repair cost	\$24,860.00

Total repairs of \$24,860.00 — the shop asks Crestline to evaluate the vehicle as a possible total loss.

Fictional people, companies, policies and numbers created for LSH training. Not a real claim file.