

Table of Contents

NOTE: Click on the desired item or	page number to	jump directly	to that page.
------------------------------------	----------------	---------------	---------------

Introduction to Gates Products
Drive Comparison Graphs
Synchronous Drive Comparisons
PowerGrip® GT®2, HTD®, and Timing Belt Drive Selection Procedure - Single Sided
PowerGrip® GT®2 Belt Drives - Single Sided
Belt Lengths and Widths
Pitch Selection Guide
PowerGrip® GT®2, HTD®, and Timing Belt Drive Selection Procedure - Twin Power
PowerGrip® GT®2 Belt Drives - Twin Power
Belt Lengths and Widths
Pitch Selection Guide
PowerGrip® GT®2 Sprocket Information
PowerGrip® HTD® Belt Drives
Belt Lengths and Widths - Single Sided
Belt Width Selection / Torque Ratings - Single Sided & Twin Power
Twin Power Belt Drives
Belt Lengths and Widths - Twin Power .43 Sprocket Information .44 - 45
PowerGrip® Timing Belt Drives
Belt Lengths and Widths - Single Sided
Pitch Selection Guide
Twin Power Belt Drives
Belt Lengths and Widths - Twin Power
Pulley Information
PowerGrip® Long Length Belting
Clamp Plate Specifications
Synchronous Belt Drive Engineering
Belt Tensioning
Synchronous Belt Specifications
Polyflex® JB® Belt Drives
Belt Lengths
Sheave Information
Micro-V° Belt Drives
Polyflex® and Micro-V® Drive Selection Procedures
Polyflex® JB® Power Ratings
Micro-V® Power Ratings
Polyflex® and Micro-V® Belt Drive Engineering
Belt Tensioning
Polyflex® Sheave Groove Specifications
Micro-V® Pulley Groove Specifications
Useful Formulas and Calculations

Introduction

Gates belt drive systems offer more advantages at lower cost than other methods of motion transfer or power transmission.

The popularity of Gates drive systems can be attributed to our commitment to customer satisfaction and quality.

Gates continually makes strides in specialized research, product development, testing and overnight availability of products. The team of your design engineers and Gates application engineers assures an efficient, low-cost and quality drive system.

Total quality support

Gates offers professional support from conceptual design to delivery of the finished product. We make sure you...

- use the best product for the application
- · minimize drive package size and cost
- minimize testing time using our experience

Experienced technical support

Our seasoned Application Engineering Group is waiting for you to tap their knowledge. They are armed with the latest in design software and are ready to make your ideas a reality.

Continuous engineering support is available for complex drive layouts including hardware design and specifications.

$(PD + pd) + \pi \phi (P)$ **MADE-TO-ORDER METALS**


(800) 709-6001

CUSTOMER SERVICE


(877) 782-3587

PRODUCT APPLICATION


(303) 744-5800 (303) 744-4600 fax ptpasupport@gates.com



Introduction – PowerGrip® GT®2 Belt Drives



PowerGrip® GT® 2 Belt Tooth/Groove Contact



PowerGrip® HTD® Belt Tooth/Groove Contact



PowerGrip® Timing Belt Tooth/Groove Contact

PowerGrip® GT®2 Belts are an advanced design of Gates HTD® system and feature:

- a modified curvilinear belt tooth profile with mating sprocket groove.
- registration and indexing accuracy equivalent to the conventional PowerGrip Timing Belt System.
- a higher load-carrying capacity and longer belt life than either PowerGrip HTD or Timing belts.

It's difficult to make a true quantitative comparison between the backlash of a trapezoidal tooth drive and PowerGrip® GT®2 tooth drive due to the difference in "sprocket to belt tooth" fit. (See illustrations at left). Trapezoidal belts contact the sprocket in the root radius — upper flank area only, while the PowerGrip® GT®2 system permits full flank contact.

The main stress line in a trapezoidal tooth timing belt is at the tooth base. During operation stress greatly reduces belt life. The PowerGrip® GT®2 system overcomes this with complete tooth flank contact...which eliminates the tooth stress line area. This greatly increases belt life and prevents tooth distortion caused by drive torque. In addition, the conventional timing belt has a chordal effect as it wraps small sprockets. This is significantly reduced in the PowerGrip® GT®2 system due to full tooth support along the sprocket. Full support improves meshing, reduces vibration and minimizes tooth deformation.

On drives using a low installation tension, small pulleys, and light loads, the backlash of the PowerGrip® GT®2 system will be slightly better than the trapezoidal timing belt system. However, with increased tension and/or loads and/or sprocket sizes, the performance of the PowerGrip® GT®2 system becomes significantly better than the trapezoidal timing belt system.

HTD was developed for high torque drive applications, but is not acceptable for most precision indexing or registration applications. The HTD design requires substantial belt tooth to sprocket groove clearance (backlash) to perform. As smaller diameter sprockets are used, the clearance required to operate properly is increased. HTD drive clearance, using small diameter sprockets, is approximately four times greater than an equivalent timing belt drive.

The PowerGrip® GT® 2 deep tooth profile provides...

- increased contact area and improves resistance to ratcheting.
- easy, clean entering and exiting the sprocket grooves...resulting in reduced vibration.
- parallel contact with the groove and eliminates stress concentrations and tooth deformation under load.
- improved registration characteristics and maintains high torque carrying capability.



Introduction – PowerGrip® GT®2 Belt Drives

This PowerGrip® GT®2 synchronous belt fits in tight, hard to fit applications with room to spare.

Lasts longer than competitive belts

PowerGrip® GT®2 belts were tested against the competition, under equivalent conditions, at speeds up to 9,000 RPM. They outlasted the competition more than two to one. Here's why...

- Fiberglass tensile cords wrapped in a durable neoprene body provide flexibility and increase service life.
- Deep tooth profile provides superior loadcarrying strength and reduces ratcheting when using Gates sprockets.
- A durable nylon fabric tooth covering increases tooth strength and provides wear and abrasion resistance.

Precision registration

PowerGrip® GT®2 belts provide timing and synchronization accuracy for flawless registration, with no loss of torque carrying capability.

Increases load-carrying capacity

Load capacities exceed HTD and trapezoidal belt capabilities...making PowerGrip® GT®2 the choice for accurate registration, heavy loads and small sprockets. Smaller and tougher than HTD or trapezoidal belts, PowerGrip® GT®2 belts give engineers more space-saving flexibility for micro-technology.

Sounds this quiet ...

PowerGrip® GT®2 belt's specially engineered teeth reduce noise and vibration. Clean meshing and reduced belt width results in noise reduction when compared to PowerGrip Timing and HTD belts.

When precision is critical, depend on PowerGrip®GT®2 belts

PowerGrip® GT®2 belts are designed for precision applications. Custom-built constructions are available for applications requiring maximum performance. Worldwide manufacturing capabilities assure you of prompt service for important markets.

PowerGrip® GT® 2 belts are available in 2mm, 3mm and 5mm pitches. Larger 8mm and 14mm pitch belts are also available. See Catalog 17195 - PowerGrip® GT® 2 Belt Drive Design Manual.

2mm 3mm


PowerGrip® GT®2 Belt Profiles/Pitches

Here are some of the many PowerGrip® GT®2 belt applications:

- data storage equipment
- machine tools
- hand power tools
- postage handling equipment
- DC stepper/servo applications
- food processors
- centrifuges
- printers
- · floor care equipment
- · money handling equipment
- medical diagnostic equipment
- sewing machines
- · automated teller machines
- ticket dispensers
- plotters
- copiers
- · robotics equipment
- · vending equipment
- vacuum cleaners
- · office equipment

PowerGrip® GT®2 Belt Drives Pages 13-35

Introduction – PowerGrip® HTD® Belt Drives



PowerGrip® HTD® Belt Profiles/Pitches

Good torque carrying capability and design versatility

PowerGrip HTD drives provide advantages over conventional gear and chain type drives...

- run quiet
- do not need lubricating
- · require virtually zero maintenance
- · high reliability and low operating costs

Gates 3mm and 5mm pitch HTD belts are capable of operating at both low and high speeds while carrying heavy loads. They can provide higher speed ratios than comparable XL and L pitch timing belts in the same space. Compared to conventional timing belts, they transmit the same power in a more compact drive package.

HTD belts have the same characteristics as larger 8mm and 14mm pitch belts, but are designed for smaller horsepower and higher speed requirements.

3mm and 5mm pitch HTD belts provide positive non-slip power transmission with many advantages over conventional drive systems. They can handle tough applications, even those subject to sudden shock and overloading.

Some PowerGrip HTD Belt Applications are:

- floor polishers
- vacuum cleaners
- · sewing machines
- sanders
- office equipment
- planers
- centrifuges
- diagnostic equipment
- power tools
- · vending machines
- juicers

PowerGrip HTD Drives Pages 36-45

PowerGrip® Timing Belt Drives



PowerGrip® Timing Belt Profiles/Pitches

Provide positive, non-slip power transmission

PowerGrip Timing Belts are a good standard line product with a history of reliability. Around for over 60 years, this product line was the flagship of synchronous power transmission prior to Gates introduction of PowerGrip HTD and GT Belts.

Gates timing belts are made with a true design pitch, a standard of the Rubber Manufacturers Association and the International Standards Organization.

PowerGrip Timing Belts Application Types:

- office equipment
- · money handling equipment
- food processors
- medical equipment
- robotics
- data processing equipment
- miniaturized applications
- · mailing equipment
- printers/plotters

PowerGrip Timing Drives Pages . . . 46-50

Introduction – PowerGrip® Twin Power® Belt Drives

Dual driving surfaces allow for unique,

Gates Twin Power Belts have teeth on both sides to provide synchronization from both driving surfaces.

This feature makes possible drive designs such as

multi-point drives, rotation reversal with one belt,

serpentine drives, etc. Twin Power belts provide

Twin Power Belts are similar in construction to

problem solving drive designs

solutions to difficult design problems.



PowerGrip Twin Power Timing Belt Profile/Pitch



PowerGrip Twin Power HTD Timing Belt Profile/Pitch




regular synchronous belts, including nylon-faced teeth on both sides. This construction uses essentially the same design parameters as standard synchronous belts. They are rated at the same horsepower capacity as conventional PowerGrip Belts of identical pitch and width on either side of the belt.

NOTE: Twin Power Belts are available in GT2. HTD and Timing Belt configurations, so designers can use them in a wide variety of applications.

Some typical PowerGrip Twin Power applications are:

- copiers
- serpentine drives
- reversing rotations

PowerGrip GT2 Twin Power Belts . . . Pages 22-23 PowerGrip HTD Twin Power Belts ... Pages 42-43 PowerGrip Twin Power Belts Pages 51-52



PowerGrip Twin Power GT2 Timing Belt Profile/Pitch

PowerGrip® Long Length Belting

For drives that require belt lengths longer than can be produced in the conventional endless form

PowerGrip Long-length Belting has the same basic construction as conventional Gates timing belts. Gates can make continuous belting in spiral cut form on a made-to-order basis.

For information or assistance on any long length belt problem, contact Gates Application Engineering.

Typical PowerGrip Long Length Belting uses are:

- reciprocating carriage drives
- rack and pinion drives
- large plotters

PowerGrip Long Length Belting Page 54 Clamp Plate Specifications Page 55



Introduction – Polyflex® JB® Belt Drives







Polyflex® JB Belt Profile

Gates Polyflex® JB® is a joined belt with a different angle

"High Power Density" is what you get from this high-precision belt. Developed by Gates and produced using patented manufacturing processes, Polyflex JB belts provide load-carrying capacity at higher speeds on precision applications. Polyflex JB belts can operate at shaft speeds well in excess of 10,000 rpm.

Polyflex JB features joined belt construction for stability. Backside ribs relieve bending stress on small sheaves and provide lateral rigidity. The 60° angle provides more undercord support to the tensile section and distributes the load evenly.

The small cross-section allows belts to be used on short centers and small diameter sheaves for "cleaner" machine designs. It virtually eliminates the need for double-reduction drives and lets you use more cost-effective single-reduction drives.

Gates Polyflex JB belts are a homogenous product. State-of-the-art manufacturing processes assure uniformity of construction, resulting in minimal vibration and smooth operation on precision applications.

Gates special high modulus polyurethane compound has a high coefficient of friction that resists fatigue, wear, ozone and most adverse environmental conditions.


Cost Savings — **PLUS!** Polyflex JB belts bring V-belt economy and simplicity to applications where conventional V-belts are not feasible, resulting in cost savings and design freedom never before possible.

Typical Polyflex JB applications are:


- computer peripherals
- bench-type milling machines
- glass blowing lathes
- · valve grinding machines
- · crankshaft grinding machines
- woodworking spindle drives
- · horizontal milling machines
- · dental grinders
- floor care equipment
- microfiche readers
- · drilling machines
- lathe drives
- · knife grinders
- scissor sharpeners
- centrifuges
- blowers
- wheelchairs
- optical lens grinders
- fans
- metalworking spindle drives

Polyflex JB Drives Pages......77-81

For additional Polyflex and data refer to Gates Heavy Duty V-Belt Drive Design Manual #14995-A



Introduction – Micro-V® Belt Drives



Micro-V Belt Profiles

For the best ribs around, look no further than Gates Micro-V® Belts

Truncated tooth profile increases flexibility and reduces heat

Gates Micro-V Belts outperform other V-ribbed belts because the Vees are shorter. The truncated (shortened) profile of the Vees give Gates Micro-V Belts increased flexibility, reduced heat buildup and lets them perform at extra high speeds on smaller diameter sheaves.

Gates exclusive truncated design gives you...

- 80% higher horsepower capacity than RMA standards.
- extra load-carrying capacity for extra long life.
- Truncated belt ribs for improved wedging in the pulley grooves and greater load capacity.


Micro-V Belts are smooth running and resistant to oil, heat and other adverse conditions. Plus, undercords are static conductive.

Just some of the applications for Micro-V Belts are:

- · high speed machine tools
- · milling lathes
- washing machines
- precision surface grinders
- floor polishers
- tool grinders
- high-speed printing presses
- centrifuges
- agitators
- precision center lathes
- pumps
- high-speed atomizers
- trash compactors
- planers and molders
- dryers
- food slicers
- · electric massagers
- lawn mowers
- juice mixers
- industrial vacuum cleaners
- microwave ovens
- bakery equipment


Micro-V Drives Pages 82-83

For additional Micro-V Belt data refer to Gates Heavy Duty V-Belt Drive Design Manual 14995-A.




Drive Comparison Graphs

High Speed Drive Rating Graph The following graph contains a representation of horsepower ratings, over a wide speed range, of the belt types represented in this catalog. The sprocket/pulley/sheave diameters and belt widths are all comparable for a realistic comparison of product capability.



Low Speed Synchronous Drive Rating Graph

The following graph provides a comparison of the rated torque carrying capabilities of synchronous belts, on small diameter sprockets/pulleys at low speeds. The sprocket/ pulley diameters and belt widths are all comparable for a realistic comparison.



Synchronous Drive Comparisons

Designers and engineers find that PowerGrip belt drives provide exceptional versatility and reliability. Small and lighter weight drive packages can be used in a wide variety of applications. PowerGrip drives also offer efficient operation over a wide range of loads and speeds.

Drive Package Comparison

Compact, space saving belt drives can be designed with high-performance drive systems like PowerGrip® GT®2. As illustrated, PowerGrip® GT®2 drives are significantly narrower than comparably designed PowerGrip HTD and PowerGrip Timing Belt drives, resulting in space, weight and cost savings.

3mm PowerGrip® GT®2 Belt Drive - 9mm

DriveR: 3MR-30S-09 (1.128 P.D.) DriveN: 3MR-60S-09 (2.256 P.D.)


Belt Width: 9mm



3mm PowerGrip HTD® Belt Drive - 15mm

DriveR: P30-3M-15 (1.128 P.D.) DriveN: P60-3M-15 (2.256 P.D.)


Belt Width: 15mm



XL® PowerGrip Timing Belt Drive – 25mm

DriveN: 18XL100 (1.146 P.D.) DriveN: 36XL100 (2.292 P.D.)

Belt Width: 25mm



Synchronous Drive Comparisons - continued


The development of the PowerGrip® GT®2 belt has produced an impressive range of enhanced properties and subsequent design opportunities for engineers.


The following comparative studies have been included to allow designers to make quantitative assessments and to highlight the most significant improvements and design opportunities.

Particularly significant points from the following comparative studies are:

Durability

The greatly increased durability of the PowerGrip® GT®2 design has resulted in power capacities far above those quoted for similar size belts. The resulting small drive packages will increase design flexibility, space utilization and cost effectiveness.







Speed: 2300 rpm Power: 3.35 lb-in/mm width Pulleys: DriveR - 20 grooves DriveN - 20 grooves


Tooth Jump Resistance

The very significant improvement in tooth jump resistance of PowerGrip® GT®2 when compared to similar belts has several important advantages.

- a. Ratcheting resistance during high start-up torques.
- **b.** Reduced bearing loads, particularly in fixed-center drives. Lower average tensions can be used without encountering tooth jump at the low-tension end of the tolerance ranges.
- **c.** Reduced system losses result from lower pretensioning, with less potential for tooth jumping.








Synchronous Drive Comparisons

Noise

The smoother meshing action of the PowerGrip® GT®2 belt, with its optimized design produces significantly lower noise levels when compared with other, similar sized belt types operating under similar speeds and tensions. These improvements are enhanced by the fact that narrower belts can be used due to increased power capacities.




 Belt
 No, of teeth - 188

 Width - 15mm

 Pulleys
 DriveR - 26 grooves

 DriveN - 26 grooves

Microphone location midway between the sprockets, 100mm from the belt edge



 Belt
 No. of teeth - 118

 Width - 30mm

 Pulleys
 DriveR - 20 grooves


 DriveN - 20 grooves


Microphone location midway between the sprockets, 100mm from the belt edge

Positioning Accuracy

The PowerGrip® HTD® belt tooth forms were primarily designed to transmit high torque loads. This requirement increased tooth to groove clearances which resulted in increased backlash when compared with the original classical designs.

PowerGrip® GT®2 has reversed this with power capacities now exceeding those of PowerGrip® HTD® while giving equivalent or higher levels of positional accuracy than PowerGrip Timing belts.





PowerGrip® GT®2, HTD® and Timing Belt Drive Selection Procedure – single sided

Step 1. Determine design load.

Service factors between 1.5 and 2.0 are generally recommended when designing small pitch synchronous drives. Knowledge of drive loading characteristics should influence the actual value selected. A higher service factor should be selected for applications with high peak loads, high operating speeds, unusually severe operating conditions, etc. Lower service factors can be used when the loading is smooth, well defined, etc. and the reliability is less critical. Some designs may require service factors outside the 1.5 to 2.0 range, depending upon the nature of the application. Contact Gates Application Engineering for additional information.

Stall torque of the driveR, or peak torque of the driveN unit, may be part of the nameplate data. If not, calculate Torque (Q) by using these formulas:

$$\mbox{Q (lb - in)} = \; \frac{63{,}025 \; \mbox{x Shaft HP}}{\mbox{Shaft RPM}} \; , \label{eq:quantum_potential}$$

 $Q (lb - in) = 8.85 \times Q (N - m) or$

 $Q (oz - in) = 16 \times Q (lb - in)$

Peak Design Load = Load x Service Factor

NOTE: When performing drive calculations based upon torque loads, drive input/output power is constant but drive input/output torque is not. Drive input/output torque is a function of the speed ratio. Drive designs should be based upon the smaller, faster sprocket, at the torque load calculated for its operating speed. These critical drive parameters should be used for all engineering calculations. See engineering calculations on Page 102 for additional formulas and unit conversions.

Step 2. Determine belt pitch and select sprockets.

- **A.** Select Belt Pitch by using the Belt Pitch Selection Guide on pages 25, 39 and 49.
- **B.** Determine the speed ratio by dividing the larger speed, Sprocket Pitch Diameter or Sprocket Groove Number by the lesser speed, Sprocket Pitch Diameter or Sprocket Groove Number.
- C. Refer to the appropriate Sprocket Diameter Tables on pages 29-31, pages 44-45 or page 53. Select sprockets based upon speed ratio and drive requirements. Use stock sprocket sizes whenever possible.

D. Check the Belt Speed, V, of the smaller sprocket selected, using the following formula:

V (fpm) = 0.262 x Sprocket PD (in) x Sprocket RPM

V (m/s) = 0.0000524 x Sprocket PD (mm) x Sprocket RPM and

m/s = 0.00508 x fpm

NOTE: Belt speeds in excess of 6,500 fpm (33.02 m/s) require special sprocket materials and dynamic balancing.

Step 3. Determine belt length and nominal center distance.

A. Using the allowable range of center distances required by the drive design, calculate the belt Pitch Length (PL) using the following formula:

$$PL = 2CD + [1.57 \times (PD + pd)] + \frac{(PD - pd)^2}{4CD}$$

Where CD = Drive center distance (in)

PD = Large pitch diameter (in)

pd = Small pitch diameter (in)

Using the calculated range of pitch lengths, select a belt of the proper length from the appropriate belt length table. Use a standard length as shown in the tables on pages 15-16, pages 37-38 or pages 47-48, if possible.

B. The approximate nominal center distance for the drive can be calculated using the following formula:

Center distance =
$$\frac{\text{K} + \sqrt{\text{K}^2 - 32 \text{ (PD - pd)}^2}}{16}$$

 $\text{K} = 4\text{PL - 6.28 \text{ (PD + pd)}}$

Where PD = Large pitch diameter (in)

pd = Small pitch diameter (in)

PL = Belt pitch length (in)

See Engineering calculations on page 102 or contact Gates Application Engineering for accuracy within 0.001".

Step 4. Determine belt width.

Belt Width Selection Tables on pages 18-21, pages 40-41 and page 50 show the load ratings for the stock widths of each of the stock belt pitches. Using the smaller sprocket groove number and rpm as determined in Step 2, locate a torque or horsepower rating in the Belt Width Selection Tables of the proper belt pitch nearest to, but greater than,

the peak design load from Step 1. Torque or horsepower ratings for various belt widths can be calculated by multiplying the table rating by the appropriate belt width multiplier.

When designing with PowerGrip® GT®2 or HTD, use the belt length from Step 3 to find the proper belt length factor in the Length Factor Tables included with each Belt Width Selection table. Multiply the torque rating selected above by the belt length factor to obtain the corrected rating. For all designs, the torque or horsepower rating must be equal to, or greater than, the peak design load of Step 1.

NOTE: The torque or horsepower ratings are based on 6 or more teeth in mesh for the smaller sprocket. Calculate the teeth in mesh for the selected drive design using the Teeth In Mesh Formula on Page 103. If the teeth in mesh is less than 6, the drive must be de-rated as indicated, which may require redesign for additional drive capacity.

Step 5. Determine proper belt installation tension.

Procedures to calculate proper belt installation tension for specific applications are included on pages 60-62.

Step 6. Check and specify drive components.

After the drive system components have been selected and checked against drive system requirements, contact Gates Application Engineering before going into production.


Helpline: (303)744-5800 E-mail: ptpasupport@gates.com

Belt Construction

PowerGrip® GT®2 drives provide positive, trouble-free power transmission in low-speed high-torque applications and offer many advantages over conventional chain, gear and other belt drives.

Advantages:

- · Higher capacity
- · Improved registration
- Reduced noise
- No lubrication required
- · Minimal elongation due to wear
- Corrosion resistance
- Excellent abrasion resistance
- Clean operation
- Long trouble-free service




Construction Features

The tooth design substantially improves stress distribution and allows heavy loading. The molded teeth enter and leave the sprocket grooves smoothly with negligible friction — functioning in much the same way as teeth on a gear.

Construction consists of these components:

- **1. Tensile Member** Provides high strength, excellent flex life and high resistance to elongation.
- 2. **Neoprene Backing** Strong Neoprene bonded to the tensile member for protection against grime, oil and moisture. It also protects from frictional wear if idlers are used on the back of the belt.
- 3. **Neoprene Teeth** Shear-resistant Neoprene compound is molded integrally with the Neoprene backing. They are precisely formed and accurately spaced to assure smooth meshing with the sprocket grooves.
- 4. Nylon Facing Tough nylon fabric with a low coefficient of friction covers the wearing surfaces of the belt. It protects the tooth surfaces and provides a durable wearing surface for long service.



Single Sided Belt Drive Systems

Gates 2mm, 3mm and 5mm pitch PowerGrip® GT®2 belts have helically-wound fiberglass tension members embedded in a Neoprene body with the belt teeth faced with a tough wear-resistant nylon fabric.

As shown below, three principal dimensions of a belt (Pitch, Pitch Length and Width) in millimeters are used to specify a PowerGrip® GT®2 belt:

3MR	300	09
Pitch	Pitch Length	Width


Belt pitch is the distance in millimeters between two adjacent tooth centers as measured on the pitch line of the belt. Belt pitch length is the total length (circumference) in millimeters as measured along the pitch line. The theoretical pitch line of a PowerGrip® GT®2 belt lies within the tensile member.


Three principal dimensions of a sprocket — number of grooves, pitch and belt width in millimeters — are used to specify a PowerGrip® GT®2 sprocket as shown below:


3MR	22 \$	09
Pitch	Number of Grooves	Belt Width


PowerGrip® GT®2 drives have a higher load capacity than PowerGrip® HTD® and PowerGrip® Timing drives. They also feature equivalent or better backlash characteristics when compared to PowerGrip® Timing drives. These attributes make PowerGrip® GT®2 the drive of choice for today's design engineers.

PowerGrip® GT®2 belts must run in PowerGrip® GT®2 sprockets. PowerGrip® GT®2 belts are not compatible with PowerGrip® HTD® sprockets, or any other sprockets available on the market.









PowerGrip® GT®2 Belt Lengths and Widths

						2m	m Pitch	Belt Lengths	5						
Description	Pitch L (mm)	ength (in)	No. of Teeth	Description	Pitch (mm)	Length (in)	No. of Teeth	Description	Pitch (mm)	Length (in)	No. of Teeth	Description	Pitch (mm)	Length (in)	No. of Teeth
2MR-74 2MR-76 •2MR-100 •2MR-112 •2MR-124 •2MR-126 •2MR-130 •2MR-132 •2MR-134 •2MR-140 2MR-140	74 76 100 112 124 126 130 132 134 136 140 142	2.913 2.992 3.937 4.409 4.882 4.961 5.118 5.197 5.276 5.354 5.512 5.591	37 38 50 56 62 63 65 66 67 68 70	•2MR-186 •2MR-192 •2MR-200 •2MR-202 2MR-208 •2MR-210 •2MR-216 •2MR-216 •2MR-220 2MR-224 •2MR-232 •2MR-236	186 192 200 202 208 210 212 216 220 224 232 236	7.323 7.559 7.874 7.953 8.189 8.268 8.346 8.504 8.661 8.819 9.134 9.291	93 96 100 101 104 105 106 108 110 112 116 118	2MR-286 2MR-288 •2MR-300 2MR-318 •2MR-320 •2MR-322 •2MR-332 •2MR-346 •2MR-350 2MR-356 •2MR-364 •2MR-370	286 288 300 318 320 322 332 346 350 356 364 370	11.260 11.339 11.811 12.520 12.598 12.677 13.071 13.622 13.780 14.016 14.331 14.567	143 144 150 159 160 161 166 173 175 178 182	•2MR-456 •2MR-470 •2MR-474 •2MR-488 2MR-502 •2MR-504 •2MR-528 2MR-544 •2MR-552 •2MR-576 •2MR-600 •2MR-640	456 470 474 488 502 504 528 544 552 576 600 640	17.953 18.504 18.661 19.213 19.764 19.843 20.787 21.417 21.732 22.677 23.622 25.197	228 235 237 244 251 252 264 272 276 288 300 320
•2MR-152 •2MR-158 •2MR-160 •2MR-164 •2MR-166 •2MR-168 •2MR-172 •2MR-172	152 158 160 164 166 168 172 180	5.984 6.220 6.299 6.457 6.535 6.614 6.772 7.087	76 79 80 82 83 84 86 90	•2MR-240 2MR-242 •2MR-250 •2MR-252 •2MR-258 2MR-264 •2MR-278 •2MR-280	240 242 250 252 258 264 278 280	9.449 9.528 9.843 9.921 10.157 10.394 10.945 11.024	120 121 125 126 129 132 139 140	•2MR-380 •2MR-386 •2MR-392 •2MR-400 •2MR-406 •2MR-420 2MR-428 2MR-430	380 386 392 400 406 420 428 430	14.961 15.197 15.433 15.748 15.984 16.535 16.850 16.929	190 193 196 200 203 210 214 215	2MR-660 •2MR-696 •2MR-744 •2MR-848 •2MR-1164 2MR-1700	660 696 744 848 1164 1700	25.984 27.402 29.291 33.386 45.827 66.929	330 348 372 424 582 850

Stock lengths are denoted by a ullet. All other sizes, contact Gates Customer Service for availablity.

2mm Pitch Stock Belt Widths												
Belt Width Code	Belt Width (mm)	Belt Width (in)										
04	4	0.157										
06	6	0.236										
09	9	0.354										

						3mi	m Pitch I	Belt Length:	5						
	Pitch L	ength.	No. of		Pitch	Length	No. of		Pitch		No. of		Pitch	Length	No. of
Description	(mm)	(in)	Teeth	Description	(mm)	(in)	Teeth	Description	(mm)	(in)	Teeth	Description	(mm)	(in)	Teeth
•3MR-99	99	3.898	33	3MR-252	252	9.921	84	3MR-408	408	16.063	136	•3MR-552	552	21.732	184
•3MR-111	111	4.370	37	•3MR-255	255	10.039	85	•3MR-414	414	16.299	138	•3MR-564	564	22.205	188
•3MR-123	123	4.843	41	•3MR-267	267	10.512	89	•3MR-420	420	16.535	140	•3MR-600	600	23.622	200
•3MR-129	129	5.079	43	•3MR-282	282	11.102	94	•3MR-447	447	17.598	149	•3MR-630	630	24.803	210
•3MR-159	159	6.260	53	3MR-285	285	11.220	95	•3MR-450	450	17.717	150	•3MR-684	684	26.929	228
•3MR-165	165	6.496	55	•3MR-291	291	11.457	97	•3MR-474	474	18.661	158	•3MR-735	735	28.937	245
•3MR-180	180	7.087	60	•3MR-300	300	11.811	100	•3MR-480	480	18.898	160	•3MR-750	750	29.528	250
•3MR-183	183	7.205	61	•3MR-339	339	13.346	113	•3MR-483	483	19.016	161	•3MR-786	786	30.945	262
•3MR-189	189	7.441	63	•3MR-348	348	13.701	116	•3MR-489	489	19.252	163	•3MR-840	840	33.071	280
3MR-195	195	7.677	65	•3MR-357	357	14.055	119	3MR-495	495	19.488	165	•3MR-945	945	37.205	315
•3MR-201	201	7.913	67	●3MR-360	360	14.173	120	3MR-501	501	19.724	167	•3MR-1050	1050	41.339	350
•3MR-219	219	8.622	73	3MR-363	363	14.291	121	•3MR-504	504	19.843	168	•3MR-1080	1080	42.520	360
•3MR-225	225	8.858	75	●3MR-375	375	14.764	125	3MR-510	510	20.079	170	•3MR-1536	1536	60.472	512
•3MR-240	240	9.449	80	3MR-390	390	15.354	130	3MR-513	513	20.197	171	•3MR-1587	1587	62.480	529
•3MR-243	243	9.567	81	●3MR-393	393	15.472	131	•3MR-537	537	21.142	179	•3MR-2061	2061	81.142	687

Stock lengths denoted by a •. All other sizes, contact Gates Customer Service for availablity.

3mm Pitch Stock Belt Widths												
Belt Width Code	Belt Width (mm)	Belt Width (in)										
06	6	0.236										
09	9	0.354										
15	15	0.591										


PowerGrip® GT®2 Belt Lengths and Widths – *continued*

						5mi	m Pitch I	Belt Length:	S						
Description	Pitch (mm)	Length (in)	No. of Teeth	Description	Pitch (mm)	Pitch Length (mm) (in)		Description			No. of Teeth	Description	Pitch (mm)	Length (in)	No. of Teeth
5MR-225	225	8.858	45	•5MR-375	375	14.764	75	5MR-550	550	21.654	110	•5MR-900	900	35.433	180
5MR-250	250	9.843	50	•5MR-400	400	15.748	80	•5MR-565	565	22.244	113	5MR-950	950	37.402	190
5MR-265	265	10.433	53	•5MR-405	405	15.945	81	•5MR-575	575	22.638	115	•5MR-1000	1000	39.370	200
5MR-275	275	10.827	55	5MR-410	410	16.142	82	•5MR-580	580	22.835	116	5MR-1050	1050	41.339	210
5MR-285	285	11.220	57	•5MR-425	425	16.732	85	•5MR-600	600	23.622	120	•5MR-1150	1150	45.276	230
•5MR-300	300	11.811	60	●5MR-450	450	17.717	90	●5MR-625	625	24.606	125	•5MR-1300	1300	51.181	260
5MR-325	325	12.795	65	5MR-460	460	18.110	92	●5MR-650	650	25.591	130	•5MR-1450	1450	57.087	290
5MR-330	330	12.992	66	5MR-475	475	18.701	95	●5MR-700	700	27.559	140	•5MR-1600	1600	62.992	320
5MR-340	340	13.386	68	●5MR-500	500	19.685	100	●5MR-750	750	29.528	150	•5MR-1720	1720	67.717	344
5MR-350	350	13.780	70	5MR-525	525	20.669	105	●5MR-800	800	31.496	160	•5MR-1755	1755	69.094	351
●5MR-355	355	13.976	71	●5MR-535	535	21.063	107	●5MR-815	815	32.087	163	●5MR-2100	2100	82.677	420
5MR-360	360	14.173	72	5MR-540	540	21.260	108	●5MR-850	850	33.465	170	5MR-2440	2440	96.063	488

Stock lengths are denoted by a •. All other sizes, contact Gates Customer Service for availablity.

5mm Pitch Stock Belt Widths												
Belt Width Code	Belt Width (mm)	Belt Width (in)										
09	9	0.354										
15	15	0.591										
25	25	0.984										

Belt Pitch Selection Guide



Belt Width Selection Tables – 2mm PowerGrip® GT®2 Belts

The following table represents the torque ratings for each belt in its base width at the predetermined number of grooves, pitch diameters and rpm. These ratings must be multiplied by the appropriate width factor and applicable belt length factor to obtain the corrected torque rating. (See Step 4 of Drive Selection Procedure on Page 12.)

Belt Width (mm)	4	6	9	12
Width Multiplier	0.67	1.00	1.50	2.00

				Rated	Torque ((lb-in) F	or Smal	I Sprock	cet - 6m	m Be	lt Wid	lth				
Number of Grooves	12	14	16	18	20	24	28	32	36		0	45	56	62	74	80
Pitch mm	7.64	8.91	10.19	11.46	12.73	15.28	17.83	20.37	22.92	25		28.65	35.65	39.47	47.11	50.93
Diameter (in)	0.301	0.351	0.401	0.451	0.501	0.602	0.702	0.802	0.902	1.0		1.128	1.404	1.154	1.855	2.005
10 20	0.90 0.89	1.09 1.07	1.27 1.25	1.45 1.42	1.63 1.60	1.99 1.96	2.35 2.31	2.71 2.66	3.07 3.01	3.	37	3.87 3.80	4.84 4.76	5.37 5.28	6.43 6.32	6.95 6.83
40 60	0.87 0.86	1.05 1.03	1.22 1.21	1.40 1.38	1.57 1.55	1.92 1.90	2.27 2.25	2.62 2.59	2.96 2.93	3.	31 27	3.74 3.70	4.68 4.63	5.19 5.13	6.21 6.14	6.71 6.64
100	0.85	1.02	1.19	1.36 1.34	1.53 1.50	1.88	2.22	2.55 2.51	2.89 2.84	3.	23	3.65 3.58	4.57	5.07 4.98	6.06 5.95	6.56 6.44
200 300 400	0.83 0.82	1.00 0.99	1.17 1.15	1.32	1.49	1.84 1.82	2.15	2.48	2.81	3.	14	3.54	4.49 4.44	4.92	5.89	6.37
500	0.81 0.80	0.98 0.97	1.14 1.14	1.31 1.30	1.47 1.46	1.81 1.79	2.13 2.12	2.46 2.44	2.78 2.77	3.	09	3.52 3.49	4.40 4.38	4.88 4.85	5.84 5.81	6.32 6.28
600 800	0.80	0.97 0.96	1.13 1.12	1.29 1.28	1.46 1.44	1.78 1.77	2.11	2.43	2.75	3.		3.48 3.45	4.35 4.32	4.83 4.79	5.78 5.73	6.25 6.20
1000 1200	0.79 0.78	0.95 0.94	1.11	1.27	1.43	1.76 1.75	2.08	2.40	2.71 2.70	3.	03	3.43 3.41	4.29 4.27	4.76 4.74	5.70 5.67	6.16 6.13
1400	0.78	0.94	1.11 1.10	1.26	1.42	1.74	2.06	2.37	2.69	3.	00	3.40	4.25	4.72	5.65	6.11
1600 1800	0.78 0.77	0.94 0.93	1.10 1.09	1.26 1.25	1.41 1.41	1.73 1.73	2.05	2.36 2.36	2.68	2.		3.38 3.37	4.24 4.22	4.70 4.68	5.63 5.61	6.08 6.06
2000 2400	0.77 0.76	0.93 0.92	1.09 1.08	1.25 1.24	1.41 1.40	1.72 1.71	2.04 2.03	2.35 2.34	2.66 2.65	2.	97	3.36 3.34	4.21 4.19	4.67 4.65	5.59 5.56	6.05 6.01
2800 3200	0.76 0.76	0.92 0.92	1.08 1.07	1.23	1.39 1.39	1.71	2.02	2.33	2.63	2.	95	3.33	4.17 4.15	4.63 4.61	5.54 5.51	5.99 5.96
3600	0.75	0.91	1.07	1.22	1.38	1.69	2.00	2.31	2.62	2.5	92	3.30	4.14	4.59	5.50	5.94
4000 5000	0.75 0.75	0.91 0.90	1.06 1.06	1.22 1.21	1.38 1.37	1.69 1.68	2.00 1.98	2.30 2.29	2.61 2.59	2.	90	3.29 3.27	4.13 4.10	4.58 4.55	5.48 5.44	5.92 5.88
6000 8000	0.74 0.73	0.90 0.89	1.05 1.04	1.20 1.19	1.36 1.35	1.67 1.65	1.97 1.95	2.27 2.25	2.58 2.55	2.		3.25 3.23	4.08 4.04	4.52 4.48	5.41 5.36	5.85 5.79
10000 12000	0.73 0.72	0.88 0.88	1.03 1.03	1.18 1.18	1.34 1.33	1.64 1.63	1.94 1.93	2.24 2.22	2.53 2.52	2. 2.	33 82	3.20 3.18	4.01 3.98	4.45 4.42	5.32 5.28	5.75 5.70
න් 14000	0.72	0.87	1.02	1.17	1.32	1.62	1.92	2.21	2.51	2.		3.17	3.96	4.39	0.20	0.70
12000 14000 10 10 20 20							Rated To	orque (N	-m)							
10 E 20	0.10 0.10	0.12 0.12	0.14 0.14	0.16 0.16	0.18 0.18	0.23 0.22	0.27 0.26	0.31 0.30	0.35 0.34	0.0		0.44 0.43	0.55 0.54	0.61 0.60	0.71 0.69	0.73 0.71
40 60	0.10 0.10	0.12 0.12	0.14 0.14	0.16 0.16	0.18 0.18	0.22 0.21	0.26 0.25	0.30 0.29	0.33 0.33	0.:	37	0.42 0.42	0.53 0.52	0.59 0.58	0.68 0.68	0.70 0.69
100	0.10	0.12	0.13	0.15	0.17	0.21	0.25	0.29	0.33	0.3	36	0.41	0.52	0.57	0.67	0.69
200 300	0.09 0.09	0.11 0.11	0.13 0.13	0.15 0.15	0.17 0.17	0.21 0.21	0.25 0.24	0.28 0.28	0.32 0.32	0.0	35	0.40 0.40	0.51 0.50	0.56 0.56	0.65 0.65	0.67 0.67
400 500	0.09 0.09	0.11 0.11	0.13 0.13	0.15 0.15	0.17 0.17	0.20 0.20	0.24 0.24	0.28 0.28	0.31 0.31	0.	35	0.40 0.39	0.50 0.49	0.55 0.55	0.64 0.64	0.66 0.66
600 800	0.09	0.11 0.11	0.13 0.13	0.15	0.16 0.16	0.20	0.24	0.27	0.31	0.3		0.39	0.49 0.49	0.55 0.54	0.64 0.63	0.65 0.65
1000 1200	0.09	0.11 0.11	0.13 0.12	0.14	0.16 0.16	0.20 0.20	0.23	0.27 0.27	0.31	0.0	34	0.39 0.39	0.49 0.48	0.54 0.54	0.63 0.62	0.64 0.64
1400 1600	0.09	0.11 0.11 0.11	0.12 0.12 0.12	0.14	0.16 0.16	0.20 0.20 0.20	0.23 0.23	0.27 0.27 0.27	0.30	0.0	34	0.38 0.38	0.48 0.48	0.53 0.53	0.62 0.62	0.64 0.64
1800	0.09	0.11	0.12	0.14	0.16	0.20	0.23	0.27	0.30	0.3	34	0.38	0.48	0.53	0.62	0.63
2000 2400	0.09 0.09	0.10 0.10	0.12 0.12	0.14 0.14	0.16 0.16	0.19 0.19	0.23 0.23	0.27 0.26	0.30 0.30	0.0	33	0.38 0.38	0.48 0.47	0.53 0.52	0.61 0.61	0.63 0.63
2800 3200	0.09	0.10 0.10	0.12 0.12	0.14 0.14	0.16 0.16	0.19 0.19	0.23 0.23	0.26 0.26	0.30 0.30	0.:	33 33	0.38 0.37	0.47 0.47	0.52 0.52	0.61 0.61	0.63 0.62
3600 4000	0.09	0.10 0.10	0.12 0.12	0.14 0.14	0.16 0.16	0.19 0.19	0.23 0.23	0.26 0.26	0.30 0.29	0.0		0.37 0.37	0.47 0.47	0.52 0.52	0.60 0.60	0.62 0.62
5000 6000	0.08	0.10 0.10 0.10	0.12 0.12 0.12	0.14 0.14 0.14	0.15 0.15	0.19 0.19 0.19	0.22	0.26 0.26	0.29	0.0	33	0.37 0.37 0.37	0.46 0.46	0.51 0.51	0.60 0.59	0.61 0.61
8000	0.08	0.10	0.12	0.13	0.15	0.19	0.22	0.25	0.29	0.3	32	0.36	0.46	0.51	0.59	0.61
10000 12000	0.08 0.08	0.10 0.10	0.12 0.12	0.13 0.13	0.15 0.15	0.19 0.18	0.22 0.22	0.25 0.25	0.29 0.28	0.	32	0.36 0.36	0.45 0.45	0.50 0.50	0.58 0.58	0.60 0.60
14000	0.08	0.10	0.12	0.13	0.15	0.18	0.22	0.25	0.28	0.3		0.36	0.45	0.50		
Length Corre	ction Fa From	Length (mm)	0.70	0.75	0.80	0.85	0.90 170	0.95	1.00 232	1.05 272	1.10 318		1.20 436	1.25 510	1.30 598	1.35 698
For Belt		# of teeth	50	53	62	73	85	99	116	136	159	186	218	255	299	349
Length	То	Length (mm) # of teeth	104 52	122 61	144 72	168 84	196 98	230 115	270 135	316 158	370 185		508 254	596 298	696 348	800 400
			1												0.0	

Belt Width Selection Tables – 3mm PowerGrip® GT®2 Belts

The following table represents the torque ratings for each belt in its base width at the predetermined number of grooves, pitch diameters and rpm's. These ratings must be multiplied by the appropriate width factor and applicable belt length factor to obtain the corrected torque rating. (See Step 4 of Drive Selection Procedure on Page 12.)

Belt Width (mm)	6	9	12	15
Width Multiplier	1.00	1.50	2.00	2.50

				Rated	Torque	(lb-in) F	or Small	Sprocke	et - 6mm	n Belt W	idth				
Number o		40	00		0.4	-00		0.4	-00	45					-00
Grooves Pitch	16 mm 15.28	18 17.19	20 19.10	22 21.01	24 22.92	28 24.83	30 28.65	34 32.47	38 36.29	45 42.97	50 47.75	56 53.48	62 59.21	74 70.66	80 76.39
Diameter (0.752	0.827	0.902	0.977	1.128	1.278	1.429	1.692	1.88	2.105	2.331	2.782	3.008
10 20	14.02 12.82	16.27 14.92	18.50 17.00	20.70 19.05	22.89 21.09	25.06 23.11	29.38 27.13	33.61 31.06	37.82 34.97	45.04 41.67	50.13 46.38	56.15 51.95	62.13 57.48	73.87 68.32	79.67 73.68
40 60	11.62	13.57	15.50 14.62	17.40	19.29	21.16	24.88 23.56	28.51 27.02	32.12	38.29 36.32	42.63 40.44	47.75 45.30	52.83 50.11	62.77 59.53	67.68 64.17
100	10.03	11.78	13.51	16.44 15.22	16.91	18.59	21.90	25.14	30.45 28.35	33.83	37.67	42.20	46.68	55.44	59.74
200 300		10.43 9.64	12.01 11.14	13.57 12.61	15.11 14.06	16.64 15.50	19.65 18.34	22.59 21.10	25.50 23.83	30.45 28.48	33.92 31.73	38.00 35.54	42.03 39.31	49.89 46.64	53.74 50.23
400 500	7.63	9.08 8.65	10.51 10.03	11.92 11.39	13.32 12.74	14.69 14.06	17.40 16.68	20.04 19.22	22.65 21.73	27.08 25.99	30.17 28.96	33.80 32.45	37.38 35.88	44.33 42.54	47.73 45.79
600	6.92	8.29	9.64	10.96	12.26	13.55	16.09	18.55	20.98	25.10	27.97	31.34	34.65	41.07	44.21
800 1000	6.04	7.73 7.30	9.01 8.53	10.27 9.74	11.52 10.94	12.74	15.15 14.43	17.49 16.67	19.79 18.87	23.70 22.60	26.41 25.20	29.59 28.23	32.71 31.20	38.75 36.94	41.69 39.73
1200 1400	5.46	6.94 6.64	8.14 7.80	9.31 8.94	10.46 10.06	11.60 11.16	13.83 13.33	15.99 15.42	18.12 17.48	21.71 20.95	24.20 23.36	27.11 26.16	29.96 28.91	35.45 34.19	38.12 36.74
1600 1800		6.38 6.15	7.51 7.26	8.62 8.34	9.71 9.40	10.78 10.45	12.89 12.51	14.93 14.49	16.93 16.44	20.29 19.71	22.62 21.97	25.34 24.60	27.99 27.17	33.08 32.09	35.54 34.46
2000 2400	4.84	5.94 5.59	7.03 6.63	8.09 7.65	9.13 8.65	10.15 9.64	12.16 11.56	14.10 13.42	16.00 15.23	19.19 18.27	21.39 20.37	23.94 22.79	26.44 25.15	31.20 29.63	33.49 31.77
2800 3200	4.25	5.28 5.02	6.29 6.00	7.28 6.96	8.25 7.90	9.20 8.81	11.05 10.61	12.84 12.33	14.58 14.01	17.49 16.81	19.49 18.72	21.80 20.93	24.04 23.05	28.26 27.04	30.27 28.92
3600	3.81	4.79	5.74	6.67	7.58	8.48	10.22	11.88	13.50	16.20	18.03	20.14	22.16	25.92	27.68
4000 5000	3.24	4.58 4.14	5.51 5.02	6.42 5.87	7.30 6.71	8.17 7.52	9.86 9.10	11.48 10.60	13.04 12.05	15.64 14.42	17.40 16.02	19.41 17.81	21.34 19.50	24.89 22.52	26.52 23.86
6000 8000		3.77 3.19	4.61 3.95	5.42 4.69	6.21 5.40	6.98 6.09	8.46 7.41	9.86 8.63	11.20 9.77	13.38 11.57	14.81 12.70	16.40 13.89	17.87 14.88	20.36 16.27	21.39 16.64
12000	1.99 1.64	2.72 2.32	3.42 2.97	4.10 3.59	4.74 4.17	5.36 4.73	6.53 5.75	7.59 6.64	8.55 7.41	9.97 8.45	10.79 8.93	11.54	12.03		
12000 14000 12000 10000	1.34	1.98	2.57	3.13	3.66	4.15	5.03	5.75	6.33	6.95					
f Fas							Rated Tor								I.
E 20	1.45	1.84 1.69	2.09 1.92	2.34 2.15	2.59 2.38	2.83 2.61	3.32 3.06	3.80 3.51	4.27 3.95	5.09 4.71	5.66 5.24	6.34 5.87	7.02 6.49	8.35 7.72	9.00 8.32
60	1.23	1.53 1.44	1.75 1.65	1.97 1.86	2.18 2.06	2.39 2.26	2.81 2.66	3.22 3.05	3.63 3.44	4.33 4.10	4.82 4.57	5.40 5.12	5.97 5.66	7.09 6.73	7.65 7.25
100 200		1.33 1.18	1.53 1.36	1.72	1.91	2.10	2.47	2.84	3.20 2.88	3.82 3.44	4.26 3.83	4.77 4.29	5.27 4.75	6.26 5.64	6.75 6.07
300 400	0.92	1.09 1.03	1.26 1.19	1.42	1.59 1.50	1.75 1.66	2.07	2.38	2.69 2.56	3.22 3.06	3.58 3.41	4.02 3.82	4.44 4.22	5.27 5.01	5.68 5.39
500 600	0.82	0.98 0.94	1.13	1.29	1.44	1.59 1.53	1.88	2.17	2.45 2.37	2.94 2.84	3.27 3.16	3.67 3.54	4.05 3.92	4.81 4.64	5.17 4.99
800	0.73	0.87	1.02	1.16	1.30	1.44	1.71	1.98	2.24	2.68	2.98	3.34	3.70	4.38	4.71
1000 1200	0.65	0.82 0.78	0.96 0.92	1.10 1.05	1.24 1.18	1.37 1.31	1.63 1.56	1.88 1.81	2.13 2.05	2.55 2.45	2.85 2.73	3.19 3.06	3.53 3.39	4.17 4.01	4.49 4.31
1400 1600	0.62 0.59	0.75 0.72	0.88 0.85	1.01 0.97	1.14 1.10	1.26 1.22	1.51 1.46	1.74 1.69	1.97 1.91	2.37 2.29	2.64 2.56	2.96 2.86	3.27 3.16	3.86 3.74	4.15 4.02
1800 2000		0.69 0.67	0.82 0.79	0.94 0.91	1.06 1.03	1.18 1.15	1.41 1.37	1.64 1.59	1.86 1.81	2.23 2.17	2.48 2.42	2.78 2.71	3.07 2.99	3.63 3.53	3.89 3.78
2400 2800	0.51	0.63 0.60	0.75 0.71	0.86 0.82	0.98 0.93	1.09 1.04	1.31 1.25	1.52 1.45	1.72 1.65	2.06 1.98	2.30 2.20	2.58 2.46	2.84 2.72	3.35 3.19	3.59 3.42
3200	0.45	0.57	0.68	0.79	0.89	1.00	1.20	1.39	1.58	1.90	2.12	2.36	2.60	3.06	3.27
3600 4000	0.41	0.54 0.52	0.65 0.62	0.75 0.73	0.86 0.83	0.96 0.92	1.15	1.34	1.53 1.47	1.83	2.04	2.19	2.50 2.41	2.93 2.81	3.13 3.00
5000 6000	0.33	0.47 0.43	0.57 0.52	0.66 0.61	0.76 0.70	0.85	1.03 0.96	1.20	1.36 1.27	1.63 1.51	1.81	2.01 1.85	2.20	2.55	2.70 2.42
8000 10000		0.36 0.31	0.45 0.39	0.53 0.46	0.61 0.54	0.69 0.61	0.84 0.74	0.97 0.86	1.10 0.97	1.31 1.13	1.44 1.22	1.57	1.68 1.36	1.84	1.88
10000 12000 14000	0.19 0.15	0.26 0.22	0.34 0.29	0.41 0.35	0.47 0.41	0.53 0.47	0.65 0.57	0.75 0.65	0.84 0.72	0.95 0.79	1.01				
	rrection Fa		0.70	0.75	0.80	0.85	-		00 1.05		1.15	1.20	1.25 1	.30 1.3	5 1.40
Longin 60	From	Length (mm)	120	129	153	180			94 348		480	567		'86 924	
For Belt	Te	# of teeth	40	43	51	60			98 116		160	189		262 308	
Length	То	Length (mm) # of teeth	126 42	150 50	177 59	210 70	249 29 83 9		45 405 15 135		564 188	663 221		921 1089 307 363	

Shaded area indicates drive conditions where reduced service life can be expected. Contact Gates Application Engineering for specific recommendations.



Belt Width Selection Tables – 5mm PowerGrip® GT®2 Belts

The following table represents the torque ratings for each belt in its base width at the predetermined number of grooves, pitch diameters and rpm's. These ratings must be multiplied by the appropriate width factor and applicable belt length factor to obtain the corrected torque rating, (See Step 4 of Drive Selection Procedure on Page 12.)

Belt Width (mm) 9	15	20	25
Width Multiplier	0.60	1.00	1.33	1.67

				Rated T	orque (I	b-in) Fo	Small S	Sprocke	t - 15mr	n Belt W	idth*				
Number of															
Grooves	18	20	22	24	26	28	32	36	40	45	50	56	62	74	80
Pitch mm Diameter (in)	28.65 1.128		35.01 1.379	38.20 1.504	41.38 1.629	44.56 1.754	50.93 2.005	57.30 2.256	63.66 2.506	71.62 2.820	79.58 3.133	89.13 3.509	98.68 3.885	117.77 4.637	127.32 5.013
10	78.24		109.00	124.20	139.30	154.3	184.3	214.10	243.6	280.3	316.6	359.9	403.0	488.3	530.6
20	72.38	87.11	101.80	116.40	130.90	145.2	173.9	202.40	230.6	265.6	300.4	341.7	382.8	464.2	504.6
40 60	66.53 63.11	80.60 76.80	94.69 90.51	108.60 104.00	122.40 117.50	136.1 130.8	163.5 157.5	190.70 183.90	217.6 209.9	251.0 242.4	284.1 274.6	323.5 312.9	362.7 350.9	440.2 426.1	478.5 463.3
100	58.80	72.01	85.23	98.27	111.20	124.1	149.8	175.20	200.4	231.7	262.6	299.5	336.0	408.3	444.1
200 300	52.94 49.52	65.51 61.70	78.08 73.89	90.46 85.90	102.80 97.83	115.0 109.7	139.4 133.3	163.50 156.70	187.4 179.7	217.0 208.4	246.3 236.8	281.2 270.6	315.8 304.0	384.2 370.1	418.1 402.8
400	47.09	59.00	70.92	82.65	94.31	105.9	129.0	151.80	174.3	202.3	230.0	263.0	295.6	360.0	391.8
500 600	45.20 43.66		68.61 66.73	80.14 78.08	91.59 89.36	103.0 100.6	125.6 122.9	148.00 144.90	170.1 166.7	197.6 193.7	224.7 220.4	257.0 252.2	289.0 283.6	352.1 345.6	383.3 376.2
800	41.22	52.49	63.74	74.83	85.83	96.76	118.5	140.00	161.2	187.6	213.5	244.4	275.0	335.2	36/10
1000 1200	39.33 37.78		61.43 59.53	72.30 70.22	83.09 80.83	93.80 91.37	115.1 112.3	136.20	156.9 153.4	182.7 178.7	208.1 203.7	238.3 233.3	268.2 262.5	326.9 320.0	355.9 348.2 341.4
1400	36.47	47.20	59.53 57.92	68.46	78.92	89.31	109.9	133.00 130.30	150.4	178.7 175.3	199.8	228.9	257.6	320.0 313.8	341.4
1600	35.33 34.32		56.51 55.27	66.93 65.57	77.25 75.77	87.50 85.90	107.9 106.0	128.00 125.90	147.8 145.4	172.3 169.6	196.4 193.3	225.0 221.5	253.2 249.1	308.3 303.2	335.3 329.6
1800 2000	33.41	43.79	54.16	64.34	74.44	84.46	104.3	124.00	143.2	167.1	190.5	218.2	245.4	298.4	324.2 314.1
2400 2800	31.84 30.49		52.20 50.53	62.20 60.36	72.10 70.09	81.92 79.73	101.4 98.84	120.60 117.60	139.4 136.0	162.7 158.7	185.4 180.9	212.3 206.9	238.6 232.3	289.5 281.0	314.1 304.4
3200	29.31	39.20	49.06	58.73	68.31	77.79	96.54	115.00	132.9	155.1	176.6	201.8	226.3	272.8	304.4 294.9
3600 4000	28.26 27.31	38.02 36.94	47.74 46.53	57.27 55.93	66.70 65.21	76.02 74.39	94.45 92.50	112.50 110.20	130.1 127.4	151.7 148.4	172.6 168.8	197.0 192.3	220.5 214.8	264.7 256.5	285.3 275.7
5000	25.23	34.58	43.88	52.96	61.91	70.74	88.07	104.90	121.1	140.7	159.4	180.6	200.4	235.4	213.1
6000 8000	23.45 20.43	32.55 29.03	41.56 37.50	50.35 45.69	58.98 53.67	67.46 61.43	84.01 76.33	99.93 90.27	115.1 103.1	133.2 117.8	150.1 130.5	168.7	185.5		
10000	17.77	25.88	33.79	41.35	48.63	55.06	68.66	80.34	100.1	117.0	100.0				
12000 14000	15.29 12.88		30.19 26.56	37.07 32.69	43.57 38.34	49.67 43.46	60.63								
10000 14000 1000 10000 10000 10000 10000 10000 10000 10000	12.00	15.51	20.00	02.00	00.04		ated Tor	rauo (M	m)*						
E 10	0.04	40.50	10.00	14.00	45.74					00.04	05.77	40.07	45.54	55.47	50.05
10 20	8.84 8.18	9.84	12.32 11.51	14.03 13.15	15.74 14.78	17.44 16.41	20.83 19.65	24.19 22.87	27.52 26.05	30.84 29.22	35.77 33.94	40.67 38.61	45.54 43.26	55.17 52.45	59.95 57.01
40 60	7.52 7.13	9.11 8.68	10.70 10.23	12.27 11.75	13.83 13.27	15.38 14.78	18.48 17.79	21.55	24.58 23.72	27.60 26.66	32.10 31.03	36.55 35.35	40.98 39.65	49.73 48.14	54.07 52.35
100	6.64	8.14	9.63	11.10	12.57	14.02	16.92	19.80	22.64	25.47	29.67	33.83	37.97	46.14	50.18
200 300	5.98 5.59	7.40 6.97	8.82 8.38	10.22 9.71	11.61 11.05	12.99 12.39	15.75 15.06	18.48 17.70	21.17 20.31	23.85 22.90	27.83 26.76	31.78 30.57	35.69 34.35	43.42 41.82	47.24 45.51
400	5.32	6.67	8.01	9.34	10.66	11.96	14.57	17.15	19.70	22.23	25.99	29.71	34.35 33.40	40.68	44.27
500 600	5.11 4.93	6.43 6.24	7.75 7.54	9.05 8.82	10.35 10.10	11.63 11.36	14.19 13.88	16.72 16.37	19.22 18.83	21.71 21.28	25.40 24.91	29.04 28.49	32.66 32.05	39.79 39.05	43.31 42.51
800	4.66	5.93	7.20	8.45	9.70	10.93	13.39	15.82	18.21	20.60	24.13	27.62	31.07	37.88	41.23
1000 1200	4.44 4.27		6.94 6.73	8.17 7.93	9.39 9.13	10.60 10.32	13.01 12.69	15.39 15.03	17.73 17.33	20.06 19.62	23.52 23.01	26.93 26.36	30.30 29.66	36.94 36.15	41.23 40.21 39.34 38.58 37.89
1400	4.12	5.33	6.54 6.39	7.73	8.92	10.09	12.42	14.73	16.99	19.24	22.58	25.86	29.10 28.61	35.46	38.58
1600 1800	3.99		6.24	7.56 7.41	8.73 8.56	9.89 9.71	12.19 11.98	14.46 14.22	16.69 16.43	18.91 18.61	22.19 21.85	25.42 25.02	28.01	34.84 34.26	37.89
1800 2000	3.78	4.95	6.12	7.27	8.41	9.54	11.79	14.01	16.18	18.34	21.53	24.65	28.15 27.73	34.26 33.72	37.24 36.63
2400 2800	3.60 3.45	4.75 4.58	5.90 5.71	7.03 6.82	8.15 7.92	9.26 9.01	11.46 11.17	13.62 13.29	15.75 15.37	17.85 17.42	20.95 20.44	23.98 23.38	26.96 26.25	32.71 31.76	35.49 34.39
3200	3.31	4.43	5.54	6.64	7.72	8.79	10.91	12.99	15.02	17.02	19.96	22.80	25.57	30.83	33.32
3600 4000	3.19		5.39 5.26	6.47	7.54 7.37	8.59 8.41	10.67 10.45	12.71 12.45	14.70 14.40	16.65 16.30	19.51 19.07	22.26 21.72	24.91 24.27	29.91 28.99	32.24 31.15
5000	2.85	3.91	4.96	5.98	7.00	7.99	9.95	11.85	13.68	15.46	18.01	20.41	22.64	26.60	
6000 8000	2.65 2.31		4.70 4.24	5.69 5.16	6.66 6.06	7.62 6.94	9.49 8.62	11.29 10.20	13.01 11.65	14.65 12.99	16.96 14.75	19.06	20.96		
10000	2.01	2.92	3.82	4.67	5.49	6.28	7.76	9.08							
12000 14000	1.73 1.45		3.41 3.00	4.19 3.69	4.92 4.33	5.61 4.91	6.85								
Length Corre	ction Fa	ctor	0.65	0.70	0.75	0.80	0.85	0.90 (0.95 1	.00 1.0	5 1.10	1.15	1.20	1.25	1.30
	From	Length (mm)	200	215	260	315	375			650 78			1355	1625	1960
For Belt		# of teeth	40	43	52	63	75			30 15			271	325	392
Length	To	Length (mm) # of teeth	210 42	255 51	310 62	370 74	445 89			775 90			1620 324	1955 391	2000 400
		# UI LEELII	44	υI	UZ	14	บฮ	107	123	155 18	36 225	210	324	১৪।	400

Shaded area indicates drive conditions where reduced service life can be expected. Contact Gates Application Engineering for specific recommendations. *See page 21 for hp or kw ratings.



Belt Width Selection Tables – 5mm PowerGrip® GT®2 Belts

The following table represents the power ratings for each belt in its base width at the predetermined number of grooves, pitch diameters and rpm's. These ratings must be multiplied by the appropriate width factor and applicable belt length factor to obtain the corrected power rating. (See Step 4 of Drive Selection Procedure on Page 12.)

Belt Width (mr	n) 9	15	20	25
Width Multiplier	0.60	1.00	1.33	1.67

Number of Grooves 18 20 22 24 26 28 32 36 40 45 48 50 62 Pitch mm 28.65 31.83 35.01 38.20 41.38 44.56 50.93 57.30 63.66 71.62 76.39 79.58 98.68	74 80 117.77 127.3																
	117.77 127.3																
		_			_	_	_										
Diameter (in) 1.128 1.253 1.379 1.504 1.629 1.754 2.005 2.256 2.506 2.820 3.008 3.133 3.885	4.637 5.01						1					l	1				
10 0.01 0.01 0.02 0.02 0.02 0.02 0.03 0.04 0.04 0.05 0.06 0.07 0.08 0.09 0.10 0.12 0.02 0.03 0.04 0.04 0.05 0.06 0.07 0.08 0.09 0.10 0.12	0.08 0.0 0.15 0.1																10
40 0.04 0.05 0.06 0.07 0.08 0.09 0.10 0.12 0.14 0.16 0.17 0.18 0.23	0.28 0.3	.23 0.3	0.23	0.18	0.17	6	0.16	0.14	0.12	0.10	0.09	0.08	0.07	0.06	0.05	0.04	40
60 0.06 0.07 0.09 0.10 0.11 0.12 0.15 0.18 0.20 0.23 0.25 0.26 0.33 100 0.09 0.11 0.14 0.16 0.18 0.20 0.24 0.28 0.32 0.37 0.40 0.42 0.53	0.41 0.4 0.65 0.7	.33 0.4 .53 0.0	0.33 0.53	0.26 0.42	0.25	3	0.23	0.20	0.18	0.15				0.09 0.14			
200 0.17 0.21 0.25 0.29 0.33 0.36 0.44 0.52 0.59 0.69 0.74 0.78 1.00	1.22 1.3 1.76 1.9					9	0.69		0.52	0.44				0.25			200
400 0.30 0.37 0.45 0.52 0.60 0.67 0.82 0.96 1.11 1.28 1.39 1.46 1.88	2.28 2.4	.88 2.5	1.88	1.46	1.39	.8	1.28	1.11	0.96	0.82	0.67	0.60	0.52	0.45	0.37	0.30	400
500 0.36 0.45 0.54 0.64 0.73 0.82 1.00 1.17 1.35 1.57 1.70 1.78 2.29 600 0.42 0.53 0.64 0.74 0.85 0.96 1.17 1.38 1.59 1.84 2.00 2.10 2.70	3.29 3.5	.70 2. .70 3.	2.29	2.10				1.35		1.00							600
800 0.52 0.67 0.81 0.95 1.09 1.23 1.50 1.78 2.05 2.38 2.58 2.71 3.49 1000 0.62 0.80 0.97 1.15 1.32 1.49 1.83 2.16 2.49 2.90 3.14 3.30 4.26	4.26 4.6 5.19 5.6	49 4.1	3.49 4.26	2.71	2.58	8	2.38	2.05	1.78 2.16	1.50	1.23	1.09	0.95	0.81 0.97			800 1000
1200 0.72 0.93 1.13 1.34 1.54 1.74 2.14 2.53 2.92 3.40 3.69 3.88 5.00 1400 0.81 1.05 1.29 1.52 1.75 1.98 2.44 2.90 3.34 3.89 4.22 4.44 5.72	6.09 6.6 6.97 7.5	.00 6.0	5.00	3.88	3.69	0	3.40	2.92	2.53	2.14	1.74	1.54	1.34	1.13	0.93	0.72	1200
1600 0.90 1.17 1.43 1.70 1.96 2.22 2.74 3.25 3.75 4.37 4.74 4.99 6.43	7.83 8.5	.43 7.8	6.43	4.99	4.74	7	4.37	3.75	3.25	2.74	2.22	1.96	1.70	1.43	1.17	0.90	1600
1800 0.98 1.28 1.58 1.87 2.16 2.45 3.03 3.59 4.15 4.84 5.25 5.52 7.12 2000 1.06 1.39 1.72 2.04 2.36 2.68 3.31 3.93 4.55 5.30 5.75 6.05 7.79	8.66 9.4 9.47 10.2			5.52 6.05	5.25 5.75	0	5.30		3.59 3.93	3.03				1.58 1.72	1.28 1.39		1800 2000
2400 1.21 1.60 1.99 2.37 2.75 3.12 3.86 4.59 5.31 6.19 6.72 7.06 9.08	11.00 11.9 12.50 13.5 13.90 14.9	.08 11.0 .30 12.5	9.08	7.06 8.04	6.72	9	6.19		4.59	3.86	3.12 3.54	2.75 3.11	2.37 2.68	1.99	1.60 1.80	1.21 1.35	2400
3200 1.49 1.99 2.49 2.98 3.47 3.95 4.90 5.84 6.75 7.87 8.53 8.97 11.50		.50 13.9	11.50	8.97	8.53	7	7.87	6.75	5.84	4.90	3.95	3.47	2.98	2.49	1.99	1.49	3200
4000 1.73 2.34 2.95 3.55 4.14 4.72 5.87 6.99 8.09 9.42 10.20 10.70 13.60	15.10 16.3 16.30 17.5	.60 16.3	13.60	10.70	10.20	2	9.42	8.09	6.99	5.87	4.72	4.14	3.55	2.95	2.34	1.73	4000
6000 2.23 3.10 3.96 4.79 5.62 6.42 8.00 9.51 10.96 12.7 13.66 14.30 17.70	18.70	.90 18. .70	15.90 17.70	14.30	13.66	' l	12.7	10.96	9.51	8.00	6.42	5.62	4.79	3.96	3.10	2.23	6000
8000 2.59 3.69 4.76 5.80 6.81 7.80 9.69 11.46 13.09 14.9 15.95 16.60 10000 2.82 4.11 5.36 6.56 7.72 8.82 10.89 12.75				16.60	15.95	'	14.9	13.09		1							10000
12000 2.91 4.36 5.75 7.06 8.30 9.46 11.54 14000 2.86 4.42 5.90 7.26 8.52 9.65									12.70		9.46	8.30	7.06	5.75	4.36	2.91	12000
## 10000								*	ilowatts	Rated k	3.00	0.02	7.20	0.00	7.72	2.00	ster
10 0.01 0.01 0.01 0.01 0.02 0.02 0.02 0.	0.06 0.0	05 0.0	0.05	0.04	0.04	3	0.03				0.02	0.02	0.01	0.01	0.01	0.01	5 10
E 20 0.02 0.02 0.02 0.03 0.03 0.03 0.04 0.05 0.06 0.06 0.08 0.09 0.10 0.12 0.13 0.13 0.17	0.11 0.1	.09 0.	0.09	0.07	0.07	6	0.06	0.05	0.05	0.04	0.03	0.03	0.03	0.02	0.02	0.02	E 20
60 0.04 0.05 0.06 0.07 0.08 0.09 0.11 0.13 0.15 0.17 0.19 0.19 0.25 100 0.07 0.09 0.10 0.12 0.13 0.15 0.18 0.21 0.24 0.27 0.30 0.31 0.40	0.21 0.2 0.30 0.3 0.48 0.5	.25 0.3	0.25	0.19	0.19	7	0.17	0.15	0.13	0.11	0.09	0.08	0.07	0.06	0.05	0.04	60
200 0.13 0.16 0.18 0.21 0.24 0.27 0.33 0.39 0.44 0.51 0.56 0.58 0.75	0.46 0.5	.75 0.9	0.75	0.58	0.56	1	0.51	0.44	0.39	0.33	0.27	0.24	0.21	0.18	0.16	0.13	200
300 0.18 0.22 0.26 0.30 0.35 0.39 0.47 0.56 0.64 0.74 0.80 0.84 1.08 400 0.22 0.28 0.34 0.39 0.45 0.50 0.61 0.72 0.83 0.96 1.04 1.09 1.40	0.91 0.9 1.31 1.4 1.70 1.8			0.84 1.09		6	0.74			0.47 0.61			0.30				300 400
500 0.27 0.34 0.41 0.47 0.54 0.61 0.74 0.88 1.01 1.17 1.27 1.33 1.71 600 0.31 0.39 0.47 0.55 0.63 0.71 0.87 1.03 1.18 1.38 1.49 1.56 2.01	2.08 2.2 2.45 2.6	.71 2.0 .01 2.4			1.27 1.49				0.88 1.03								500 600
800 0.39 0.50 0.60 0.71 0.81 0.92 1.12 1.33 1.53 1.78 1.92 2.02 2.60 1000 0.47 0.60 0.73 0.86 0.98 1.11 1.36 1.61 1.86 2.16 2.34 2.46 3.17	3.17 3.4 3.87 4.2	.60 3.	2.60	2.02	1.92	8	1.78	1.53	1.33	1.12	0.92	0.81	0.71	0.60	0.50	0.39	800
1200 0.54 0.69 0.85 1.00 1.15 1.30 1.59 1.89 2.18 2.54 2.75 2.89 3.73	4.54 4.9	.73 4.5	3.73	2.89	2.75	4	2.54	2.18	1.89	1.59	1.30	1.15	1.00	0.85	0.69	0.54	1200
1400 0.60 0.78 0.96 1.13 1.31 1.48 1.82 2.16 2.49 2.90 3.15 3.31 4.27 1600 0.67 0.87 1.07 1.27 1.46 1.66 2.04 2.42 2.80 3.26 3.54 3.72 4.79	5.20 5.6 5.84 6.3	.79 5.8	4.79	3.31	3.54	16	3.26	2.49	2.42	2.04			1.27				
1800 0.73 0.95 1.18 1.40 1.61 1.83 2.26 2.68 3.10 3.61 3.92 4.12 5.31 2000 0.79 1.04 1.28 1.52 1.76 2.00 2.47 2.93 3.39 3.95 4.29 4.51 5.81	6.46 7.0 7.06 7.6				3.92 4.29	15	3.61 3.95	3.10 3.39	2.68 2.93				1.40 1.52			0.73 0.79	1800 2000
2400 0.90 1.19 1.48 1.77 2.05 2.33 2.88 3.42 3.96 4.62 5.01 5.27 6.77 2800 1.01 1.34 1.67 2.00 2.32 2.64 3.27 3.90 4.51 5.26 5.70 5.99 7.70	8.22 8.9 9.31 10.0	.77 8.1	6.77	5.27	5.01	2	4.62	3.96	3.42	2.88	2.33	2.05	1.77	1.48	1.19	0.90	2400
3200 1.11 1.48 1.86 2.22 2.59 2.95 3.66 4.35 5.03 5.87 6.36 6.69 8.57	10.30 11.1	.57 10.3	8.57	6.69	6.36	7	5.87	5.03	4.35	3.66	2.95	2.59	2.22	1.86	1.48	1.11	3200
4000 1.29 1.75 2.20 2.65 3.09 3.52 4.38 5.22 6.03 6.02 7.61 7.99 10.20	11.30 12.1 12.10 13.0	.20 12.	10.20	7.99	7.61	2	6.02	6.03	5.22	4.38	3.52	3.09	2.65	2.20	1.75	1.29	4000
6000 1.67 2.31 2.95 3.57 4.19 4.79 5.96 7.09 8.17 9.45 10.19 10.70 13.20	13.90			10.70	10.19	5	9.45	8.17	7.09	5.96	4.79	4.19	3.57	2.95	2.31	1.67	6000
8000 1.93 2.75 3.55 4.32 5.08 5.81 7.23 8.54 9.76 11.10 11.89 12.4 10000 2.10 3.06 4.00 4.89 5.75 6.58 8.12 9.51				12.4	11.89	0	11.10	9.76						3.55			
12000 2.17 3.25 4.29 5.26 6.19 7.05 8.61 14000 2.13 3.30 4.40 5.42 6.35 7.20									3.01		7.05	6.19	5.26	4.29	3.25	2.17	12000
Length Correction Factor 0.65 0.70 0.75 0.80 0.85 0.90 0.95 1.00 1.05 1.10 1.15 1.20	1.25 1.	1.20	1.20	1.15	1.10	1.05	.00	.95 1.	0.90 0	0.85	0.80	0.75	0.70	0.65	or	ction Fac	Length Corre
From Length (mm) 200 215 260 315 375 450 540 650 780 935 1130 1355	1625 190															From	Eor Doll
For Belt # of teeth 40 43 52 63 75 90 108 130 156 187 226 271 Length To Length (mm) 210 255 310 370 445 535 645 775 930 1125 1350 1620	325 39 1955 200															To	

Shaded area indicates drive conditions where reduced service life can be expected. Contact Gates Application Engineering for specific recommendations. *See page 20 for torque ratings.



of teeth

Twin Power Belt Drive Systems

Belt Construction

Gates Twin Power Belts have teeth on both sides to provide synchronization from both driving surfaces. This special feature makes possible unique drive designs such as multipoint drives, rotation reversal with one belt, serpentine drives, etc. It may also provide solutions to other difficult design problems.

Twin Power Belts are similar in construction to standard synchronous belts, including nylon-faced teeth on both sides. This construction uses essentially the same design parameters as standard synchronous belts. Gates 3mm and 5mm pitch Twin Power PowerGrip® GT®2 belts have helicallywound fiberglass tension members embedded in a Neoprene body with the belt teeth faced with a tough wear-resistant nylon fabric. A unique feature of this construction is that Gates Twin Power belts can transmit their full rated load on either the front or back side.

As shown below, three principal dimensions of a belt (Pitch, Pitch Length and Width) in millimeters are used to specify a Twin Power PowerGrip® GT®2 belt:

TP	3MR	450	09
Twin Power	Pitch	Pitch Length	Width

Belt pitch is the distance in millimeters between two adjacent tooth centers as measured on the pitch line of the belt. Belt pitch length is the total length (circumference) in millimeters as measured along the pitch line. The theoretical pitch line of a GT belt lies within the tensile member.

PowerGrip® GT®2 drives have a higher load capacity than PowerGrip® HTD® and PowerGrip® Timing drives. They also feature equivalent or better backlash characteristics when compared to PowerGrip® Timing drives. These attributes make PowerGrip® GT®2 the drive of choice for today's design engineers.

PowerGrip® GT®2 belts must run in PowerGrip® GT®2 sprockets. PowerGrip GT®2 belts are not compatible with PowerGrip® HTD® sprockets.


Made-To-Order Twin Power Belts

Additional sizes of Twin Power PowerGrip® GT®2 Belts are available on a made-to-order basis in pitch lengths from 385mm (15.2 in) up to lengths as great as tooling is available. If a mold is not available for the desired pitch length, tooling will be required.


Belts in nonstandard widths are available on a made-to-order basis.

Contact Customer Service for all made-to-order belt needs.

3M PowerGrip GT2 Twin Power – Reference Dimensions



5M PowerGrip GT2 Twin Power – Reference Dimensions



PowerGrip® GT®2 Belt Drives – Twin Power – continued

PowerGrip® GT®2 Belt Lengths and Widths

						3mm	Pitch	Belt Lengths							
	Pitch	Length	No. of		Pitch I	_ength	No. of		Pitch	Length	No. of		Pitch L	.ength	No. of
Description	(mm)	(in)	Teeth	Description	(mm)	(in)	Teeth	Description	(mm)	(in)	Teeth	Description	(mm)	(in)	Teeth
TP3MR-372 TP3MR-375 TP3MR-381 TP3MR-384 TP3MR-387	372 375 381 384 387	14.646 14.764 15.000 15.118 15.236	124 125 127 128 129	TP3MR-483 TP3MR-486 TP3MR-489 TP3MR-492 TP3MR-501	483 486 489 492 501	19.016 19.134 19.252 19.370 19.724	161 162 163 164 167	TP3MR-630 TP3MR-633 TP3MR-639 TP3MR-645 TP3MR-648	630 633 639 645 648	24.803 24.921 25.157 25.394 25.512	210 211 213 215 216	TP3MR-891 TP3MR-900 TP3MR-915 TP3MR-945 TP3MR-951	891 900 915 945 951	35.079 35.433 36.024 37.205 37.441	297 300 305 315 317
TP3MR-390 TP3MR-393 TP3MR-396 TP3MR-399 TP3MR-405	390 393 396 399 405	15.354 15.472 15.591 15.709 15.945	130 131 132 133 135	TP3MR-504 TP3MR-510 TP3MR-513 TP3MR-519 TP3MR-525	504 510 513 519 525	19.843 20.079 20.197 20.433 20.669	168 170 171 173 175	TP3MR-654 TP3MR-657 TP3MR-663 TP3MR-669 TP3MR-684	654 657 663 669 684	25.748 25.866 26.102 26.339 26.929	218 219 221 223 228	TP3MR-981 TP3MR-1002 TP3MR-1026 TP3MR-1035 TP3MR-1050	981 1002 1026 1035 1050	38.622 39.449 40.394 40.748 41.339	327 334 342 345 350
TP3MR-411 TP3MR-414 TP3MR-417 TP3MR-420 TP3MR-426	411 414 417 420 426	16.181 16.299 16.417 16.535 16.772	137 138 139 140 142	TP3MR-528 TP3MR-531 TP3MR-537 TP3MR-552 TP3MR-558	528 531 537 552 558	20.787 20.906 21.142 21.732 21.969	176 177 179 184 186	TP3MR-687 TP3MR-696 TP3MR-711 TP3MR-735 TP3MR-738	687 696 711 735 738	27.047 27.402 27.992 28.937 29.055	229 232 237 245 246	TP3MR-1056 TP3MR-1062 TP3MR-1080 TP3MR-1125 TP3MR-1155	1056 1062 1080 1125 1155	41.575 41.811 42.520 44.291 45.472	352 354 360 375 385
TP3MR-432 TP3MR-435 TP3MR-438 TP3MR-444 TP3MR-447	432 435 438 444 447	17.008 17.126 17.244 17.480 17.598	144 145 146 148 149	TP3MR-564 TP3MR-570 TP3MR-576 TP3MR-585 TP3MR-591	564 570 576 585 591	22.205 22.441 22.677 23.031 23.268	188 190 192 195 197	TP3MR-750 TP3MR-753 TP3MR-786 TP3MR-795 TP3MR-822	750 753 786 795 822	29.528 29.646 30.945 31.299 32.362	250 251 262 265 274	TP3MR-1191 TP3MR-1263 TP3MR-1335 TP3MR-1500 TP3MR-1512	1191 1263 1335 1500	46.890 49.724 52.559 59.055 59.528	397 421 445 500 504
TP3MR-459 TP3MR-465 TP3MR-468 TP3MR-471 TP3MR-474	459 465 468 471 474	18.071 18.307 18.425 18.543 18.661	153 155 156 157 158	TP3MR-597 TP3MR-600 TP3MR-606 TP3MR-609 TP3MR-612	597 600 606 609 612	23.504 23.622 23.858 23.976 24.094	199 200 202 203 204	TP3MR-837 TP3MR-840 TP3MR-843 TP3MR-873 TP3MR-882	837 840 843 873 882	32.953 33.071 33.189 34.370 34.724	279 280 281 291 294	TP3MR-1536 TP3MR-1587 TP3MR-1956 TP3MR-2004 TP3MR-2061	1536 1587 1956 2004 2061	60.472 62.480 77.008 78.898 81.142	512 529 652 668 687
TP3MR-480	480	18.898	160	TP3MR-627	627	24.685	209								

All sizes are made to order. Contact Gates Customer Service for availability.

3mm Pitch Stock Belt Widths									
Belt Width Code	Belt Width (mm)	Belt Width (in)							
04	4	0.157							
06	6	0.236							
09	9	0.354							

						5mm	Pitch	Belt Lengths							
Description	Pitch (mm)	Length (in)	No. of Teeth	Description	Pitch (mm)	Length (in)	No. of Teeth	Description	Pitch (mm)	Length (in)	No. of Teeth	Description	Pitch (mm)	Length (in)	No. of Teeth
TP5MR-400	400	15.748	80	TP5MR-765	765	30.118	153	TP5MR-1125	1125	44.291	225	TP5MR-1790	1790	70.472	358
TP5MR-405	405	15.945	81	TP5MR-790	790	31.102	158	TP5MR-1150	1150	45.276	230	TP5MR-1800	1800	70.866	360
TP5MR-425	425	16.732	85	TP5MR-800	800	31.496	160	TP5MR-1195	1195	47.047	239	TP5MR-1895	1895	74.606	379
TP5MR-450	450	17.717	90	TP5MR-815	815	32.087	163	TP5MR-1250	1250	49.213	250	TP5MR-1945	1945	76.575	389
TP5MR-500	500	19.685	100	TP5MR-830	830	32.677	166	TP5MR-1270	1270	50.000	254	TP5MR-1980	1980	77.953	396
TP5MR-535	535	21.063	107	TP5MR-835	835	32.874	167	TP5MR-1295	1295	50.984	259	TP5MR-2000	2000	78.740	400
TP5MR-565	565	22.244	113	TP5MR-850	850	33.465	170	TP5MR-1300	1300	51.181	260	TP5MR-2110	2110	83.071	422
TP5MR-575	575	22.638	115	TP5MR-870	870	34.252	174	TP5MR-1375	1375	54.134	275	TP5MR-2250	2250	88.583	450
TP5MR-580	580	22.835	116	TP5MR-890	890	35.039	178	TP5MR-1420	1420	55.906	284	TP5MR-2525	2525	99.409	505
TP5MR-600	600	23.622	120	TP5MR-900	900	35.433	180	TP5MR-1450	1450	57.087	290	TP5MR-2760	2760	108.661	552
TP5MR-625	625	24.606	125	TP5MR-925	925	36.417	185	TP5MR-1575	1575	62.008	315	TP5MR-3120	3120	122.835	624
TP5MR-650	650	25.591	130	TP5MR-950	950	37.402	190	TP5MR-1595	1595	62.795	319	TP5MR-3170	3170	124.803	634
TP5MR-700	700	27.559	140	TP5MR-975	975	38.386	195	TP5MR-1600	1600	62.992	320	TP5MR-3200	3200	125.984	640
TP5MR-710	710	27.953	142	TP5MR-985	985	38.780	197	TP5MR-1635	1635	64.370	327	TP5MR-3430	3430	135.039	686
TP5MR-740	740	29.134	148	TP5MR-1000	1000	39.370	200	TP5MR-1690	1690	66.535	338	TP5MR-3800	3800	149.606	760
TP5MR-745 TP5MR-750	745 750	29.331 29.528	149 150	TP5MR-1050 TP5MR-1115	1050 1115	41.339 43.898	210 223	TP5MR-1720 TP5MR-1755	1720 1755	67.717 69.094	344 351				

All sizes are made to order. Contact Gates Customer Service for availability.

5mm Pitch Stock Belt Widths									
Belt Width Code	Belt Width (mm)	Belt Width (in)							
06	6	0.236							
09	9	0.354							
15	15	0.591							

PowerGrip® GT®2, HTD® and Timing Belt Drive Selection Procedure – Twin Power

Step 1. Determine design load.

Service factors between 1.5 and 2.0 are generally recommended when designing small pitch synchronous drives. Knowledge of drive loading characteristics should influence the actual value selected. A higher service factor should be selected for applications with high peak loads, high operating speeds, unusually severe operating conditions, etc. Lower service factors can be used when the loading is smooth, well defined, etc. and the reliability is less critical. Some designs may require service factors outside the 1.5 to 2.0 range, depending upon the nature of the application. Contact Gates Application Engineering for additional information.

Stall torque of the driveR, or peak torque of the driveN unit, may be part of the nameplate data. If not, calculate Torque (Q) by using the formulas below. Determine the design torque or design power load for each driveN component in the belt drive system.

Q (lb - in) =
$$\frac{63,025 \text{ x Shaft HP}}{\text{Shaft RPM}}$$

 $Q (lb - in) = 8.85 \times Q (N - m) or$

$$Q (oz - in) = 16 \times Q (lb - in)$$

Peak Design Load = Load x Service Factor

Sum all design loads from each of the driveN components together for a total design load value.

NOTE: When performing drive calculations based upon torque loads, drive input/output power is constant but drive input/output torque is not. Drive input/output torque is a function of the speed ratio. Drive designs should be based upon the smaller, faster sprocket, at the torque load calculated for its operating speed. These critical drive parameters should be used for all engineering calculations. See engineering calculations on Page 102 for additional formulas and unit conversions.

Step 2. Determine belt pitch and select sprockets.

A. Select Belt Pitch by using the Belt Pitch Selection Guide on pages 25, 39 and 49.

- B. Determine the speed ratios by dividing the larger speed, Sprocket Pitch Diameter or Sprocket Groove Number by the lesser speed, Sprocket Pitch Diameter or Sprocket Groove Number.
- C. Refer to the appropriate Sprocket Diameter Tables on pages 29-31, pages 44-45 or page 53. Select sprockets based upon speed ratio and drive requirements. Use stock sprocket sizes whenever possible.
- **D.** Check the Belt Speed, V, of the smaller sprocket selected, using the following formula:

V (fpm) = $0.262 \times \text{Sprocket PD}$ (in) x Sprocket RPM V (m/s) = $0.0000524 \times \text{Sprocket PD}$ (mm) x Sprocket RPM and.

m/s = 0.00508 x fpm

NOTE: Belt speeds in excess of 6,500 fpm (33.02 m/s) require special sprocket materials and dynamic balancing.

Step 3. Belt length in a multi-point or serpentine drive layout can be best determined using either graphical methods or computer software. For computer aided belt drive design assistance, contact Gates Application Engineering for assistance.

Using the calculated range of pitch lengths, select a belt of the proper length from the appropriate belt length table. Use a standard length as shown in the tables on pages 23, page 43 or 52, if possible.

Step 4. Determine belt width.

Belt Width Selection Tables on pages 26-28, pages 40-41 and page 50 show the load ratings for the stock widths of each of the stock belt pitches. Locate the critical sprocket in the drive system. It may be the small drive sprocket, or it may be one of the larger driveN sprockets with less than 6 teeth in mesh. Using the critical sprocket groove number and rpm as determined in Step 2, locate a torque or horsepower rating in the Belt Width Selection Tables of the proper belt pitch nearest to, but greater than, the peak design load from Step 1 based upon the critical sprocket. Evaluate each individual driveN sprocket using the same procedure, but with the appropriate design load and speed. The critical sprocket will yield the greatest belt width. The greatest belt width

resulting from this process should be selected for the application.

NOTE: The torque or horsepower ratings are based on 6 or more teeth in mesh for the smaller sprocket. Calculate the teeth in mesh for the selected drive design using the Teeth In Mesh Formula on Page 103. If the teeth in mesh is less than 6, the drive must be de-rated as indicated, which may require redesign for additional drive capacity.

Torque or horsepower ratings for various belt widths can be calculated by multiplying the table rating by the appropriate belt width multiplier.

When designing with PowerGrip GT2 or HTD, use the belt length from Step 3 to find the proper belt length factor in the Length Factor Tables included with each Belt Width Selection table. Multiply the torque rating selected above by the belt length factor to obtain the corrected rating. For all designs, the torque or horsepower rating must be equal to, or greater than, the peak design load of Step 1, or the design load of the critical sprocket.

Step 5. Determine proper belt installation tension.


Procedures to calculate proper belt installation tension for specific applications are included on Pages 60-62.

Step 6. Check and specify drive components.

After the drive system components have been selected and checked against drive system requirements, contact Gates Application Engineering before going into production.



Belt Pitch Selection Guide



Belt Width Selection Tables – 3mm PowerGrip® GT®2 Belts

The following table represents the torque ratings for each belt in its base width at the predetermined number of grooves, pitch diameters and rpm's. These ratings must be multiplied by the appropriate width factor and applicable belt length factor to obtain the corrected torque rating. (See Step 4 of Drive Selection Procedure on Page 24.)

Belt Width (mm)	6	9	12	15
Width Multiplier	1.00	1.50	2.00	2.50

				Rated	Torque	(lb-in) F	or Small	Sprocke	et - 6mn	n Belt W	idth				
Number of															
Grooves Pitch mm	16 15.28	18 17.19	20 19.10	22 21.01	24 22.92	28 24.83	30 28.65	34 32.47	38 36.29	45 42.97	50 47.75	56 53.48	62 59.21	74 70.66	80 76.39
Diameter (in)	0.602	0.677	0.752	0.827	0.902	0.977	1.128	1.278	1.429	1.692	1.88	2.105	2.331	2.782	3.008
10 20	14.02 12.82	16.27 14.92	18.50 17.00	20.70 19.05	22.89 21.09	25.06 23.11	29.38 27.13	33.61 31.06	37.82 34.97	45.04 41.67	50.13 46.38	56.15 51.95	62.13 57.48	73.87 68.32	79.67 73.68
40 60	11.62 10.91	13.57 12.78	15.50 14.62	17.40 16.44	19.29 18.24	21.16 20.02	24.88 23.56	28.51 27.02	32.12 30.45	38.29 36.32	42.63 40.44	47.75 45.30	52.83 50.11	62.77 59.53	67.68 64.17
100 200	10.03	11.78 10.43	13.51 12.01	15.22 13.57	16.91 15.11	18.59 16.64	21.90 19.65	25.14 22.59	28.35 25.50	33.83 30.45	37.67 33.92	42.20 38.00	46.68 42.03	55.44 49.89	59.74 53.74
300 400	8.12 7.63	9.64 9.08	11.14 10.51	12.61 11.92	14.06 13.32	15.50 14.69	18.34 17.40	21.10 20.04	23.83	28.48 27.08	31.73	35.54 33.80	39.31 37.38	46.64 44.33	50.23 47.73
500 600	7.24 6.92	8.65 8.29	10.03	11.39	12.74 12.26	14.06 13.55	16.68 16.09	19.22 18.55	21.73 20.98	25.99 25.10	28.96 27.97	32.45 31.34	35.88 34.65	42.54 41.07	45.79 44.21
800 1000	6.43 6.04	7.73 7.30	9.01 8.53	10.27 9.74	11.52 10.94	12.74 12.11	15.15 14.43	17.49 16.67	19.79 18.87	23.70 22.60	26.41 25.20	29.59 28.23	32.71 31.20	38.75 36.94	41.69 39.73
1200 1400	5.72 5.46	6.94 6.64	8.14 7.80	9.31 8.94	10.46	11.60	13.83	15.99 15.42	18.12 17.48	21.71 20.95	24.20 23.36	27.11 26.16	29.96 28.91	35.45 34.19	38.12 36.74
1600	5.22	6.38	7.51	8.62	9.71	10.78	12.89	14.93	16.93	20.29	22.62	25.34	27.99	33.08	35.54
1800 2000	5.02 4.84	6.15 5.94	7.26 7.03	8.34 8.09	9.40 9.13	10.45	12.51 12.16	14.49 14.10	16.44 16.00	19.71 19.19	21.97	24.60 23.94	27.17 26.44	32.09 31.20	34.46 33.49
2400 2800	4.52 4.25	5.59 5.28	6.63 6.29	7.65 7.28	8.65 8.25 7.90	9.64 9.20 8.81	11.56 11.05	13.42 12.84 12.33	15.23 14.58	18.27 17.49	20.37 19.49 18.72	22.79	25.15 24.04 23.05	29.63 28.26 27.04	31.77 30.27 28.92
3200 3600	4.02 3.81	5.02 4.79	6.00 5.74	6.96 6.67	7.58	8.48	10.61 10.22	11.88	14.01 13.50	16.81 16.20	18.03	20.93	22.16	25.92	27.68
4000 5000	3.63	4.58 4.14	5.51 5.02	6.42 5.87	7.30 6.71	8.17 7.52	9.86 9.10	11.48 10.60	13.04 12.05	15.64 14.42	17.40 16.02	19.41 17.81	21.34 19.50	24.89 22.52	26.52 23.86
6000 8000	2.91 2.40	3.77 3.19	4.61 3.95	5.42 4.69	6.21 5.40	6.98 6.09	8.46 7.41	9.86 8.63	11.20 9.77	13.38 11.57	14.81 12.70	16.40 13.89	17.87 14.88	20.36 16.27	21.39 16.64
10000 12000	1.99 1.64	2.72 2.32	3.42 2.97	4.10 3.59	4.74 4.17	5.36 4.73	6.53 5.75	7.59 6.64	8.55 7.41	9.97 8.45	10.79 8.93	11.54	12.03		
10000 14000 10 10 10 10 10 10 10 10 10 10 10 10	1.34	1.98	2.57	3.13	3.66	4.15	5.03 Rated To	5.75	6.33	6.95					
E 10	1.58	1.84	2.09	2.34	2.59	2.83	3.32	3.80	4.27	5.09	5.66	6.34	7.02	8.35	9.00
E 20 40	1.45	1.69 1.53	1.92 1.75	2.15	2.38	2.61 2.39	3.06	3.51 3.22	3.95 3.63	4.71 4.33	5.24 4.82	5.87 5.40	6.49 5.97	7.72 7.09	8.32 7.65
60 100	1.23	1.44 1.33	1.65 1.53	1.86 1.72	2.06	2.26	2.66 2.47	3.05 2.84	3.44	4.10 3.82	4.57 4.26	5.12 4.77	5.66 5.27	6.73 6.26	7.25 6.75
200 300	1.00 0.92	1.18 1.09	1.36 1.26	1.53 1.42	1.71 1.59	1.88 1.75	2.22 2.07	2.55 2.38	2.88 2.69	3.44 3.22	3.83 3.58	4.29 4.02	4.75 4.44	5.64 5.27	6.07 5.68
400 500	0.86	1.03 0.98	1.19 1.13	1.35	1.50	1.66 1.59	1.97 1.88	2.26 2.17	2.56 2.45	3.06 2.94	3.41 3.27	3.82 3.67	4.22 4.05	5.01 4.81	5.39 5.17
600 800	0.78	0.94 0.87	1.09 1.02	1.24 1.16	1.39 1.30	1.53 1.44	1.82 1.71	2.10 1.98	2.37 2.24	2.84 2.68	3.16 2.98	3.54 3.34	3.92 3.70	4.64 4.38	4.99 4.71
1000 1200	0.68 0.65	0.82 0.78	0.96 0.92	1.10	1.24	1.37	1.63 1.56	1.88	2.13	2.55 2.45	2.85	3.19	3.53 3.39	4.17 4.01	4.49 4.31
1400 1600	0.62	0.75 0.72	0.88 0.85	1.01	1.14	1.26	1.51	1.74	1.97	2.37 2.29	2.64 2.56	2.96 2.86	3.27 3.16	3.86 3.74	4.15 4.02
1800 2000	0.57 0.55	0.69 0.67	0.82 0.79	0.94 0.91	1.06	1.18	1.41 1.37	1.64 1.59	1.86	2.23 2.17	2.48 2.42	2.78 2.71	3.07 2.99	3.63 3.53	3.89 3.78
2400 2800	0.55 0.51 0.48	0.63 0.60	0.75 0.71	0.86	0.98	1.09	1.31 1.25	1.52 1.45	1.72 1.65	2.06 1.98	2.30 2.20	2.71 2.58 2.46	2.84 2.72	3.35 3.19	3.59 3.42
3200 3600	0.45	0.57 0.54	0.68 0.65	0.79	0.89	1.00	1.20	1.39	1.58	1.90	2.12	2.36	2.60	3.06	3.27
4000 5000	0.43 0.41 0.37	0.54 0.52 0.47	0.62 0.57	0.73 0.66	0.83 0.76	0.90 0.92 0.85	1.15 1.11 1.03	1.30 1.20	1.47 1.36	1.83 1.77 1.63	1.97 1.81	2.20 2.19 2.01	2.41 2.20	2.93 2.81 2.55	3.00 2.70
6000 8000	0.37 0.33 0.27	0.47 0.43 0.36	0.57 0.52 0.45	0.61 0.53	0.70 0.70 0.61	0.69 0.79	0.96 0.84	1.11 0.97	1.27 1.10	1.51 1.31	1.67	1.85 1.57	2.02 1.68	2.30 1.84	2.70 2.42 1.88
10000	0.22	0.31	0.39	0.46	0.54	0.61	0.74	0.86	0.97	1.13	1.22	1.30	1.36	1.04	1.00
12000 14000	0.19 0.15	0.26 0.22	0.34 0.29	0.41 0.35	0.47 0.41	0.53 0.47	0.65 0.57	0.75 0.65	0.84 0.72	0.95 0.79	1.01				
Length Corre			0.70	0.75	0.80	0.85			00 1.05		1.15	1.20		30 1.3	
For Belt	From	Length (mm) # of teeth	120 40	129 43	153 51	180 60			94 348 98 116		480 160	567 189		86 924 62 308	
Length	То	Length (mm)	126	150	177	210	249 2	91 3	45 405	477	564	663	783 9	21 1089	1200
		# of teeth	42	50	59	70	83	97 1	15 135	159	188	221	261 3	07 363	400

Shaded area indicates drive conditions where reduced service life can be expected. Contact Gates Application Engineering for specific recommendations.



Belt Width Selection Tables – 5mm PowerGrip® GT®2 Belts

The following table represents the torque ratings for each belt in its base width at the predetermined number of grooves, pitch diameters and rpm's. These ratings must be multiplied by the appropriate width factor and applicable belt length factor to obtain the corrected torque rating. (See Step 4 of Drive Selection Procedure on Page 24.)

Belt Width (mm)	9	15	20	25
Width Multiplier	0.60	1.00	1.33	1.67

					Rated T	orque (I	b-in) F <u>o</u>	r Small S	Sprocket	- 15mn	n Belt W	idth*				
Pich		10	20	22	24	26	20	22	26	40	45	50	56	62	74	90
20	Diameter (in)	1.128	1.253		1.504	1	1.754	1	2.256	2.506		3.133			l	5.013
40 66.53 80.60 94.69 108.60 122.40 138.1 1635.5 180.70 271.6 251.0 284.1 232.5 362.7 440.2 478.5 60 65.11 76.80 90.51 104.00 117.50 130.8 163.5 180.70 200.4 24.2 47.6 230.5 332.9 350.0 463.3 444.1 200.5 58.0 17.0 17.0 17.0 17.0 17.0 17.0 17.0 17					124.20				214.10	243.6				403.0		530.6 504.6
200 58.80 72.01 85.23 98.27 111.20 124.1 149.8 175.20 200.4 231.7 282.6 299.5 38.00 408.3 444.1 200 48.29 44.65.1 77 78.08 90.46 102.80 115.0 139.4 163.50 187.4 127.0 246.3 231.2 315.8 38.4 24.81.1 200 48.2 417.0 246.3 231.2 315.8 384.2 418.1 200 47.0 195.0 195.0 195	40	66.53	80.60	94.69	108.60	122.40	136.1	163.5	190.70	217.6	251.0	284.1	323.5	362.7	440.2	478.5
The state of the s	60 100			90.51 85.23	104.00 98.27				183.90 175.20	209.9	242.4	274.6 262.6		350.9 336.0	426.1 408.3	463.3 444.1
400 47,09 \$9.00 70.92 82.65 94.31 105.9 129.0 151.80 174.3 202.3 230.0 256.6 360.0 391.8 500 43.66 55.19 66.73 78.08 83.85 100.6 122.9 144.90 170.1 197.6 22.4 257.2 283.6 383.2 500 43.66 55.19 66.73 78.08 83.85 100.6 122.9 144.90 166.7 137.7 220.4 252.2 283.6 36.5 376.2 1000 393.3 10.38 01.43 77.32 83 85.83 96.76 1185.1 140.00 161.2 187.6 27.3 244.4 275.0 338.2 384.9 1000 393.3 10.38 01.43 77.32 82.2 83.09 83.30 115.1 138.20 169.8 115.7 220.8 12.2 283.6 284.9 38.0 1400 36.47 47.20 57.92 786.4 79.22 83.0 83.0 1400 36.47 47.20 57.92 786.4 79.22 83.0 83.0 1800 34.2 44.80 55.2 65.7 75.77 78.9 85.0 10.9 128.00 147.8 172.3 186.4 225.0 253.2 283.3 341.4 1800 34.32 44.80 55.27 65.7 75.77 85.0 10.9 128.00 147.8 172.3 186.4 225.0 253.2 283.3 341.4 2000 33.41 43.79 54.16 64.34 74.44 84.66 104.3 124.00 143.2 167.1 180.5 218.2 245.4 288.4 324.2 2400 31.84 42.03 56.55 60.36 70.00 79.73 98.84 117.60 136.0 186.7 180.9 20.9 232.3 281.0 304.4 2800 30.49 40.53 50.55 60.36 70.00 79.73 98.84 117.60 136.0 186.7 180.9 20.9 223.3 27.8 281.0 304.4 2800 30.49 40.53 50.55 60.36 70.00 79.73 98.84 117.60 136.0 186.7 180.9 20.9 223.3 27.8 281.0 304.4 2800 29.31 39.20 49.00 58.7 36.8 31 77.79 96.54 115.0 136.0 186.7 180.9 20.9 223.3 27.8 281.0 304.4 2800 29.31 39.20 44.55 55.33 65.21 17.44 20.83 24.11 12.0 136.1 180.5 180.7 180.9 20.9 223.3 27.8 281.0 304.9 2800 29.34 38.84 42.88 52.83 65.21 17.44 20.83 24.11 12.0 130.1 117.8 130.5 180.7 180.9 20.9 223.3 27.8 281.0 304.9 2800 29.34 38.34 43.88 52.83 65.21 17.44 20.83 24.11 12.0 13.0 12.1 140.7 189.8 180.5 20.8 22.0 25.5 25.5 25.5 25.5 25.5 25.5 25.5	200	52.94	65.51	78.08	90.46	102.80	115.0	139.4	163.50	187.4	217.0	246.3	281.2	315.8	384.2	418.1
600 45.20 56.91 68.61 90.14 91.59 103.0 125.6 148.00 1701 17076 224.7 257.0 289.0 820.1 383.3 60.0 41.22 52.49 63.74 74.83 68.83 96.76 118.5 140.00 161.2 91.6 21.35 244.4 275.0 385.2 364.9 91.00 39.33 50.38 61.43 72.30 83.09 38.0 115.1 18.5 140.00 161.2 91.6 21.35 244.4 275.0 385.2 364.9 91.00 100 39.33 50.38 61.43 72.30 83.09 38.0 115.1 18.5 140.00 161.2 91.6 21.35 244.4 275.0 385.2 364.9 91.00 100 39.33 50.38 61.43 72.20 83.09 89.36 118.5 140.00 36.7 78.2 48.86 99.33 70.22 80.83 91.37 112.3 133.00 153.4 178.7 203.7 233.3 262.5 32.00 348.2 140.00 36.47 47.20 5.7 59.0 66.7 78.2 88.3 10.09 91.30.30 155.4 175.3 198.3 22.98 257.6 318.8 39.1 10.99 17.2 80.00 147.5 175.3 198.3 22.15 249.1 30.2 32.9 32.0 13.0 150.4 175.3 198.4 175.3 1	300 400			73.89 70.92	85.90 82.65			133.3 129.0	156.70	179.7 174.3	208.4	236.8		304.0 295.6	370.1 360.0	402.8 391.8
800 4122 5249 6374 7483 8583 96.76 1185 1165 1 14000 161.2 1876 2135 244.4 2750 335.2 364.9 365.9 1000 39.33 50.33 61.43 72.20 83.09 93.00 115.5 1 136.20 165.9 182.7 203.7 203.7 203.3 262.5 320.0 335.1 1000 37.78 48.66 59.33 70.22 80.83 91.37 112.3 130.0 153.4 178.7 203.7 203.7 203.3 262.5 320.0 34.0 1600 35.33 45.93 56.51 66.93 77.75 87.50 107.9 1 25.00 147.8 172.3 196.4 225.0 253.2 300.3 341.4 32.2 44.6 55.27 65.7 75.7 85.90 106.0 125.90 147.8 172.3 196.4 225.0 253.2 300.3 36.3 341.4 23.9 42.4 48.0 55.27 65.7 75.7 85.90 106.0 125.90 147.8 172.3 196.4 225.0 253.2 300.3 36.3 40.2 44.0 143.9 54.16 64.3 74.44 84.6 104.3 125.0 143.2 140.0 143.2 167.1 190.5 182.2 245.6 298.4 324.2 49.0 140.0	500	45.20	56.91	68.61	80.14	91.59	103.0	125.6	148.00	170.1	197.6	224.7	257.0	289.0	352.1	383.3
1000 39.33 50.38 61.43 72.30 83.09 93.80 115.1 136.20 156.9 182.7 208.1 228.3 288.2 236.9 335.0 348.2 349.0 348.2 349.0 348.2 349.0 348.2 349.0 348.2 349.0 348.2 349.0 349.0 349.2 349.0 349.2 349.0 349.0 349.2 349.0 349.0 349.0 349.2 349.0 349.						1			1	II.		1 1				
1600 35.33 45.93 65.91 66.93 77.25 87.50 107.9 128.00 147.8 172.3 196.4 225.0 253.2 308.3 335.3 1800 34.32 44.80 65.27 65.57 75.77 85.90 107.9 128.00 145.4 196.9 193.3 221.5 249.1 303.2 329.6 2000 33.41 43.79 65.16 64.34 74.44 84.46 104.3 124.00 143.2 167.1 190.3 221.5 249.1 303.2 329.6 220 27.21 82.00 30.49 40.53 30.53 60.36 70.09 79.73 98.44 117.60 136.0 159.4 12.3 228.6 228.5 314.1 220.0 29.31 39.20 49.06 58.78 68.31 77.79 95.4 115.00 136.0 158.7 180.9 206.9 223.3 281.0 304.4 3200 29.31 39.20 49.06 58.78 68.31 77.79 95.4 115.00 136.0 158.7 180.9 206.9 225.3 228.0 289.5 314.1 30.0 20.0 29.31 39.20 49.06 58.73 68.31 77.79 95.4 115.00 132.9 155.1 176.6 201.8 226.3 225.2 228.2 249.9 4000 27.31 36.94 46.53 55.93 65.21 74.39 92.50 110.20 127.4 184.4 168.8 192.3 214.8 226.5 275.7 40.00 23.45 32.55 41.66 50.35 58.88 67.46 84.01 99.93 115.1 133.5 180.0 20.4 235.4 180.0 20.4 235.4 180.0 20.4 235.4 180.0 20.4 235.4 180.0 20.4 235.4 180.0 20.4 235.4 180.0 12.28 19.91 20.0 15.28 19.91 26.55 25.69 33.79 44.57 60.63 180.0 15.28 19.91 20.0 15.28 19.91 26.55 25.69 33.57 44.56 60.63 180.0 12.28 19.91 20.0 15.28 19.91 20.0 15.29 15.0 10.0 15.20 15.0 10.0 10.0 15.20 15.0 10.0 15.20 15.0 10.0 15.20 15.0 10.0 15.2	1000	39.33	50.38	61.43	72.30	83.09	93.80	115.1	136.20	156.9	182.7	208.1	238.3	268.2	326.9	355.9
1600 35.33 45.93 65.91 66.93 77.25 87.50 107.9 128.00 147.8 172.3 196.4 225.0 253.2 308.3 335.3 1800 34.32 44.80 65.27 65.57 75.77 85.90 107.9 128.00 145.4 196.9 193.3 221.5 249.1 303.2 329.6 2000 33.41 43.79 65.16 64.34 74.44 84.46 104.3 124.00 143.2 167.1 190.3 221.5 249.1 303.2 329.6 220 27.21 82.00 30.49 40.53 30.53 60.36 70.09 79.73 98.44 117.60 136.0 159.4 12.3 228.6 228.5 314.1 220.0 29.31 39.20 49.06 58.78 68.31 77.79 95.4 115.00 136.0 158.7 180.9 206.9 223.3 281.0 304.4 3200 29.31 39.20 49.06 58.78 68.31 77.79 95.4 115.00 136.0 158.7 180.9 206.9 225.3 228.0 289.5 314.1 30.0 20.0 29.31 39.20 49.06 58.73 68.31 77.79 95.4 115.00 132.9 155.1 176.6 201.8 226.3 225.2 228.2 249.9 4000 27.31 36.94 46.53 55.93 65.21 74.39 92.50 110.20 127.4 184.4 168.8 192.3 214.8 226.5 275.7 40.00 23.45 32.55 41.66 50.35 58.88 67.46 84.01 99.93 115.1 133.5 180.0 20.4 235.4 180.0 20.4 235.4 180.0 20.4 235.4 180.0 20.4 235.4 180.0 20.4 235.4 180.0 20.4 235.4 180.0 12.28 19.91 20.0 15.28 19.91 26.55 25.69 33.79 44.57 60.63 180.0 15.28 19.91 20.0 15.28 19.91 26.55 25.69 33.57 44.56 60.63 180.0 12.28 19.91 20.0 15.28 19.91 20.0 15.29 15.0 10.0 15.20 15.0 10.0 10.0 15.20 15.0 10.0 15.20 15.0 10.0 15.20 15.0 10.0 15.2				59.53 57.92	68.46	78.92		112.3	133.00	150.4				257.6		341.4
2000 33.41 43.79 54.16 64.34 74.44 84.46 104.3 124.00 14.32 167.1 190.5 218.2 245.4 298.4 324.2 2400 31.84 42.03 5 52.0 62.20 72.10 81.92 101.4 120.60 139.4 162.7 185.4 212.3 238.6 299.5 314.1 3200 29.31 39.20 49.06 55.73 68.31 77.79 98.84 117.60 130.0 158.7 180.9 20.09 232.3 281.0 304.4 3200 29.31 39.20 49.06 55.73 68.31 77.79 98.84 117.60 130.0 156.1 176.6 190.9 20.09 232.3 272.8 294.0 30.00 28.26 38.02 49.06 55.73 68.31 77.79 98.54 115.00 132.9 155.1 176.6 190.9 20.09 232.3 272.8 294.0 30.00 27.31 36.94 46.35 55.93 65.21 74.39 92.50 110.20 127.4 14.4 168.8 192.3 214.8 256.5 275.7 6000 25.23 34.58 4.88 52.96 61.91 70.74 88.07 104.90 121.1 140.7 159.4 180.6 200.4 235.4 16.0 00.00 23.45 32.55 41.56 50.35 58.98 67.46 84.01 99.93 115.1 133.2 150.1 168.7 168.7 168.7 10000 17.77 258.8 33.79 45.69 53.67 66.68 80.34 143.6 10.00 12.8 10.00 12.8 19.91 26.56 32.69 38.34 43.46 60.3 10.00 12.8 19.91 26.56 32.69 38.34 43.46 60.3 14.00 12.8 19.91 26.56 32.69 38.34 43.46 10.00 12.8 10.00 12.8 19.91 26.56 32.69 38.34 43.46 10.00 12.8 10.00 12.00			45.93	56.51	66.93	77.25		107.9	128.00			1 1	225.0	253.2	308.3	335.3
2800 30.49 40.53 50.33 60.36 70.09 79.73 98.4 117.60 136.0 156.7 186.4 212.3 238.6 289.5 314.1 2800 30.49 40.53 50.53 60.36 70.09 79.73 98.4 117.60 136.0 156.7 186.9 206.9 223.3 281.0 30.41 40.00 12.31 39.20 47.74 57.27 66.7 77.79 96.54 115.00 132.9 155.1 167.6 201.8 226.3 272.8 294.9 3600 28.26 38.02 47.74 66.5 57.27 66.7 76.02 94.55 112.00 132.9 155.1 167.6 201.8 226.3 272.8 294.9 3600 28.26 38.02 47.74 66.5 59.36 65.21 74.38 92.50 110.20 127.4 148.4 168.8 192.3 214.8 256.5 257.7 6000 23.45 32.55 41.66 50.35 59.98 61.91 70.74 88.07 104.09 121.1 140.7 159.4 180.6 200.4 255.4 6000 23.45 32.55 44.66 50.35 58.98 67.46 84.01 99.93 115.1 133.2 150.1 168.7 185.5 180.00 17.77 25.88 30.19 37.07 43.57 43.67 60.63 12.00 12.28 19.91 26.56 32.69 38.34 43.46 180.24 12.00 12.28 19.91 26.56 32.69 38.34 43.46 180.4 20.45 12.00 12.28 19.91 26.56 32.69 38.34 43.46 180.4 20.45 12.00 12.28 19.91 26.56 32.69 38.34 43.46 180.4 20.45 12.00 12.28 19.91 26.56 32.69 11.10 12.57 14.02 16.92 19.80 22.66 31.03 35.5 36.6 48.14 52.8 12.00 12.28 11.75 13.27 14.78 16.31 19.65 22.87 26.66 31.03 35.5 36.66 48.14 52.8 12.00 12.29 11.00 66.64 8.14 96.3 11.10 12.57 14.02 16.92 19.80 22.66 31.03 35.3 36.65 48.14 52.30 12.29 11.00 66.64 8.14 96.3 11.10 12.57 14.02 16.92 19.80 22.67 22.66 31.03 35.3 36.6 48.14 52.6 52.45 50.00 20.0 5.98 7.40 8.82 10.22 11.6 12.99 15.75 18.84 21.55 22.87 26.66 31.03 35.3 36.6 48.14 52.6 52.45 50.00 20.0 5.98 7.40 8.82 10.22 11.6 12.99 15.75 18.84 21.55 12.29 22.27 29.91 33.83 37.97 45.14 20.20 15.75 12.90 12.20		34.32 33.41							125.90					249.1 245.4	298.4	329.6 324.2
29.00 29.31 39.20 49.06 58.73 68.31 77.79 90.54 115.00 132.9 155.1 176.6 201.8 226.3 272.8 294.9 38000 22.63 36.02 47.74 67.77 67.07 76.02 94.45 112.50 130.1 151.7 172.6 187.0 22.05 254.7 285.3 5000 25.23 34.88 43.88 52.96 61.91 70.74 88.07 104.90 121.1 140.7 159.4 180.6 200.4 235.4 8000 23.45 32.55 41.56 50.35 58.98 67.46 84.01 99.93 115.1 133.2 150.1 168.7 185.5 8000 20.43 29.03 37.50 45.69 53.67 61.43 76.33 90.27 103.1 117.8 130.5 8000 17.77 25.88 33.79 41.35 48.63 55.06 68.66 80.34 8000 12.88 19.91 26.56 32.69 38.34 43.46 8000 12.88 19.91 26.56 32.69 38.34 43.46 8000 20.40 20.81 20.81 20.81 8000 20.40 20.81 20.81 20.81 8000 20.40 20.81 20.81 20.81 8000 20.40 20.81 20.81 20.81 8000 20.40 20.81 20.81 20.81 8000 20.40 20.81 20.81 20.81 8000 20.40 20.81 20.81 20.81 20.81 8000 20.40 20.81 20.81 20.81 20.81 20.81 8000 20.81 20	2400	31.84	42.03	52.20	62.20	72.10	81.92	101.4	120.60	139.4	162.7	185.4	212.3	238.6	289.5	314.1
## 1000 27.31 36.94 46.53 55.93 65.21 74.39 92.50 110.20 127.4 148.4 168.8 192.3 214.8 256.5 275.7	3200			49.06	58.73	68.31			115.00	132.9				232.3	272.8	294.9
## 1000 25,23 34,58 43,88 52,96 61,91 70,74 88,07 104,90 121,1 140,7 159,4 180,6 200,4 235,4 8000 20,43 29,03 37,50 45,69 53,67 61,43 76,33 90,27 103,1 117,8 130,5 161,7 185,5 10000 15,29 22,88 30,19 37,07 43,57 49,67 60,63 14000 15,29 22,88 39,19 37,07 43,57 49,67 60,63 14000 12,88 19,91 26,56 32,69 38,34 43,46 140,67 43,57 43,57 44,67 48,	3600	28.26			57.27		76.02		112.50	130.1				220.5	264.7	285.3
\$\begin{array}{c c c c c c c c c c c c c c c c c c c	5000	25.23	34.58	43.88	52.96	61.91	74.39	88.07	104.90	121.1	140.7	159.4	180.6	200.4	235.4	2/5./
The leading	6000 8000			41.56 37.50	50.35 45.69			84.01 76.33	99.93				168.7	185.5		
60 7.13 8.68 10.23 11.75 13.27 14.78 17.79 27.70 23.72 26.66 31.03 36.53 40.96 49.13 54.01 50.18 100 6.64 8.14 9.63 11.10 12.57 14.02 16.92 19.80 22.64 25.47 29.67 33.83 37.97 46.14 52.35 100 5.59 8.7.40 8.82 10.22 11.61 12.99 15.75 18.48 21.17 23.85 27.83 31.78 35.69 43.42 47.24 20.00 5.59 6.97 8.38 9.71 11.05 12.39 15.06 17.70 20.31 22.90 26.76 30.57 34.35 41.82 45.51 40.00 5.32 6.67 8.01 9.34 10.66 11.96 14.57 17.15 19.70 22.23 25.99 29.71 33.40 40.68 44.27 40.00 5.32 6.67 8.01 9.34 10.66 11.96 14.57 17.15 19.70 22.23 25.99 29.71 33.40 40.68 44.27 40.00 4.93 6.24 7.54 8.82 10.10 11.36 13.88 16.37 18.83 21.28 24.91 28.49 32.05 39.05 42.51 80.00 4.66 5.93 7.20 8.45 9.70 10.93 13.39 15.82 18.21 20.60 24.13 27.62 31.07 37.88 41.23 10.00 4.44 5.69 6.94 8.17 9.39 10.60 13.01 15.39 17.73 20.06 23.52 26.93 30.30 36.94 40.21 12.00 4.27 5.50 6.73 7.93 9.13 10.32 12.69 15.03 17.33 19.62 23.31 26.36 29.66 36.15 39.34 14.00 4.12 5.33 6.54 7.73 8.92 10.09 12.42 14.73 16.99 19.24 22.58 25.86 29.10 35.48 38.8 16.00 3.89 5.19 6.39 7.56 8.73 9.89 12.19 14.46 16.69 18.91 22.19 22.19 25.42 28.61 34.84 37.89 18.00 3.88 5.06 6.24 7.41 8.56 9.71 11.98 14.22 16.43 18.61 21.85 25.02 28.15 34.26 37.24 20.00 3.78 4.95 6.12 7.27 8.41 9.54 11.79 14.01 16.18 18.34 21.53 24.65 27.73 33.27 36.63 20.00 3.45 4.58 5.71 6.82 7.92 9.01 11.70 13.29 15.37 17.42 20.44 23.38 26.29 31.76 33.93 32.01 26.00 3.31 4.43 5.54 6.64 7.72 8.79 10.91 14.46 16.69 18.91 22.19 22.19 22.26 24.91 29.91 32.24 20.00 3.45 4.58 5.71 6.82 7.92 9.01 11.70 11.71 13.29 15.02 17.02 19.96 22.80 25.57 30.83 33.15 34.00 2.85 3.91 4.95 6.64 7.72 8.79 10.91 11.79 11.29 15.02 17.02 19.96 22.80 25.57 30.83 33.32 30.00 3.49 4.02 11.00 2.25 3.91 2.26 3.44 5.55 3.91 4.96 5.98 7.00 7.99 9.95 11.46 16.80 15.40 11.65 12.99 14.75 12.26 24.91 29.91 32.24 20.00 3.45 4.58 5.71 6.82 7.92 9.01 11.70 11.99 15.02 17.02 19.96 22.80 25.57 30.83 33.20 25.57 30.83 33.20 25.57 30.83 33.32 36.00 3.19 4.30 5.39 6.47 7.54 8.59 10.00 7.93 8.15 9.26 11.46 13.62 15.75 17.42 20.44 23.38 26.25 31.76 34.99	10000	17.77		33.79		1				100.1	117.0	100.0				
60 7.13 8.68 10.23 11.75 13.27 14.78 17.79 27.70 23.72 26.66 31.03 36.53 40.96 49.13 54.01 50.18 100 6.64 8.14 9.63 11.10 12.57 14.02 16.92 19.80 22.64 25.47 29.67 33.83 37.97 46.14 52.35 100 5.59 8.7.40 8.82 10.22 11.61 12.99 15.75 18.48 21.17 23.85 27.83 31.78 35.69 43.42 47.24 20.00 5.59 6.97 8.38 9.71 11.05 12.39 15.06 17.70 20.31 22.90 26.76 30.57 34.35 41.82 45.51 40.00 5.32 6.67 8.01 9.34 10.66 11.96 14.57 17.15 19.70 22.23 25.99 29.71 33.40 40.68 44.27 40.00 5.32 6.67 8.01 9.34 10.66 11.96 14.57 17.15 19.70 22.23 25.99 29.71 33.40 40.68 44.27 40.00 4.93 6.24 7.54 8.82 10.10 11.36 13.88 16.37 18.83 21.28 24.91 28.49 32.05 39.05 42.51 80.00 4.66 5.93 7.20 8.45 9.70 10.93 13.39 15.82 18.21 20.60 24.13 27.62 31.07 37.88 41.23 10.00 4.44 5.69 6.94 8.17 9.39 10.60 13.01 15.39 17.73 20.06 23.52 26.93 30.30 36.94 40.21 12.00 4.27 5.50 6.73 7.93 9.13 10.32 12.69 15.03 17.33 19.62 23.31 26.36 29.66 36.15 39.34 14.00 4.12 5.33 6.54 7.73 8.92 10.09 12.42 14.73 16.99 19.24 22.58 25.86 29.10 35.48 38.8 16.00 3.89 5.19 6.39 7.56 8.73 9.89 12.19 14.46 16.69 18.91 22.19 22.19 25.42 28.61 34.84 37.89 18.00 3.88 5.06 6.24 7.41 8.56 9.71 11.98 14.22 16.43 18.61 21.85 25.02 28.15 34.26 37.24 20.00 3.78 4.95 6.12 7.27 8.41 9.54 11.79 14.01 16.18 18.34 21.53 24.65 27.73 33.27 36.63 20.00 3.45 4.58 5.71 6.82 7.92 9.01 11.70 13.29 15.37 17.42 20.44 23.38 26.29 31.76 33.93 32.01 26.00 3.31 4.43 5.54 6.64 7.72 8.79 10.91 14.46 16.69 18.91 22.19 22.19 22.26 24.91 29.91 32.24 20.00 3.45 4.58 5.71 6.82 7.92 9.01 11.70 11.71 13.29 15.02 17.02 19.96 22.80 25.57 30.83 33.15 34.00 2.85 3.91 4.95 6.64 7.72 8.79 10.91 11.79 11.29 15.02 17.02 19.96 22.80 25.57 30.83 33.32 30.00 3.49 4.02 11.00 2.25 3.91 2.26 3.44 5.55 3.91 4.96 5.98 7.00 7.99 9.95 11.46 16.80 15.40 11.65 12.99 14.75 12.26 24.91 29.91 32.24 20.00 3.45 4.58 5.71 6.82 7.92 9.01 11.70 11.99 15.02 17.02 19.96 22.80 25.57 30.83 33.20 25.57 30.83 33.20 25.57 30.83 33.32 36.00 3.19 4.30 5.39 6.47 7.54 8.59 10.00 7.93 8.15 9.26 11.46 13.62 15.75 17.42 20.44 23.38 26.25 31.76 34.99	12000 14000	15.29 12.88		30.19 26.56	37.07 32.69			60.63								
60 7.13 8.68 10.23 11.75 13.27 14.78 17.79 27.70 23.72 26.66 31.03 36.53 40.96 49.13 54.01 50.18 100 6.64 8.14 9.63 11.10 12.57 14.02 16.92 19.80 22.64 25.47 29.67 33.83 37.97 46.14 52.35 100 5.59 8.7.40 8.82 10.22 11.61 12.99 15.75 18.48 21.17 23.85 27.83 31.78 35.69 43.42 47.24 20.00 5.59 6.97 8.38 9.71 11.05 12.39 15.06 17.70 20.31 22.90 26.76 30.57 34.35 41.82 45.51 40.00 5.32 6.67 8.01 9.34 10.66 11.96 14.57 17.15 19.70 22.23 25.99 29.71 33.40 40.68 44.27 40.00 5.32 6.67 8.01 9.34 10.66 11.96 14.57 17.15 19.70 22.23 25.99 29.71 33.40 40.68 44.27 40.00 4.93 6.24 7.54 8.82 10.10 11.36 13.88 16.37 18.83 21.28 24.91 28.49 32.05 39.05 42.51 80.00 4.66 5.93 7.20 8.45 9.70 10.93 13.39 15.82 18.21 20.60 24.13 27.62 31.07 37.88 41.23 10.00 4.44 5.69 6.94 8.17 9.39 10.60 13.01 15.39 17.73 20.06 23.52 26.93 30.30 36.94 40.21 12.00 4.27 5.50 6.73 7.93 9.13 10.32 12.69 15.03 17.33 19.62 23.31 26.36 29.66 36.15 39.34 14.00 4.12 5.33 6.54 7.73 8.92 10.09 12.42 14.73 16.99 19.24 22.58 25.86 29.10 35.48 38.8 16.00 3.89 5.19 6.39 7.56 8.73 9.89 12.19 14.46 16.69 18.91 22.19 22.19 25.42 28.61 34.84 37.89 18.00 3.88 5.06 6.24 7.41 8.56 9.71 11.98 14.22 16.43 18.61 21.85 25.02 28.15 34.26 37.24 20.00 3.78 4.95 6.12 7.27 8.41 9.54 11.79 14.01 16.18 18.34 21.53 24.65 27.73 33.27 36.63 20.00 3.45 4.58 5.71 6.82 7.92 9.01 11.70 13.29 15.37 17.42 20.44 23.38 26.29 31.76 33.93 32.01 26.00 3.31 4.43 5.54 6.64 7.72 8.79 10.91 14.46 16.69 18.91 22.19 22.19 22.26 24.91 29.91 32.24 20.00 3.45 4.58 5.71 6.82 7.92 9.01 11.70 11.71 13.29 15.02 17.02 19.96 22.80 25.57 30.83 33.15 34.00 2.85 3.91 4.95 6.64 7.72 8.79 10.91 11.79 11.29 15.02 17.02 19.96 22.80 25.57 30.83 33.32 30.00 3.49 4.02 11.00 2.25 3.91 2.26 3.44 5.55 3.91 4.96 5.98 7.00 7.99 9.95 11.46 16.80 15.40 11.65 12.99 14.75 12.26 24.91 29.91 32.24 20.00 3.45 4.58 5.71 6.82 7.92 9.01 11.70 11.99 15.02 17.02 19.96 22.80 25.57 30.83 33.20 25.57 30.83 33.20 25.57 30.83 33.32 36.00 3.19 4.30 5.39 6.47 7.54 8.59 10.00 7.93 8.15 9.26 11.46 13.62 15.75 17.42 20.44 23.38 26.25 31.76 34.99	ster	12.00	. 5.5 .	20.00	02.00	00.01		ated Tor	rue (N-1	n)*						
60 7.13 8.68 10.23 11.75 13.27 14.78 17.79 27.70 23.72 26.66 31.03 36.53 40.96 49.13 54.01 50.18 100 6.64 8.14 9.63 11.10 12.57 14.02 16.92 19.80 22.64 25.47 29.67 33.83 37.97 46.14 52.35 100 5.59 8.7.40 8.82 10.22 11.61 12.99 15.75 18.48 21.17 23.85 27.83 31.78 35.69 43.42 47.24 20.00 5.59 6.97 8.38 9.71 11.05 12.39 15.06 17.70 20.31 22.90 26.76 30.57 34.35 41.82 45.51 40.00 5.32 6.67 8.01 9.34 10.66 11.96 14.57 17.15 19.70 22.23 25.99 29.71 33.40 40.68 44.27 40.00 5.32 6.67 8.01 9.34 10.66 11.96 14.57 17.15 19.70 22.23 25.99 29.71 33.40 40.68 44.27 40.00 4.93 6.24 7.54 8.82 10.10 11.36 13.88 16.37 18.83 21.28 24.91 28.49 32.05 39.05 42.51 80.00 4.66 5.93 7.20 8.45 9.70 10.93 13.39 15.82 18.21 20.60 24.13 27.62 31.07 37.88 41.23 10.00 4.44 5.69 6.94 8.17 9.39 10.60 13.01 15.39 17.73 20.06 23.52 26.93 30.30 36.94 40.21 12.00 4.27 5.50 6.73 7.93 9.13 10.32 12.69 15.03 17.33 19.62 23.31 26.36 29.66 36.15 39.34 14.00 4.12 5.33 6.54 7.73 8.92 10.09 12.42 14.73 16.99 19.24 22.58 25.86 29.10 35.48 38.8 16.00 3.89 5.19 6.39 7.56 8.73 9.89 12.19 14.46 16.69 18.91 22.19 22.19 25.42 28.61 34.84 37.89 18.00 3.88 5.06 6.24 7.41 8.56 9.71 11.98 14.22 16.43 18.61 21.85 25.02 28.15 34.26 37.24 20.00 3.78 4.95 6.12 7.27 8.41 9.54 11.79 14.01 16.18 18.34 21.53 24.65 27.73 33.27 36.63 20.00 3.45 4.58 5.71 6.82 7.92 9.01 11.70 13.29 15.37 17.42 20.44 23.38 26.29 31.76 33.93 32.01 26.00 3.31 4.43 5.54 6.64 7.72 8.79 10.91 14.46 16.69 18.91 22.19 22.19 22.26 24.91 29.91 32.24 20.00 3.45 4.58 5.71 6.82 7.92 9.01 11.70 11.71 13.29 15.02 17.02 19.96 22.80 25.57 30.83 33.15 34.00 2.85 3.91 4.95 6.64 7.72 8.79 10.91 11.79 11.29 15.02 17.02 19.96 22.80 25.57 30.83 33.32 30.00 3.49 4.02 11.00 2.25 3.91 2.26 3.44 5.55 3.91 4.96 5.98 7.00 7.99 9.95 11.46 16.80 15.40 11.65 12.99 14.75 12.26 24.91 29.91 32.24 20.00 3.45 4.58 5.71 6.82 7.92 9.01 11.70 11.99 15.02 17.02 19.96 22.80 25.57 30.83 33.20 25.57 30.83 33.20 25.57 30.83 33.32 36.00 3.19 4.30 5.39 6.47 7.54 8.59 10.00 7.93 8.15 9.26 11.46 13.62 15.75 17.42 20.44 23.38 26.25 31.76 34.99	5 10	8.84	10.58	12 32	1/1 03	15.74		_			30.84	35.77	40.67	45.54	55 17	50.05
60 7.13 8.68 10.23 11.75 13.27 14.78 17.79 27.70 23.72 26.66 31.03 36.53 40.96 49.13 54.01 50.18 100 6.64 8.14 9.63 11.10 12.57 14.02 16.92 19.80 22.64 25.47 29.67 33.83 37.97 46.14 52.35 100 5.59 8.7.40 8.82 10.22 11.61 12.99 15.75 18.48 21.17 23.85 27.83 31.78 35.69 43.42 47.24 20.00 5.59 6.97 8.38 9.71 11.05 12.39 15.06 17.70 20.31 22.90 26.76 30.57 34.35 41.82 45.51 40.00 5.32 6.67 8.01 9.34 10.66 11.96 14.57 17.15 19.70 22.23 25.99 29.71 33.40 40.68 44.27 40.00 5.32 6.67 8.01 9.34 10.66 11.96 14.57 17.15 19.70 22.23 25.99 29.71 33.40 40.68 44.27 40.00 4.93 6.24 7.54 8.82 10.10 11.36 13.88 16.37 18.83 21.28 24.91 28.49 32.05 39.05 42.51 80.00 4.66 5.93 7.20 8.45 9.70 10.93 13.39 15.82 18.21 20.60 24.13 27.62 31.07 37.88 41.23 10.00 4.44 5.69 6.94 8.17 9.39 10.60 13.01 15.39 17.73 20.06 23.52 26.93 30.30 36.94 40.21 12.00 4.27 5.50 6.73 7.93 9.13 10.32 12.69 15.03 17.33 19.62 23.31 26.36 29.66 36.15 39.34 14.00 4.12 5.33 6.54 7.73 8.92 10.09 12.42 14.73 16.99 19.24 22.58 25.86 29.10 35.48 38.8 16.00 3.89 5.19 6.39 7.56 8.73 9.89 12.19 14.46 16.69 18.91 22.19 22.19 25.42 28.61 34.84 37.89 18.00 3.88 5.06 6.24 7.41 8.56 9.71 11.98 14.22 16.43 18.61 21.85 25.02 28.15 34.26 37.24 20.00 3.78 4.95 6.12 7.27 8.41 9.54 11.79 14.01 16.18 18.34 21.53 24.65 27.73 33.27 36.63 20.00 3.45 4.58 5.71 6.82 7.92 9.01 11.70 13.29 15.37 17.42 20.44 23.38 26.29 31.76 33.93 32.01 26.00 3.31 4.43 5.54 6.64 7.72 8.79 10.91 14.46 16.69 18.91 22.19 22.19 22.26 24.91 29.91 32.24 20.00 3.45 4.58 5.71 6.82 7.92 9.01 11.70 11.71 13.29 15.02 17.02 19.96 22.80 25.57 30.83 33.15 34.00 2.85 3.91 4.95 6.64 7.72 8.79 10.91 11.79 11.29 15.02 17.02 19.96 22.80 25.57 30.83 33.32 30.00 3.49 4.02 11.00 2.25 3.91 2.26 3.44 5.55 3.91 4.96 5.98 7.00 7.99 9.95 11.46 16.80 15.40 11.65 12.99 14.75 12.26 24.91 29.91 32.24 20.00 3.45 4.58 5.71 6.82 7.92 9.01 11.70 11.99 15.02 17.02 19.96 22.80 25.57 30.83 33.20 25.57 30.83 33.20 25.57 30.83 33.32 36.00 3.19 4.30 5.39 6.47 7.54 8.59 10.00 7.93 8.15 9.26 11.46 13.62 15.75 17.42 20.44 23.38 26.25 31.76 34.99	E 20	8.18	9.84	11.51	13.15	14.78	16.41	19.65	22.87	26.05	29.22	33.94	38.61	43.26	52.45	57.01
100 6.64 8.14 9.63 11.10 12.57 14.02 16.92 19.80 22.64 25.47 29.67 33.83 37.97 46.14 50.18 200 5.98 7.40 8.82 10.22 11.61 12.99 15.75 18.48 21.17 23.85 27.83 31.78 35.69 43.42 47.24 400 5.32 6.67 8.01 9.34 10.66 11.96 14.57 17.15 19.70 22.23 25.99 29.71 33.40 40.68 44.27 500 5.11 6.43 7.75 9.05 10.35 11.63 13.88 16.27 19.22 21.71 25.40 29.04 32.66 39.79 43.31 800 4.66 5.93 7.20 8.45 9.70 10.93 13.39 15.82 18.21 20.60 24.13 27.62 31.07 37.88 41.23 1200 4.27 5.50 6.73 7.93 9.13 <td>- 40 I</td> <td></td> <td></td> <td>10.70 10.23</td> <td>12.27</td> <td>13.83</td> <td>15.38 14.78</td> <td></td> <td>21.55</td> <td>24.58</td> <td></td> <td></td> <td>36.55 35.35</td> <td></td> <td></td> <td>54.07 52.35</td>	- 40 I			10.70 10.23	12.27	13.83	15.38 14.78		21.55	24.58			36.55 35.35			54.07 52.35
300		6.64	8.14	9.63	11.10	12.57	14.02	16.92	19.80	22.64	25.47	29.67	33.83	37.97		50.18
400 5.32 6.67 8.01 9.34 10.66 11.96 14.57 17.15 19.70 22.23 25.99 29.71 33.40 40.68 44.27 500 5.11 6.43 7.75 9.05 10.35 11.63 14.19 16.72 19.22 21.71 25.40 29.04 32.66 39.79 43.31 800 4.66 5.93 7.20 8.45 9.70 10.93 13.39 15.82 18.21 20.60 24.13 27.62 31.07 37.88 41.23 1000 4.44 5.69 6.94 8.17 9.39 10.60 13.01 15.39 17.73 20.06 23.52 26.93 30.30 36.94 40.21 1200 4.27 5.50 6.73 7.93 9.13 10.32 12.69 15.03 17.33 19.62 23.01 26.36 29.66 36.15 39.34 1400 4.12 5.33 6.54 7.73 8.92 10.09 12.42 14.73 16.99 19.24 22.58 25.86 29.10 35.46 38.58 1600 3.99 5.19 6.39 7.56 8.73 9.89 12.19 14.46 16.69 18.91 22.19 25.42 28.61 34.84 37.89 1800 3.88 5.06 6.24 7.41 8.56 9.71 11.98 14.22 16.43 18.61 21.85 25.02 28.15 34.26 37.24 2000 3.78 4.95 6.12 7.27 8.41 9.54 11.79 14.01 16.18 18.34 21.55 24.95 23.98 26.96 32.71 33.49 2800 3.45 4.58 5.71 6.82 7.92 9.01 11.17 13.29 15.02 15.75 17.85 20.95 23.98 26.96 32.71 33.49 2000 3.09 4.17 5.26 6.32 7.37 8.41 10.45 12.45 14.40 16.30 19.07 21.72 24.27 28.99 31.15 5000 2.85 3.91 4.96 5.98 7.00 7.99 9.95 11.85 13.68 15.46 18.01 20.41 22.64 26.60 8000 2.21 2.25 3.00 3.69 4.33 4.91	200 300			8.82 8.38	10.22 9.71				18.48 17.70							47.24 45.51
600 4.93 6.24 7.54 8.82 10.10 11.36 13.88 16.37 18.83 21.28 24.91 28.49 32.05 39.05 42.51 800 4.66 5.93 7.20 8.45 9.70 10.93 13.39 15.82 18.21 20.60 24.13 27.62 31.07 37.88 41.23 1000 4.44 5.69 6.94 8.17 9.39 10.60 13.01 15.39 17.73 20.06 23.52 26.93 30.30 36.94 40.21 1200 4.27 5.50 6.73 7.93 9.13 10.32 12.69 15.03 17.33 19.62 23.01 26.36 29.66 36.15 39.34 1400 4.12 5.33 6.54 7.73 8.92 10.09 12.42 14.73 16.99 19.24 22.58 25.86 29.10 35.46 38.58 1800 3.88 5.06 6.24 7.41 8.56	400	5.32	6.67	8.01	9.34	10.66	11.96	14.57	17.15	19.70	22.23	25.99	29.71	33.40	40.68	44.27
1000 4.44 5.69 6.94 8.17 9.39 10.60 13.01 15.39 17.73 20.06 23.52 26.93 30.30 36.94 40.21 1200 4.27 5.50 6.73 7.93 9.13 10.32 12.69 15.03 17.73 19.62 23.01 26.36 29.66 36.15 39.34 1400 4.12 5.33 6.54 7.73 8.92 10.09 12.42 14.73 16.99 19.24 22.58 25.86 29.10 38.58 1600 3.99 5.19 6.39 7.56 8.73 9.89 12.19 14.46 16.69 18.91 22.19 25.42 28.61 34.84 37.89 1800 3.88 5.06 6.24 7.41 8.56 9.71 11.98 14.22 16.43 18.61 21.85 25.02 28.15 34.26 37.24 2000 3.78 4.95 6.12 7.27 8.41 9.54	600	4.93												32.05	39.05	42.51
1200 4.27 5.50 6.73 7.93 9.13 10.32 12.69 15.03 17.33 19.62 23.01 26.36 29.66 36.15 39.34 1400 4.12 5.33 6.54 7.73 8.92 10.09 12.42 14.73 16.99 19.24 22.58 25.86 29.10 35.46 38.58 1600 3.99 5.19 6.39 7.56 8.73 9.89 12.19 14.46 16.69 18.91 22.19 25.42 28.61 34.84 37.89 1800 3.88 5.06 6.24 7.41 8.56 9.71 11.98 14.22 16.43 18.61 21.85 25.02 28.15 34.26 37.24 2000 3.78 4.95 6.12 7.27 8.41 9.54 11.79 14.01 16.18 18.34 21.53 24.65 27.73 33.72 36.63 2400 3.60 4.75 5.90 7.03 8.15																41.23
1600 3.99 5.19 6.39 7.56 8.73 9.89 12.19 14.46 16.69 18.91 22.19 25.42 28.61 34.84 37.89 1800 3.88 5.06 6.24 7.41 8.56 9.71 11.98 14.22 16.43 18.61 21.85 25.02 28.15 34.26 37.24 2000 3.78 4.95 6.12 7.27 8.41 9.54 11.79 14.01 16.18 18.34 21.53 24.65 27.73 33.72 36.63 2400 3.60 4.75 5.90 7.03 8.15 9.26 11.46 13.62 15.75 17.85 20.95 23.98 26.96 32.71 35.49 2800 3.45 4.58 5.71 6.82 7.92 9.01 11.17 13.29 15.37 17.42 20.44 23.38 26.25 31.76 34.39 3200 3.31 4.43 5.54 6.64 7.72	1200	4.27	5.50	6.73	7.93	9.13	10.32	12.69	15.03	17.33	19.62	23.01	26.36	29.66	36.15	39.34
1800 3.88 5.06 6.24 7.41 8.56 9.71 11.98 14.22 16.43 18.61 21.85 25.02 28.15 34.26 37.24 2000 3.78 4.95 6.12 7.27 8.41 9.54 11.79 14.01 16.18 18.34 21.53 24.65 27.73 33.72 36.63 2400 3.60 4.75 5.90 7.03 8.15 9.26 11.46 13.62 15.75 17.85 20.95 23.98 26.96 32.71 35.49 2800 3.45 4.58 5.71 6.82 7.92 9.01 11.17 13.29 15.37 17.42 20.44 23.38 26.25 31.76 34.39 3200 3.31 4.43 5.54 6.64 7.72 8.79 10.91 12.99 15.02 17.02 19.96 22.80 25.57 30.83 33.32 3600 3.19 4.30 5.39 6.47 7.54				6.54 6.39						16.99 16.69			25.86 25.42	29.10 28.61		38.58 37.89
2400 3.60 4.75 5.90 7.03 8.15 9.26 11.46 13.62 15.75 17.85 20.95 23.98 26.96 32.71 35.49 2800 3.45 4.58 5.71 6.82 7.92 9.01 11.17 13.29 15.37 17.42 20.44 23.38 26.25 31.76 34.39 3200 3.31 4.43 5.54 6.64 7.72 8.79 10.91 12.99 15.02 17.02 19.96 22.80 25.57 30.83 33.32 3600 3.19 4.30 5.39 6.47 7.54 8.59 10.67 12.71 14.70 16.65 19.51 22.26 24.91 29.91 32.24 4000 3.09 4.17 5.26 6.32 7.37 8.41 10.45 12.45 14.40 16.30 19.07 21.72 24.27 28.99 31.15 5000 2.85 3.91 4.96 5.98 7.00 7.99 9.95 11.85 13.68 15.46 18.01 20.41 22.64	1800	3.88	5.06	6.24	7.41	8.56	9.71	11.98	14.22	16.43	18.61	21.85	25.02	28.15	34.26	37.24
2800 3.45 4.58 5.71 6.82 7.92 9.01 11.17 13.29 15.37 17.42 20.44 23.38 26.25 31.76 34.39 3200 3.31 4.43 5.54 6.64 7.72 8.79 10.91 12.99 15.02 17.02 19.96 22.80 25.57 30.83 33.32 3600 3.19 4.30 5.39 6.47 7.54 8.59 10.67 12.71 14.70 16.65 19.51 22.26 24.91 29.91 32.24 4000 3.09 4.17 5.26 6.32 7.37 8.41 10.45 12.45 14.40 16.30 19.07 21.72 24.27 28.99 31.15 5000 2.85 3.68 4.70 5.69 6.66 7.62 9.49 11.29 13.01 14.65 18.01 20.41 22.64 26.60 8000 2.31 3.28 4.24 5.16 6.06 6.94 8.62 10.20 11.65 12.99 14.75 10000 2.01				6.12 5.90	7.27				14.01	16.18 15.75	18.34 17.85	21.53	24.65 23.98			36.63 35.49
3600 3.19 4.30 5.39 6.47 7.54 8.59 10.67 12.71 14.70 16.65 19.51 22.26 24.91 29.91 32.24 4000 3.09 4.17 5.26 6.32 7.37 8.41 10.45 12.45 14.40 16.30 19.07 21.72 24.27 28.99 31.15 5000 2.85 3.91 4.96 5.98 7.00 7.99 9.95 11.85 13.68 15.46 18.01 20.41 22.64 26.60 6000 2.65 3.68 4.70 5.69 6.66 7.62 9.49 11.29 13.01 14.65 16.96 19.06 20.96 8000 2.31 3.28 4.24 5.16 6.06 6.94 8.62 10.20 11.65 12.99 14.75 10000 1.73 2.59 3.41 4.19 4.92 5.61 6.85 14000 1.45 2.25 3.00 3.	2800	3.45	4.58	5.71	6.82	7.92	9.01	11.17	13.29	15.37	17.42	20.44	23.38	26.25	31.76	34.39
4000 3.09 4.17 5.26 6.32 7.37 8.41 10.45 12.45 14.40 16.30 19.07 21.72 24.27 28.99 31.15 5000 2.85 3.91 4.96 5.98 7.00 7.99 9.95 11.85 13.68 15.46 18.01 20.41 22.64 26.60 6000 2.65 3.68 4.70 5.69 6.66 7.62 9.49 11.29 13.01 14.65 16.96 19.06 20.96 8000 2.31 3.28 4.24 5.16 6.06 6.94 8.62 10.20 11.65 12.99 14.75 10000 2.01 2.92 3.82 4.67 5.49 6.28 7.76 9.08 12000 1.73 2.59 3.41 4.19 4.92 5.61 6.85 14000 1.45 2.25 3.00 3.69 4.33 4.91					1							1 1			l	
6000 2.65 3.68 4.70 5.69 6.66 7.62 9.49 11.29 13.01 14.65 16.96 19.06 20.96 8000 2.31 3.28 4.24 5.16 6.06 6.94 8.62 10.20 11.65 12.99 14.75 10000 2.01 2.92 3.82 4.67 5.49 6.28 7.76 9.08 12000 1.73 2.59 3.41 4.19 4.92 5.61 6.85 14000 1.45 2.25 3.00 3.69 4.33 4.91 4.91 4.92 5.61 6.85 4.91 4.92 5.61 6.85 4.91 4.92 5.61 6.85 4.91 4.92 5.61 6.85 4.91 4.92 5.61 6.85 4.91 4.92 5.61 6.85 4.91 4.92 6.85 4.91 4.92 6.85 4.91 4.92 6.85 4.91 4.92 6.85 4.91 4.92 6.85 4.91 4.92 6.85 4.91 4.92 6.85 4.91 4.92 6.85 4.91 4.92 6.85 4.91 4.92 6.85 4.91 4.92 6.85 4.92 4.92 4.92 6.85 4.92 4.9	4000	3.09	4.17	5.26	6.32	7.37	8.41	10.45	12.45	14.40	16.30	19.07	21.72	24.27	28.99	
10000 2.01 2.92 3.82 4.67 5.49 6.28 7.76 9.08 12000 1.73 2.59 3.41 4.19 4.92 5.61 6.85 14000 1.45 2.25 3.00 3.69 4.33 4.91	6000	2.65	3.68	4.70	5.69	6.66	7.62	9.49	11.29	13.01	14.65	16.96		20.96	20.00	
12000 1.73 2.59 3.41 4.19 4.92 5.61 6.85 14000 1.45 2.25 3.00 3.69 4.33 4.91					1	1				11.65	12.99	14.75				
	12000	1.73	2.59	3.41	4.19	4.92	5.61		9.00							
Length Correction Factor 0.65 0.70 0.75 0.80 0.85 0.90 0.95 1.00 1.05 1.10 1.15 1.20 1.25 1.30								0.05	0.00	.05 1	00 45			4.00		4.00
From Length (mm) 200 215 260 315 375 450 540 650 780 935 1130 1355 1625 1960	Length Correc															
For Belt # of teeth 40 43 52 63 75 90 108 130 156 187 226 271 325 392			. ,													
Length To Length (mm) 210 255 310 370 445 535 645 775 930 1125 1350 1620 1955 2000 # of teeth 42 51 62 74 89 107 129 155 186 225 270 324 391 400	Length	To														

Shaded area indicates drive conditions where reduced service life can be expected. Contact Gates Application Engineering for specific recommendations. *See page 28 for hp or kw ratings.



Belt Width Selection Tables – 5mm PowerGrip® GT®2 Belts

The following table represents the torque ratings for each belt in its base width at the predetermined number of grooves, pitch diameters and rpm's. These ratings must be multiplied by the appropriate width factor and applicable belt length factor to obtain the corrected torque rating. (See Step 4 of Drive Selection Procedure on Page 24.)


Belt Width (mm)	9	15	20	25
Width Multiplier	0.60	1.00	1.33	1.67


				Rated I	Horsepo	wer For	Small S	procket	- 15m	n Bel	t Wid	ith*				
Number of											_					
Grooves Pitch mm	18 28.65	20 31.83	22 35.01	24 38.20	26 41.38	28 44.56	32 50.93	36 57.30	40 63.66	_	.62	48 76.39	50 79.58	62 98.68	74 117.77	80 127.32
Diameter (in)	1.128	1.253	1.379	1.504	1.629	1.754	2.005	2.256	2.506		320	3.008	3.133	3.885	4.637	5.013
10 20	0.01 0.02	0.01 0.03	0.02 0.03	0.02 0.04	0.02 0.04	0.02 0.05	0.03 0.06	0.03 0.06	0.04 0.07		04 08	0.05 0.09	0.05 0.10	0.06 0.12	0.08 0.15	0.08 0.16
40 60	0.04	0.05 0.07	0.06 0.09	0.07	0.08	0.09 0.12	0.10 0.15	0.12 0.18	0.14		16	0.17 0.25	0.18 0.26	0.23 0.33	0.28 0.41	0.30 0.44
100	0.00	0.11	0.14	0.16	0.18	0.20	0.13	0.18	0.32	0.		0.40	0.42	0.53	0.65	0.70
200 300	0.17 0.24	0.21 0.29	0.25 0.35	0.29 0.41	0.33 0.47	0.36 0.52	0.44 0.63	0.52 0.75	0.59 0.86	0. 0.	69 99	0.74 1.07	0.78 1.13	1.00 1.45	1.22 1.76	1.33 1.92
400 500	0.30 0.36	0.37 0.45	0.45 0.54	0.52 0.64	0.60 0.73	0.67 0.82	0.82	0.96 1.17	1.11	1.	28	1.39	1.46 1.78	1.88 2.29	2.28 2.79	2.49 3.04
600	0.42	0.53	0.64	0.74	0.85	0.96	1.17	1.38	1.59	1.	84	2.00	2.10	2.70	3.29	3.58
800 1000	0.52 0.62	0.67 0.80	0.81 0.97	0.95 1.15	1.09 1.32	1.23 1.49	1.50 1.83	1.78 2.16	2.05 2.49		90	2.58 3.14	2.71 3.30	3.49 4.26	4.26 5.19	4.63 5.65
1200 1400	0.72 0.81	0.93 1.05	1.13 1.29	1.34 1.52	1.54 1.75	1.74 1.98	2.14 2.44	2.53 2.90	2.92 3.34		40 89	3.69 4.22	3.88 4.44	5.00 5.72	6.09 6.97	6.63 7.58
1600	0.90 0.98	1.17 1.28	1.43	1.70	1.96	2.22	2.74 3.03	3.25	3.75	4.	37	4.74	4.99	6.43 7.12	7.83 8.66	8.51
1800 2000	1.06	1.39	1.58 1.72	1.87 2.04	2.16 2.36	2.45 2.68	3.31	3.59 3.93	4.15 4.55	5.	84 30	5.25 5.75	5.52 6.05	7.79	9.47	9.41 10.29
2400 2800	1.21 1.35	1.60 1.80	1.99 2.24	2.37 2.68	2.75 3.11	3.12 3.54	3.86 4.39	4.59 5.23	5.31 6.04	7.	19 05	6.72 7.64	7.06 8.04	9.08 10.30	11.00 12.50	11.96 13.52
3200 3600	1.49 1.61	1.99 2.17	2.49 2.73	2.98 3.27	3.47 3.81	3.95 4.34	4.90 5.40	5.84 6.43	6.75 7.43	7.	87 66	8.53 9.39	8.97 9.86	11.50 12.60	13.90 15.10	14.97 16.30
4000 5000	1.73 2.00	2.34 2.74	2.95 3.48	3.55 4.20	4.14 4.91	4.72 5.61	5.87 6.99	6.99 8.32	8.09 9.61		42	10.20 12.06	10.70 12.60	13.60 15.90	16.30 18.70	17.50
6000	2.23	3.10	3.96	4.79	5.62	6.42	8.00	9.51	10.96	12.	7	13.66	14.30	17.70	10.70	
8000 - 10000	2.59 2.82	3.69 4.11	4.76 5.36	5.80 6.56	6.81 7.72	7.80 8.82	9.69 10.89	11.46 12.75	13.09	14.	9	15.95	16.60			
12000 14000	2.91 2.86	4.36 4.42	5.75 5.90	7.06 7.26	8.30 8.52	9.46 9.65	11.54									
10000 14000 10 10 10 10 10 10 10 10 10 10 10 10							Rated k	ilowatt	s*							
10	0.01	0.01	0.01	0.01	0.02	0.02	0.02	0.03	0.03		03	0.04	0.04	0.05	0.06	0.06
E 20 40	0.02 0.03	0.02 0.04	0.02 0.04	0.03	0.03	0.03 0.06	0.04 0.08	0.05	0.05 0.10		06 12	0.07 0.13	0.07 0.13	0.09 0.17	0.11 0.21	0.12 0.23
60 100	0.04 0.07	0.05 0.09	0.06 0.10	0.07	0.08	0.09 0.15	0.11 0.18	0.13 0.21	0.15 0.24	0.		0.19 0.30	0.19 0.31	0.25 0.40	0.30 0.48	0.33 0.53
200	0.13	0.16	0.18	0.21	0.24	0.27	0.33	0.39	0.44	0.	51	0.56	0.58	0.75	0.91	0.99
300 400	0.18	0.22 0.28	0.26 0.34	0.30	0.35 0.45	0.39 0.50	0.47 0.61	0.56 0.72	0.64 0.83	0. 0.	96	0.80 1.04	0.84 1.09	1.08 1.40	1.31	1.43 1.85
500 600	0.27 0.31	0.34 0.39	0.41 0.47	0.47 0.55	0.54 0.63	0.61 0.71	0.74 0.87	0.88 1.03	1.01 1.18	1. 1.		1.27 1.49	1.33 1.56	1.71 2.01	2.08 2.45	2.27 2.67
800 1000	0.39 0.47	0.50 0.60	0.60 0.73	0.71 0.86	0.81 0.98	0.92 1.11	1.12 1.36	1.33 1.61	1.53 1.86		78 16	1.92 2.34	2.02 2.46	2.60 3.17	3.17 3.87	3.45 4.21
1200 1400	0.54 0.60	0.69 0.78	0.85 0.96	1.00	1.15 1.31	1.30 1.48	1.59	1.89	2.18	2.	54 90	2.75 3.15	2.89 3.31	3.73 4.27	4.54 5.20	4.94 5.66
1600	0.67	0.87	1.07	1.27	1.46	1.66	2.04	2.42	2.80	3.	26	3.54	3.72	4.79	5.84	6.35
1800 2000	0.73 0.79	0.95 1.04	1.18 1.28	1.40 1.52	1.61 1.76	1.83 2.00	2.26 2.47	2.68 2.93	3.10 3.39	3. 3.	95	3.92 4.29	4.12 4.51	5.31 5.81	6.46 7.06	7.02 7.67
2400 2800	0.90 1.01	1.19 1.34	1.48 1.67	1.77 2.00	2.05 2.32	2.33 2.64	2.88 3.27	3.42 3.90	3.96 4.51	5.	62 26	5.01 5.70	5.27 5.99	6.77 7.70	8.22 9.31	8.92 10.08
3200 3600	1.11 1.20	1.48 1.62	1.86 2.03	2.22	2.59 2.84	2.95 3.24	3.66 4.02	4.35 4.79	5.03 5.54	5.	87 46	6.36 7.00	6.69 7.35	8.57 9.39	10.30 11.30	11.16 12.15
4000	1.29	1.75	2.20	2.65	3.09	3.52	4.38	5.22	6.03	6.	02	7.61	7.99	10.20	12.10	13.05
5000 6000	1.49 1.67	2.05 2.31	2.60 2.95	3.13 3.57	3.66 4.19	4.18 4.79	5.21 5.96	6.21 7.09	7.16 8.17	9.	32 45	9.00 10.19	9.43 10.70	11.90 13.20	13.90	
8000 10000	1.93 2.10	2.75 3.06	3.55 4.00	4.32 4.89	5.08 5.75	5.81 6.58	7.23 8.12	8.54 9.51	9.76	11.	10	11.89	12.4			
12000 14000	2.17 2.13	3.25 3.30	4.29 4.40	5.26 5.42	6.19 6.35	7.05 7.20	8.61	3.01								
Length Correc			0.65	0.70	0.75	0.80	0.85	0.90	0.95	1.00	1.0	5 1.10) 1.15	1.20	1.25	1.30
-ongai ouile	From	Length (mm)	200	215	260	315			540	650	78		5 1130	1355	1625	1960
For Belt Length	T-	# of teeth	40	43	52	63	75		108	130	15			271	325	392
3	To	Length (mm) # of teeth	210 42	255 51	310 62	370 74			645 129	775 155	93 18			1620 324	1955 391	2000 400

Shaded area indicates drive conditions where reduced service life can be expected. Contact Gates Application Engineering for specific recommendations. *See page 27 for torque ratings.



Sprocket Specification Tables – 2mm Pitch PowerGrip® GT®2 Sprockets





				6 m	m (.236 in) Wide Bel	ts (2MR-06)				
	No.				Flange		Nominal Dim	ensions (in)		Plain Bor	o* (in)	_
Code Symbol	of Grooves	Туре	Pitch Diameter	Outside Diameter	0.D. (+0.016)	W (+0.005)	L (+0.010)	H (+0.016)	E (hub width)	Min.	Max.	Set Screws**
2MR-12S-06-AL	12	6FC	0.301	0.281	0.480	0.282	0.562	0.480	0.235	0.125	0.125	4-40
2MR-13S-06-AL	13	6FC	0.326	0.306	0.505	0.282	0.562	0.505	0.235	0.125	0.125	4-40
2MR-14S-06-AL 2MR-15S-06-AL	14 15	6FC 6FC	0.351 0.376	0.331 0.356	0.530 0.555	0.282 0.282	0.562 0.562	0.530 0.555	0.235 0.235	0.125 0.188	0.125 0.188	4-40 6-40
2MR-16S-06-AL	16	6FC	0.401	0.381	0.580	0.282	0.562	0.580	0.235	0.188	0.188	6-40
2MR-17S-06-AL 2MR-18S-06-AL	17 18	6F 6F	0.426 0.451	0.406 0.431	0.635 0.635	0.282 0.282	0.562 0.622	0.312 0.312	0.235 0.236	0.188 0.188	0.188 0.188	4-40 4-40
2MR-19S-06-AL	19	6F	0.476	0.456	0.635	0.282	0.622	0.338	0.236	0.188	0.188	4-40
2MR-20S-06-AL 2MR-21S-06-AL	20 21	6F 6F	0.501 0.526	0.481 0.506	0.685 0.710	0.282 0.282	0.622 0.622	0.364 0.390	0.236 0.236	0.188 0.188	0.188 0.188	4-40 4-40
2MR-22S-06-AL	22	6F	0.551	0.531	0.740	0.282	0.622	0.390	0.236	0.188	0.188	4-40
2MR-24S-06-AL 2MR-26S-06-AL	24 26	6F 6F	0.602 0.652	0.582 0.632	0.815 0.840	0.282 0.282	0.684 0.684	0.442 0.490	0.298 0.298	0.250 0.250	0.250 0.250	6-40 6-40
2MR-28S-06-AL 2MR-30S-06-AL	28 30	6F 6F	0.702 0.752	0.682 0.732	0.895 0.945	0.282 0.282	0.684 0.684	0.494 0.546	0.298 0.298	0.250 0.250	0.250 0.313	6-40 8-32
2MR-32S-06-AL	32	6F	0.802	0.782	1.000	0.282	0.684	0.598	0.298	0.250	0.375	8-32
2MR-36S-06-AL 2MR-40S-06-AL	36 40	6F 6F	0.902 1.003	0.882 0.983	1.105 1.210	0.282 0.282	0.684 0.715	0.676 0.754	0.298 0.313	0.250 0.250	0.438 0.500	8-32 8-32
2MR-45S-06-AL	45	6F	1.128	1.108	1.340	0.282	0.715	0.900	0.313	0.250	0.500	8-32
2MR-50S-06-AL	50	6F	1.253	1.233	1.470	0.282	0.715	0.940	0.313	0.250	0.688	8-32
2MR-56S-06-AL 2MR-62S-06-AL	56 62	6F 6	1.404 1.554	1.384 1.534	1.575 -	0.282 0.375	0.715 0.750	1.030 1.148	0.313 0.375	0.250 0.250	0.813 0.938	8-32 8-32
2MR-68S-06-AL 2MR-74S-06-AL	68 74	6 6	1.704 1.855	1.684 1.835	-	0.375 0.375	0.750 0.750	1.185 1.215	0.375 0.375	0.250 0.250	0.938 1.000	8-32 8-32
2MR-80S-06-AL	80	6	2.005	1.985	-	0.375	0.750	1.500	0.375	0.313	1.250	8-32
				9mr	n (.354 in)	Wide Belt	s (2MR-09)					
2MR-12S-09-AL 2MR-13S-09-AL	12 13	6FC 6FC	0.301 0.326	0.281 0.306	0.480 0.505	0.401 0.401	0.681 0.681	0.480 0.505	0.235 0.235	0.125 0.125	0.125 0.125	4-40 4-40
2MR-14S-09-AL	14	6FC	0.351	0.331	0.530	0.401	0.681	0.530	0.235	0.125	0.125	4-40
2MR-15S-09-AL 2MR-16S-09-AL	15 16	6FC 6FC	0.376 0.401	0.356 0.381	0.555 0.580	0.401 0.401	0.681 0.681	0.555 0.580	0.235 0.235	0.188 0.188	0.188 0.188	6-40 6-40
2MR-17S-09-AL	17	6F	0.426	0.406	0.635	0.401	0.741	0.312	0.295	0.188	0.188	4-40
2MR-18S-09-AL 2MR-19S-09-AL	18 19	6F 6F	0.451 0.476	0.431 0.456	0.635 0.635	0.401 0.401	0.741 0.741	0.312 0.338	0.235 0.235	0.188 0.188	0.188 0.188	4-40 4-40
2MR-20S-09-AL 2MR-21S-09-AL	20 21	6F 6F	0.501 0.526	0.481 0.506	0.685 0.710	0.401 0.401	0.741 0.741	0.364 0.390	0.235 0.235	0.188 0.188	0.188 0.188	4-40 4-40
2MR-22S-09-AL	22	6F	0.551	0.531	0.740	0.401	0.741	0.390	0.235	0.188	0.188	4-40
2MR-24S-09-AL 2MR-26S-09-AL	24 26	6F 6F	0.602 0.652	0.582 0.632	0.815 0.840	0.401 0.401	0.803 0.803	0.442 0.490	0.297 0.297	0.250 0.250	0.250 0.250	6-40 6-40
2MR-28S-09-AL	28	6F	0.702	0.682	0.895	0.401	0.803	0.494	0.297	0.250	0.250	6-40
2MR-30S-09-AL 2MR-32S-09-AL	30 32	6F 6F	0.752 0.802	0.732 0.782	0.945 1.000	0.401 0.401	0.803 0.803	0.546 0.598	0.297 0.297	0.250 0.250	0.313 0.375	8-32 8-32
2MR-36S-09-AL	36	6F 6F	0.902	0.882	1.105	0.401	0.803	0.676	0.297	0.250	0.438	8-32
2MR-40S-09-AL 2MR-45S-09-AL	40 45	6F	1.003 1.128	0.983 1.108	1.210 1.340	0.401 0.401	0.834 0.834	0.754 0.900	0.302 0.302	0.250 0.250	0.500 0.688	8-32 8-32
2MR-50S-09-AL 2MR-56S-09-AL	50 56	6F 6F	1.253 1.404	1.233 1.384	1.470 1.575	0.401 0.401	0.834 0.834	0.940 1.030	0.302 0.302	0.250 0.250	0.688 0.813	8-32 8-32
2MR-62S-09-AL	62	6	1.554	1.534	-	0.493	0.868	1.148	0.375	0.250	0.938	8-32
2MR-68S-09-AL 2MR-74S-09-AL	68 74	6	1.704 1.855	1.684 1.835	-	0.493 0.493	0.868 0.868	1.185 1.215	0.375 0.375	0.250 0.250	0.938 1.000	8-32 8-32
2MR-80S-09-AL	80	6	2.005	1.985	-	0.493	0.868	1.500	0.375	0.313	1.250	8-32

^{*}Plain bore style stocked in smallest bore.


NOTE: See Synchronous Belt Drives - Sprocket Specifications section, Page 69, for a complete table of stock and non-stock sprocket diameters.



For non-standard designs contact Gates Made-To-Order Metals Team at (800)709-6001

^{** 2} ea. set screws at 90 degrees.

Sprocket Specification Tables – 3mm Pitch PowerGrip® GT®2 Sprockets



				9 m	m (.354 in) Wide Bel	ts (3MR-09))				
							Nominal Dime	ensions (in)				
Codo	No.		Ditab	Outoido	Flange	w			_	Plain Bo	re* (in)	Set
Code Symbol	of Grooves	Туре	Pitch Diameter	Outside Diameter	0.D. (+0.016)	(+0.005)	(+0.010)	H (+0.016)	E (hub width)	Min.	Max.	Screws**
3MR-16S-09-AL	16	6FC	0.602	0.572	0.710	0.401	0.691	0.710	0.238	0.188	0.188	6-40
3MR-17S-09-AL 3MR-18S-09-AL	17 18	6FC 6F	0.639 0.677	0.609 0.647	0.740 0.790	0.401 0.401	0.691 0.821	0.740 0.442	0.238 0.315	0.188 0.188	0.188 0.188	6-40 4-40
3MR-19S-09-AL	19	6F	0.077	0.684	0.790	0.401	0.821	0.442	0.315	0.188	0.100	4-40
3MR-20S-09-AL	20	6F	0.752	0.722	0.895	0.401	0.821	0.500	0.315	0.188	0.250	4-40
3MR-21S-09-AL	21	6F	0.790	0.760	0.895	0.401	0.821	0.500	0.315	0.188	0.250	4-40
3MR-22S-09-AL 3MR-24S-09-AL	22 24	6F 6F	0.827 0.902	0.797 0.872	0.945 1.025	0.401 0.401	0.821 0.821	0.562 0.625	0.315 0.315	0.188 0.250	0.313 0.375	4-40 6-40
3MR-26S-09-AL	26	6F	0.902	0.947	1.105	0.401	0.821	0.625	0.315	0.250	0.375	6-40
3MR-28S-09-AL	28	6F	1.053	1.023	1.173	0.401	0.821	0.701	0.315	0.250	0.500	8-32
3MR-30S-09-AL	30	6F	1.128	1.098	1.250	0.401	0.821	0.776	0.315	0.250	0.563	8-32
3MR-32S-09-AL 3MR-34S-09-AL	32 34	6F 6F	1.203 1.278	1.173 1.248	1.323 1.398	0.401 0.401	0.821 0.833	0.851 0.921	0.315 0.306	0.250 0.250	0.625 0.688	8-32 8-32
3MR-36S-09-AL	36	6F	1.353	1.323	1.473	0.401	0.833	1.000	0.306	0.250	0.750	8-32
3MR-38S-09-AL	38	6F	1.429	1.399	1.549	0.401	0.833	1.075	0.306	0.250	0.875	8-32
3MR-40S-09-AL 3MR-45S-09-AL	40 45	6F 6F	1.504 1.692	1.474 1.662	1.625 1.775	0.401 0.401	0.833 0.833	1.150 1.250	0.306 0.306	0.250 0.133	0.938 1.000	8-32 8-32
3MR-50S-09-AL	50	6	1.880	1.850	1.775	0.401	0.875	1.250	0.306	0.133	1.000	8-32
3MR-56S-09-AL	56	6	2.105	2.075	-	0.500	0.875	1.250	0.375	0.313	1.000	8-32
3MR-62S-09-AL	62	6	2.331	2.301	-	0.500	0.875	1.250	0.375	0.313	1.000	8-32
3MR-68S-09-AL 3MR-74S-09-AL	68 74	6	2.557 2.782	2.527 2.752	-	0.500 0.500	0.875 0.875	1.250 1.250	0.375 0.375	0.313 0.313	1.000 1.000	8-32 8-32
3MR-80S-09-AL	80	6	3.008	2.978	-	0.500	0.875	1.250	0.375	0.313	1.000	8-32
		,		15 m	m (.591 ir	ı) Wide Be	ts (3MR-1	5)			'	
3MR-16S-15-AL	16	6FC	0.602	0.572	0.710	0.637	0.927	0.710	0.238	0.188	0.188	6-40
3MR-17S-15-AL	17	6FC	0.639	0.609	0.740	0.637	0.927	0.740	0.238	0.188	0.188	6-40
3MR-18S-15-AL 3MR-19S-15-AL	18 19	6F 6F	0.677 0.714	0.647 0.684	0.790 0.827	0.637 0.637	1.057 1.057	0.442 0.479	0.315 0.315	0.188 0.188	0.188 0.250	4-40 4-40
3MR-20S-15-AL	20	6F	0.714	0.004	0.895	0.637	1.057	0.479	0.315	0.100	0.250	4-40
3MR-21S-15-AL	21	6F	0.790	0.760	0.895	0.637	1.057	0.500	0.315	0.188	0.250	4-40
3MR-22S-15-AL	22	6F	0.827	0.797	0.945	0.637	1.057	0.562	0.315	0.188	0.313	4-40
3MR-24S-15-AL 3MR-26S-15-AL	24 26	6F 6F	0.902 0.977	0.872 0.947	1.025 1.105	0.637 0.637	1.057 1.057	0.625 0.625	0.315 0.315	0.250 0.250	0.375 0.375	6-40 6-40
3MR-28S-15-AL	28	6F	1.053	1.023	1.173	0.637	1.057	0.701	0.315	0.250	0.500	6-40
3MR-30S-15-AL	30	6F	1.128	1.098	1.250	0.637	1.057	0.776	0.315	0.250	0.563	8-32
3MR-32S-15-AL	32	6F	1.203	1.173	1.323	0.637	1.057	0.851	0.315	0.250	0.625	8-32
3MR-34S-15-AL 3MR-36S-15-AL	34 36	6F 6F	1.278 1.353	1.248 1.323	1.398 1.473	0.637 0.637	1.069 1.069	0.921 1.000	0.306 0.306	0.250 0.250	0.688 0.750	8-32 8-32
3MR-38S-15-AL	38	6F	1.429	1.399	1.549	0.637	1.069	1.075	0.306	0.250	0.875	8-32
3MR-40S-15-AL	40	6F	1.504	1.474	1.625	0.637	1.069	1.150	0.306	0.250	0.938	8-32
3MR-45S-15-AL 3MR-50S-15-AL	45 50	6F 6	1.692 1.880	1.662 1.850	1.775	0.637 0.736	1.069 1.111	1.250 1.250	0.306 0.375	0.250 0.313	1.000 1.000	8-32 8-32
3MR-56S-15-AL	56	6	2.105	2.075	-	0.736	1.111	1.250	0.375	0.313	1.000	8-32
3MR-62S-15-AL	62	6	2.331	2.301	-	0.736	1.111	1.250	0.375	0.313	1.000	8-32
3MR-68S-15-AL	68	6	2.557	2.527	-	0.736	1.111	1.250	0.375	0.313	1.000	8-32
3MR-74S-15-AL 3MR-80S-15-AL	74 80	6	2.782 3.008	2.752 2.978	-	0.736 0.736	1.111 1.111	1.250 1.250	0.375 0.375	0.313 0.313	1.000 1.000	8-32 8-32
ONTIT GOO TO AL	00	J	0.000	2.010		0.700	'.'''	1.200	0.070	0.010	1.000	002

For non-standard designs contact Gates Made-To-Order Metals Team at (800)709-6001


NOTE: See Synchronous Belt Drives - Sprocket Specifications section, Page 70, for a complete table of stock and non-stock sprocket diameters.



^{*} Plain bore style stocked in smallest bore.

^{** 2} ea. set screws at 90 degrees.

Sprocket Specification Tables – 5mm Pitch PowerGrip® GT®2 Sprockets



		туре Аг					mm /	591 i n	\ Wide	Rolt	s (5M		ype oi						
	No		Diamotor	(in)		10	(.	Jai II				11-15							
Sprocket	No. of	<u> </u>	Diameter 	(In) Flange	Design				υlr	nensior	is (I∏) ∣			Bushing	Bore	Sizes	Approx.	Approx.	Matl.
Number	Teeth	Pitch	0.D.	Ref.	Туре	Α	В	C	D	E	F	M	F-CL	Size	Min.	Max.	Wt. (lb)	WR2	Spec.
P18-5MGT-15 PB P19-5MGT-15 PB P19-5MGT-15 PB P20-5MGT-15 PB P21-5MGT-15 PB P22-5MGT-15 PB P23-5MGT-15 PB P25-5MGT-15 PB P26-5MGT-15 PB P30-5MGT-15 PB P30-5MGT-15 PB P30-5MGT-15 PB P30-5MGT-15 PB P34-5MGT-15 PB P36-5MGT-15 PB P38-5MGT-15 PB P38-5MGT-15 PB P38-5MGT-15 PB P40-5MGT-15 PB P40-5MGT-15 PB P40-5MGT-15 PB P45-5MGT-15 PB P46-5MGT-15 PB P48-5MGT-15 PB P48-5MGT-15 PB P48-5MGT-15 PB P48-5MGT-15 PB P50-5MGT-15 PB P60-5MGT-15 PB	18 19 20 21 22 23 24 25 26 28 30 32 34 36 36 36 38 40 44 44 45 50 52 56 60 64 68 72 80 90 112	1.128 1.191 1.253 1.316 1.379 1.441 1.504 1.556 1.629 1.754 1.880 2.005 2.381 2.381 2.506 2.256 2.256 2.256 3.038 3.509 3.760 4.010 4.261 4.511 5.639 4.013 5.639 7.018	1.083 1.146 1.208 1.271 1.334 1.394 1.459 1.521 1.582 1.709 1.835 1.960 2.085 2.211 2.211 2.211 2.336 2.336 2.461 2.712 2.775 2.963 3.288 3.213 3.464 4.266	1.385 1.420 1.510 1.530 1.530 1.530 1.660 1.780 1.780 1.900 2.130 2.130 2.130 2.375 2.380 2.387 2.610 2.610 2.730 3.090 3.390 3.330 3.330 2.570 3.810 4.140 4.520 4.670 ————————————————————————————————————	6F-1 6F-1 6F-1 6F-1 6F-1 6F-1 6F-1 6F-1		0.68 0.88 0.90 0.90 0.94 1.18 1.18 1.21 1.53 1.55 1.69 2.09 2.34 2.65 2.88 3.25 3.25 3.25 3.25 3.25 4.38	0.69 0.69 0.69 0.69 0.69 0.69 0.69 0.69	1.25 1.25 1.25 1.25 1.28 1.28 1.28 1.28 1.34 1.34 1.34 0.88 1.34 0.88 1.34 0.88 1.34 0.88 1.34 0.88 1.30 1.00 1.00 1.00 1.00 1.00 1.00	0.36 0.36 0.36 0.39 0.39 0.39 0.45 0.45 0.45 0.45 0.45 0 0.49 0 0.49 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0.89 0.89 0.89 0.89 0.89 0.89 0.89 0.89	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0.45 0.45	MPB	0.250 0.250 0.250 0.250 0.250 0.375 0.375 0.375 0.500	0.375 0.437 0.500 0.500 0.500 0.625 0.625 0.625 0.750 0.937 0.937 1.000 1.125 1.250 1.125 1.250	0.3 0.3 0.3 0.4 0.4 0.5 0.6 0.6 0.7 0.8 0.9 1.1 0.6 1.6 0.9 2.1 0.0 2.6 1.3 1.4 1.7 2.1 2.4 2.8 3.7 4.9 8.3	0.0003 0.0003 0.0004 0.0005 0.0006 0.0008 0.0009 0.001 0.001 0.002 0.002 0.003 0.002 0.003 0.005 0.004 0.005 0.001	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
						2	5 mm	(.984)	Wide	Belts	(5MF	R-25)							
P18-5MGT-25 PB P19-5MGT-25 PB P20-5MGT-25 PB P20-5MGT-25 PB P21-5MGT-25 PB P23-5MGT-25 PB P23-5MGT-25 PB P24-5MGT-25 PB P25-5MGT-25 PB P26-5MGT-25 PB P30-5MGT-25 PB P30-5MGT-25 PB P34-5MGT-25 PB P34-5MGT-25 PB P38-5MGT-25 PB P38-5MGT-25 PB P38-5MGT-25 PB P38-5MGT-25 PB P40-5MGT-25 PB P40-5MGT-25 PB P40-5MGT-25 PB P45-5MGT-25 PB P45-5MGT-25 PB P46-5MGT-25 PB P48-5MGT-25 PB P52-5MGT-25 PB P52-5MGT-25 PB P52-5MGT-25 PB P58-5MGT-25 PB P58-5MGT-25 PB P59-5MGT-25 PB P50-5MGT-25 PB	18 19 20 21 22 23 24 25 26 28 30 32 34 36 38 38 40 40 44 45 50 56 60 64 68 72 80 90 112	1.128 1.191 1.253 1.316 1.3179 1.441 1.504 1.629 1.754 1.880 2.005 2.130 2.256 2.256 2.256 2.256 2.381 2.381 2.381 2.381 2.506 2.506 2.757 2.820 3.008 3.133 3.258 3.100 4.010 4.261 4.511 5.013 5.639 7.018	1.083 1.146 1.208 1.271 1.334 1.396 1.459 1.521 1.584 1.709 2.085 2.211 2.336 2.336 2.336 2.336 2.3461 2.461 2.775 2.963 3.088 3.218 3.218 3.218 3.216 4.464 4.466 4.466 4.466 4.968 4.973	1.385 1.420 1.510 1.530 1.530 1.660 1.780 1.780 1.900 2.125 2.375 2.375 2.375 2.375 2.375 2.373 2.610 2.730 3.090 3.328 3.330 3.566 3.805 4.044 4.170 4.520 4.670 ————————————————————————————————————	6F-1 6F-1 6F-1 6F-1 6F-1 6F-1 6F-1 6F-1		0.68 0.88 0.90 0.90 0.94 1.15 1.18 1.21 1.37 1.55 1.69 — 2.09 — 2.65 — — — — — — — — — — — — — — — — — — —	1.08 1.08 1.08 1.08 1.08 1.08 1.08 1.08	1.65 1.65 1.65 1.68 1.68 1.68 1.68 1.73 1.73 1.73 0.88 1.73 0.88 1.78 0.88 1.78 0.88 1.78 0.88 1.78 0.89 1.70 1.00 1.00 1.00 1.25 1.25 1.25	0.37 0.37 0.37 0.40 0.40 0.40 0.45 0.45 0.45 0.45 0 0.50 0 0.50 0 0.50 0 0 0.03 0.03 0.0	1.28 1.28 1.28 1.28 1.28 1.28 1.28 1.28	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0.41 0 0.41 0 0.28 0.28 0.28 0.28 0.28 0.28 0.28 0.	0.64 0.64 0.64 0.64 0.64 0.64 0.64 0.64	MPB	0.250 0.250 0.250 0.250 0.250 0.250 0.375 0.375 0.375 0.500	0.375 0.437 0.500 0.500 0.500 0.625 0.625 0.625 0.687 0.750 0.937 1.000 1.000 1.125 1.125 1.125 1.250 1.	0.4 0.4 0.5 0.5 0.6 0.7 0.8 0.8 1.0 1.1 1.2 1.4 0.7 1.9 0.8 2.2 1.1 2.7 1.6 1.6 2.1 2.7 3.4 1.6 2.1 2.7 3.4 3.6 3.6 3.7 3.8 3.8 3.8 3.8 3.8 3.8 3.8 3.8	0.0003 0.0004 0.0005 0.0006 0.0007 0.001 0.001 0.002 0.003 0.004 0.005 0.004 0.005 0.004 0.009 0.009 0.009 0.014 0.012 0.024 0.033 0.042 0.057 0.057 0.057 0.057	a


Material Spec: S - Steel SS - Sintered Steel G - Grey Iron

Design Type Suffix: 1 - Solid 2 - Web 3 - Arms

For non-standard designs contact Gates Made-To-Order Metals Team at (800)709-6001

Bushing and Shaft Specification Tables – 5mm Pitch PowerGrip® GT®2 Sprockets





								Bore Range (i	n)			
	Torque	Dimen	sions (in)	Bolt	Mounting	Screws		Max B		Weight F	Range (lb)	Keyseat
Bushing	Capacity			Circle				Standard	Shallow			(in)
Size	(lb-in)	Α	В	(in)	Qty.	Size	Min. Bore	Keyseat	Keyseat*	Max. Bore	Min. Bore	
1008	1,200	1.386	0.875	1.328	2	1/4 X 1/2	0.500	0.875	1.000	0.2	0.3	Standard 1/4 x 1/16
1108	1,300	1.511	0.875	1.328	2	1/4 X 1/2	0.500	1.000	1.125	0.1	0.3	Standard 1/4 x 1/16
1210	3,600	1.875	1.000	1.750	2	¾ x ⅓	0.500	1.250		0.4	0.6	Standard
1610	4,300	2.250	1.000	2.125	2	% x %	0.500	1.500	1.688	0.5	0.9	Standard 3/8 x 1/8
1615	4,300	2.250	1.500	2.125	2	% x %	0.500	1.500	1.688	0.6	1.3	Standard 3/8 x 1/8
2012	7,150	2.750	1.250	2.625	2	⁷ /₁6 X ⁷ /8	0.500	1.875	2.125	0.9	1.7	Standard 1/2 x 3/16

^{*} Key is furnished with each bushing having a shallow keyseat.

Sprocket Installation

To Install TAPER-LOCK® Type Bushings

- Clean the shaft, bore of bushing, outside of bushing and the sprocket hub bore of all oil, paint and dirt. File away any burrs.
 - **Note:** The use of lubricants can cause sprocket breakage.
 - USE NO LUBRICANTS IN THIS INSTALLATION.
- Insert the bushing into the sprocket hub. Match the hole pattern, not threaded holes (each complete hole will be threaded on one side only).
- 3. LIGHTLY oil the set screws and thread them into those half-threaded holes indicated by on the diagram above.
 - **Note:** Do not lubricate the bushing taper, hub taper, bushing bore, or the shaft. Doing so could result in sprocket breakage.
- 4. With the key in the shaft keyway, position the assembly onto the shaft allowing for small axial movement of the sprocket which will occur during the tightening process.
 - **Note:** When mounting sprockets on a vertical shaft, precautions must be taken to positively prevent the sprocket and/or bushing from falling during installation.
- Alternately torque the set screws until the sprocket and bushing tapers are completely seated together (at approximately half of the recommended torque; see table below).
 Note: Do not use worn hex key wrenches.
 Doing so may result in a loose assembly or may damage screws.
- 6. Check the alignment and sprocket axial runout (wobble), and correct as necessary.
- Continue alternate tightening of the cap screws to the recommended torque values specified in Table 1 on this page.

- 8. To increase the bushing gripping force, hammer the face of the bushing using a drift or sleeve (Do Not Hit The Bushing Directly With The Hammer).
- 9. Re-torque the bushing screws after hammering.
- Recheck all screw torque values after the initial drive run-in, and periodically thereafter. Repeat steps 5 through 9 if loose.

Table 1 – Sprocket Installation Bolts (in) Torque Wrench Qty Size (lb-ft) (lb-in) **Bushing Style** 1008 2 1/4-20 x 1/2 2 1/4-20 x 1/2 55 1108 4.6 1210 2 3/8-16 x 5/8 14.6 175 2 1610 3/8-16 x 5/8 14.6 175 2 175 1615 3/8-16 x 5/8 146 2012 2 7/16-14 x 7/8 23.3 280

To Remove

- 1. Loosen and remove all mounting screws.
- 2. Insert screws into all jack screw holes indicated by " " (see figure at top of page).
- Loosen the bushing by alternately tightening the screws in small but equal increments until the tapered sprocket and bushing surfaces disengage.

Standard Keyseat Dimensions										
	K	eyseat (in)	Key (in)						
Shaft Diam. (In)	Width	Depth	Width	Depth						
0.313-0.438	3/32	3/64	3/32	3/32						
0.500-0.563	1/8	1/16	1/8	1/8						
0.625-0.875	3/16	3/32	3/16	3/16						
0.938-1.250	1/4	1/8	1/4	1/4						
1.313-1.375	5/16	5/32	5/16	5/16						
1.438-1.750	3/8	3/16	3/8	3/8						
1.813-2.250	1/2	1/4	1/2	1/2						

For Minimum Plain Bore (MPB) Sprockets

When using MPB PowerGrip® GT®2 sprockets in power transmission systems, important guidelines should be followed for proper product finishing and application. Due to the high load carrying capacity and high operating tensions often found in PowerGrip® GT®2 belt drive systems, it is imperative to use and adhere to industry standard practices.

When finishing MPB sprockets for high performance belt drive systems, care should be taken to ensure proper functionality and performance. General re-bore instructions and specifications are as follows:

- Materials used in PowerGrip® GT®2 sprockets are steel, gray iron, and ductile iron. The materials used may vary with the size of the sprocket. See the Sprocket Specification Tables, page 31.
- 2. The maximum bore diameter specified by the manufacturer for each sprocket size should NOT be exceeded, or a keyway used which reduces the hub thickness to less than its minimum allowable value. See the Sprocket Specification Tables for a listing of recommended bore ranges by sprocket size. Bores exceeding the maximum recommended value for a particular sprocket size can adversely affect the structural integrity, thereby reducing their load-carrying capability.

^{*} Taper-Lock® is a Registered trademark of Reliance Electric.



Bushing and Shaft Specification Tables – 5mm Pitch PowerGrip® GT®2 Sprockets - continued

The minimum metal thickness between the keyway and hub 0.D. should be no less than the set screw diameter specified for the corresponding sprocket size. See Figure 1 below.

1. A listing of minimum set screw diameters is included below.

P18-5MGT: 8-32

P19-5MGT thru P22-5MGT: 10-32

P23-5MGT thru P32-5MGT: 1/4

P34-5MGT thru P38-5MGT: 5/16

P40-5MGT thru P50-5MGT: 3/8




Figure 1 — Minimum Hub Thickness And Set Screw Placement Guidelines

3. The fit between a finished sprocket bore and its mating shaft in a power transmission system must not allow relative movement between the bore and the shaft when the drive is subjected to belt tension and torque loads. This is accomplished, in the case of plain bore sprockets, with the use of set screws and keys and by controlling the fit or clearance between the sprocket bore and its mating shaft. Cyclical, pulsating, or reversing loads may wear the sprocket bore and/or keyway due to the relative movement between the contacting surfaces of the shaft and the bore. The resulting wear may increase the clearance further, if an interference fit is not used.

In order to maximize the performance of high capacity belt drives using plain bore style sprockets, the following for recommendations presented in Table 2 should be followed:


Class 1 Clearance Fits should be used when the transmitted load is smooth in nature.

Interference Fits should be used for PowerGrip GT2 curvilinear drives transmitting cyclical, pulsating, or reversing loads.

	Table 2 -	Recommend	led Shaft /	Bore Fits	(Inches)		
		Clearan	ce Fits		Interfere	nce Fits	
		Class 1-	Smooth		Cyclical,	Pulsating],
		Loa	ad		Reversi	ng Load	
Nominal Bore	Shaft	Bore		Bore 1	olerance	Fit Tole	rance
Range	Tol.	Tol.	Fit Tol.	Ra	inge	Ran	ge
Over - To (Incl.)	(minus)	(Plus)	(Plus)	(M	inus)	(Min	us)
0.4375 - 0.5626	0.0005	0.0010	0.0015	0.0005	0.0010	0.0000	0.0010
0.5625 - 0.8750	0.0005	0.0010	0.0015	0.0005	0.0010	0.0000	0.0010
0.8750 - 1.2500	0.0005	0.0010	0.0015	0.0005	0.0010	0.0000	0.0010
1.2500 - 1.3750	0.0005	0.0010	0.0015	0.0005	0.0010	0.0000	0.0010
1.3750 - 1.500	0.0005	0.0010	0.0015	0.0005	0.0010	0.0000	0.0010
1.5000 - 1.7500	0.0010	0.0010	0.0020	0.0010	0.0020	0.0000	0.0020

Table 2 was extracted in part from AGMA Standard for Bores and Keyways for Flexible Couplings (Inch Series) AGMA 9002-A86 Table.

4. DO NOT chuck or center the sprocket on guide flanges. Soft jaws should be used when chucking on the sprocket teeth. Center (indicate) the sprocket using the sprocket tooth O.D.



5. Set screw holes in the sprocket hub must be placed properly for maximum holding strength. For both standard and shallow keyseats, two (2) set screws should be used as illustrated in Figure 2. The total holding strength of the set screws is dependent upon their placement and design. Generally, one screw should be placed directly over the keyway, and the other screw at ninety degrees (90°) from the keyway, or at sixty-five degrees (65°) from the keyway—a more recent practice that improves holding power. Sometimes four set screws (or two pair) are used for increased holding strength.





Figure 2 - Set Screw Angles

For Minimum Plain Bore (MPB) Sprockets

Each set screw should be placed axially—a minimum of one set screw diameter from the end of the sprocket hub extension. See Figure 1. For recommended set screw tightening torque values see Table 3 below.

Table 3–Recommended Tightening Torque Values For Set Screws

Set Screw Size	Hex Key Size (in)	Approximate Installation Torque Values (lb-in)
8-32	5/64	20
10-32	3/32	35
1/4	1/8	80
5/16	5/32	160
3/8	3/16	275
7/16	7/32	430
1/2	1/4	615
5/8	5/16	1315

- 6. After reboring, the sprocket may require rebalancing. Vibration, noise, reduced bearing life, and undue stresses on the mechanical components in the system could result if improper rebalancing practices are used. See Sprocket Specifications, page 74, for recommended sprocket balancing specifications.
- 7. Standard square or rectangular keys should be used. See page 32 for standard key dimensions.

Refer to Sprocket Specifications, page 74, for specifications and tolerances for sprocket eccentricity, parallelism, and balancing.



Bar Stock and Flanges

For sample and prototype needs, a full range of PowerGrip® GT®2 bar stock and flanges is available.

Bar Stock

Diameter Selection

2MR: 12-80 Groove3MR: 16-80 Groove

Material

• Aluminum

Availability

Other stock sizes and materials are available on a made-to-order basis. Check with Customer Service for availability.

Flanges


Material

Aluminum

Finish

· Unplated so user can finish to suit

Standard Flange Selection



	2mm Pitch Sprocket Barstock - Aluminum													
Catalog Description	No. of Grooves	Pitch Dia. (in)	Length	Material	Catalog Description	No. of Grooves	Pitch Dia. (in)	Length	Material	Catalog Description	No. of Grooves	Pitch Dia. (in)	Length	Material
2MR-12S-PS-2A 2MR-13S-PS-2A 2MR-14S-PS-3A 2MR-15S-PS-3A	12 13 14 15	0.301 0.326 0.351 0.376	2" 2" 3" 3"	AL AL AL AL	2MR-20S-PS-4A 2MR-21S-PS-4A 2MR-22S-PS-4A 2MR-24S-PS-5A	20 21 22 24	0.501 0.526 0.551 0.602	4" 4" 4" 5"	AL AL AL AL	2MR-36S-PS-6A 2MR-40S-PS-7A 2MR-45S-PS-7A 2MR-50S-PS-7A	36 40 45 50	0.902 1.003 1.128 1.253	6" 7" 7" 7"	AL AL AL AL
2MR-16S-PS-3A 2MR-17S-PS-3A 2MR-18S-PS-3A 2MR-19S-PS-3A	16 17 18 19	0.401 0.426 0.451 0.476	3" 3" 3" 3"	AL AL AL AL	2MR-26S-PS-5A 2MR-28S-PS-5A 2MR-30S-PS-6A 2MR-32S-PS-6A	26 28 30 32	0.652 0.702 0.752 0.802	5" 5" 6" 6"	AL AL AL AL	2MR-56S-PS-7A 2MR-62S-PS-8A 2MR-68S-PS-8A 2MR-74S-PS-8A 2MR-80S-PS-8A	56 62 68 74 80	1.404 1.554 1.704 1.855 2.005	7" 8" 8" 8"	AL AL AL AL


3mm Pitch Sprocket Barstock - Aluminum														
Catalog Description	No. of Grooves	Pitch Dia. (in)	Length	Material	Catalog Description	No. of Grooves	Pitch Dia. (in)	Length	Material	Catalog Description	No. of Grooves	Pitch Dia. (in)	Length	Material
3MR-16S-PS-5A 3MR-17S-PS-5A 3MR-18S-PS-5A 3MR-19S-PS-5A 3MR-20S-PS-6A 3MR-21S-PS-6A 3MR-22S-PS-6A 3MR-24S-PS-6A	16 17 18 19 20 21 22 24	0.602 0.639 0.677 0.714 0.752 0.790 0.827 0.902	5" 5" 5" 6" 6" 6"	AL AL AL AL AL AL	3MR-26S-PS-6A 3MR-28S-PS-6A 3MR-30S-PS-7A 3MR-32S-PS-7A 3MR-34S-PS-7A 3MR-36S-PS-8A 3MR-38S-PS-8A 3MR-40S-PS-8A	26 28 30 32 34 36 38 40	0.978 1.053 1.128 1.203 1.278 1.353 1.429 1.504	6" 6" 7" 7" 7" 8" 8"	AL AL AL AL AL AL AL	3MR-45S-PS-8A 3MR-50S-PS-8A 3MR-56S-PS-8A 3MR-62S-PS-8A 3MR-68S-PS-8A 3MR-74S-PS-8A 3MR-80S-PS-8A	45 50 56 62 68 74 80	1.692 1.880 2.105 2.331 2.557 2.782 3.008	8" 8" 8" 8" 8"	AL AL AL AL AL AL

	Table 4 – 2M Flanges (inches)													
Code	Inside	Outside	Material	Overall	Code	Inside	Outside	Material	Overall	Code	Inside	Outside	Material	Overall Thick.
Number	Dia.	Dia.	Gauge	Thick.	Number	Dia.	Dia.	Gauge	Thick.	Number	Dia.	Dia.	Gauge	
10M2-FA	0.188	0.425	0.025	0.045	22M2-FA	0.452	0.740	0.032	0.052	36M2-FA	0.774	1.105	0.032	0.052
11M2-FA	0.214	0.450	0.025	0.045	24M2-FA	0.504	0.790	0.032	0.052	38M2-FA	0.826	1.155	0.032	0.052
12M2-FA	0.218	0.480	0.025	0.045	25M2-FA	0.530	0.815	0.032	0.052	40M2-FA	0.874	1.210	0.040	0.060
13M2-FA	0.244	0.505	0.025	0.045	26M2-FA	0.556	0.840	0.032	0.052	42M2-FA	0.926	1.260	0.040	0.060
14M2-FA	0.270	0.530	0.025	0.045	28M2-FA	0.574	0.895	0.032	0.052	44M2-FA	0.978	1.315	0.040	0.060
15M2-FA	0.296	0.555	0.025	0.045	30M2-FA	0.626	0.945	0.032	0.052	45M2-FA	1.004	1.340	0.040	0.060
16M2-FA	0.322	0.580	0.025	0.045	32M2-FA	0.678	1.000	0.032	0.052	48M2-FA	1.058	1.420	0.040	0.060
18M2-FA	0.374	0.635	0.032	0.052	33M2-FA	0.704	1.025	0.032	0.052	50M2-FA	1.110	1.470	0.040	0.060
20M2-FA	0.426	0.685	0.032	0.052	34M2-FA	0.722	1.050	0.032	0.052	54M2-FA	1.200	1.575	0.040	0.060
21M2-FA	0.452	0.710	0.032	0.052	35M2-FA	0.748	1.080	0.032	0.052	60M2-FA	1.356	1.730	0.040	0.060

	Table 5 – 3M Flanges (inches)													
Code	Inside	Outside	Material	Overall	Code	Inside	Outside	Material	Overall	Code	Inside	Outside	Material	Overall
Number	Dia.	Dia.	Gauge	Thick.	Number	Dia.	Dia.	Gauge	Thick.	Number	Dia.	Dia.	Gauge	Thick.
15M3-FA	0.426	0.685	0.032	0.052	22M3-FA	0.626	0.945	0.032	0.052	32M3-FA	0.999	1.323	0.032	0.052
16M3-FA	0.452	0.710	0.032	0.052	24M3-FA	0.704	1.025	0.032	0.052	34M3-FA	1.074	1.398	0.040	0.060
17M3-FA	0.452	0.740	0.032	0.052	25M3-FA	0.738	1.060	0.032	0.052	36M3-FA	1.149	1.478	0.040	0.060
18M3-FA	0.504	0.790	0.032	0.052	26M3-FA	0.774	1.105	0.032	0.052	38M3-FA	1.225	1.549	0.040	0.060
19M3-FA	0.541	0.827	0.032	0.052	28M3-FA	0.849	1.173	0.032	0.052	40M3-FA	1.300	1.625	0.040	0.060
20M3-FA	0.574	0.895	0.032	0.052	30M3-FA	0.924	1.250	0.032	0.052	44M3-FA	1.450	1.775	0.040	0.060

Sprocket Flange Selection Procedure

- **1.** Determine Sprocket Size and Finished O.D. (See tables on pages 69-70.
- 2. Determine Root Diameter (Root Diameter = Finished O.D. 2 x Nominal Groove Depth).
- **3.** Determine Maximum Flange Seat Diameter (Maximum Flange Seat Diameter = Root Diameter Pitch Factor).
- **4.** Select Flange with Inside Diameter less than maximum Flange Seat Diameter (See Table 4, or 5 on Page 34.
- Determine Flange Seat Diameter.
 (Flange Seat Diameter = Flange I.D. +0.000" -0.003"
- **6.** Determine Flange Seat Width
 (Flange Seat Width = Flange Gauge +0.020"
 +/-0.005". (See Table 4, or 5 on Page 34.)
- **7.** Flanges can be rolled, staked or punched on.



Single Sided Belt Drive Systems

Gates 3mm and 5mm pitch HTD belts have components identical to the larger-sized 8mm and 14mm pitch HTD belts — helically-wound fiberglass tension members embedded in a Neoprene body with the belt teeth faced with a tough wear-resistant nylon fabric.

The three principal dimensions in millimeters, shown below, are used to specify an HTD belt.

300	3M	09
Pitch Length	Pitch	Width


Belt pitch is the distance in millimeters between two adjacent tooth centers as measured on the pitch line of the belt. Belt pitch length is the total length (circumference) in millimeters as measured along the pitch line. The theoretical pitch line of an HTD belt lies within the tensile member.

The three principal dimensions used to specify a sprocket – number of grooves, pitch and belt width in millimeters – are shown below.


P22	3M	09
Number of Grooves	Pitch	Belt Width

NOTE: For drive design procedure, see page 12.


Belt tooth to sprocket groove clearance is greater in PowerGrip HTD drives than in PowerGrip Timing drives. If the higher torque capacity of PowerGrip HTD is required together with minimal backlash characteristics, use PowerGrip® GT®2.



3mm Pitch - Reference Dimensions



5mm Pitch - Reference Dimensions



PowerGrip HTD Belt Lengths

Code Pitch Length Ode Code (in)					3n	ım Pitch Be	It Lengths					
B7-3M		Pitch	Length			Pitch I	Length			Pitch	Length	No. of
*102:3M		(in)	(mm)	Teeth		(in)	(mm)	Teeth		(in)	(mm)	Teeth
*105-3M				29	•324-3M	12.756	324	108				200
*** **********************************												202
*123-3M												203
126-3M					•336-3M	13.228	336	112				204
129-3M 5.079 129 43 •357-3M 14.055 357 119 •639-3M 25.157 639 24.14.3M 5.551 141 47 360-3M 14.73 360 120 •648-3M 25.394 645 644 48 9.663-3M 14.291 363 121 •648-3M 25.312 648 644 48 9.663-3M 14.291 363 121 •648-3M 25.512 648 654 47.3M 5.669 144 48 9.663-3M 14.291 363 121 •648-3M 25.512 648 654 47.3M 5.669 150 50 •369-3M 14.693 369 122 •657-3M 25.748 654 654 48.163-3M 5.966 150 50 •369-3M 14.698 369 122 •657-3M 25.748 654 654 48.163-3M 6.142 156 52 372-3M 14.646 372 124 •663-3M 26.39 663 159 53 •381-3M 15.000 381 127 •669-3M 26.39 663 159 53 •381-3M 15.100 381 127 •669-3M 26.39 663 165 55 •384-3M 15.118 384 128 672-3M 26.347 672 48.168-3M 6.614 168 56 •387-3M 15.236 387 129 681-3M 26.811 681 48.174-3M 6.860 174 58 •390-3M 15.254 390 390 390 390 390 390 390 390 484 18.174-3M 6.969 177 59 9.396-3M 15.591 396 132 •687-3M 26.99 684 48.177-3M 6.969 177 59 9.396-3M 15.709 399 313 •686-3M 27.047 687 48.183-3M 7.087 180 60 •399-3M 15.709 399 313 •686-3M 27.402 699 48.183-3M 7.205 183 61 •405-3M 15.945 405 135 *711-3M 27.992 711 186-3M 7.323 186 62 *411-3M 16.181 411 137 720-3M 28.346 729 411-3M 18.93M 7.559 192 64 *420-3M 16.535 420 140 *738-3M 28.937 735 192-3M 7.6579 192 64 *420-3M 16.535 420 140 *738-3M 29.055 738 192-3M 7.991 201 67 *432-3M 17.008 432 144 189 63 *477-3M 16.477 41 189 63 *477-3M 16.477 41 189 63 *477-3M 16.477 41 189 63 *477-3M 16.335 420 140 *738-3M 29.055 738 201-3M 7.913 201 67 *432-3M 17.008 432 144 *887-3M 32.995 735 420-43M 8.031 204 68 *435-3M 17.244 438 146 *822-3M 32.995 735 420-43M 8.031 204 68 *435-3M 17.244 438 146 *822-3M 32.995 735 420-43M 8.031 204 68 *435-3M 17.244 438 140 *837-3M 32.995 837 420-43M 8.031 204 68 *435-3M 17.244 438 140 *837-3M 32.995 837 420-43M 8.031 204 68 *435-3M 17.244 438 447 449 *843-3M 31.899 795 204-3M 8.258 210 70 *444-3M 17.480 444 148 *837-3M 32.995 337 219-3M 8.268 210 70 *444-3M 17.480 444 148 *837-3M 32.995 337 219-3M 8.268 210 70 *444-3M 17.480 444 148 *837-3M 32.995 337 219-3M 8.268-3M 8.268 210 70 *444-3M 18.898 490 18.898 490 18.30 490-3M 39.449 1002 4					•339-3M	13.346	339	113				209
141-3M 5.551 141 47 386-3M 14.173 360 120 645-3M 25.314 645 2 144-3M 5.689 144 48 363-3M 14.291 363 121 648-3M 25.512 648 147-3M 5.787 147 49 366-3M 14.499 366 122 654-3M 25.512 648 2 147-3M 5.787 147 49 366-3M 14.499 366 122 654-3M 25.512 648 2 145-3M 5.787 147 49 366-3M 14.528 369 122 654-3M 25.512 648 2 155-3M 5.069 150 50 369-3M 14.528 369 123 657-3M 25.866 657 2 155-3M 6.260 159 53 381-3M 15.000 381 127 669-3M 26.339 669 165 55 3381-3M 15.118 384 128 672-3M 26.457 672 124 663-3M 26.451 681 168 168 56 387-3M 15.128 384 128 672-3M 26.457 672 124 663-3M 26.451 681 168 168 168 168 168 168 168 168 16				42								211
144-3M 5.689												213
•147-3M 5.787 147 49												215
150-3M 5.906						14.291						216 218
*195-3M								122				219
159-3M												
•165-3M 6.496 165 55 •384-3M 15.118 384 128 672-3M 26.457 672 2 168-3M 6.614 168 56 •387-3M 15.236 387 129 681-3M 26.457 672 2 168-3M 6.614 168 56 •387-3M 15.236 387 129 681-3M 26.811 681 2 177-3M 6.969 1777 59 •396-3M 15.354 390 130 •684-3M 26.929 684 2 177-3M 6.969 1777 59 •396-3M 15.591 396 132 •687-3M 27.047 687 2 180-3M 7.087 180 60 •399-3M 15.709 399 133 •686-3M 27.402 696 2 183-3M 7.205 183 61 •405-3M 15.945 405 135 •771-3M 27.992 7711 186-3M 7.323 186 62 •411-3M 16.181 411 137 720-3M 28.346 720 1889-3M 7.559 192 64 •420-3M 16.535 420 140 •738-3M 29.055 738 192-3M 7.559 192 64 •420-3M 16.535 420 140 •738-3M 29.055 738 2 195-3M 7.677 195 65 •426-3M 16.772 426 142 •753-3M 29.646 753 2 101-3M 8.031 204 68 •435-3M 17.008 432 144 •795-3M 31.299 795 2 120-3M 8.031 204 68 •435-3M 17.264 438 146 •822-3M 32.362 822 2 10-3M 8.268 210 70 •444-3M 17.480 444 148 •837-3M 32.953 837 2 121-3M 8.268 210 70 •444-3M 17.480 444 148 •837-3M 32.953 837 2 121-3M 8.622 219 73 462-3M 18.007 465 155 882-3M 33.189 843 2 121-3M 8.622 219 73 462-3M 18.007 465 155 882-3M 33.189 843 2 121-3M 8.622 219 73 462-3M 18.007 465 155 881-3M 34.70 873 2 129-3M 8.622 219 73 462-3M 18.007 465 155 881-3M 34.70 873 2 129-3M 8.622 219 73 462-3M 18.007 465 155 881-3M 34.70 873 2 129-3M 8.622 219 73 462-3M 18.007 465 155 881-3M 34.70 873 2 129-3M 8.622 219 73 462-3M 18.307 465 155 881-3M 35.079 881 2 122-3M 8.662 219 73 462-3M 18.307 465 155 881-3M 35.079 881 2 122-3M 8.662 219 73 462-3M 18.307 465 155 881-3M 35.079 891 2 122-3M 8.662 219 73 462-3M 18.806 477 159 9951-3M 36.024 915 2 123-3M 8.662 219 73 462-3M 18.806 477 159 9951-3M 36.024 915 2 123-3M 8.662 219 73 462-3M 18.806 477 159 9951-3M 36.024 915 2 123-3M 8.662 219 73 462-3M 18.806 477 159 9951-3M 36.024 915 2 123-3M 8.663 225 376 468-3M 18.307 465 155 881-3M 37.205 945 3 1222-3M 8.668 226 384 848-3M 19.134 486 162 1002-3M 39.449 1002 3 124-3M 9.449 240 80 480-3M 18.898 480 160 4963-3M 39.449 1002 3 124-3M 9.803 249-3M 9.803 249 83 4489-3M 19.252 489 163 1002-3M 39.449 1002 3 124-3M 9.803 24												221 223
•168-3M												223
•174-3M 6.850 174 58 •390-3M 15.354 390 130 •684-3M 26.929 684 27.77-3M 6.969 177 59 •396-3M 15.591 396 132 •687-3M 27.402 696 87.83-3M 7.087 180 60 •339-3M 15.709 399 133 •696-3M 27.402 696 68183-3M 7.205 183 61 •405-3M 15.945 405 135 •711-3M 27.992 711 180-3M 7.323 186 62 •411-3M 16.181 411 137 720-3M 28.346 720 189-3M 7.441 189 63 •417-3M 16.417 417 139 •735-3M 28.937 735 192-3M 7.559 192 64 •420-3M 16.535 420 140 •738-3M 29.055 738 192-3M 7.677 195 65 •426-3M 16.772 426 142 •753-3M 29.056 753 201-3M 7.913 201 67 •432-3M 17.008 432 144 •795-3M 31.299 795 201-3M 8.031 204 68 •435-3M 17.126 435 145 804-3M 31.654 804 207-3M 8.268 210 70 •444-3M 17.480 444 148 •822-3M 32.362 822 210-3M 8.268 210 70 •444-3M 17.480 444 148 •837-3M 32.953 837 219-3M 8.504 216 72 •459-3M 18.071 459 153 •873-3M 34.370 873 219-3M 8.588 225 75 •468-3M 18.207 465 155 6990-3M 34.204 915 300-225-3M 8.858 225 75 •468-3M 18.254 486 156 990-3M 35.079 891 225-3M 9.331 234 78 •477-3M 18.898 480 160 •981-3M 37.205 394 1002 327-3M 30.031 204 68 436-3M 18.189 462 154 •882-3M 34.704 882 422-3M 34.704 882 447 149 \$843-3M 33.189 843 219-3M 8.504 216 72 •459-3M 18.071 459 153 \$873-3M 34.370 873 219-3M 8.504 216 72 •459-3M 18.189 462 154 \$882-3M 34.704 882 422-3M 32.362 822 328-34 34.504 216 72 •459-3M 18.189 462 154 \$882-3M 34.704 882 325-3M 36.024 915 327-3M 9.213 234 78 \$477-3M 18.543 471 157 \$915-3M 36.024 915 327-3M 9.213 234 78 \$477-3M 18.543 471 157 \$915-3M 36.024 915 327-3M 9.331 237 79 477-3M 18.898 480 160 \$981-3M 37.205 945 327-3M 9.331 237 79 477-3M 18.898 480 160 \$981-3M 37.205 945 327-3M 9.203 249 83 \$489-3M 19.134 486 162 \$1002-3M 9.494 1002 324-3M 9.803 249 83 \$489-3M 19.134 486 162 \$1002-3M 40.394 1002 324-3M 9.803 249 83 \$489-3M 19.134 486 162 \$1002-3M 40.394 1002 324-3M 9.803 249 83 \$489-3M 19.370 499 163 \$1026-3M 40.394 1002 324-3M 9.803 249 83 \$489-3M 19.370 499 164 \$1035-3M 40.394 1002 324-3M 9.803 249 83 \$489-3M 19.370 499 164 \$1035-3M 40.748 1035												227
• 177-3M												228
•180-3M				58		15.354						229
*** **********************************												232
186-3M 7.323 186 62 •411-3M 16.181 411 137 720-3M 28.346 720 22 •189-3M 7.441 189 63 •417-3M 16.417 417 139 •735-3M 28.937 735 2 •195-3M 7.559 192 64 •420-3M 16.535 420 140 •738-3M 29.055 738 2 •195-3M 7.677 195 65 •426-3M 16.772 426 142 •753-3M 29.646 753 •201-3M 7.913 201 67 •432-3M 17.008 435 145 804-3M 31.654 804 •207-3M 8.150 207 69 •438-3M 17.126 435 145 804-3M 31.654 804 •213-3M 8.268 210 70 •444-3M 17.480 444 148 •837-3M 32.953 837 •219-3M 8.622 219 73 <												237
•189-3M												240
192 193 193 194 195 192 194 194 195												245
•195-3M 7.677 195 65 •426-3M 16.772 426 142 •753-3M 29.646 753 22 •201-3M 7.913 201 67 •432-3M 17.008 432 144 •795-3M 31.299 795 22 •204-3M 8.031 204 68 •435-3M 17.126 435 145 804-3M 31.654 804 •207-3M 8.150 207 69 •438-3M 17.244 438 146 •822-3M 32.362 822 22 210-3M 8.268 210 70 •444-3M 17.480 444 148 •837-3M 32.953 837 2213-3M 8.386 213 71 •447-3M 17.598 447 149 •843-3M 33.189 843 2219-3M 8.622 219 73 462-3M 18.189 462 154 •882-3M 34.724 882 222-3M 873-3M 34.724 882 222-3M 8.740 222 <												246
•201-3M 7.913 201 67 •432-3M 17.008 432 144 •795-3M 31.299 795 2204-3M •204-3M 8.031 204 68 •435-3M 17.126 435 145 804-3M 31.654 804 207-3M 8.150 207 69 •438-3M 17.244 438 146 •822-3M 32.362 822 22 210-3M 8.268 210 70 •444-3M 17.480 444 148 •837-3M 32.953 837 219-3M 8.216-3M 32.953 837 22 213-3M 8.386 213 71 •447-3M 17.598 447 149 •843-3M 33.189 843 2416-3M 8.504 216 72 •459-3M 18.071 459 153 •873-3M 34.370 873 222-3M 8.622 219 73 466-3M 18.189 462 154 •882-3M 34.724 882 222-3M 8.858 225 75 •468-3M 18.307					●420-3IVI ●426-3M							251
•204-3M 8.031 204 68 •435-3M 17.126 435 145 804-3M 31.654 804 •207-3M 8.150 207 69 •438-3M 17.244 438 146 •822-3M 32.362 822 210-3M 8.268 210 70 •444-3M 17.480 444 148 •837-3M 32.953 837 •213-3M 8.386 213 71 •447-3M 17.598 447 149 •843-3M 33.189 843 •216-3M 8.504 216 72 •459-3M 18.071 459 153 •873-3M 34.370 873 219-3M 8.622 219 73 462-3M 18.189 462 154 •882-3M 34.724 882 222-3M 8.740 222 74 465-3M 18.307 465 155 •891-3M 35.079 891 4225-3M 462-3M 18.425 468 156 •900-3M 35.433 900 36.224-3M												265
•207-3M 8.150 207 69 •438-3M 17.244 438 146 •822-3M 32.362 822 22 210-3M 8.268 210 70 •444-3M 17.480 444 148 •837-3M 32.953 837 2 •213-3M 8.366 213 71 •447-3M 17.598 447 149 •843-3M 33.189 843 2 •216-3M 8.504 216 72 •459-3M 18.071 459 153 •873-3M 34.370 873 2 •219-3M 8.622 219 73 462-3M 18.189 462 154 •882-3M 34.724 882 225 75 •465-3M 18.307 465 155 •891-3M 35.079 891 2 225-3M 8.858 225 75 •468-3M 18.425 468 156 •900-3M 35.433 900 3 900 3 9234-3M 9.213 234 78 •471												268
210-3M 8.268 210 70 •444-3M 17.480 444 148 •837-3M 32.953 837 4	●207-3M	8 150	207	60					•822-3M	32.362	822	274
•213-3M 8.386 213 71 •447-3M 17.598 447 149 •843-3M 33.189 843 2216-3M 9.813-3M 34.370 873 23.189 843 24.73M 17.598 447 149 •843-3M 33.189 843 24.73M 18.189 153 •873-3M 34.370 873 22.73M 22.73M 8.622 219 73 462-3M 18.189 462 154 •882-3M 34.724 882 22.73M 8.740 222 74 465-3M 18.307 465 155 •891-3M 35.079 891 225-3M 8.858 225 75 •468-3M 18.425 468 156 •900-3M 35.433 900 35.433 900 36.024 915-3M 36.024 915-3M 36.024 915-3M 36.024 915-3M 36.024 915-3M 37.205 945-3M 947-3M 18.661 474 158 •945-3M 37.205 945 37.30 9240-3M 9.480-3M <					•444-3M	17 480	444	148	●837-3M	32.953	837	279
•216-3M 8.504 216 72 •459-3M 18.071 459 153 •873-3M 34.370 873 2219-37 873 222-3M 8.622 219 73 462-3M 18.189 462 154 •882-3M 34.724 882 22 8222-3M 8.740 222 74 465-3M 18.307 465 155 •891-3M 35.079 891 228.76 468-3M 18.425 468 156 •900-3M 35.433 900 35.433 900 36.024 915-3M 36.024 915-3M 36.024 915-3M 36.024 915-3M 36.024 915-3M 36.024 915-3M 37.205 945-3M 948-3M <												281
219-3M 8.622 219 73 462-3M 18.189 462 154 •882-3M 34.724 882 22 •222-3M 8.740 222 74 465-3M 18.307 465 155 •891-3M 35.079 891 2 •225-3M 8.858 225 75 •468-3M 18.425 468 156 •900-3M 35.433 900 35.433 900 35.433 900 36.024 915-3M 36.024 915-3M 36.024 915-3M 36.024 915-3M 36.024 915-3M 37.205 945-3M 37.205 945-3M 37.205 945-3M 37.205 945-3M 37.441 951 36.024 915-3M 37.441 951 37.441 951-3M 37.441 951 37.441 951 37.441 951 37.441 951 37.441 951 37.441 951 37.441 951 37.441 951 37.441 951 37.441 951 37.441 951	•216-3M	8.504	216	72					●873-3M	34.370	873	291
•225-3M 8.858 225 75 •468-3M 18.425 468 156 •900-3M 35.433 900 3 •228-3M 8.976 228 76 •471-3M 18.543 471 157 •915-3M 36.024 915 3 •234-3M 9.213 234 78 •474-3M 18.661 474 158 •945-3M 37.205 945 3 •237-3M 9.331 237 79 477-3M 18.780 477 159 •951-3M 37.441 951 3 •240-3M 9.449 240 80 •480-3M 18.898 480 160 •981-3M 38.622 981 3 •246-3M 9.685 246 82 •486-3M 19.134 486 162 •1002-3M 39.449 1002 3 •252-3M 9.921 252 84 •492-3M 19.370 492 164 •1035-3M 40.748 1035	219-3M	8.622	219	73	462-3M		462	154				294
•225-3M 8.858 225 75 •468-3M 18.425 468 156 •900-3M 35.433 900 35.433 900 35.433 900 35.433 900 35.433 900 35.433 900 35.433 900 35.433 900 35.433 900 35.433 900 35.433 900 35.433 900 36.024 915.3M 36.024 915.3M 36.024 915.3M 37.205 945.3M 37.205 945.3M 37.205 945.3M 37.441 951.3M 37.441 951.3M 37.441 951.3M 37.441 951.3M 38.622 981.3M 38.622 981.3M 38.622 981.3M 38.622 981.3M 39.449 1002.3M 39.449 1002.3M 39.449 1002.3M 39.449 1002.3M 39.449 1002.3M 39.449 1002.3M 489.3M 19.252 489 163 •1026.3M 40.394 1026 30.3M 492.3M 19.370 492 164 •1035.3M 40.748	•222-3M	8.740	222	74					●891-3M	35.079	891	297
•234-3M 9.213 234 78 •474-3M 18.661 474 158 •945-3M 37.205 945 37.205 •237-3M 9.331 237 79 477-3M 18.780 477 159 •951-3M 37.441 951 •240-3M 9.449 240 80 •480-3M 18.898 480 160 •981-3M 38.622 981 •246-3M 9.685 246 82 •486-3M 19.134 486 162 •1002-3M 39.449 1002 249-3M 9.803 249 83 •489-3M 19.252 489 163 •1026-3M 40.394 1026 •252-3M 9.921 252 84 •492-3M 19.370 492 164 •1035-3M 40.748 1035		8.858			●468-3M	18.425	468	156	•900-3M	35.433	900	300
•237-3M 9.331 237 79 477-3M 18.780 477 159 •951-3M 37.441 951 37.441					•471-3M	18.543	471	157				305
•240-3M 9.449 240 80 •480-3M 18.898 480 160 •981-3M 38.622 981 38.622 •246-3M 9.685 246 82 •486-3M 19.134 486 162 •1002-3M 39.449 1002 39.449 249-3M 9.803 249 83 •489-3M 19.252 489 163 •1026-3M 40.394 1026 30.489 •252-3M 9.921 252 84 •492-3M 19.370 492 164 •1035-3M 40.748 1035					•474-3M	18.661						315
•240-3M 9.685 246 82 •486-3M 19.134 486 162 •1002-3M 39.449 1002 3 249-3M 9.803 249 83 •489-3M 19.252 489 163 •1026-3M 40.394 1026 3 •252-3M 9.921 252 84 •492-3M 19.370 492 164 •1035-3M 40.748 1035	•237-3M	9.331	237	79								317
249-3M 9.803 249 83 •489-3M 19.252 489 163 •1026-3M 40.394 1026 3 •252-3M 9.921 252 84 •492-3M 19.370 492 164 •1035-3M 40.748 1035												327
•252-3M 9.921 252 84 •492-3M 19.370 492 164 •1035-3M 40.748 1035 3												334
•252-3M 9.921 252 84 •492-3M 19.370 492 164 •1035-3M 40.748 1035 3												342
**DEF OM 10 000 0EF 0E 504 0M 44 E7E 10EC 4		9.921										345
540 0M 00 070 540 470 41000 0M 41 011 1000 0												352 354
*200-5W												357
₹201-3W 10.270 201 07 510 5W 251107 0.00												
												360 375
												375
500 0M												397
*270°-0101 10.000 270 92							l					415
-202 dW 11.102 202 04												420
												420
												500
294.3M 11.575 294 98 •564-3M 22.205 564 188 •1512-3M 59.528 1512 5					●564-3M							504
					•570-3M				1530-3M			510
201 0111 111000 201	•300-3M								●1587-3M		1587	529
						22.677						621
•312-3M 12.283 312 104 •585-3M 23.031 585 195 1926-3M 75.827 1926 6												642
•315-3M 12.402 315 105 •591-3M 23.268 591 197 1944-3M 76.535 1944 6			1			23.268			1944-3M	76.535	1944	648
•318-3M 12.520 318 106 594-3M 23.386 594 198 •1956-3M 77.008 1956 6	•318-3M	12.520	318	106		23.386	594					652
•597-3M 23.504 597 199 •2004-3M 78.898 2004 6					●597-3M	23.504	597	199	●2004-3M	/8.898	2004	668

Stock lengths are denoted by a ullet. All other sizes, contact Gates Customer Service for availability.

3mm Pitch Stock Belt Widths									
Belt Width Code Belt Width (mm) Belt Width (in)									
06	6	0.236							
09	9	0.354							
15	15	0.591							


PowerGrip HTD Belt Lengths – continued

				5n	nm Pitch Be	It Lengths					
Belt Length	Pitch I	Length	No. of	Belt Length		Length	No. of	Belt Length	Pitch	Length	No. of
Code	(in)	(mm)	Teeth	Code	(in)	(mm)	Teeth	Code	(in)	(mm)	Teeth
180-5M	7.087	180	36	560-5M	22.047	560	112	●975-5M	38.386	975	195
•200-5M	7.874	200	40	●565-5M	22.244	565	113	●985-5M	38.780	985	197
225-5M	8.858	225	45	575-5M	22.638	575	115	●1000-5M	39.370	1000	200
●240-5M	9.449	240	48	●580-5M	22.835	580	116	1025-5M	40.354	1025	205
255-5M	10.039	255	51					1035-5M	40.748	1035	207
				●585-5M	23.031	585	117				
●260-5M	10.236	260	52	590-5M	23.228	590	118	●1050-5M	41.339	1050	210
265-5M	10.433	265	53	●600-5M	23.622	600	120	1100-5M	43.307	1100	220
•270-5M	10.630	270	54	610-5M	24.016	610	122	●1115-5M	43.898	1115	223
275-5M	10.827	275	55	•615-5M	24.213	615	123	●1125-5M	44.291	1125	225
280-5M	11.024	280	56	●635-5M	25.000	635	127	1135-5M	44.685	1135	227
								1175-5M	46.260	1175	235
●285-5M	11.220	285	57	640-5M	25.197	640	128				
295-5M	11.614	295	59	645-5M	25.394	645	129	●1195-5M	47.047	1195	239
•300-5M	11.811	300	60	●655-5M	25.787	655	131	1200-5M	47.244	1200	240
305-5M	12.008	305	61	●665-5M	26.181	665	133	1225-5M	48.228	1225	245
•310-5M	12.205	310	62	●670-5M	26.378	670	134	●1250-5M	49.213	1250	250
•320-5M		000	64	●680-5M	26.772	680		•1270-5M	50.000	1270	254
	12.598	320					136				
325-5M	12.795	325	65	●685-5M	26.969	685	137	•1295-6M	50.984	1295	259
330-5M	12.992	330	66	●695-5M	27.362	695	139	1350-5M	53.150	1350	270
335-5M	13.189	335	67	700-5M	27.559	700	140	●1375-5M	54.134	1375	275
340-5M	13.386	340	68	●710-5M	27.953	710	142	●1420-5M	55.906	1420	284
345-5M	13.583	345	69	•740-5M	29.134	740	148	●1575-5M	62.008	1575	315
•350-5M	13.780	350	70	•745-5M	29.331	745	149	●1595-5M	62.795	1595	319
360-5M	14.173	360	72	750-5M	29.528	750	150	•1635-5M	64.370	1635	327
365-5M	14.370	365	73	755-5M	29.724	755	151	●1690-5M	66.535	1690	338
370-5M	14.567	370	74	●765-5M	30.118	765	153	●1720-5M	67.717	1720	344
•375-5M	14.764	375	75	770-5M	30.315	770	154	●1790-5M	70.472	1790	358
385-5M	15.157	385	77	775-5M	30.512	775	155	●1800-5M	70.866	1800	360
●400-5M	15.748	400	80	●790-5M	31.102	790	158	1870-5M	73.622	1870	374
405-5M	15.746	405	81	●800-5M	31.496	800	160	●1895-5M	74.606	1895	379
●415-5M	16.339	415	83	825-5M	32.480	825	165	•1945-5M	76.575	1945	389
•425-5M	16.732	425	85	●830-5M	32.677	830	166	●1980-5M	77.953	1980	396
•450-5M	17.717	450	90	●835-5M	32.874	835	167	●2000-5M	78.740	2000	400
•460-5M	18.110	460	92	●850-5M	33.465	850	170	2100-5M	82.677	2100	420
•475-5M	18.701	475	95	860-5M	33.858	860	172	●2110-5M	83.071	2110	422
•480-5M	18.898	480	96					•2250-5M	88.583	2250	450
	1			●870-5M	34.252	870	174	2350-5M	92.520	2350	470
●495-5M	19.488	495	99	●890-5M	35.039	890	178				
●500-5M	19.685	500	100	900-5M	35.433	900	180	•2525-5M	99.409	2525	505
•520-5M	20.472	520	104	•925-5M	36.417	925	185	●2760-5M	108.661	2760	552
525-5M	20.669	525	105	935-5M	36.811	935	187	•3120-5M	122.835	3120	624
●535-5M	21.063	535	107					•3170-5M	124.803	3170	634
				940-5M	37.008	940	188	•3430-5M	135.039	3430	686
550-5M	21.654	550	110	●950-5M	37.402	950	190				
●555-5M	21.850	555	111	965-5M	37.992	965	193	3540-5M	139.370	3540	708
	1			1	1			•3800-5M	149.606	3800	760

Stock lengths are denoted by a •. All other sizes, contact Gates Customer Service for availability.

5mm	5mm Pitch Stock Belt Widths										
Belt Width Code	Belt Width (mm)	Belt Width (in)									
09	9	0.354									
15	15	0.591									
25	25	0.984									

Belt Pitch Selection Guide



Belt Width Selection Tables – 3mm PowerGrip HTD Belts

The following table represents the torque ratings for each belt in its base width at the predetermined number of grooves, pitch diameters and rpm. These ratings must be multiplied by the appropriate width factor and applicable belt length factor to obtain the corrected torque rating. (See Step 4 of Drive Selection Procedure on Page 12).

Belt Width (mm)	6	9	15
Width Multiplier	1.00	1.66	2 97

	Rated Torque (lb-in) For Small Sprocket - 6mm Belt Width															
Number of Grooves	10	12	14	16	18	22	26	30	34	38	44	50	56	62	72	80
Pitch mm	9.55	11.46	13.37	15.28	17.19	21.01	24.83	28.65	32.47	36.29	42.02	47.75	53.48	59.21	68.75	76.39
Diameter (in)	.376	.451	.526	.602	.677	.827	.977	1.128	1.278	1.429	1.654	1.880	2.105	2.331	2.707	3.008
10 20 40 60 100	3.3 3.3 3.3 3.3 3.3	4.0 4.0 4.0 4.0 4.0	4.8 4.8 4.8 4.8 4.8	5.6 5.6 5.6 5.6 5.6	6.5 6.5 6.5 6.5	8.3 8.3 8.3 8.3 8.3	10.2 10.2 10.2 10.2 10.2	12.3 12.3 12.3 12.3 12.3	14.5 14.5 14.5 14.5 14.5	16.8 16.8 16.8 16.8 16.8	20.5 20.5 20.5 20.5 20.5	24.6 24.6 24.6 24.6 24.6	27.7 27.7 27.7 27.7 27.7	30.7 30.7 30.7 30.7 30.7	35.7 35.7 35.7 35.7 35.7	39.6 39.6 39.6 39.6 39.6
200 300 400 500 600	3.3 3.0 2.8 2.7 2.6	4.0 3.7 3.4 3.3 3.1	4.8 4.4 4.1 3.9 3.7	5.6 5.1 4.8 4.5 4.3	6.5 5.9 5.5 5.2 5.0	8.3 7.5 7.0 6.6 6.3	10.2 9.2 8.6 8.1 7.7	12.3 11.1 10.3 9.7 9.2	14.5 13.0 12.0 11.3 10.8	16.8 15.0 13.9 13.1 12.4	20.5 18.3 16.9 15.8 15.0	24.6 21.8 20.0 18.8 17.8	27.7 24.6 22.6 21.2 20.1	30.7 27.3 25.0 23.4 22.2	35.7 31.6 29.1 27.2 25.8	39.6 35.2 32.3 30.2 28.6
700 800 870 1000 1160	2.5 2.4 2.4 2.3 2.2	3.0 2.9 2.9 2.8 2.7	3.6 3.5 3.4 3.3 3.2	4.2 4.1 4.0 3.9 3.7	4.8 4.7 4.6 4.4 4.3	6.1 5.9 5.8 5.6 5.4	7.4 7.2 7.0 6.8 6.5	8.9 8.6 8.4 8.1 7.8	10.4 10.0 9.8 9.4 9.1	11.9 11.5 11.2 10.8 10.4	14.4 13.9 13.5 13.0 12.5	17.0 16.3 15.9 15.3 14.6	19.2 18.4 18.0 17.2 16.5	21.2 20.4 19.9 19.1 18.2	24.6 23.7 23.1 22.1 21.2	27.4 26.3 25.6 24.6 23.5
1450 1600 1750 2000 2500	2.1 2.0 2.0 1.9 1.9	2.6 2.5 2.5 2.4 2.3	3.0 3.0 2.9 2.8 2.7	3.5 3.4 3.4 3.3 3.1	4.0 3.9 3.9 3.7 3.5	5.1 5.0 4.9 4.7 4.4	6.2 6.0 5.9 5.7 5.4	7.3 7.2 7.0 6.7 6.4	8.5 8.3 8.1 7.8 7.4	9.8 9.5 9.3 8.9 8.4	11.7 11.4 11.1 10.7 10.0	13.7 13.3 12.9 12.4 11.6	15.4 15.0 14.6 14.0 13.0	17.1 16.5 16.1 15.4 14.4	19.8 19.2 18.7 17.9 16.6	22.0 21.3 20.7 19.8 18.4
3000 3500 5000 8000 10000	1.8 1.7 1.6 1.4 1.3	2.2 2.1 1.9 1.7 1.6	2.6 2.5 2.3 2.0 1.9	3.0 2.9 2.6 2.3 2.2	3.4 3.3 3.0 2.6 2.5	4.2 4.1 3.7 3.3 3.0	5.1 4.9 4.5 3.9 3.6	6.1 5.8 5.2 4.5 4.1	7.0 6.7 6.0 5.1 4.6	8.0 7.6 6.8 5.7 5.1	9.4 9.0 8.0 6.6 5.7	11.0 10.4 9.2 7.3 6.3	12.3 11.7 10.2 8.0 6.6	13.5 12.8 11.1 8.5 6.8	15.6 14.8 12.7 9.1	17.3 16.3 13.8 9.3
Shaft							Rate	d Torque	(N-m)							
10	.4 .4 .4 .4 .4 .3 .3	.5 .5 .5 .5 .5 .5 .4 .4	.5 .5 .5 .5 .5 .5 .5 .5	.6 .6 .6 .6 .6 .6 .5	.7 .7 .7 .7 .7 .7 .7	.9 .9 .9 .9 .9 .8 .8	1.2 1.2 1.2 1.2 1.2 1.2 1.0 1.0	1.4 1.4 1.4 1.4 1.4 1.2 1.2 1.2	1.6 1.6 1.6 1.6 1.6 1.5 1.4	1.9 1.9 1.9 1.9 1.9 1.7 1.6 1.5	2.3 2.3 2.3 2.3 2.3 2.3 2.1 1.9	2.8 2.8 2.8 2.8 2.8 2.8 2.5 2.3 2.1	3.1 3.1 3.1 3.1 3.1 2.8 2.6 2.4	3.5 3.5 3.5 3.5 3.5 3.5 3.1 2.8 2.6	4.0 4.0 4.0 4.0 4.0 4.0 3.6 3.3 3.1	4.5 4.5 4.5 4.5 4.5 4.5 4.0 3.6 3.4
600 700 800 870 1000 1160	.3 .3 .3 .3 .3	.4 .3 .3 .3 .3	.4 .4 .4 .4 .4	.5 .5 .4 .4	.6 .5 .5 .5 .5	.7 .7 .7 .7 .6	.9 .8 .8 .8 .8	1.0 1.0 1.0 .9 .9	1.2 1.2 1.1 1.1 1.1 1.0	1.4 1.3 1.3 1.3 1.2 1.2	1.7 1.6 1.6 1.5 1.5	2.0 1.9 1.8 1.8 1.7 1.7	2.3 2.2 2.1 2.0 1.9 1.9	2.5 2.4 2.3 2.2 2.2 2.1	2.9 2.8 2.7 2.6 2.5 2.4	3.2 3.1 3.0 2.9 2.8 2.7
1450 1600 1750 2000 2500	.2 .2 .2 .2	.3 .3 .3 .3	.3 .3 .3 .3	.4 .4 .4 .4	.5 .4 .4 .4 .4	.6 .6 .5 .5	.7 .7 .7 .6	.8 .8 .8 .8	1.0 .9 .9 .9	1.1 1.1 1.0 1.0 .9	1.3 1.3 1.3 1.2 1.1	1.5 1.5 1.5 1.4 1.3	1.7 1.7 1.6 1.6 1.5	1.9 1.9 1.8 1.7 1.6	2.2 2.2 2.1 2.0 1.9	2.5 2.4 2.3 2.2 2.1
3000 3500 5000 8000 10000	.2 .2 .2 .2	.2 .2 .2 .2	.3 .3 .3 .2 .2	.3 .3 .3 .3	.4 .4 .3 .3	.5 .5 .4 .4 .3	.6 .6 .5 .4 .4	.7 .7 .6 .5	.8 .8 .7 .6	.9 .9 .8 .6	1.1 1.0 .9 .7 .6	1.2 1.2 1.0 .8 .7	1.4 1.3 1.2 .9	1.5 1.5 1.3 1.0	1.8 1.7 1.4 1.0	1.9 1.8 1.6 1.1

Length Correction Factor			0.80	0.90	1.00	1.10	1.20
	From	Length (mm)	144	198	264	408	600
For Belt Length		# of teeth	48	66	88	136	200
Length	To	Length (mm)	195	261	405	597	603 & up
		# of teeth	65	87	135	199	201 & up

Shaded area indicates sprocket and rpm that will result in reduced service life. Contact Gates Application Engineering for specific recommendations.



Belt Width Selection Tables – 5mm PowerGrip HTD Belts

The following table represents the torque ratings for each belt in its base width at the predetermined number of grooves, pitch diameters and rpm. These ratings must be multiplied by the appropriate width factor and applicable belt length factor to obtain the corrected torque rating. (See Step 4 of Drive Selection Procedure on Page 12).

Belt Width (mm)	9	15	25
Width Multiplier	1.0	1.89	3.38

					Ra	ted Torq	ue (lb-iı	1) For Si	nall Spr	ocket -	9mm Be	elt Width	1				
	ımber of ooves	14	16	18	20	22	24	26	28	32	36	40	44	48	56	64	72
Pitcl		22.28	25.46	28.65	31.83	35.01	38.20	41.38	44.56	50.93	57.30	63.66	70.03	76.39	89.13	101.86	114.59
Dian	neter (in)	.877	1.003	1.128	1.253	1.379	1.504	1.629	1.754	2.005	2.256	2.506	2.757	3.008	3.509	4.010	4.511
	10 20	19.0 19.0	22.3 22.3	25.7 25.7	29.3 29.3	33.0 33.0	36.9 36.9	40.9 40.9	45.1 45.1	53.8 53.8	63.1 63.1	73.0 73.0	83.5 83.5	94.5 94.5	113.3 113.3	129.5 129.5	145.7 145.7
	40 60	19.0 19.0	22.3 22.3	25.7 25.7	29.3 29.3	33.0 33.0	36.9 36.9	40.9 40.9	45.1 45.1	53.8 53.8	63.1 63.1	73.0 73.0	83.5 83.5	94.5 94.5	113.3 113.3	129.5 129.5	145.7 145.7
	100 200	19.0 19.0	22.3 22.3	25.7 25.7	29.3 29.3	33.0 33.0	36.9 36.9	40.9 40.9	45.1 45.1	53.8 53.8	63.1 63.1	73.0 73.0	83.5 83.5	94.5 94.5	113.3 113.3	129.5 129.5	145.7 145.7
	300 400	17.3 16.2	20.2 18.9	23.7	26.5 24.7	29.9 27.8	33.3 31.0	36.9 34.3	40.6 37.7	48.3 44.8	56.5	65.2 60.2	74.4 68.5	84.0 77.2	100.4 92.2	114.8 105.3	129.1 118.5
	500	15.3	17.9	20.6	23.4	26.3	29.3	32.4	35.6	42.2	52.3 49.2	56.5	64.3	72.3	86.2	98.5	110.8
	600 700	14.7 14.2	17.2 16.5	19.7 19.0	22.4 21.6	25.1 24.2	28.0 26.9	30.9 29.7	33.9 32.6	40.2 38.6	46.8 44.9	53.7 51.5	61.0 58.3	68.5 65.5	81.7 78.0	93.3 89.1	104.9 100.1
	800 870	13.7 13.5	16.0 15.7	18.4 18.0	20.9 20.4	23.4 22.9	26.0 25.5	28.7 28.1	31.5 30.8	37.2 36.4	43.3 42.3	49.6 48.4	56.1 54.8	63.0 61.4	74.9 73.0	85.5 83.4	96.2 93.7
	1000 1160	13.0 12.6	15.2 14.7	17.4 16.8	19.8 19.1	22.1 21.3	24.6 23.7	27.1 26.1	29.7 28.6	35.1 33.7	40.7 39.1	46.5 44.6	52.6 50.4	58.9 56.4	70.0 66.9	79.9 76.3	89.8 85.7
	1400	12.0	14.0	16.1	18.2	20.4	22.6	24.9	27.2	32.0	37.1	42.3	47.7	53.2	63.1	71.9	80.7
	1450 1600	11.9 11.7	13.9 13.6	15.9 15.6	18.0 17.6	20.2 19.7	22.4	24.6 24.0	27.0 26.3	31.7 30.9	36.7 35.7	41.9 40.7	47.2 45.8	52.7 51.1	62.4 60.4	71.1 68.9	79.8 77.2
	1750 1800	11.4 11.3	13.3 13.2	15.2 15.1	17.2 17.1	19.2 19.1	21.3 21.2	23.5 23.3	25.6 25.5	30.1 29.9	34.8 34.5	39.6 39.3	44.6 44.2	49.7 49.2	58.7 58.2	66.8 66.2	74.9 74.1
	2000 2500	11.1 10.5	12.9 12.2	14.7 13.9	16.6 15.7	18.6 17.6	20.6 19.4	22.7 21.3	24.7 23.3	29.0 27.3	33.5 31.4	38.1 35.6	42.8 39.9	47.6 44.2	56.2 51.9	63.9 58.8	71.4 65.5
	3000 3600	10.0 9.6	11.7	13.3	15.0 14.3	16.7 15.9	18.5 17.6	20.3	22.1 21.0	25.8 24.4	29.7 27.9	33.5 31.5	37.5 35.1	41.5 38.6	48.5 44.8	54.6 50.1	60.5 55.0
haft	5000	8.8	10.2	11.6	13.1	14.5	15.9	17.4	18.9	21.8	24.7	27.6	30.4	33.1	37.4	40.6	43.0
rpm of Faster Shaft	8000 10000	7.8 7.2	8.9 8.2	10.1 9.2	11.2 10.1	12.3 11.0	13.4 11.9	14.4 12.7	15.4 13.4	17.3 14.5	19.0 15.3	20.4	21.5	22.3			
of Fa									d Torque								
rpm	10 20	2.1 2.1	2.5 2.5	2.9 2.9	3.3 3.3	3.7 3.7	4.2 4.2	4.6 4.6	5.1 5.1	6.1 6.1	7.1 7.1	8.3 8.3	9.4 9.4	10.7 10.7	12.8 12.8	14.6 14.6	16.5 16.5
	40 60	2.1 2.1	2.5 2.5	2.9 2.9	3.3 3.3	3.7 3.7	4.2 4.2	4.6 4.6	5.1 5.1	6.1 6.1	7.1 7.1	8.3 8.3	9.4 9.4	10.7 10.7	12.8 12.8	14.6 14.6	16.5 16.5
	100 200	2.1 2.1	2.5 2.5	2.9 2.9	3.3 3.3	3.7 3.7	4.2 4.2	4.6 4.6	5.1 5.1	6.1 6.1	7.1 7.1	8.3 8.3	9.4 9.4	10.7 10.7	12.8 12.8	14.6 14.6	16.5 16.5
	300 400	2.0 1.8	2.3 2.1	2.6 2.5	3.0 2.8	3.4 3.1	3.8 3.5	4.2 3.9	4.6 4.3	5.5 5.1	6.4 5.9	7.4 6.8	8.4 7.7	9.5 8.7	11.3 10.4	13.0 11.9	14.6 13.4
	500 600	1.7 1.7	2.0 1.9	2.3 2.2	2.6 2.5	3.0 2.8	3.3 3.2	3.7 3.5	4.0 3.8	4.8 4.5	5.6 5.3	6.4 6.1	7.3 6.9	8.2 7.7	9.7 9.2	11.1 10.5	12.5 11.9
	700 800	1.6 1.6	1.9 1.8	2.1 2.1	2.4 2.4	2.7 2.6	3.0 2.9	3.4 3.2	3.7 3.6	4.4 4.2	5.1 4.9	5.8 5.6	6.6 6.3	7.4 7.1	8.8 8.5	10.1 9.7	11.3 10.9
	870 1000	1.5 1.5	1.8 1.7	2.0 2.0	2.3	2.6 2.5	2.9 2.8	3.2 3.1	3.5 3.4	4.1 4.0	4.8 4.6	5.5 5.3	6.2 5.9	6.9 6.7	8.2 7.9	9.4 9.0	10.6 10.1
	1160 1400	1.4 1.4	1.7 1.6	1.9 1.8	2.2	2.4 2.3	2.7 2.6	3.0 2.8	3.2 3.1	3.8 3.6	4.4 4.2	5.0 4.8	5.7 5.4	6.4 6.0	7.6 7.1	8.6 8.1	9.7 9.1
	1450 1600	1.3	1.6 1.5	1.8	2.0	2.3 2.2	2.5 2.5	2.8 2.7	3.0	3.6 3.5	4.1 4.0	4.7 4.6	5.3 5.2	6.0 5.8	7.0 6.8	8.0 7.8	9.0 8.7
	1750 1800	1.3 1.3	1.5 1.5	1.7	1.9 1.9	2.2	2.4 2.4	2.7 2.6	2.9 2.9	3.4 3.4	3.9	4.5 4.4	5.0 5.0	5.6 5.6	6.6 6.6	7.6 7.5	8.5 8.4
	2000 2500	1.3 1.2	1.5 1.4	1.7 1.6	1.9 1.8	2.1 2.0	2.3	2.6 2.4	2.8 2.6	3.3	3.8 3.5	4.3 4.0	4.8 4.5	5.4	6.3 5.9	7.2 6.6	8.1 7.4
	3000 3600	1.2 1.1 1.1	1.3 1.3	1.5 1.4	1.7 1.6	2.0 1.9 1.8	2.2 2.1 2.0	2.4 2.3 2.2	2.5 2.4	2.9 2.8	3.4 3.2	3.8 3.6	4.5 4.2 4.0	5.0 4.7 4.4	5.5 5.1	6.2 5.7	6.8 6.2
	5000	1.0	1.2	1.3	1.5	1.6	1.8	2.0	2.1	2.5	2.8	3.1	3.4	3.7	4.2	4.6	4.9
	8000 10000	.9 .8	1.0 .9	1.1 1.0	1.3 1.1	1.4 1.2	1.5 1.3	1.6 1.4	1.7 1.5	2.0 1.6	2.1 1.7	2.3	2.4	2.5			

Shaded area indicates sprocket and rpm that will result in reduced service life. Contact Gates Application Engineering for specific recommendations.



0.80

350

70

435

87

Length Correction Factor

For Belt

Length (mm)

of teeth

of teeth

1.20

1100 & up

220 & up

1095

219

1.00

555

111

840

1.10

845

169

1090

218

0.90

440

88

550

PowerGrip® HTD® Belt Drives – Twin Power

Twin Power Belt Drive Systems

Twin Power Belts are similar in construction to standard synchronous belts, including nylon-faced teeth on both sides. This construction uses essentially the same design parameters as standard synchronous belts. Gates 3mm and 5mm pitch Twin Power PowerGrip® HTD® belts have helically-wound fiberglass tension members embedded in a Neoprene body with the belt teeth faced with a tough wear-resistant nylon fabric. A unique feature of this construction is that Gates Twin Power belts can transmit their full rated load on either the front or back side.

The three principal dimensions, in millimeters, shown below, are used to specify a Twin Power PowerGrip® HTD® belt.:

TP	450	3M	09
Twin	Pitch	Pitch	Width
Power	Length		

Belt pitch is the distance in millimeters between two adjacent tooth centers as measured on the pitch line of the belt. Belt pitch length is the total length (circumference) in millimeters as measured along the pitch line. The theoretical pitch line of a PowerGrip® HTD® belt lies within the tensile member.


Three principal dimensions of a sprocket — number of grooves, pitch and belt width in millimeters — are used to specify a PowerGrip® HTD® sprocket as shown below:

P22	3M	09
Number of	Pitch	Belt
Grooves		Width


NOTE: For drive design procedure, see Page 24.

Belt tooth to sprocket groove clearance is greater in PowerGrip® HTD® drives than in PowerGrip Timing drives. If the higher torque capacity of PowerGrip® HTD® is required together with minimal backlash characteristics, use PowerGrip® GT2®.

3mm Pitch - Reference Dimensions



5mm Pitch - Reference Dimensions



PowerGrip® HTD® Belt Drives – Twin Power

PowerGrip HTD Belt Lengths

				3m	ım Pitch Be	It Lengths					
Belt Length Code		Length	No. of	Belt Length		Pitch Length		Belt Length		Length	No. of Teeth
-	(mm)	(in)	Teeth	Code	(mm)	(in)	Teeth	Code	(mm)	(in)	
TP381-3M	381	15.00	127	TP525-3M	525	20.67	175	TP735-3M	735	28.94	245
TP384-3M	384	15.12	128	TP528-3M	528	20.79	176	TP738-3M	738	29.06	246
TP387-3M	387	15.24	129	TP531-3M	531	20.91	177	TP753-3M	753	29.65	251
TP390-3M	390	15.35	130	TP537-3M	537	21.14	179	TP795-3M	795	31.30	265
TP396-3M	396	15.59	132	TP558-3M	558	21.97	186	TP822-3M	822	32.36	274
TP399-3M	399	15.71	133	TP564-3M	564	22.20	188	TP837-3M	837	32.95	279
TP405-3M	405	15.94	135	TP570-3M	570	22.44	190	TP843-3M	843	33.19	281
TP411-3M	411	16.18	137	TP576-3M	576	22.68	192	TP873-3M	873	34.37	291
TP417-3M	417	16.42	139	TP585-3M	585	23.03	195	TP882-3M	882	34.72	294
TP420-3M	420	16.54	140	TP591-3M	591	23.27	197	TP891-3M	891	35.08	297
TP426-3M	426	16.77	142	TP597-3M	597	23.50	199	TP900-3M	900	35.43	300
TP432-3M	432	17.01	144	TP600-3M	600	23.62	200	TP915-3M	915	36.02	305
TP435-3M	435	17.13	145	TP606-3M	606	23.86	202	TP945-3M	945	37.20	315
TP438-3M	438	17.24	146	TP609-3M	609	23.98	203	TP951-3M	951	37.44	317
TP444-3M	444	17.48	148	TP612-3M	612	24.09	204	TP981-3M	981	38.62	327
TP447-3M	447	17.60	149	TP627-3M	627	24.69	209	TP1002-3M	1002	39.45	334
TP459-3M	459	18.07	153	TP633-3M	633	24.92	211	TP1026-3M	1026	40.39	342
TP468-3M	468	18.43	156	TP639-3M	639	25.16	213	TP1035-3M	1035	40.75	345
TP471-3M	471	18.54	157	TP645-3M	645	25.39	215	TP1062-3M	1062	41.81	354
TP474-3M	474	18.66	158	TP648-3M	648	25.51	216	TP1125-3M	1125	44.29	375
TP480-3M	480	18.90	160	TP654-3M	654	25.75	218	TP1155-3M	1155	45.47	385
TP486-3M	486	19.13	162	TP657-3M	657	25.87	219	TP1191-3M	1191	46.89	397
TP489-3M	489	19.25	163	TP663-3M	663	26.10	221	TP1263-3M	1263	49.72	421
TP492-3M	492	19.37	164	TP669-3M	669	26.34	223	TP1500-3M	1500	59.06	500
TP501-3M	501	19.72	167	TP684-3M	684	26.93	228	TP1512-3M	1512	59.53	504
TP510-3M	510	20.08	170	TP687-3M	687	27.05	229	TP1587-3M	1587	62.48	529
TP513-3M	513	20.20	171	TP696-3M	696	27.40	232	TP1956-3M	1956	77.01	652
TP519-3M	519	20.43	173	TP711-3M	711	27.99	237	TP2004-3M	2004	78.90	668

All sizes are made-to-order. Contact Gates Customer Service for availability.

3mm Pitch Stock Belt Widths										
Belt Width Code	Belt Width (mm)	Belt Width (in)								
	6	0.236								
09	9	0.354								
15	15	0.591								


5mm	5mm Pitch Stock Belt Widths										
Belt Width Code	Belt Width (mm)	Belt Width (in)									
09	9	0.354									
15	15	0.591									
25	25	0.984									

	5mm Pitch Belt Lengths												
Belt Length Code	Pitch Length (mm) (in)		No. of Teeth	of Length		Pitch Length (mm) (in)		Belt Length Code	Pitch (mm)	Length (in)	No. of Teeth		
TP400-5M	400	15.75	80	TP695-5M	695	27.36	139	TP1295-5M	1295	50.98	259		
TP415-5M	415	16.34	83	TP710-5M	710	27.95	142	TP1375-5M	1375	54.13	275		
TP425-5M	425	16.73	85	TP740-5M	740	29.13	148	TP1420-5M	1420	55.91	284		
TP450-5M	450	17.72	90	TP745-5M	745	29.33	149	TP1575-5M	1575	62.01	315		
TP460-5M	460	18.11	92	TP765-5M	765	30.12	153	TP1595-5M	1595	62.80	319		
TP475-5M	475	18.70	95	TP790-5M	790	31.10	158	TP1635-5M	1635	64.37	327		
TP480-5M	480	18.90	96	TP800-5M	800	31.50	160	TP1690-5M	1690	66.54	338		
TP495-5M	495	19.49	99	TP830-5M	830	32.68	166	TP1720-5M	1720	67.72	344		
TP500-5M	500	19.69	100	TP835-5M	835	32.87	167	TP1790-5M	1790	70.47	358		
TP520-5M	520	20.47	104	TP850-5M	850	33.46	170	TP1800-5M	1800	70.87	360		
TP535-5M	535	21.06	107	TP870-5M	870	34.25	174	TP1895-5M	1895	74.61	379		
TP555-5M	555	21.85	111	TP890-5M	890	35.04	178	TP1945-5M	1945	76.57	389		
TP565-5M	565	22.24	113	TP925-5M	925	36.42	185	TP1980-5M	1980	77.95	396		
TP580-5M	580	22.83	116	TP950-5M	950	37.40	190	TP2000-5M	2000	78.74	400		
TP585-5M	585	23.03	117	TP975-5M	975	38.39	195	TP2110-5M	2110	83.07	422		
TP600-5M	600	23.62	120	TP985-5M	985	38.78	197	TP2250-5M	2250	88.58	450		
TP615-5M	615	24.21	123	TP1000-5M	1000	39.37	200	TP2525-5M	2525	99.41	505		
TP635-5M	635	25.00	127	TP1050-5M	1050	41.34	210	TP2760-5M	2760	108.66	552		
TP655-5M	655	25.79	131	TP1115-5M	1115	43.90	223	TP3120-5M	3120	122.83	624		
TP665-5M	665	26.18	133	TP1125-5M	1125	44.29	225	TP3170-5M	3170	124.80	634		
TP670-5M TP680-5M TP685-5M	670 680 685	26.38 26.77 26.97	134 136 137	TP1195-5M TP1250-5M TP1270-5M	1195 1250 1270	47.05 49.21 50.00	239 250 254	TP3430-5M TP3800-5M	3430 3800	135.04 149.61	686 760		

All sizes are made-to-order. Contact Gates Customer Service for availability.



Sprocket Specification Tables – 3mm Pitch HTD Sprockets



	6 mm (.236 in) Wide Belts (3M-06)											
	No.				Flange	Nominal D	imensions (in)		Plain Bo	ro* (in)	
Code Symbol	of Grooves	Туре	Pitch Diameter	Outside Diameter	0.D. (+0.016)	W (+0.005)	L (+0.010)	H (+0.016)	E (hub width)	Min.	Max.	Set Screws**
P10-3M-06-AL P12-3M-06-AL P14-3M-06-AL P15-3M-06-AL P16-3M-06-AL	10 12 14 15 16	6FC 6FC 6FC 6FC 6FC	.376 .451 .526 .564 .602	.346 .421 .496 .534	.505 .580 .635 .685	.282 .282 .282 .282 .282 .282	.562 .562 .572 .572 .572	.505 .580 .635 .685	.235 .235 .238 .238 .238	.125 .187 .187 .187 .187	.125 .187 .187 .187 .187	4-40 4-40 6-40 6-40 6-40
P17-3M-06-AL P18-3M-06-AL P19-3M-06-AL P20-3M-06-AL P22-3M-06-AL	17 18 19 20 22	6FC 6F 6F 6F 6F	.639 .677 .714 .752 .827	.609 .647 .684 .722 .797	.740 .790 .827 .895 .945	.282 .282 .282 .282 .282	.572 .691 .691 .691	.740 .442 .479 .500	.238 .305 .305 .305 .305	.187 .250 .250 .250 .250	.187 .250 .250 .250 .250	6-40 8-32 8-32 8-32 8-32
P24-3M-06-AL P26-3M-06-AL P28-3M-06-AL P30-3M-06-AL P32-3M-06-AL	24 26 28 30 32	6F 6F 6F 6F 6F	.902 .977 1.053 1.128 1.203	.872 .947 1.023 1.098 1.173	1.025 1.105 1.173 1.250 1.323	.282 .282 .282 .282 .282	.691 .691 .691 .691	.625 .625 .701 .776 .851	.305 .305 .305 .305 .305	.250 .250 .250 .250 .250	.312 .312 .375 .437 .500	8-32 8-32 8-32 8-32 8-32
P34-3M-06-AL P36-3M-06-AL P38-3M-06-AL P40-3M-06-AL P44-3M-06-AL	34 36 38 40 44	6F 6F 6F 6F 6F	1.278 1.353 1.429 1.504 1.654	1.248 1.324 1.399 1.474 1.624	1.398 1.473 1.549 1.625 1.775	.282 .282 .282 .282 .282	.713 .713 .713 .713 .713	.921 1.000 1.075 1.150 1.300	.306 .306 .306 .306 .306	.250 .250 .250 .250 .250	.562 .625 .750 .812 .937	8-32 8-32 8-32 8-32 8-32
P50-3M-06-AL P56-3M-06-AL P62-3M-06-AL P72-3M-06-AL	50 56 62 72	6 6 6 6	1.880 .105 2.331 2.707	1.850 2.075 2.301 2.677	- - - -	.407 .407 .407 .407	.734 .734 .734 .734	1.250 1.250 1.250 1.250	.327 .327 .327 .327	.312 .312 .312 .312	.937 .937 .937 .937	8-32 8-32 8-32 8-32
		ı		9 mm (.354 in) Wi	ide Belts	(3M-09)	ı				
P10-3M-09-AL P12-3M-09-AL P14-3M-09-AL P15-3M-09-AL P16-3M-09-AL	10 12 14 15 16	6FC 6FC 6FC 6FC	.376 .451 .526 .564 .602	.346 .421 .496 .534 .572	.505 .580 .635 .685 .710	.401 .401 .401 .401 .401	.681 .681 .691 .691	.505 .580 .635 .685 .710	.235 .235 .238 .238 .238	.125 .187 .187 .187 .187	.125 .187 .187 .187 .187	4-40 4-40 6-40 6-40 6-40
P17-3M-09-AL P18-3M-09-AL P19-3M-09-AL P20-3M-09-AL P22-3M-09-AL	17 18 19 20 22	6FC 6F 6F 6F 6F	.639 .677 .714 .752 .827	.609 .647 .684 .722 .797	.740 .790 .827 .895 .945	.401 .401 .401 .401 .401	.691 .821 .821 .821 .821	.740 .442 .479 .500 .562	.238 .306 .306 .306 .306	.187 .250 .250 .250 .250	.187 .250 .250 .250 .250	6-40 8-32 8-32 8-32 8-32
P24-3M-09-AL P26-3M-09-AL P28-3M-09-AL P30-3M-09-AL P32-3M-09-AL	24 26 28 30 32	6F 6F 6F 6F 6F	.902 .977 1.053 1.128 1.203	.872 .947 1.023 1.098 1.173	1.025 1.105 1.173 1.250 1.323	.401 .401 .401 .401 .401	.821 .821 .821 .821 .821	.625 .625 .701 .776 .851	.306 .306 .306 .306	.250 .250 .250 .250 .250	.312 .312 .375 .437 .500	8-32 8-32 8-32 8-32 8-32
P34-3M-09-AL P36-3M-09-AL P38-3M-09-AL P40-3M-09-AL P44-3M-09-AL	34 36 38 40 44	6F 6F 6F 6F 6F	1.278 1.353 1.429 1.504 1.654	1.248 1.324 1.399 1.474 1.624	1.398 1.473 1.549 1.625 1.775	.401 .401 .401 .401 .401	.833 .833 .833 .833 .833	.921 1.000 1.075 1.150 1.300	.306 .306 .306 .306	.250 .250 .250 .250 .250	.562 .625 .750 .812 .937	8-32 8-32 8-32 8-32 8-32
P50-3M-09-AL P56-3M-09-AL P62-3M-09-AL P72-3M-09-AL	50 56 62 72	6 6 6	1.880 2.105 2.331 2.707	1.850 2.075 2.301 2.677	- - - -	.500 .500 .500 .500	.875 .875 .875 .875	1.250 1.250 1.250 1.250	.375 .375 .375 .375	.312 .312 .312 .312	.937 .937 .937 .937	8-32 8-32 8-32 8-32

^{*}Plain bore style stocked in smallest bore.


*** 2 ea. set screws at 90 degrees.

NOTE: See Synchronous Belt Drives – Sprocket Specifications section, Page 70, for a complete table of stock and non-stock sprocket diameters.



For non-standard designs contact Gates Made-To-Order Metals Team at (800)709-6001

Sprocket Specification Tables – 5mm Pitch PowerGrip HTD Sprockets



				9 mm./	354 in) W	ide Relts	(5M_0Q)					
				a mini (.	JJ4 III) W		mensions (i	n)				
	No.			Flange						Plain Bore* (in)		
Code Symbol	of Grooves	Туре	Pitch Diameter	Outside Diameter	0.D. (+0.016)	W (+0.005)	L (+0.010)	H (+0.016)	E (hub width)	Min.	Max.	Set Screws**
P14-5M-09-AL P15-5M-09-AL P16-5M-09-AL P17-5M-09-AL P18-5M-09-AL	14 15 16 17 18	6F 6F 6F 6F 6F	.877 .940 1.003 1.065 1.128	.832 .895 .958 1.020 1.083	1.000 1.063 1.094 1.187 1.250	.416 .416 .416 .416 .416	.790 .790 .790 .790 .790	.500 .562 .625 .625 .687	.250 .250 .250 .250 .250	.250 .250 .250 .250 .250	.250 .250 .250 .312 .375	8-32 8-32 8-32 8-32 8-32
P19-5M-09-AL P20-5M-09-AL P22-5M-09-AL P24-5M-09-AL P26-5M-09-AL	19 20 22 24 26	6F 6F 6F 6F 6F	1.191 1.253 1.379 1.504 1.629	1.146 1.208 1.334 1.459 1.584	1.312 1.375 1.500 1.625 1.750	.416 .416 .416 .416 .416	.790 .790 .790 .852 .852	.750 .812 .937 1.000 1.062	.250 .250 .250 .312 .312	.250 .250 .250 .250 .250	.437 .500 .625 .687 .750	8-32 8-32 8-32 8-32 8-32
P28-5M-09-AL P30-5M-09-AL P32-5M-09-AL P34-5M-09-AL P36-5M-09-AL	28 30 32 34 36	6F 6F 6F 6F	1.754 1.880 2.005 2.130 2.256	1.709 1.835 1.960 2.085 2.211	1.875 2.000 2.125 2.250	.416 .416 .416 .416 .546	.852 .852 .852 .852 .937	1.187 1.187 1.250 1.375 1.500	.312 .312 .312 .312 .391	.250 .250 .250 .250 .312	.875 .875 .937 1.062 1.062	8-32 8-32 8-32 8-32 8-32
P38-5M-09-AL P40-5M-09-AL P44-5M-09-AL P50-5M-09-AL P56-5M-09-AL	38 40 44 50 56	6 6 6W 6W 6W	2.381 2.506 2.757 3.133 3.509	2.336 2.461 2.712 3.088 3.464	- - - -	.546 .546 .546 .546 .546	.937 .937 .937 .937 .937	1.500 1.500 1.500 1.500 1.500	.391 .391 .391 .391 .391	.312 .312 .312 .375 .375	1.187 1.187 1.187 1.187 1.187	8-32 8-32 8-32 10-32 10-32
P62-5M-09-AL P72-5M-09-AL	62 72	6W 6W	3.885 4.511	3.840 4.466	-	.546 .546	.937 .937	1.500 1.500	.391 .391	.375 .375	1.187 1.187	10-32 10-32
				15 mm	(.591 in) W	ide Belts	(5M-15)					
P14-5M-15-AL P15-5M-15-AL P16-5M-15-AL P17-5M-15-AL P18-5M-15-AL	14 15 16 17 18	6F 6F 6F 6F 6F	.877 .940 1.003 1.065 1.128	.832 .895 .958 1.020 1.083	1.000 1.063 1.094 1.188 1.250	.656 .656 .656 .656	1.025 1.025 1.025 1.025 1.025	.500 .562 .625 .625 .687	.250 .250 .250 .250 .250	.250 .250 .250 .250 .250	.250 .250 .250 .312 .375	8-32 8-32 8-32 8-32 8-32
P19-5M-15-AL P20-5M-15-AL P22-5M-15-AL P24-5M-15-AL P26-5M-15-AL	19 20 22 24 26	6F 6F 6F 6F 6F	1.191 1.253 1.379 1.504 1.629	1.146 1.208 1.334 1.459 1.584	1.312 1.375 1.500 1.625 1.750	.656 .656 .656 .656	1.025 1.025 1.025 1.087 1.087	.750 .812 .937 1.000 1.062	.250 .250 .250 .312 .312	.250 .250 .250 .250 .250	.437 .500 .625 .687 .750	8-32 8-32 8-32 8-32 8-32
P28-5M-15-AL P30-5M-15-AL P32-5M-15-AL P34-5M-15-AL P36-5M-15-AL	28 30 32 34 36	6F 6F 6F 6	1.754 1.880 2.005 2.130 2.256	1.709 1.835 1.960 2.085 2.211	1.875 2.000 2.125 2.250	.656 .656 .656 .656 .781	1.087 1.087 1.087 1.087 1.187	1.187 1.187 1.250 1.375 1.500	.312 .312 .312 .312 .406	.250 .250 .250 .250 .312	.875 .875 .937 1.062 1.062	8-32 8-32 8-32 8-32 8-32
P38-5M-15-AL P40-5M-15-AL P44-5M-15-AL P50-5M-15-AL P56-5M-15-AL	38 40 44 50 56	6 6 6W 6W 6W	2.381 2.506 2.757 3.133 3.509	2.336 2.461 2.712 3.088 3.464	- - - -	.781 .781 .781 .781 .781	1.187 1.187 1.187 1.187 1.187	1.500 1.500 1.500 1.500 1.500	.406 .406 .406 .406 .406	.312 .312 .312 .375 .375	1.187 1.187 1.187 1.187 1.187	8-32 8-32 8-32 8-32 8-32
P62-5M-15-AL P72-5M-15-AL	62 72	6W 6W	3.885 4.511	3.840 4.466	-	.781 .781	1.187 1.187	1.500 1.500	.406 .406	.375 .375	1.187 1.187	10-32 10-32

^{*}Plain bore style stocked in smallest bore.

** 2 ea. set screws at 90 degrees.

Material:

Clear Anodized Aluminum

NOTE: See Synchronous Belt Drives – Sprocket Specifications section, Page 71, for a complete table of stock and non-stock sprocket diameters.



For non-standard designs contact Gates Made-To-Order Metals Team at (800)709-6001

Single Sided Belt Drive Systems

PowerGrip® Timing Belt drives operate on the tooth-grip principle, with the molded teeth of the belt designed to make positive engagement with the matching grooves on the pulleys. Gates PowerGrip® Timing belts have helically-wound fiberglass tension members embedded in a Neoprene body with the belt teeth faced with a tough wear-resistant nylon fabric.

The three principal dimensions in inches, shown below, are used to specify a timing belt.


330	XL	025
33.0" Pitch Length	.200" Pitch	.25" Wide

Belt pitch is the distance in inches between two adjacent tooth centers as measured on the pitch line of the belt. Belt pitch length is the total length (circumference) in inches as measured along the pitch line. The theoretical pitch line of a Timing belt lies within the tensile member.


The three principal dimensions used to specify a pulley—number of grooves, pitch and belt width in inches—are shown below.

20	XL	025
Number of grooves	Pitch	Belt Width (0.25")


NOTE: For drive design procedure, see page 12. When ordering MXL Timing belts, please specify pitch and number of teeth.



MXL Pitch – Reference Dimensions



XL Pitch – Reference Dimensions



PowerGrip Belt Lengths and Widths

						MXL (.08	0 in) Belt	Lengths	S					
Desc.	Pitch Length (in)	No. of Teeth	Desc.	Pitch Length (in)	No. of Teeth	Desc.	Pitch Length (in)	No. of Teeth	Desc.	Pitch Length (in)	No. of Teeth	Desc.	Pitch Length (in)	No. of Teeth
29MXL	2.880	36	• 62MXL	6.160	77	94MXL	9.440	118	• 160MXL	16.000	200	286MXL	28.640	358
 32MXL 	3.200	40	• 63MXL	6.320	79	 96MXL 	9.600	120	• 166MXL	16.640	208	288MXL	28.800	360
 34MXL 	3.360	42	• 64MXL	6.400	80	98MXL	9.760	122	• 168MXL	16.800	210	• 297MXL	29.680	371
 36MXL 	3.600	45	65MXL	6.480	81	• 98MXL	9.840	123	• 170MXL	16.960	212	• 298MXL	29.760	372
 38MXL 	3.760	47	66MXL	6.560	82	• 100MXL	10.000	125	• 177MXL	17.680	221	312MXL	31.200	390
 40MXL 	4.000	50	• 66MXL	6.640	83	• 101MXL	10.080	126	• 178MXL	17.760	222	• 320MXL	32.000	400
42MXL	4.240	53	67MXL	6.720	84	102MXL	10.160	127	• 180MXL	18.000	225	326MXL	32.640	408
 43MXL 	4.320	54	• 68MXL	6.800	85	103MXL	10.320	129	183MXL	18.320	229	• 330MXL	32.960	412
 44MXL 	4.400	55	• 69MXL	6.960	87	• 104MXL	10.400	130	• 184MXL	18.400	230	336MXL	33.600	420
 45MXL 	4.480	56	• 70MXL	7.040	88	• 106MXL	10.560	132	186MXL	18.560	232	• 339MXL	33.920	424
46MXL	4.560	57	• 72MXL	7.200	90	107MXL	10.720	134	188MXL	18.800	235	340MXL	34.000	425
46MXL	4.640	58	• 74MXL	7.360	92	111MXL	11.120	139	• 196MXL	19.600	245	345MXL	34.480	431
 47MXL 	4.720	59	74MXL	7.440	93	• 112MXL	11.200	140	• 198MXL	19.840	248	• 347MXL	34.720	434
 48MXL 	4.800	60	• 75MXL	7.520	94	• 115MXL	11.520	144	199MXL	19.920	249	• 348MXL	34.800	435
49MXL	4.880	61	• 76MXL	7.600	95	116MXL	11.600	145	• 200MXL	20.000	250	352MXL	35.200	440
50MXL	5.040	63	78MXL	7.760	97	• 120MXL	12.000	150	201MXL	20.080	251	362MXL	36.240	453
• 51 MXL	5.120	64	• 80MXL	8.000	100	• 122MXL	12.240	153	205MXL	20.480	256	370MXL	37.040	463
 52MXL 	5.200	65	81MXL	8.080	101	• 124MXL	12.400	155	• 208MXL	20.800	260	380MXL	38.000	475
 53MXL 	5.360	67	• 81MXL	8.160	102	126MXL	12.640	158	• 212MXL	21.200	265	• 390MXL	38.960	487
54MXL	5.440	68	• 82MXL	8.240	103	128MXL	12.800	160	214MXL	21.360	267	390MXL	39.040	488
55MXL	5.520	69	84MXL	8.400	105	• 132MXL	13.200	165	• 224MXL	22.400	280	• 398MXL	39.840	498
 56MXL 	5.600	70	• 84MXL	8.480	106	• 133MXL	13.280	166	• 236MXL	23.600	295	400MXL	40.000	500
 57MXL 	5.680	71	• 85MXL	8.560	107	• 136MXL	13.600	170	238MXL	23.840	298	404MXL	40.400	505
 58MXL 	5.760	72	• 86MXL	8.640	108	• 140MXL	14.000	175	• 240MXL	24.000	300	426MXL	42.560	532
58MXL	5.840	73	• 87MXL	8.720	109	144MXL	14.400	180	• 252MXL	25.200	315	437MXL	43.680	546
 59MXL 	5.920	74	• 88MXL	8.800	110	• 147MXL	14.720	184	254MXL	25.440	318	474MXL	47.360	592
60MXL	6.000	75	• 90MXL	8.960	112	• 152MXL	15.200	190	274MXL	27.440	343	• 480MXL	48.000	600
• 61 MXL	6.080	76	• 91MXL	9.120	114	• 156MXL	15.600	195	• 278MXL	27.760	347	• 490MXL	48.960	612
												• 518MXL	51.840	648

Stock Lengths are denoted by a •. All other sizes, contact Gates Customer Service for availability.

MXL Stock	Belt Widths
Belt Width Code	Width (in)
012	1/8 (0.125)
019	3/16 (0.187)
025	1/4 (0.250)

Neoprene 0.0816" belts are designed with standard 40° MXL type belt teeth on a 0.0816" pitch, and are not compatible with MXL type pulleys.

	Neoprene (.0816 in) Belt Lengths												
Pitch Length (in)	No. of Teeth	Pitch Length (in)	No. of Teeth	Pitch Length (in)	No. of Teeth	Pitch Length (in)	No. of Teeth	Pitch Length (in)	No. of Teeth	Pitch Length (in)	No. of Teeth		
3.101 4.162 4.570 4.651 4.896 4.978 5.222 5.304	38 51 56 57 60 61 64 65	5.386 5.794 5.875 6.120 6.283 6.528 6.854 7.262	66 71 72 75 77 80 84 89	7.752 7.834 7.997 8.160 8.323 8.894 8.976 9.629	95 96 98 100 102 109 110 118	10.037 10.771 11.342 11.669 11.750 11.832 12.403 12.485	123 132 139 143 144 145 152 153	13.219 15.749 17.462 18.278 18.605 19.176 19.992 20.971	162 193 214 224 228 235 245 257	21.542 22.440 27.744	264 275 340		

NOTE: Sizes above are nonstock sizes. Minimum quantities required. Contact Gates Customer Service for availability.


PowerGrip Belt Lengths and Widths – continued

							XL (.2	00 in)	Belt Le r	gths							
Belt Length Code	Pitch Length (in)	No. of Teeth	Belt Length Code	Pitch Length (in)	No. of Teeth	Belt Length Code	Pitch Length (in)	No. of Teeth	Belt Length Code	Pitch Length (in)	No. of Teeth	Belt Length Code	Pitch Length (in)	No. of Teeth	Belt Length Code	Pitch Length (in)	No. of Teeth
• 42XL • 50XL • 54XL • 56XL • 56XL • 66XL • 66XL • 72XL • 74XL • 76XL • 78XL • 80XL • 88XL • 88XL • 90XL • 92XL • 94XL • 96XL	4.200 5.000 5.400 5.600 6.200 6.400 6.600 7.000 7.400 7.800 8.000 8.200 8.400 8.400 8.800 9.200 9.400 9.400 9.800 10.000 10.200	21 25 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51	• 106XL • 108XL • 110XL • 112XL • 114XL • 116XL • 120XL • 122XL • 122XL • 128XL • 130XL • 130XL • 136XL • 136XL • 136XL • 140XL • 140XL • 140XL • 140XL • 150XL • 150XL • 150XL • 150XL • 150XL • 150XL • 150XL • 150XL	10.600 10.800 11.000 11.200 11.400 11.600 12.200 12.200 12.400 12.800 13.000 13.400 13.600 13.400 14.400 14.400 14.400 15.000 15.200 15.400 15.500 15.600	53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 70 71 72 73 74 75 76 77 78	• 160XL • 162XL • 164XL • 166XL • 166XL • 170XL • 170XL • 174XL • 178XL • 180XL • 182XL • 184XL • 184XL • 190XL • 192XL • 194XL 196XL • 196XL • 200XL • 200XL • 201XL • 201XL • 201XL • 201XL • 201XL • 201XL • 201XL • 201XL	16.000 16.200 16.400 16.600 17.000 17.200 17.400 17.800 18.000 18.200 18.400 18.600 19.000 19.200 19.400 20.200 20.400 20.400 20.600 20.800 21.200	80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100 101 102 103 104 105 106	214XL 218XL 220XL 222XL 226XL 228XL 230XL 232XL 234XL 234XL 240XL 244XL 250XL 254XL 256XL 266XL 266XL 266XL 266XL 270XL 274XL 286XL 286XL 286XL 290XL	21.400 21.800 22.200 22.200 22.200 22.800 23.000 23.400 24.400 24.600 25.000 25.400 26.200 26.200 26.200 26.200 27.000 27.000 27.400 28.600 28.400 29.200 29.200 20	107 109 110 111 113 114 115 116 117 118 120 122 123 125 127 129 130 131 132 133 134 135 137 140 142 143	296XL 300XL 306XL 310XL 310XL 320XL 322XL 330XL 3340XL 344XL 348XL 350XL 350XL 372XL 380XL 380XL 380XL 380XL 390XL 404XL 424XL 423XL	29.600 30.000 30.600 31.000 32.200 32.200 33.000 33.800 34.400 34.800 35.000 37.200 37.200 38.200 38.200 39.200 40.200 40.400 41.200 42.400 43.200	148 150 153 155 158 160 161 165 169 170 172 174 175 176 181 185 186 190 191 192 195 196 200 202 206 210 212	434XL 438XL 444XL 450XL 454XL 460XL 460XL 480XL 490XL 490XL 500XL 500XL 506XL 524XL 570XL 554XL 570XL 630XL 672XL 660XL 672XL 680XL 736XL 770XL 850XL	43.400 43.800 44.400 45.000 46.000 46.800 49.000 49.200 49.200 49.800 50.600 52.400 52.400 55.400 67.200 63.000 67.200 69.000 77.000 85.000	217 219 222 225 227 230 234 240 245 250 253 262 270 277 285 296 306 315 336 345 368 385 425

Stock Lengths are denoated by a . All other sizes, contact Gates Customer Service for availability.

XL Stock I	Belt Widths
Belt Width Code	Width (in)
025	1/4 (0.250)
037	3/8 (0.375)

Belt Pitch Selection Guide



Belt Width Selection Tables – MXL (.080 in)

The following table represents the torque ratings for each belt in its base width at the predetermined number of grooves, pitch diameters and rpm. These ratings must be multiplied by the appropriate width factor to obtain the corrected torque rating. (See Step 4 of Drive Selection Procedure on Page 12.)

	Rated Torque (oz-in) For Small Sprocket - 1/8 in. Top Width																				
No. o Groo		10	11	12	14	15	16	18	20	21	22	24	28	30	32	36	40	42	44	48	60
P.D	. mm (in)	6.48 .255	7.11 .280	7.77 .306	9.07 .357	9.70 .382	10.34 .407	11.63 .458	12.93 .509	13.59 .535	14.22 .560	15.52 .611	18.11 .713	19.41 .764	20.70 .815	23.29 .917	25.88 1.019	27.18 1.070		31.04 1.222	38.81 1.528
Faster Shaft	10 100 1000 2000 2500	4.61 4.61 4.61 4.61 4.61	5.06 5.06 5.06 5.06 5.06	5.53 5.53 5.53 5.53 5.53	6.45 6.45 6.45 6.45 6.45	6.91 6.91 6.91 6.90 6.90	7.36 7.36 7.36 7.36 7.35	8.28 8.28 8.28 8.28 8.28	9.20 9.20 9.20 9.20 9.20	9.67 9.67 9.67 9.67 9.66	10.1 10.1 10.1 10.1 10.1	11.0 11.0 11.0 11.0 11.0	12.9 12.9 12.9 12.9 12.9	13.8 13.8 13.8 13.8 13.8	14.7 14.7 14.7 14.7 14.7	16.6 16.6 16.6 16.6 16.5	18.4 18.4 18.4 18.4 18.4	19.3 19.3 19.3 19.3 19.3	20.2 20.2 20.2 20.2 20.2 20.2	22.1 22.1 22.1 22.0 22.0	27.6 27.6 27.6 27.5 27.4
rpm of	3000 3500 5000 8000 10000 12000	4.61 4.61 4.61 4.60 4.59 4.59	5.06 5.06 5.06 5.05 5.04 5.03	5.53 5.53 5.53 5.52 5.51 5.49	6.45 6.45 6.44 6.43 6.41 6.39	6.90 6.90 6.89 6.87 6.85 6.83	7.35 7.35 7.34 7.32 7.30 7.27	8.27 8.27 8.26 8.22 8.19 8.15	9.19 9.19 9.17 9.12 9.08 9.03	9.66 9.66 9.64 9.58 9.53 9.47	10.1 10.1 10.1 10.0 9.96 9.89	11.0 11.0 11.0 10.9 10.8 10.7	12.9 12.8 12.8 12.7 12.6 12.4	13.8 13.8 13.7 13.5 13.4 13.2	14.7 14.7 14.6 14.4 14.2 14.0	16.5 16.5 16.4 16.1 15.9 15.5	18.3 18.3 18.2 17.8 17.4 17.0	19.2 19.2 19.1 18.6 18.2 17.7	20.1 20.1 19.9 19.4 18.9 18.4	21.9 21.9 21.7 21.0 20.4 19.6	27.3 27.2 26.8 25.5 24.3 22.8

Belt Width (in)	1/8	3/16	1/4	5/16	3/8	7/16	1/2
Width Multiplier	1.00	1.66	2.33	2.84	3.50	4.18	4.86

Belt Width Selection Tables – XL (.200 in) Belts

				R	ated Torq	ue (lb-in)	For Smal	l Sprocke	et - 1/4 in.	Top Widt	th			
No. Gro	of oves	10	11	12	14	15	16	18	20	21	22	24	28	30
P.D.	mm (in)	16.18 .637	17.78 . 700	19.41 .764	22.63 .891	24.26 .955	25.883 1.019	29.11 1.146	32.33 1.273	33.96 1.337	35.59 1.401	38.81 1.528	45.29 1.783	48.51 1.910
Faster Shaft	10 100 500 1000 1160	2.32 2.32 2.32 2.32 2.32 2.32	2.55 2.55 2.55 2.54 2.54	2.78 2.78 2.78 2.78 2.78 2.78	3.24 3.24 3.24 3.24 3.24	3.47 3.47 3.47 3.47 3.47	3.71 3.71 3.70 3.70 3.70	4.17 4.17 4.17 4.16 4.16	4.63 4.63 4.63 4.62 4.62	4.86 4.86 4.86 4.86 4.85	5.09 5.09 5.09 5.09 5.08	5.56 5.56 5.55 5.55 5.54	6.48 6.48 6.48 6.47 6.46	6.95 6.95 6.94 6.93 6.92
rpm of	1450 1600 1750 2000 2500	2.31 2.31 2.31 2.31 2.31	2.54 2.54 2.54 2.54 2.54	2.78 2.78 2.77 2.77 2.77	3.24 3.24 3.23 3.23 3.23	3.47 3.47 3.47 3.46 3.46	3.70 3.70 3.70 3.69 3.69	4.16 4.16 4.15 4.15 4.14	4.62 4.61 4.61 4.61 4.59	4.85 4.84 4.84 4.84 4.82	5.08 5.07 5.07 5.06 5.05	5.54 5.53 5.53 5.52 5.49	6.45 6.44 6.42 6.38	6.90 6.90 6.89 6.87 6.82
	3000 3500 5000 8000 10000	2.31 2.31 2.30 2.27 2.24	2.54 2.53 2.52 2.48 2.45	2.77 2.76 2.75 2.70 2.65	3.22 3.22 3.19 3.11 3.04	3.45 3.44 3.41 3.32 3.23	3.68 3.67 3.63 3.52 3.41	4.13 4.12 4.06 3.90 3.75	4.58 4.56 4.48 4.26 4.05	4.80 4.78 4.69 4.43 4.19	5.03 5.00 4.90 4.60 4.32	5.47 5.43 5.31 4.92 4.56	6.34 6.29 6.09 5.47 4.89	6.77 6.71 6.46 5.70 4.99

Belt Width (in)	1/4	5/16	3/8	7/16	1/2
Width Multiplier	1.00	1.29	1.59	1.89	2.20

PowerGrip® Timing Belt Drives – Twin Power

Twin Power Belt Drive Systems

Twin Power Belts are similar in construction to standard synchronous belts, including nylon-faced teeth on both sides. This construction uses essentially the same design parameters as standard synchronous belts. Gates XL Twin Power Timing belts have helically-wound fiberglass tension members embedded in a Neoprene body with the belt teeth faced with a tough wear-resistant nylon fabric. A unique feature of this construction is that Gates Twin Power belts can transmit their full rated load on either the front or back side.


The three principal dimensions, in inches, shown below, are used to specify a Twin Power Timing belt.

TP	330	XL	025
Twin	33.0"	0.200"	0.25"
Power	Pitch Lenath	Pitch	Wide

Belt pitch is the distance in inches between two adjacent tooth centers as measured on the pitch line of the belt. Belt pitch length is the total length (circumference) in inches as measured along the pitch line. The theoretical pitch line of a Timing belt lies within the tensile member.

NOTE: For drive design procedure, see page 12.

XL Pitch - Reference Dimensions





PowerGrip® Timing Belt Drives – Twin Power


PowerGrip Belt Lengths and Widths


	XL Timing Belt Length													
Description	Pitch Length (in)	No. of Teeth	Description	Pitch Length (in)	No. of Teeth	Description	Pitch Length (in)	No. of Teeth	Description	Pitch Length (in)	No. of Teeth			
•TP124XL	12.40	62	•TP182XL	18.20	91	•TP260XL	26.00	130	•TP400XL	40.00	200			
•TP126XL	12.60	63	•TP184XL	18.40	92	•TP262XL	26.20	131	•TP412XL	41.20	206			
•TP128XL	12.80	64	•TP186XL	18.60	93	•TP264XL	26.40	132	•TP420XL	42.00	210			
•TP130XL	13.00	65	•TP188XL	18.80	94	•TP266XL	26.60	133	•TP424XL	42.40	212			
•TP132XL	13.20	66	•TP190XL	19.00	95	•TP268XL	26.80	134	•TP432XL	43.20	216			
•TP134XL	13.40	67	•TP192X	19.20	96	•TP270XL	27.00	135	•TP438XL	43.80	219			
•TP136XL	13.60	68	•TP194XL	19.40	97	•TP274XL	27.40	137	•TP444XL	44.40	222			
•TP138XL	13.80	69	•TP200XL	20.00	100	•TP280XL	28.00	140	•TP450XL	45.00	225			
•TP140XL	14.00	70	•TP202XL	20.20	101	•TP286XL	28.60	143	•TP454XL	45.40	227			
•TP142XL	14.20	71	•TP204XL	20.40	102	•TP290XL	29.00	145	•TP460XL	46.00	230			
•TP144XL	14.40	72	•TP206XL	20.60	103	•TP296XL	29.60	148	•TP468XL	46.80	234			
•TP146XL	14.60	73	•TP210XL	21.00	105	•TP300XL	30.00	150	•TP480XL	48.00	240			
•TP148XL	14.80	74	•TP212XL	21.20	106	•TP306XL	30.60	153	•TP492XL	49.20	246			
•TP150XL	15.00	75	•TP214XL	21.40	107	•TP310XL	31.00	155	•TP498XL	49.80	249			
•TP152XL	15.20	76	•TP218XL	21.80	109	•TP316XL	31.60	158	•TP500XL	50.00	250			
•TP154XL	15.40	77	•TP220XL •TP222XL •TP226XL •TP228XL •TP230XL	22.00	110	•TP320XL	32.00	160	•TP506XL	50.60	253			
•TP156XL	15.60	78		22.20	111	•TP322XL	32.20	161	•TP524XL	52.40	262			
•TP158XL	15.80	79		22.60	113	•TP330XL	33.00	165	•TP570XL	57.00	285			
•TP160XL	16.00	80		22.80	114	•TP338XL	33.80	169	•TP580XL	58.00	290			
•TP162XL	16.20	81		23.00	115	•TP340XL	34.00	170	•TP592XL	59.20	296			
•TP164XL	16.40	82	•TP232XL	23.20	116	•TP344XL	34.40	172	•TP612XL	61.20	306			
•TP166XL	16.60	83	•TP234XL	23.40	117	•TP348XL	34.80	174	•TP630XL	63.00	315			
•TP168XL	16.80	84	•TP236XL	23.60	118	•TP350XL	35.00	175	•TP672XL	67.20	336			
•TP170XL	17.00	85	•TP240XL	24.00	120	•TP352XL	35.20	176	•TP690XL	69.00	345			
•TP172XL	17.20	86	•TP244XL	24.40	122	•TP362XL	36.20	181	•TP770XL	77.00	385			
•TP174XL •TP176XL •TP178XL •TP180XL	17.40 17.60 17.80 18.00	87 88 89 90	●TP246XL ●TP250XL ●TP254XL ●TP258XL	24.60 25.00 25.40 25.80	123 125 127 129	•TP370XL •TP380XL •TP384XL •TP390XL	37.00 38.00 38.40 39.00	185 190 192 195	●TP850XL	85.00	425			


Stock lengths are denoted by a •. All other sizes, contact Gates Customer Service for availability.

XL Stock Belt Widths											
Belt Width Code	Width (in)										
025	1/4 (0.250)										
037	3/8 (0.375)										

Pulley Specification Tables – MXL and XL Pulleys







	M	XL (.080 in) PowerGr	ip Timing E	Belt Pulleys	for 1/8 in	., 3/16 in. a	and 1/4 in.	Wide Belts	;	
Pulley	No. of		Pitch Diameter	Outside Diameter	Flange Diameter		Nominal Din	nensions (in)			Stock Bore
Designation	Grooves	Туре	(in)	(in)	(in)	E	L	Н	F	Material	(in)
10MXL025	10	6FC	.255	.235	.425	-	.565	.425	.330	AL	1/8
11MXL025	11	6FC	.280	.260	.450	-	.565	.450	.330	AL	1/8
12MXL025	12	6FC	.306	.286	.480	-	.565	.480	.330	AL	1/8
14MXL025	14	6FC	.357	.337	.530	-	.565	.530	.330	AL	1/8
15MXL025	15	6FC	.382	.362	.555	-	.565	.555	.330	AL	3/16
16MXL025	16	6FC	.407	.387	.580	-	.565	.580	.330	AL	3/16
18MXL025	18	6F	.458	.438	.635	.236	.625	.312	.389	AL	3/16
20MXL025	20	6F	.509	.489	.685	.236	.625	.364	.389	AL	3/16
21MXL025	21	6F	.535	.515	.710	.236	.625	.390	.389	AL	3/16
22MXL025	22	6F	.560	.540	.740	.236	.625	.390	.389	AL	3/16
24MXL025	24	6F	.611	.591	.790	.298	.687	.442	.389	AL	1/4
28MXL025	28	6F	.713	.693	.895	.298	.687	.494	.389	AL	1/4
30MXL025	30	6F	.764	.744	.945	.298	.687	.546	.389	AL	1/4
32MXL025	32	6F	.815	.795	1.000	.298	.687	.598	.389	AL	1/4
36MXL025	36	6F	.917	.897	1.105	.298	.687	.676	.389	AL	1/4
40MXL025	40	6F 6F	1.019	.999	1.210	.313	.718	.754	.405	AL	1/4
42MXL025	42	6F	1.070	1.050	1.260	.313	.718	.806	.405	AL	1/4
44MXL025	44 48	6F	1.120	1.100	1.315	.313 .313	.718	.858 .936	.405	AL AL	1/4 1/4
48MXL025 60MXL025	60	6F	1.222 1.528	1.202 1.508	1.420 1.730	.313	.718 .718	1.222	.405 .405	AL AL	1/4
72MXL025	72	6	1.833	1.813	1.730	.375	.750	1.195	.375	AL AL	1/4
80MXL025	80	6	2.037	2.017	_	.375	.750	1.500	.375	AL AL	5/16
UUIVIALUZU	00	0	2.037	2.017	_	.575	.730	1.300	.373	/AL	3/10

NOTE: 10 through 16 groove pulleys have 1 set screw; 18 through 72 teeth pulleys have 2 set screws at 90 degrees.

	XL (.200 in) PowerGri	ip Timing E	Belt Pulleys	s for 1/4 in	n. and	3/8 in.	Wide I	Belts	(Face W	idth, F = 9	/16 in)		
Pulley	No. of	_	Pitch Diameter	Outside Diameter	Flange Diameter		ninal Dim				Bushing or		Bore* (in)	Avg. Wt.
Designation	Grooves	Туре	(in)	(in)	(in)	E	L	Н	F	Material	Bore Type	Min.	Max.	(lb)
10XL037	10	6F	0.637	0.617	0.91	0.22	0.78	0.44	0.56	ST	MPB	3/16	1/4	-
11XL037	11	6F	0.700	0.680	0.91	0.22	0.78	0.50	0.56	ST	MPB	3/16	1/4	-
12XL037	12	6F	0.764	0.744	0.97	0.22	0.78	0.50	0.56	ST	MPB	3/16	5/16	0.03
14XL037	14	6F	0.891	0.871	1.11	0.22	0.78	0.56	0.56	ST	MPB	1/4	3/8	0.05
15XL037	15	6F	0.955	0.935	1.19	0.22	0.78	0.63	0.56	ST	MPB	1/4	7/16	0.06
16XL037	16	6F	1.019	0.999	1.25	0.22	0.78	0.69	0.56	ST	MPB	1/4	3/8	0.06
18XL037	18	6F	1.146	1.126	1.38	0.22	0.78	0.81	0.56	ST	MPB	1/4	9/16	0.09
20XL037	20	6F	1.273	1.253	1.50	0.31	0.88	0.94	0.56	ST	MPB	1/4	11/16	0.12
21XL037	21	6F	1.337	1.317	1.56	0.31	0.88	1.00	0.56	ST	MPB	1/4	11/16	0.12
22XL037	22	6F	1.401	1.381	1.63	0.31	0.88	1.00	0.56	ST	MPB	1/4	3/4	0.12
24XL037	24	6F	1.528	1.508	1.75	0.31	0.88	1.06	0.56	ST	MPB	1/4	13/16	0.15
28XL037	28	6F	1.783	1.763	2.00	0.31	0.88	1.19	0.56	ST	MPB	1/4	15/16	0.21
30XL037	30	6F	1.910	1.890	2.13	0.31	0.88	1.38	0.56	ST	MPB	1/4	1 1/16	0.22
32XL037	32	6	2.037	2.017		0.44	1.00	1.50	0.56	AL	MPB	5/16	1 3/16	0.25
32XL037	32	2	2.037	2.017		-	0.88	-	0.88	SiS	1108	1/2	1	0.22
36XL037	36	6	2.292	2.272		0.44	1.00	1.50	0.56	AL	MPB	5/16	1 3/16	0.33
36XL037	36	2	2.292	2.272	-	0.32	0.88	2.13	0.56	SiS	1108	1/2	1	0.30
40XL037	40	6	2.546	2.526	-	0.44	1.00	1.50	0.56	AL	MPB	5/16	1 3/16	0.31
40XL037	40	2	2.546	2.526		0.32	0.88	2.25	0.56	SiS	1108	1/2	1	0.31
42XL037	42	6	2.674	2.654		0.44	1.00	1.50	0.56	AL	MPB	5/16	1 3/16	0.31
42XL037	42	2	2.674	2.654		0.32	0.88	2.38	0.56	SiS	1108	1/2	1	0.31
44XL037	44	6	2.801	2.781		0.44	1.00	1.50	0.56	AL	MPB	5/16	1 3/16	0.31
44XL037	44	2	2.801	2.781		0.32	0.88	2.63	0.56	SiS	1108	1/2	1	0.31
48XL037	48	6	3.056	3.036	-	0.44	1.00	1.50	0.56	AL	MPB	5/16	1 3/16	0.38
48XL037	48	2	3.056	3.036		0.32	0.88	2.88	0.56	SiS	1108	1/2	1	0.38
60XL037	60	6	3.820	3.800	-	0.44	1.00	1.50	0.56	AL	MPB	3/8	1 3/16	0.38
60XL037	60	2	3.820	3.800	-	0.44	1.00	3.50	0.56	SiS	1210	1/2	1 1/4	0.38
72XL037	72	6	4.584	4.564	-	0.44	1.00	1.50	0.56	AL	MPB	3/8	1 3/16	0.50
72XL037	72	2	4.584	4.564	-	0.44	1.00	4.00	0.56	SiS	1610	1/2	1 11/16	0.50

^{*}Plain bore style stocked in smallest bore.

NOTE: All pulleys have 2 set screws at 90 degrees.

NOTE: See Synchronous Belt Drives — Sprocket Specifications section, Page 72, for a complete table of stock and non-stock pulley diameters.



For non-standard designs contact Gates Made-To-Order Metals Team at (800)709-6001

PowerGrip® Long-Length Belting

Long-Length belting is produced in Spiral form. Spiral cut belting is produced from a belt sleeve by moving the slitter laterally while the belt sleeve is rotating.

The resulting belting does not have continuous tensile cords, and the teeth are not perfectly perpendicular to the longitudinal axis of the belt. As long as the belt width is narrow, these properties have been found to contribute little if any detrimental effects to belt performance. Tensile modulus and strength are equivalent to conventional endless and long length belting.

This innovative product is available in all types of PowerGrip belting in all pitches. Reciprocating carriage drives requiring the use of higher performance curvilinear tooth belt products in long length form can now be easily handled. Contact Gates Application Engineering for specific application details and assistance in design.

Long Length Belting Specifications

Long-Length Belting Designations

PowerGrip Long-Length Belting is specified using the same width and pitch codes as standard PowerGrip belts, except that it includes an LL prefix and omits the length code. Thus a 250 ft. length of XL (.200 in) pitch belting in a 3/8 in. width carries the specification 250 ft. LL037XL.

Drive Selection With PowerGrip Long-Length Belting

Drive selection procedures for drives using Long-Length Belting are much the same as for drives using conventional endless belting. Refer to the appropriate product and engineering sections in this catalog for drive torque ratings, engineering information, sprocket details, belt tension recommendations, etc. Table 6 includes rated belt working tension data, minimum belt tensile strength, and belt tensile modulus values for those applications for which it could be helpful, as well as minimum order quantities. For drive design selection assistance with PowerGrip Long-Length Belting, contact Gates Application Engineering.

Clamping Plates - See page 55.

				Table 6	– Pow	erGrip	Long-L	ength B	elting	Specific	ations			
											Fibergl	ass Cord		
					Rated	Working	Tension	(Ta) (lb))		Minimum Breaking	Elongation Tension (lb)	Minimum Order	Maximum Cont.
							ulley Gro				Strength	For 0.1% '	Quantity	Length
Pitch	Width	Code	12	14	16	18	24	32	40	>48	(lb)	Elongation	(ft)	(ft)
MXL (0.080 in)	1/4 in. 3/8 in. 1/2 in.	LL025MXL LL037MXL LL050MXL	5.3 8.0 11.1	120 180 270	5.2 8.6 11.5	50 50 50	300 300 300							
XL														
(0.200 in)	1/4 in. 3/8 in. 1/2 in.	LL025XL LL037XL LL050XL	7.3 11.6 16.1	250 375 555	6.1 10.1 13.5	50 50 50	300 225 150							
3M HTD	0	11.01400	10	10	00	00	04	00	0.4	07	070	0.4	F0	000
(3mm)	6mm 9mm 15mm	LL3M06 LL3M09 LL3M15	18 30 55	19 32 57	20 33 58	20 33 59	21 35 61	22 37 90	24 40 95	27 45 106	270 447 672	9.4 15.7 28.1	50 50 50	300 300 185
5M HTD	0	11.51400		00	44	4.4		F0	04				F0	
(5mm)	9mm 15mm	LL5M09 LL5M15		39 60	41 66	44 70	52 83	59 93	61 96	61 96	830 1197	32.8 57.5	50 50	300 185
2MR GT2													=-	
(2mm)	6mm 9mm 12mm	LL2MR06 LL2MR09 LL2MR12	5.6 8.4 11.2	5.8 8.7 11.6	5.9 8.9 11.8	6.0 9.0 12.0	6.2 9.3 12.4	6.3 9.5 12.6	6.4 9.6 12.8	6.4 9.6 12.8	125 190 280	3.8 5.7 8.5	50 50 50	300 300 300
3MR GT2	6mm	LL3MR06			31	32	33	36	38	42	270	9.4	50	600
(3mm)	9mm 15mm	LL3MR09 LL3MR15	 		51 51 92	53 95	55 98	60 107	70 113	70 125	447 672	15.7 28.1	50 50 50	385 240
5MR GT2	Omm	LL5MR09				60	73	83	88	92	830	20.0	50	260
(5mm)	9mm 15mm	LL5MR15				95	115	131	139	145	1187	32.8 57.8	50	360 230


NOTE: The width tolerance on all long length spiral cut belting is +0.031 in. (0.8mm) -0.047 in. (1.2mm).


For non-standard belt widths, contact Gates Customer Service for mimimum order quantity.





PowerGrip® Long-Length Belting

Clamp Plate Specification Table










Code	Belt		A		В		C	I)	E	E	F	•	ı	Н		K	N	1	S) 1	5	2)	(Wt.
Symbol	Width	(in)	(mm)	(in)	(mm)	(in)	(mm)	(lb)																		
	2MR Clamps																									
CP-04-2MR	4mm	0.71	18	0.08	2.0	0.66	16.8	0.09	2.4	0.29	7.4	0.19	4.7	0.17	4.4	0.39	10.0	0.16	4.0	0.16	4.0	0.16	4.0	0.08	2.0	0.01
CP-06-2MR	6mm	0.71	18	0.08	2.0	0.74	18.8	0.09	2.4	0.37	9.4	0.19	4.7	0.17	4.4	0.39	10.0	0.16	4.0	0.16	4.0	0.16	4.0	0.08	2.0	0.03
CP-09-2MR	9mm	0.71	18	0.08	2.0	0.86	21.8	0.09	2.4	0.49	12.4	0.19	4.7	0.17	4.4	0.39	10.0	0.16	4.0	0.16	4.0	0.16	4.0	0.08	2.0	0.04
	3MR Clamps																									
CP-06-3MR	6mm	1.06	27.0	0.12	3.0	0.87	22.0	0.13	3.4	0.41	10.4	0.23	5.8	0.26	6.5	0.59	15.0	0.24	6.0	0.24	6.0	0.20	5.0	0.12	3.0	0.04
CP-09-3MR	9mm	1.06	27.0	0.12	3.0	0.98	25.0	0.13	3.4	0.53	13.4	0.23	5.8	0.26	6.5	0.59	15.0	0.24	6.0	0.24	6.0	0.20	5.0	0.12	3.0	0.04
CP-15-3MR	15mm	1.06	27.0	0.12	3.0	1.24	31.5	0.13	3.4	0.78	19.9	0.23	5.8	0.26	6.5	0.59	15.0	0.24	6.0	0.24	6.0	0.20	5.0	0.12	3.0	0.05
	5MR Clamps																									
CP-09-5MR	9mm	1.77	45.0	0.20	5.0	1.20	30.5	0.22	5.5	0.61	15.5	0.30	7.5	0.39	10.0	0.98	25.0	0.39	10.0	0.39	10.0	0.31	8.0	0.20	5.0	0.13
CP-15-5MR	15mm	1.77	45.0	0.20	5.0	1.46	37	0.22	5.5	0.87	22	0.30	7.5	0.39	10.0	0.98	25.0	0.39	10.0	0.39	10.0	0.31	8.0	0.20	5.0	0.16
CP-25-5MR	25mm	1.77	45.0	0.20	5.0	1.85	47	0.22	5.5	1.26	32	0.30	7.5	0.39	10.0	0.98	25.0	0.39	10.0	0.39	10.0	0.31	8.0	0.20	5.0	0.21
		1									XL (lamp	S								'		'			
CP-025-XL	0.25 in.	1.74	44.2	0.17	4.3	1.09	27.7	0.22	5.6	0.51	13.0	0.29	7.4	0.38	9.5	1.00	25.4	0.37	9.4	0.38	9.7	0.32	8.1	0.19	4.8	0.12
CP-031-XL	0.31 in.	1.74	44.2	0.17	4.3	1.15	29.2	0.22	5.6	0.57	14.5	0.29	7.4	0.38	9.5	1.00	25.4	0.37	9.4	0.38	9.7	0.32	8.1	0.19	4.8	0.13
CP-037-XL	0.38 in.	1.74	44.2	0.17	4.3	1.22	31.0	0.22	5.6	0.64	16.3	0.29	7.4	0.38	9.5	1.00	25.4	0.37	9.4	0.38	9.7	0.32	8.1	0.19	4.8	0.14
CP-050-XL	0.50 in.	1.74	44.2	0.17	4.3	1.34	34.0	0.22	5.6	0.76	19.3	0.29	7.4	0.38	9.5	1.00	25.4	0.37	9.4	0.38	9.7	0.32	8.1	0.19	4.8	0.14
CP-075-XL	0.75 in.	1.74	44.2	0.17	4.3	1.59	40.4	0.22	5.6	1.01	25.7	0.29	7.4	0.38	9.5	1.00	25.4	0.37	9.4	0.38	9.7	0.32	8.1	0.19	4.8	0.18
CP-100-XL	1.00 in.	1.74	44.2	0.17	4.3	1.84	46.7	0.22	5.6	1.26	32.0	0.29	7.4	0.38	9.5	1.00	25.4	0.37	9.4	0.38	9.7	0.32	8.1	0.19	4.8	0.21
CP-150-XL	1.50 in.	1.74	44.2	0.17	4.3	2.34	59.4	0.22	5.6	1.76	44.7	0.29	7.4	0.38	9.5	1.00	25.4	0.37	9.4	0.38	9.7	0.32	8.1	0.19	4.8	0.27
CP-200-XL	2.00 in.	1.74	44.2	0.17	4.3	2.84	72.1	0.22	5.6	2.26	57.4	0.29	7.4	0.38	9.5	1.00	25.4	0.37	9.4	0.38	9.7	0.32	8.1	0.19	4.8	0.32

Contact Gates Customer Service for clamping plate availability.

Side View of Belt In Grooved Clamp Plate



PowerGrip $\operatorname{GT2}$ - Grooved plates end on the center of the belt tooth bottom



PowerGrip Timing - Grooved plates end on radius of the tooth bottom

Note: Standard Grooved Plates have 8 complete grooves and 9 full teeth for belt engagement.

Bolt Kits For Clamping Plates

Product	Bolt	Lock	Hex
Description	Dimensions	Washer	Nut
2MR BOLT KIT	M2 x 0.4 x 12	M2	M2
3MR BOLT KIT	M3 x 0.5 x 16	M3	М3
5MR BOLT KIT	M5 x 0.8 x 25	M5	M5
.200-XL BOLT KIT	#10-24 x 1.0	#10	#10



I. Operating Characteristics

NOTE: This engineering section provides general engineering information for synchronous belts and sprockets (or pulleys) which are useful in general drive design work. Where we refer to "sprockets" (for PowerGrip® GT®2 and HTD belts), you can substitute "pulleys" for PowerGrip Timing Belts. If you need additional information, contact Gates Application Engineering, Denver.

A. Low Speed Operation

Synchronous drives are especially well suited for low speed-high torque applications. Their positive driving nature prevents potential slippage associated with V-belt drives, and even allows significantly greater torque carrying capability. Small pitch synchronous drives operating at speeds of 50 ft./min. (.25 m/s) or less are considered to be low speed. Care should be taken in the drive selection process as stall and peak torques can sometimes be very high. While intermittent peak torques can often be carried by synchronous drives without special considerations, high cyclic peak torque loading should be carefully reviewed.

Proper belt installation tension and rigid drive bracketry and framework is essential in preventing belt tooth jumping under peak torque loads. It is also helpful to design with more than the normal minimum of 6 belt teeth in mesh to ensure adequate belt tooth shear strength.

Newer generation curvilinear systems like PowerGrip® GT®2 and PowerGrip HTD should be used in low speed-high torque applications, as PowerGrip Timing Belts are more prone to tooth jumping, and have significantly less load carrying capacity.

B. High Speed Operation

Synchronous belt drives are often used in high speed applications even though V-belt drives are typically better suited. They are often used because of their positive driving characteristic (no creep or slip), and because they require minimal maintenance (minimal stretch). A significant drawback of high speed synchronous drives is drive noise. High speed synchronous drives will nearly always produce more noise than V-belt drives. Small pitch synchronous drives operating at speeds in excess of 1300 ft/min (6.6 m/s) are considered to be high speed.

Special considerations should be given to high speed drive designs, as a number of factors can significantly influence belt performance. Cord fatigue and belt tooth wear are the two most significant

factors that must be controlled to ensure success. Moderate sprocket diameters should be used to reduce the rate of cord flex fatigue. Designing with a smaller pitch belt will often provide better cord flex fatigue characteristics than a larger pitch belt. PowerGrip® GT®2 is especially well suited for high speed drives because of its excellent belt tooth entry/exit characteristics. Smooth interaction between the belt tooth and sprocket groove minimizes wear and noise. Belt installation tension is especially critical with high speed drives. Low belt tension allows the belt to ride out of the driveN sprocket resulting in rapid belt tooth and sprocket groove wear.

C. Smooth Running

Some ultra-sensitive applications require the belt drive to operate with as little vibration as possible, as vibration sometimes has an effect on the system operation or finished manufactured product. In these cases, the characteristics and properties of all appropriate belt drive products should be reviewed. The final drive system selection should be based upon the most critical design requirements, and may require some compromise.

Vibration is not generally considered to be a problem with synchronous belt drives. Low levels of vibration typically result from the process of tooth meshing and/or as a result of their high tensile modulus properties. Vibration resulting from tooth meshing is a normal characteristic of synchronous belt drives, and cannot be completely eliminated. It can be minimized by avoiding small sprocket diameters, and instead choosing moderate sizes. The dimensional accuracy of the sprockets also influences tooth meshing quality. Additionally, the installation tension has an impact on meshing quality. PowerGrip® GT®2 drives mesh very cleanly, resulting in the smoothest possible operation. Vibration resulting from high tensile modulus can be a function of sprocket quality. Radial run out causes belt tension variation with each sprocket revolution. V-belt sheaves are also manufactured with some radial run out, but V-belts have a lower tensile modulus resulting in less belt tension variation. The high tensile modulus found in synchronous belts is necessary to maintain proper pitch under load.

D. Drive Noise

Drive noise evaluation in any belt drive system should be approached with care. There are many potential sources of noise in a system including vibration from related components, bearings, and resonance and amplification through framework and panels. Synchronous belt drives typically produce more noise than V-belt drives. Noise results from the process of belt tooth meshing and physical contact with the sprockets. The sound pressure level generally increases as operating speed and belt width increases, and as sprocket diameter decreases. Drives designed on moderate sprocket sizes without excessive capacity (over-designed) are generally the guietest. PowerGrip® GT®2 drives have been found to be significantly quieter than other systems due to their improved meshing characteristics. Polyurethane belts generally produce more noise than neoprene belts. Proper belt installation tension is also very important in minimizing drive noise. The belt should be tensioned at a level that allows it to run with as little meshing interference as possible. See section III. Belt *Tensioning* on page 60 for additional tensioning

Drive alignment also has a significant effect on drive noise. Special attention should be given to minimizing angular misalignment (shaft parallelism). This assures that belt teeth are loaded uniformly and minimizes side tracking forces against the flanges. Parallel misalignment (sprocket offset) is not as critical of a concern so long as the belt is not trapped or pinched between opposite flanges. Refer to section II. Drive Alignment on page 60 for more discussion on misalignment. Sprocket materials and dimensional accuracy also influence drive noise. Some users have found that steel sprockets are the quietest followed closely by aluminum. Polycarbonates have been found to be noisier than metallic materials. Machined sprockets are generally quieter than molded sprockets. The reasons for this revolve around material density and resonance characteristics as well as dimensional accuracy.

E. Static Conductivity

Small synchronous rubber or urethane belts can generate an electrical charge while operating on a drive. Factors such as humidity and operating speed influence the potential of the charge. If determined to be a problem, rubber belts can be produced in a conductive construction to dissipate the charge into the sprockets, and to ground. This prevents the accumulation of electrical charges that might be detrimental to material handling processes or sensitive electronics. It also greatly reduces the potential for arcing or sparking in flammable environments. Urethane belts cannot be produced in a conductive construction.



I. Operating Characteristics – continued

RMA has outlined standards for static conductive belts in their bulletin IP-3-3. Unless otherwise specified, Gates does not manufacture the synchronous rubber belt products included in this catalog to any specific conductivity standard. A static conductive construction for rubber belts is available on a made-to-order basis. Unless otherwise specified, conductive belts will be built to yield a resistance of 300,000 ohms or less when new. A static conductive belt has sufficient conductivity to prevent measurable static voltage buildup, thus preventing a static discharge.

When a belt is used in a hazardous environment, additional protection must be employed to assure that there are no accidental static spark discharges. The portion of the belt that contacts the sprocket must be conductive to ensure that static charge is conducted into the drive hardware. Synchronous belts must have a static conductive tooth surface in contact with conductive sprocket grooves.

Unusual or excessive debris or contaminant on the belt contact surface or sprocket grooves should be cleaned and removed.

Any belt drive system that operates in a potentially hazardous environment must be properly grounded. A continuous conductive path to ground is necessary to bleed off the static charge. This path includes a static conductive belt, a conductive sprocket, a conductive bushing, a conductive shaft, conductive bearings, and the ground. As an additional measure of protection, a static-conductive brush or similar device should be employed to bleed off any residual static buildup that might remain around the belt.

Non-conductive belt constructions are also available for rubber belts. These belts are generally built specifically to the customer's conductivity requirements. They are generally used in applications where one shaft must be electrically isolated from the other.

It is important to note that a static conductive belt cannot dissipate an electrical charge through plastic sprockets. At least one metallic sprocket in a drive is required for the charge to be dissipated to ground. A grounding brush or similar device can also be used to dissipate electrical charges.

Urethane timing belts are not static conductive and cannot be built in a special conductive construction. Special conductive rubber belts should be used when the presence of an electrical charge is a concern.

F. Operating Environments

Synchronous drives are suitable for use in a wide variety of environments. Special considerations may be necessary, however, depending on the application.

Temperature: Either excessively high or low environmental temperatures can present problems to synchronous belts. The maximum recommended environmental temperature for stock belts is 185 deg. F (85 deg. C). Environmental temperatures beyond this result in gradual compound hardening as the vulcanization process continues. The belt will eventually begin cracking as it stiffens. A high temperature construction capable of a continuous environmental temperature of 230 deg. F (110 deg. C) and intermittent peaks up to 250 deg. F (121 deg. C) is available on a made-to-order basis.

Dust: Dusty environments do not generally present serious problems to synchronous drives as long as the particulates are fine and dry. Particulate matter will, however, act as an abrasive resulting in a higher rate of belt and sprocket wear. Damp or sticky particulate matter deposited and packed into sprocket grooves can cause belt tension to increase significantly. This increased tension can impact shafting, bearings, and framework. Electrical charges within a drive system can sometimes attract particulate matter.

Debris: Debris should be prevented from falling into any synchronous belt drive. Debris caught in the drive is generally either forced through the belt or results in a stalling of the system. In either case, serious damage occurs to the belt and related drive hardware.

Water: Light and occasional contact with water (occasional wash downs) should not seriously affect synchronous belts. Prolonged contact (constant spray or submersion) results in significantly reduced tensile strength in fiberglass belts, and potential length variation in aramid belts. Prolonged contact with water also causes rubber compounds to swell, although less than with oil contact. Internal belt adhesion systems are also gradually broken down with the presence of water. Additives to water such as lubricants, chlorine, anti corrosives, etc. can have a more detrimental effect on the belts than pure water. Urethane timing belts also suffer from water contamination. Polyester tensile cord shrinks significantly and experiences loss of tensile strength in the presence of water. Aramid tensile cord maintains its strength fairly well, but experiences

length variation. Urethane swells more than neoprene in the presence of water. This swelling can increase belt tension significantly causing belt and related hardware problems.

Oil: Light contact with oils on an occasional basis will not generally damage synchronous belts. Prolonged contact with oil or lubricant, either directly or airborne, results in significantly reduced belt service. Lubricants cause the rubber compound to swell, break down internal adhesion systems, and reduce belt tensile strength. While alternate rubber compounds may provide some marginal improvement in durability, it is best to prevent oil from contacting synchronous belts.

Ozone: The presence of ozone can be detrimental to the compounds used in rubber synchronous belts. Ozone degrades belt materials in much the same way as excessive environmental temperatures. Although the rubber materials used in synchronous belts are compounded to resist the effects of ozone, eventually chemical break down occurs and they become hard and brittle and begin cracking. The amount of degradation depends upon the ozone concentration and time of exposure. For good performance of rubber belts, the following concentration levels should not be exceeded: (parts per hundred million)

Standard Construction: 100 pphm Non Marking Construction: 20 pphm Conductive Construction: 75 pphm Low Temperature Construction: 20 pphm

Radiation: Exposure to gamma radiation can be detrimental to the compounds used in rubber and urethane synchronous belts. Radiation degrades belt materials much the same way excessive environmental temperatures do. The amount of degradation depends upon the intensity of radiation and the exposure time. For good belt performance, the following exposure levels should not be exceeded:

Standard Construction: 10⁸ rads Non Marking Construction: 10⁴ rads Conductive Construction: 10⁶ rads Low Temperature Construction: 10⁴ rads

Dust Generation: Rubber synchronous belts are known to generate small quantities of fine dust as a natural result of their operation. The quantity of dust is typically higher for new belts, as they run in. The period of time for run in to occur depends upon the belt and sprocket size, loading, and speed. Factors



I. Operating Characteristics - continued

such as sprocket surface finish, operating speeds, installation tension, and alignment influence the quantity of dust generated.

Clean Room: Rubber synchronous belts may not be suitable for use in clean room environments where all potential contamination must be minimized or eliminated. Urethane timing belts typically generate significantly less debris than rubber timing belts. However, they are recommended only for light operating loads. Also, they cannot be produced in a static conductive construction to allow electrical charges to dissipate.

Static Sensitive: Applications are sometimes sensitive to the accumulation of static electrical charges. Electrical charges can affect material handling processes (like paper and plastic film transport), and sensitive electronic equipment. Applications like these require a static conductive belt so that the static charges generated by the belt can be dissipated into the sprockets, and to ground. Standard rubber synchronous belts do not meet this requirement, but can be manufactured in a static conductive construction on a made-to-order basis. Normal belt wear resulting from long term operation or environmental contamination can influence belt conductivity properties.

In sensitive applications, rubber synchronous belts are preferred over urethane belts since they cannot be produced in a conductive construction.

G. Belt Tracking

Lateral tracking characteristics of synchronous belts is a common area of inquiry. While it is normal for a belt to favor one side of the sprockets while running, it is abnormal for a belt to exert significant force against a flange resulting in belt edge wear and potential flange failure. Belt tracking is influenced by several factors. In order of significance, discussion about these factors is as follows:

Tensile Cord Twist: Tensile cords are formed into a single twist configuration during their manufacture. Synchronous belts made with only single twist tensile cords track laterally with a significant force. To neutralize this tracking force, tensile cords are produced in right and left hand twist (or S and Z twist) configurations. Belts made with S twist tensile cords track in the opposite direction of those built with Z twist cord. Belts made with alternating S and Z twist tensile cords track with minimal lateral force because the tracking

characteristics of the two cords offset each other. The content of S and Z twist tensile cord varies slightly with every belt that is produced. As a result, every belt has an unpredictable tendency to track in either one direction or the other. When an application requires a belt to track in one specific direction only, a single-twist construction is used. Contact Gates Application Engineering for assistance in selecting the proper belt construction for special or unusual applications.

Angular Misalignment: Angular Misalignment, or shaft non parallelism, causes synchronous belts to track laterally. See section *II. Drive Alignment* on page 60 for more on misalignment. The angle of misalignment influences the magnitude and direction of the tracking force. Synchronous belts tend to track downhill to a state of lower tension or shorter center distance.

Belt Width: The potential magnitude of belt tracking force is directly related to belt width. Wide belts tend to track with more force than narrow belts.

Sprocket Diameter: Belts operating on small sprocket diameters can tend to generate higher tracking forces than on large diameters. This is particularly true as the belt width approaches the sprocket diameter. Drives with sprocket diameters less than the belt width are not generally recommended because belt tracking forces can become excessive.

Belt Length: Because of the way tensile cords are applied on to belt molds, short belts can tend to exhibit higher tracking forces than long belts. The helix angle of the tensile cord decreases with increasing belt length.

Gravity: In drive applications with vertical shafts, gravity pulls the belt downward. The magnitude of this force is minimal with small pitch synchronous belts. Sag in long belt spans should be avoided by applying adequate belt installation tension.

Torque Loads: Sometimes while in operation, a synchronous belt will move laterally from side to side on the sprockets rather than operating in a consistent position. While not generally considered to be a significant concern, one explanation for this is varying torque loads within the drive. Synchronous belts sometimes track differently with changing loads. There are many potential reasons

for this, the primary cause is related to tensile cord distortion while under pressure against the sprockets. Variation in belt tensile loads can also cause changes in framework deflection, and angular shaft alignment, resulting in belt movement.

Belt Installation Tension: Belt tracking is sometimes influenced by the level of belt installation tension. The reasons for this are similar to the effect that varying torque loads have on belt tracking.

When problems with belt tracking are experienced, each of these potential contributing factors should be investigated in the order that they are listed. In most cases, the primary problem will probably be identified before moving completely through the list.

H. Sprocket Flanging

Sprocket guide flanges are necessary to keep synchronous belts operating on their sprockets. As discussed previously in section G on belt tracking, it is normal for synchronous belts to favor one side of the sprockets when running.

Proper flange design is important in preventing belt edge wear, minimizing noise and preventing the belt from climbing out of the sprocket. Dimensional recommendations for custom-made or molded flanges are included in Table 22 on Page 75.

Proper flange placement is important so that the belt is adequately restrained within its operating system. Because design and layout of small synchronous drives is so diverse, the wide variety of flanging situations potentially encountered cannot easily be covered in a simple set of rules without finding exceptions. Despite this, the following broad flanging guidelines should help the designer in most cases:

Two Sprocket Drives: On simple two sprocket drives, either one sprocket should be flanged on both sides, or each sprocket should be flanged on opposite sides.

Multi Sprocket Drives: On multiple sprocket (or serpentine) drives, either every other sprocket should be flanged on both sides, or every sprocket should be flanged on alternating sides around the system.

Vertical Shaft Drives: On vertical shaft drives, at least one sprocket should be flanged on both sides, and the remaining sprockets should be flanged on at least the bottom side.



I. Operating Characteristics – continued

Long Span Lengths: Flanging recommendations for small synchronous drives with long belt span lengths cannot easily be defined due to the many factors that can affect belt tracking characteristics. Belts on drives with long spans (generally 12 times the diameter of the smaller sprocket or more) often require more lateral restraint than with short spans. Because of this, it is generally a good idea to flange the sprockets on both sides.

Large Sprockets: Flanging large sprockets can be costly. Designers often wish to leave large sprockets unflanged to reduce cost and space. Belts generally tend to require less lateral restraint on large sprockets than small and can often perform reliably without flanges. When deciding whether or not to flange, the previous guidelines should be considered. The groove face width of unflanged sprockets should also be greater than with flanged sprockets. See Table 23 on Page 75 for specific recommendations.

Idlers: Flanging of idlers is generally not necessary. Idlers designed to carry lateral side loads from belt tracking forces can be flanged if needed to provide lateral belt restraint. Idlers used for this purpose can be used on the inside or backside of the belts. The previous guidelines should also be considered.

I. Servo & Stepper Motors

Within automated machinery, motors are commonly used to provide rotational energy for specific positioning and placement operations. Motor output requirements in these applications differ from conventional motors in that shaft rotation must be incremental in accurate steps, capable of starting / stopping / reversing, variable speed, and may not ever run at a fixed speed for an extended period of time. In these position control systems, the motor shaft rotational position and speed, as well as output torque, must be accurately controlled.

A special class of motors are required to provide accurate motion and position control for automated systems. This class is primarily comprised of servo motors and stepper motors. These motors are used in a broad range of products in a variety of applications. They are used in low cost computer printers to accurately position the print heads, in ATM machines and ticket dispensers to accurately increment rollers used in feeding and retrieving operations, in machine tools to accurately rotate precision lead screws and tool holders, etc.

Belt drives are sometimes used between precision motors and the final driven shafts for more compact motor placement, to multiply motor output torque, or to reduce motor output speed.

Belt Drive Design For Servo & Stepper

Motors: Establishing a design torque load from DC servo or step motor drives when designing a new belt drive system is not always a straight forward process. Every application is unique in the way that it utilizes the available motor output torque. Few applications run continuously, as most motion control systems are used for incremental positioning and placement. Many systems reciprocate back and forth, alternate speed and/or direction, operate intermittently, etc. By the nature of their operational diversity, DC servo and step motor drive systems may utilize maximum, stall, or holding motor torque at some periodic frequency.

While system duty cycle data is useful, the designer must still determine how to size a belt drive for the estimated system loads. While this determination is dependent upon many factors (design life, drive rigidity, equipment operation / usage, belt installation tension, etc.) and its basis may differ in every case, some rough guidelines from which to start may be useful.

In many DC servo or step motor drives, maximum, stall, or holding torque loads are considerably greater than continuous or intermittent loads. In addition, maximum, stall, and holding torque loads are seen on an intermittent basis. In these cases it is reasonable to size a belt drive for either the maximum, stall, or holding motor torque load rating (depending upon the system's operation) with a design service factor of 1.0. The capacity of the proposed belt drive should then be compared with normal system running loads (carried the majority of the time) to make sure that the selected belt drive will provide a design service factor within a typical range of 1.5 to 2.0.

Contact PT Product Application for assistance in designing belt drive systems with servo and stepper motors.

J. Registration

The three primary factors contributing to belt drive registration (or positioning) errors are belt elongation, backlash, and tooth deflection. When evaluating the potential registration capabilities of a synchronous belt drive, the system must first be determined to be either static or dynamic in terms of its registration function and requirements.

Static Registration: A static registration system moves from its initial static position to a secondary

static position. During the process the designer is concerned only with how accurately and consistently the drive arrives at its secondary position. Potential registration errors that occur during transport are not considered. Therefore, the primary factor contributing to registration error in a static registration system is backlash. The effects of belt elongation and tooth deflection do not have any influence on the registration accuracy of this type of system.

Dynamic Registration: A dynamic registration system is required to perform a registering function while in motion with torque loads varying as the system operates. In this case, the designer is concerned with the rotational position of the drive sprockets with respect to each other at every point in time. Therefore, belt elongation, backlash, and tooth deflection will all contribute to registrational inaccuracies.

Further discussion about each of the factors contributing to registration error is as follows:

Belt Elongation: Belt elongation, or stretch, occurs naturally when a belt is placed under tension. The total tension exerted within a belt results from installation as well as working loads. The amount of belt elongation is a function of the belt tensile modulus, which is influenced by the type of tensile cord and the belt construction. The standard tensile cord used in rubber synchronous belts is fiberglass. Fiberglass has a high tensile modulus, is dimensionally stable, and has excellent flex-fatigue characteristics. If a higher tensile modulus is needed, aramid tensile cords can be considered, although they are generally used to provide resistance to harsh shock and impulse loads. Aramid tensile cords used in small synchronous belts generally have only a marginally higher tensile modulus in comparison to fiberglass. When needed, belt tensile modulus data is available from Gates Application Engineering.

Backlash:

Backlash in a synchronous belt drive results from clearance between the belt teeth and the sprocket grooves. This clearance is needed to allow the belt teeth to enter and exit the grooves smoothly with a minimum of interference. The amount of clearance necessary depends upon the belt tooth profile. PowerGrip® Timing Belt Drives are known for having relatively little backlash. PowerGrip® HTD® Drives have improved torque carrying capability and resist ratcheting, but have a significant amount of backlash. PowerGrip® GT®2 Drives have even further improved torque carrying capability, and have as little or less



backlash than PowerGrip Timing Belt Drives. In special cases, alterations can be made to drive systems to further decrease backlash. These alterations typically result in increased belt wear, increased drive noise and shorter drive life. Contact Gates Application Engineering for additional information.

Tooth Deflection: Tooth deformation in a synchronous belt drive occurs as a torque load is applied to the system, and individual belt teeth are loaded. The amount of belt tooth deformation depends upon the amount of torque loading, sprocket size, installation tension and belt type. Of the three primary contributors to registration error, tooth deflection is the most difficult to quantify. Experimentation with a prototype drive system is the best means of obtaining realistic estimations of belt tooth deflection.

Additional guidelines that may be useful in designing registration critical drive systems are as follows:

- Select PowerGrip® GT®2 or PowerGrip Timing Drives.
- Design with large sprockets with more teeth in mesh.
- Keep belts tight, and control tension closely.
- Design frame/shafting to be rigid under load.
- Use high quality machined sprockets to minimize radial run out and lateral wobble.

II. Drive Alignment

A. Angular And Parallel

Drive misalignment is one of the most common sources of drive performance problems. Misaligned drives can exhibit symptoms such as high belt tracking forces, uneven belt tooth wear, high noise levels, and tensile cord failure. The two primary types of drive misalignment are angular and parallel. Discussion about each of these types are as follows:




Figure 3 — Angular Misalignment

Angular: Angular misalignment results when the drive shafts are not parallel (see Fig. 3). As a result, the belt tensile cords are not loaded evenly, resulting in uneven tooth / land pressure and wear. The edge cords on the high tension side are often overloaded. Overloading often results in an edge

cord failure that propagates across the entire belt width. Angular misalignment often results in high belt tracking forces as well. High tracking forces cause accelerated belt edge wear, sometimes leading to flange failure or belts tracking off of the sprockets.

Parallel: Parallel misalignment results from sprockets being mounted out of line from each other (see Fig. 4). Parallel misalignment is generally more of a concern with V-type belts than with synchronous belts because V-type belts run in grooves and are unable to free float on the sheaves. Synchronous belts will generally free float on the sprockets and essentially self align themselves as they run. This self aligning can occur so long as the sprockets have sufficient groove face width beyond the width of the belts. If not, the belts can become trapped between opposite sprocket flanges causing serious performance problems. Parallel misalignment is not generally a significant concern with synchronous drives so long as the belts do not become trapped or pinched between opposite flanges. For recommendations on sprocket groove face width, see Table 23 on Page 75.




Figure 4 — Parallel Misalignment

Allowable Misalignment: In order to maximize performance and reliability, synchronous drives should be aligned closely. This is not, however, always a simple task in a production environment. The maximum allowable misalignment, angular and parallel combined, is 1/4".

B. Practical Tips

Angular misalignment is not always easy to measure or quantify. It is sometimes helpful to use the observed tracking characteristics of a belt, to make a judgment as to the systems relative alignment.

Neutral tracking S and Z synchronous belts generally tend to track "down hill" or to a state of lower tension or shorter center distance when angularly misaligned. This may not always hold true since neutral tracking belts naturally tend to ride lightly against either one flange or the other due to numerous factors discussed in section G., Belt Tracking on Page 58. This tendency will generally hold true with belts that track hard against a flange. In those cases, the shafts will require adjustment to correct the problem.

Parallel misalignment is not often found to be a problem in synchronous belt drives. If clearance is always observable between the belt and all flanges on one side, then parallel misalignment should not be a concern.

III. Belt Tensioning

A. What Is Proper Installation Tension

One of the benefits of small synchronous belt drives is lower belt pre-tensioning in comparison to comparable V-belt drives, proper installation tension is still important in achieving the best possible drive performance. In general terms, belt pre-tensioning is needed for proper belt/sprocket meshing to prevent belt ratcheting under peak loading, to compensate for initial belt tension decay, and to pre-stress the drive framework. The amount of installation tension that is actually needed is influenced by the type of application as well as the system design. Some general examples of this are as follows:

Motion Transfer Drives: Motion transfer drives, by definition, are required to carry extremely light torque loads. In these applications, belt installation tension is needed only to cause the belt to conform to and mesh properly with the sprockets. The amount of tension necessary for this is referred to as the minimum tension (Tst). Minimum tensions on a per span basis are included in Table 7 on page 61. Some motion transfer drives carry very little torque, but have tight registration requirements. These systems may require additional static (or installation) tension in order to minimize registration error.

Normal Power Transmission Drives: Normal power transmission drives should be designed in accordance with published torque ratings and a reasonable service factor (between 1.5 and 2.0). In these applications, belt installation tension is needed to allow the belt to maintain proper fit with the sprockets while under load, and to prevent belt ratcheting under peak loads. For these drives, proper installation tension can be determined using two different approaches. If torque loads are known and well defined, and an accurate tension value is desired, Formula 1, page 61 should be used. If the torque loads are not as well defined, and a quick value is desired for use as a starting point, values from Table 8 can be used. All static tension values are on a per span basis.



III. Belt Tensioning — continued

Formula 1

$$T_{St} = \frac{1.21 \text{ Q}}{d} + mS^2$$
, lb.

Where: T_{st} = Static Tension per span, pounds

Q = driveR torque load, pound inches

d = driveR pitch diameter, inches

S = Belt Speed/1000, feet per minute

Belt Speed = (driveR pitch diameter x driveR)

rpm)/3.82

m = Mass factor from Table 7

		Table 7		
		Table 7		
Belt Section	Belt Width	m	Υ	Minimum T _{St} (lb) Per Span
2MR GT2	4mm	0.026	1.37	1.3
	6mm	0.039	2.05	2.0
	9mm	0.058	3.08	3.0
	12mm	0.077	4.10	4.0
3MR GT2	6mm	0.077	3.22	2.2
	9mm	0.120	4.83	3.3
	12mm	0.150	6.45	4.4
	15mm	0.190	8.06	5.5
5MR GT2	9mm	0.170	14.90	8.4
	12mm	0.280	24.90	14.1
	15mm	0.380	33.20	18.7
	25mm	0.470	41.50	23.4
3M HTD	6mm	0.068	3.81	2.5
	9mm	0.102	5.71	4.3
	15mm	0.170	9.52	7.8
5M HTD	9mm	0.163	14.90	6.3
	15mm	0.272	24.90	12.0
	25mm	0.453	41.50	21.3
MXL	1/8"	0.003	1.40	1.0
	3/16"	0.004	2.11	1.7
	1/4"	0.005	2.81	2.3
XL	1/4"	0.070	3.30	3.2
	3/8"	0.105	4.94	5.1

Note: If the value of T_{St} calculated with Formula 1 is less than the minimum T_{St} value in Table 7, use the Minimum T_{St} value from the table for T_{St} in all further belt tension calculations. The minimum value must be used on lightly loaded drives to ensure that belts wrap and mesh properly with the sprockets.

Registration Drives: Registration drives are required to register, or position, accurately (see section J. Registration on Page 59). Higher belt installation tensions help in increasing belt tensile modulus as well as in increasing meshing interference, both reducing backlash. Tension values for these applications should be determined experimentally to confirm that desired performance characteristics have been achieved. As a beginning point, use values from Table 8 multiplied by 1.5 to 2.0.

Table 8 – Static Belt Tension – General Values T_{St} (lb) Per Span

PowerGrip® GT® 2 Belt Widths

Section	4 mm	6 mm	9 mm	12 mm	15 mm	20 mm	25 mm	
2MR GT2	3	4	6	8	-	-	-	
3MR GT2	-	15	23	30	38	50	-	
5MR GT2	-	-	30	40	50	67	84	

PowerGrip HTD Belt Widths

3M	-	9	15	21	27	40	-
5M	-	-	16	-	30	42	54

PowerGrip Timing Belt Widths

Section	1/8"	3/16"	1/4"	5/16"	3/8"	7/16"	1/2"
MXL	2	3	4	4	5	-	-
XL	-	-	5	6	7	8	10

Most synchronous belt applications often exhibit their own individual operating characteristics. The static installation tensions recommended in this catalog should serve as a general guideline in determining the level of tension required. The drive system should be thoroughly tested to confirm that it performs as intended. Consult Gates Application Engineering for further guidance.

B. Making Measurements

Belt installation tension is generally measured in the following ways:

Force/Deflection: Belt span tension can be measured by deflecting a belt span 1/64" per inch of span length at mid-span, with a known force (see Fig. 5). This method is generally convenient, but not always very accurate due to difficulty in measuring small deflections and forces common in small synchronous drives. The force/deflection method is most effective on larger drives with long span lengths. The static or installation tension (T_{st}) can either be calculated from Formula 1 or selected from Table 7 or Table 8. The deflection forces can be calculated from Formula 3 and Formula 4. The span length can either be calculated from Formula 2 or measured. If the calculated static tension is less than the minimum T_{st} values in Table 7, use the minimum values.




Figure 5 - Belt Deflection Distance

Formula 2

$$t = \sqrt{CD^2 - \left(\frac{PD - pd}{2}\right)^2}$$

Where: t = span length, inches

CD = Drive center distance

PD = Large pitch diameter, inches

pd = Small pitch diameter, inches

Formula 3

$$\text{Deflection force, Min.} = \frac{T_{St} + \left(\frac{t}{L}\right)Y}{16} \quad \text{, lb}$$

Formula 4

$$\text{Deflection force, Max.} = \frac{1.1 \, T_{\text{St}} + \left(\!\!\frac{t}{L}\!\!\right)\! Y}{16} \quad \text{, lb.}$$

Where: $T_{st} = Static tension, pounds$

t = span length, inches

L = belt pitch length, inches

Y = constant from Table 7

III. Belt Tensioning — continued

Shaft Separation: Belt installation tension can be applied directly by exerting a force against either the driveR or driveN shaft in a simple 2 point drive system (see Fig. 6). The resulting belt tension will be accurate as the force applied to the driveR or driveN shaft. This method is considerably easier to perform than the force/deflection method, and in some cases more accurate.




Figure 6 - Shaft Separation

In order to calculate the required shaft separation force, the proper static tension (on a per span basis) should first be determined as previously discussed. This tension value will be present in both belt spans as tension is applied. The angle of the spans with respect to the movable shaft should then be determined. The belt spans should be considered to be vectors (force with direction), and be summed into a single tension vector force (see Fig. 7). Refer to section *VI. Belt Pull* on pages 65 and 66 for further instructions on summing vectors. Contact Gates Application Engineering for assistance if needed.

Idler Force: Belt installation tension can also be applied by exerting a force against an idler sprocket within the system that is used to take up belt slack (see Fig. 8). This force can be applied manually, or with a spring. Either way, the idler should be locked down after the appropriate tension has been applied.




Figure 8 - Idler Force

Calculating the required force will involve a vector analysis as described above in the shaft separation section. Contact Gates Application Engineering for assistance if needed.

Sonic Tension Meter: The Sonic Tension Meter is an electronic device that measures the natural frequency of a free stationary belt span and instantly computes the static belt tension based upon the belt span length, belt width, and belt type. This provides accurate and repeatable tension measurements while using a non-intrusive procedure (the measurement process itself doesn't change the belt span tension). A measurement is made simply by plucking the belt while holding the sensor close to the vibrating belt span.

The unit is a bit larger than a cell phone (6" long x 2" wide x 1" thick) so it can be easily handled. The sensor is about 1/2" in diameter for use in cramped spaces, and the unit is battery operated. The unit measures virtually all types of Light Power & Precision belts.

For additional details, see Gates Publication No. 17898: Sonic Tension Meter Uses Sound Waves to Measure Belt Tension Accurately Every Time.

Contact Gates Application Engineering for further technical details. Contact Gates Customer Service for price and availability.






Figure 7 - Vector Addition

IV. Installation and Take Up

A. Installation Allowance

When designing a drive system for a production product, allowance for belt installation must be built into the system. While specific installation allowances could be published, as they are for larger industrial belt drives, small synchronous drive applications are generally quite diverse making it nearly impossible to arrive at values that apply in all cases. When space is at a premium, the necessary installation allowances should be determined experimentally using actual production parts for the best possible results.

B. Belt Installation

During the belt installation process, it is very important that the belt be fully seated in the sprocket grooves before applying final tension. Serpentine drives with multiple sprockets and drives with large sprockets are particularly vulnerable to belt tensioning problems resulting from the belt teeth being only partially engaged in the sprockets during installation. In order to prevent these problems, the belt installation tension should be evenly distributed to all belt spans by rotating the system by hand. After confirming that belt teeth are properly engaged in the sprocket grooves, belt tension should be re-checked and verified. Failure to do this may result in an under-tensioned condition with the potential for belt ratcheting.

C. Belt Take-Up

Synchronous belt drives generally require little if any tensioning when used in accordance with proper design procedures. A small amount of belt tension decay can be expected within the first several hours of operation. After this time, the belt tension should remain relatively stable.

D. Fixed Center Drives

Designers sometimes attempt to design synchronous belt drive systems without any means of belt adjustment or take up. This type of system is called a Fixed Center Drive. While this approach is often viewed as being economical, and is simple for assemblers, it often results in troublesome reliability and performance problems in the long run.

The primary pitfall in a fixed center design approach is failure to consider the affects of system tolerance accumulation. Belts and sprockets are manufactured with industry accepted production

tolerances. There are limits to the accuracy that the center distance can be maintained on a production basis as well. The potential effects of this tolerance accumulation is as follows:

Low Tension:

Long Belt with Small Sprockets on a Short Center Distance

High Tension:

Short Belt with Large Sprockets on a Long Center Distance.

Belt tension in these two cases can vary by a factor of 3 or more with a standard fiberglass tensile cord, and even more with an aramid tensile cord. This potential variation is great enough to overload bearings and shafting, as well as the belts themselves. The probability of these extremes occurring is a matter of statistics, but however remote the chances may seem, they will occur in a production setting. In power transmission drives, the appearance of either extreme is very likely to impact drive system performance in a negative manner.

The most detrimental aspect of fixed center drives is generally the potentially high tension condition. This condition can be avoided by adjusting the design center distance. A common approach in these designs is to reduce the center distance from the exact calculated value by some small fraction. This results in a drive system that is inherently loose, but one that has much less probability of yielding excessively high shaft loads.

NOTE: This approach should not be used for power transmission drives since the potentially loose operating conditions could result in accelerated wear and belt ratcheting, even under nominal loading.

There are times when fixed center drive designs can't be avoided. In these cases, the following recommendations will maximize the probability of success.

- Do not use a fixed center design for power transmission drives. Consider using a fixed center design only for lightly loaded or motion transfer applications.
- **2.** Do not use a fixed center design for drives requiring high motion quality or registration precision.
- 3. When considering a fixed center design, the center distance must be held as accurately as possible, typically within 0.002" 0.003" (0.05mm 0.08mm). This accuracy often requires the use of stamped steel framework.

- Molding processes do not generally have the capability of maintaining the necessary accuracy.
- 4. Sprockets for fixed center systems should be produced with a machining process for accuracy. Molding and sintering processes are generally not capable of holding the finished O.D. with sufficient accuracy for these systems.
- 5. The performance capabilities of the drive system should be verified by testing belts produced over their full length tolerance range on drive systems representing the full potential center-distance variation. Contact Gates Application Engineering for further details.
- **6.** Contact Gates Application Engineering for design center distance recommendations, and to review the application.

V. Idler Usage

Idlers in synchronous belt drives are commonly used to take up belt slack, apply installation tension or to clear obstructions within a system. While idlers cause additional belt bending, resulting in fatigue, this effect is generally not significant as long as proper design procedures are followed. Synchronous belts elongate very little over time making them relatively maintenance free. All idlers should be capable of being locked down after being adjusted and should require little additional attention. Specific guidelines and recommendations follow in the upcoming paragraphs.

A. Inside/Outside

Inside idlers are generally preferred over backside idlers from a belt fatigue standpoint. Both are commonly used with good success. Inside idlers should be sprockets, but can be flat if the O.D. is equivalent to the pitch diameter of a 40 groove sprocket. Backside idlers should be flat and uncrowned.

B. Tight Side/Slack Side

Idlers should be placed on the slack (or non-load carrying) side if possible. Their affect on belt fatigue is less on the slack side than on the tight (or load carrying) side. If spring loaded idlers are used, they should never be placed on the tight side (see *D. Spring Loaded Idlers*). Also note that drive direction reversal causes the tight and slack spans to reverse, potentially placing the idler on the tight side.



V. Idler Usage — continued

C. Idler Placement

In synchronous belt drives, idlers can be placed nearly anywhere they are needed. Synchronous drives are much less sensitive to idler placement and belt wrap angles than V-belt drives. The designer should be sure that at least 6 belt teeth are in mesh on load carrying sprockets. For every tooth in mesh less than this (with a minimum of 2), 20% of the belt torque rating must be subtracted. In order to minimize the potential for belt ratcheting, each loaded sprocket in the system should also have a wrap angle of at least 60°. If a loaded sprocket has less than 6 teeth in mesh and 60° of wrap, idlers can often be used to improve this condition. Non-loaded idler sprockets do not have tooth meshing or wrap angle restrictions.

D. Spring Loaded Idlers

Using a spring to apply a predetermined force against a tensioning idler to obtain proper belt installation tension is a common practice. The idler is typically locked down after belt installation. This provides a simple and repeatable process that works well in a production setting.

Dynamic spring loaded idlers are generally not recommended for synchronous belt drives. If used, spring-loaded idlers should never be used on the tight (or load carrying) side. Tight side tensions vary with the magnitude and type of load carried by the system. High tight side tensions can overcome the idler spring force allowing the belt to ratchet. In order to prevent this from occurring, an excessively high spring force is required. This high spring force can result in high shaft/bearing loads and accelerated belt wear.

Note that the tight and slack spans shift as the direction of drive rotation reverses. This could place the spring loaded idler on the tight side. For this reason, dynamic spring loaded idlers are never recommended for belt drive applications that reverse rotational direction. Also note that in some cases, drive vibration and harmonic problems may also be encountered with the use of spring loaded idlers.

Dynamic spring loaded idlers can be beneficial in some belt drive systems in that they maintain constant slack side span tension regardless of the magnitude of drive loads, and can actually reduce the potential of belt ratcheting. They can also be beneficial in applications with flexing or changing centers. If dynamic spring loaded idlers are to be used, they should always be used on the slack (or non-load carrying) side of the drive.

E. Size Recommendations

Inside idler sprockets can be used in the minimum recommended size for each particular belt pitch. Inside flat idlers can be used on the tooth side of synchronous belts as long as they are of a diameter equivalent to the pitch diameter of a 40-groove sprocket in the same pitch. Drives with inside flat idlers should be tested, as noise and belt wear may occur.

Flat backside idlers should be used with diameters at least 30% larger than the minimum recommended inside sprocket size.

Table 9 summarizes our idler size recommendations.

Table 9 – Idler Size Recommendations

Belt	Minimum Inside Idler	Minimum Backside Idler	Minimum Inside Flat Idler
MXL	12 grooves	0.50" O.D.	1.00" O.D.
XL	12 grooves	1.00" O.D.	2.50" O.D.
3M HTD®	12 grooves	0.75" O.D.	1.50" O.D.
5M HTD	14 grooves	1.25" O.D.	2.50" O.D.
2MR GT®2	12 grooves	0.50" O.D.	1.00" O.D.
3MR GT 2	12 grooves	0.75" O.D.	1.50" O.D.
5MR GT 2	14 grooves	1.25" O.D.	2.50" O.D.

Contact Gates Application Engineering for additional information.

F. Specifying Shaft Locations in Multipoint Drive Layouts

When collecting geometrical layout data for multiple sprocket drive layouts, it is important to use a standard approach that is readily understood and usable for drive design calculations. This is of particular importance when the data will be provided to Gates Application Engineering for analysis.

2-Point Drive

When working with a simple 2-point drive (driveR/driveN only) it is sufficient to specify the desired distance between shaft centers for belt length calculations.

3-Point Drive

When working with a 3-point drive (driveR/driveN/idler), X-Y coordinates are desirable. It is sufficient, however, to specify desired center distances between each of the three shaft centers to form a triangle. In either case, sprocket/idler movement details for belt tensioning and take-up are also necessary.

Multipoint Drive

When working with a drive system having more than 3 shafts, the geometrical layout data must be collected in terms of X-Y coordinates for analysis. For thos unfamiliar with X-Y coordinates, the X-Y cartesian coordinate system is commonly used in mathematical and engineering calculations and utilizes a horizontal and vertical axis as illustrated in Figure 9.




Figure 9 - X-Y Coordinate Axis

V. Idler Usage — continued

The axes cross at the zero point, or origin. Along the horizontal, or "X" axis, all values to the right of the zero point are positive, and all values to the left of the zero point are negative. Along the vertical, or "Y" axis, all values above the zero point are positive, and all values below the zero point are negative. This is also illustrated in Figure 9 on page 64.

When identifying a shaft center location, each X-Y coordinate is specified with a measurement in the "X" as well as the "Y" direction. This requires a horizontal and vertical measurement for each shaft center in order to establish a complete coordinate. Either English or Metric units of measurement may be used.

A complete coordinate is specified as follows:

(X,Y) where X = measurement along X-axis (horizontal) Y = measurement along Y-axis (vertical)

In specifying X-Y coordinates for each shaft center, the origin (zero point) must first be chosen as a reference. The driveR shaft most often serves this purpose, but any shaft center can be used. Measurements for all remaining shaft centers must be taken from this origin or reference point. The origin is specified as (0,0).

An example layout of a 5-point drive system is illustrated in Figure 10. Here each of the five shaft centers are located and identified on the X-Y coordinate grid.

When specifying parameters for the moveable or adjustable shaft (for belt installation and tensioning), the following approaches are generally used:

Fixed Location: Specify the nominal shaft location coordinate with a movement direction.

Slotted Location: Specify a location coordinate for the beginning of the slot, and a location coordinate for the end of the slot along its path of linear movement.

Pivoted Location: Specify the initial shaft location coordinate along with a pivot point location coordinate and the pivot radius.

Performing belt length and idler movement/positioning calculations by hand can be quite difficult and time consuming. With a complete geometrical drive description, we can make the drive design and layout process quite simple for you. Contact Gates Application Engineering for computer-aided assistance.




Figure 10 - Drive Layout Using X-Y Coordinates

VI. Belt Pull

Synchronous belt drives are capable of exerting lower shaft loads than V-belt drives in some circumstances. If pre-tensioned according to Gates recommendations for a fully loaded steady state condition, synchronous and V-belt drives will generate comparable shaft loads. If the actual torque loads are reduced and the level of pretension remains the same, they will continue to exert comparable shaft loads. In some cases, synchronous belts can be pre-tensioned for less than full loads, under non-steady state conditions. with reasonable results. Reduced pre-tensioning in synchronous belts can be warranted in a system that operated with uniform loads most of the time, but generates peak loads on an intermittent based. While V-belt drives require pre-tensioning based upon peak loads to prevent slippage, synchronous drive pre-tensioning can be based upon lower average loads rather than intermittent peak loads, so long as the belt does not ratchet under the peak loads. When the higher peak loads are carried by the synchronous drive, the belt will self-generate tension as needed to carry the load. The process of self-tensioning results in the belt teeth riding out of the sprocket grooves as the belt enters the driveN sprocket on the slack side, resulting in increased belt tooth and sprocket wear. So long as peak loads occur intermittently and belts do not ratchet, reduced installation tension will result in reduced average belt pull without serious detrimental effects. Synchronous belts generally require less pre-tension than V-belts for the same load. They do not require additional installation tension for belt wrap less than 180 degrees on loaded sprockets and V-belt drives do. In most cases, these factors contribute to lower static and dynamic shaft loads in synchronous belt drives.

Designers often wish to calculate how much force a belt drive will exert on a shafting/bearings/ framework in order to properly design their system. It is difficult to make accurate belt pull calculations because factors such as torque load variation, installation tension and sprocket run-out all have a significant influence. Estimations, however, can be made as follows:

VI. Belt Pull — continued

A. Motion Transfer Drives

Motion transfer drives, by definition do not carry a significant torque load. As a result, the belt pull is dependent only on the installation tension. Because installation tensions are provided on a per-strand basis, the total belt pull can be calculated by vector addition.

B. Power Transmission Drives

Torque load and installation tension both influence the belt pull in power transmission drives. The level of installation tension influences the dynamic tension ratio of the belt spans. The tension ratio is defined as the tight side (or load carrying) tension T_T divided by the slack side (or non-load carrying) tension T_S. Synchronous belt drives are generally pre-tensioned to operate dynamically at a 8:1 tension ratio in order to provide the best possible performance. After running for a short time, this ratio is known to increase somewhat as the belt runs in and seats with the sprockets reducing tension. Formula 5 and Formula 6 can be used to calculate the estimated T_T and T_S tensions assuming a 8:1 tension ratio. T_T and T_S tensions can then be summed into a single vector force and direction.



$$T_T = \frac{2.286(Q)}{Pd}$$
 , lb.

Formula 6

$$T_S = \frac{0.285(Q)}{Pd}$$
 , lb.

Where: $T_T = Tight$ side tension, pounds

 $T_S = Slack$ side tension, pounds

Q = Torque Load, pound inches

Pd = Pitch diameter, inches

If both direction and magnitude of belt pull are required, the vector sum of T_T and T_S can be found by graphical vector addition as shown in Fig. 11. T_T and T_S vectors are drawn parallel to the tight and slack sides at a convenient scale. The magnitude and direction of the resultant vector, or belt pull, can then be measured graphically. The same procedures can be used for finding belt pull on the driveN shaft. This method can also be used for drives using three or more sprockets or idlers.




Figure 11 - Vector Addition




Figure 12 - Vector Sum Correction Factor

For two sprocket drives, belt pull on the driveR and driveN shafts is equal but opposite in direction. For drives using idlers, both magnitude and direction may be different. If only the magnitude of the belt pull is needed in a two sprocket drive, use the following procedure.

- 1. Add T_T and T_S
- Using the value of (D-d)/C for the drive, find the vector sum correction factor using Fig. 12. Or, use the known arc of contact on the small sprocket where:

D = large diameter

d = small diameter

C = center distance

 Multiply the sum of T_T and T_S by the vector sum correction factor to find the vector sum, or belt pull.

For drives using idlers, either use the graphical method or contact Gates Application Engineering for assistance.

C. Registration Drives

Synchronous belt drives used for purposes of accurate registration or synchronization generally require the use of higher than normal installation tensions (see section *III. Belt Tensioning, pages 60-62*). These drives will operate with higher belt pulls than normal power transmission drives. Belt pull values for these types of applications should be verified experimentally, but can be estimated by adding the installation tension in each belt span vectorially.

For guidance in calculating bearing loads, see Bearing Load Calculations on page 98.



VII. Handling And Storage

The following has been condensed from RMA Bulletin No. IP-3-4; "Storage Of Power Transmission Belts".

Recommendations for proper belt storage is of interest to designers as well as to users. Under favorable storage conditions, high quality belts maintain their performance capabilities and manufactured dimensions. Good storage conditions and practices will result in the best value from belt products.

Power transmission belts should ideally be stored in a cool and dry environment. Excess weight against belts resulting in distortion should be avoided. Avoid storing belts in environments that may allow exposure to sunlight, moisture, excessive heat, ozone, or where evaporating solvents or other chemicals are present. Belts have been found to be capable of withstanding storage, without changing significantly, for as long as 8 years at temperatures less than 85°F (30°C) and relative humidity below 70 percent without direct contact with sunlight.

Proper handling of synchronous belts is also important in preventing damage that could reduce their performance capabilities. Synchronous belts should never be crimped or tightly bent. Belts should not be bent tighter than the minimum recommended sprocket size specified for each belt section, or pitch. Belt backside bending should be limited to the values specified in Table 9 on Page 64.

VIII. Special Constructions

In addition to the standard PowerGrip® belt products listed in this catalog, there are many special belts available on a made-to-order basis. These non-standard belts can be helpful when used in unusual applications, or when the designer has special performance requirements. See Table 10 for general made-to-order manufacturing capabilities. Contact Gates Application Engineering for additional information.

	e 10 – Made-To-Order Belt Co	
Type of MTO Belt	Application	Tooth Profiles Available
Nonstock widths and/or lengths with tooling available	When exact length is required	PowerGrip® GT®
High temperature	Dry operation from -40°F to 225°F (-40°C to 107°C)	VVV
Low temperature	Dry operation from -65°F to 175°F (-54°C to 79°C)	
Oil resistant	For excessively oily atmospheres, including immersion in commercial motor oil. Temperature range: dry -40°F to 210°F (-40°C to 99°C)	PowerGrip® HTD®
Static conductive (Static dissipating)	Resistance of 300,000 ohms or less to dissipate static charge	
Nonconductive	When electrical isolation within a system is required. Conductivity properties per customer requirements	
Nonmarking backing	For conveyers or material handling processes	PowerGrip® Timing
Extra-thick rubber backing	For special applications where the belt backing serves a functional purpose	
Ground backing	For sensitive applications requiring minimal vibration from outside idlers	DouggOrio® OT®O/ \$45 V
Alternate tensile cord	For special tensile modulus, bending flexibility or durability requirements	PowerGrip® GT®2/ Micro-V
Special tracking	When belt must track in a particular direction	
Urethane PowerGrip belts	Light loads, appliances, office machinery	
Micro-V backing	Special serpentine drives	

Synchronous Belt Drives – Belt Specifications

General Belt Tolerances

Gates belt length and width tolerances for synchronous belts are based upon industry standard RMA (Rubber Manufacturers Association) tolerances.

Table 11 – Center Distance Tolerances – Single Sided Belts

Belt Len	gth	Center Distanc	e Tolerance
1)	(mm)	(in)	(mm)
10	254	±.008	±.20
10 15	254 381	±.009	±.23
15 20	381 508	±.010	±.25
20 30	508 762	±.012	±.30
30 40	762 1016	±.013	±.33
40 50	1016 1270	±.015	±.38
50 60	1270 1524	±.016	±.41
60 70	1524 1778	±.017	±.43
70 80	1778 2032	±.018	±.46
80 90	2032 2286	±.019	±.48
90 100	2286 2540	±.020	±.51
100 110	2540 2794	±.021	±.53
110 120	2794 3048	±.022	±.56
	10 10 10 15 15 20 20 30 30 40 40 40 50 50 60 60 70 70 80 80 90 100 110 110	10 254 10 254 10 254 15 381 20 508 20 508 30 762 40 1016 40 1016 50 1270 50 1270 60 1524 70 1778 70 1778 80 2032 90 2286 100 2540 110 2794 110 2794	(mm) (in) 10

Table 12 - Center Distance Tolerances - Twin Power Belts

iable 12 – Center Distant	ce loierances – Iwin Power Beits
Belt Length (in)	Tolerance Center Distance (in)
15 to 20	± .020
20.01 to 30	± .024
30.01 to 40	± .026
40.01 to 50	± .030
50.01 to 60	± .032
60.01 to 70	± .034
over 70	To be specified

Table 13 - Belt Width Tolerances - Single Sided & Twin Power Belts

			Belt Length							
(i	Belt Width (in) (mm)			33 in. 38mm) (mm)	33.01 to (839 to 1 (in)	o 66 in. 676mm) (mm)		66 in. 6mm) (mm)		
From To	0.125 0.438	3 11	+0.016 -0.031	+0.4 -0.8	+0.016 -0.031	+0.4 -0.8	-	-		
Over To	0.438 1.500	11 38.1	+0.031	+0.8	+0.031 -0.047	+0.8 -1.2	+0.031	+0.8 -1.2		
Over To	1.500 2.000	38.1 50.8	+0.031	+0.8 -1.2	+0.047 -0.047	+1.2 -1.2	+0.047	+1.2 -1.6		

Table 14 – Belt Width Tolerances – Long-Length Belting

	Belt Width	Tolerence	
All Spiral Cut Belting	+ 0.031"	- 0.047"	
	+0.8mm	-1.2mm	

Table 15 – Overall Belt Thickness Dimensions										
Pitch	Belt	Overall Thickness (ref)								
Code	Pitch	(in)	(mm)							
2MR GT2	2mm	.060	1.52							
3MR GT2	3mm	.095	2.41							
5MR GT2	5mm	.150	3.81							
3M HTD	3mm	.095	2.41							
5M HTD	5mm	.150	3.81							
MXL	.080 in.	.045	1.14							
.0816	.0816 in.	.045	1.14							
XL	.200 in.	.090	2.29							

Table 16 – Overall Belt Thickness Tolerance – Single Sided Belts

Standard	Class 2	Class 1			
±0.015 in.	±0.010 in.	±0.005 in.			
±0.38mm	±0.25mm	±0.13mm			

NOTE: Belts with pitch lengths greater than 5.5 in. (140mm) are furnished with a Class II grind unless otherwise specified. Belts with pitch lengths less than 5.5 in. (140mm) are unground and produced to standard tolerances.

NOTE: A class 1 grind is available at additional cost for finished belts only.

Table 17 – Overall Belt Thickness Dimensions – Twin Power Belts

Pitch	T (in)	W (in) (Reference)
3M GT2	.120 ±.006	.030
5M GT2	.197 ±.007	.045
3M HTD	.126 ±.006	.030
5M HTD	.209 ±.007	.045
XL (.200 in)	.120 ±.007	.020

Synchronous Belt Drives – Sprocket Specifications

Sprocket Specifications = A. Sprocket Diameters

				2mn	ı Pitch S	procket	Diamete	rs — Po	werGrip	® GT®2				
No. of	Diameters	mm (in)	No. of	Diameters	mm (in)									
Grooves	P.D.	0.D.	Grooves	P.D.	0.D.									
12	7.64 0.301	7.13 0.281	42	26.74 1.053	26.23 1.033	72	45.84 1.805	45.33 1.785	102	64.94 2.557	64.43 2.537	132	84.03 3.308	83.53 3.288
13	8.28 0.326	7.77 0.306	43	27.37 1.078	26.87 1.058	73	46.47 1.830	45.97 1.810	103	65.57 2.582	65.06 2.562	133	84.67 3.333	84.16 3.313
14	8.91 0.351	8.40 0.331	44	28.01 1.103	27.50 1.083	74	47.11 1.855	46.60 1.835	104	66.21 2.607	65.70 2.587	134	85.31 3.359	84.80 3.339
15	9.55 0.376	9.04 0.356	45	28.65 1.128	28.14 1.108	75	47.75 1.880	47.24 1.860	105	66.85	66.34 2.612	135	85.94 3.384	85.44 3.364
16	10.19 0.401	9.68 0.381	46	29.28 1.153	28.78 1.133	76	48.38 1.905	47.88 1.885	106	67.48 2.657	66.97 2.637	136	86.58 3.409	86.07 3.389
17	10.82 0.426	10.31 0.406	47	29.92 1.178	29.41 1.158	77	49.02 1.930	48.51 1.910	107	68.12 2.682	67.61 2.662	137	87.22 3.434	86.71 3.414
18	11.46 0.451	10.95 0.431	48	30.56 1.203	30.05 1.183	78	49.66 1.955	49.15 1.935	108	68.75 2.707	68.25 2.687	138	87.85 3.459	87.35 3.439
19	12.10 0.476	11.59 0.456	49	31.19 1.228	30.69 1.208	79	50.29 1.980	49.79 1.960	109	69.39 2.732	68.88 2.712	139	88.49 3.484	87.98 3.464
20	12.73 0.501	12.22 0.481	50	31.83 1.253	31.32 1.233	80	50.93 2.005	50.42 1.985	110	70.03 2.757	69.52 2.737	140	89.13 3.509	88.62 3.489
21	13.37 0.526	12.86 0.506	51	32.47 1.278	31.96 1.258	81	51.57 2.030	51.06 2.010	111	70.66 2.782	70.16 2.762	141	89.76 3.534	89.26 3.514
22	14.01 0.551	13.50 0.531	52	33.10 1.303	32.60 1.283	82	52.20 2.055	51.69 2.035	112	71.30 2.807	70.79 2.787	142	90.40 3.559	89.89 3.539
23	14.64 0.576	14.13 0.556	53	33.74 1.328	33.23 1.308	83	52.84 2.080	52.33 2.060	113	71.94 2.832	71.43 2.812	143	91.04 3.584	90.53 3.564
24	15.28 0.602	14.77 0.582	54	34.38 1.353	33.87 1.333	84	53.48 2.105	52.97 2.085	114	72.57 2.857	72.07 2.837	144	91.67 3.609	91.17 3.589
25	15.92 0.627	15.41 0.607	55	35.01 1.379	34.51 1.359	85	54.11 2.130	53.60 2.110	115	73.21 2.882	72.70 2.862	145	92.31 3.634	91.80 3.614
26	16.55 0.652	16.04 0.632	56	35.65 1.404	35.14 1.384	86	54.75 2.155	54.24 2.135	116	73.85 2.907	73.34 2.887	146	92.95 3.659	92.44 3.639
27	17.19 0.677	16.68 0.657	57	36.29 1.429	35.78 1.409	87	55.39 2.181	54.88 2.161	117	74.48 2.932	73.98 2.912	147	93.58 3.684	93.08 3.664
28	17.83 0.702	17.32 0.682	58	36.92 1.454	36.42 1.434	88	56.02 2.206	55.51 2.186	118	75.12 2.958	74.61 2.938	148	94.22 3.709	93.71 3.689
29	18.46 0.727	17.95 0.707	59	37.56 1.479	37.05 1.459	89	56.66 2.231	56.15 2.211	119	75.76 2.983	75.25 2.963	149	94.86 3.735	94.35 3.715
30	19.10 0.752	18.59 0.732	60	38.20 1.504	37.69 1.484	90	57.30 2.256	56.79 2.236	120	76.39 3.008	75.89 2.988	150	95.49 3.760	94.99 3.740
31	19.74 0.777	19.23 0.757	61	38.83 1.529	38.33 1.509	91	57.93 2.281	57.42 2.261	121	77.03 3.033	76.52 3.013	151	96.13 3.785	95.62 3.765
32	20.37 0.802	19.86 0.782	62	39.47 1.554	38.96 1.534	92	58.57 2.306	58.06 2.286	122	77.67 3.058	77.16 3.038	152	96.77 3.810	96.26 3.790
33	21.01 0.827	20.50 0.807	63	40.11 1.579	39.60 1.559	93	59.21 2.331	58.70 2.311	123	78.30 3.083	77.80 3.063	153	97.40 3.835	96.89 3.815
34	21.65 0.852	21.14 0.832	64	40.74 1.604	40.24 1.584	94	59.84 2.356	59.33 2.336	124	78.94 3.108	78.43 3.088	154	98.04 3.860	97.53 3.840
35	22.28 0.877	21.77 0.857	65	41.38 1.629	40.87 1.609	95	60.48 2.381	59.97 2.361	125	79.58 3.133	79.07 3.113	155	98.68 3.885	98.17 3.865
36	22.92 0.902	22.41 0.882	66	42.02 1.654	41.51 1.634	96	61.12 2.406	60.61 2.386	126	80.21 3.158	79.71 3.138	156	99.31 3.910	98.80 3.890
37	23.55 0.927	23.05 0.907	67	42.65 1.679	42.15 1.659	97	61.75 2.431	61.24 2.411	127	80.85 3.183	80.34 3.163	157	99.95 3.935	99.44 3.915
38	24.19 0.952	23.68 0.932	68	43.29 1.704	42.78 1.684	98	62.39 2.456	61.88 2.436	128	81.49 3.208	80.98 3.188	158	100.59 3.960	100.08 3.940
39	24.83 0.977	24.32 0.957	69	43.93 1.729	43.42 1.709	99	63.03 2.481	62.52 2.461	129	82.12 3.233	81.62 3.213	159	101.22 3.985	100.71 3.965
40	25.46 1.003	24.96 0.983	70	44.56 1.754	44.06 1.734	100	63.66 2.506	63.15 2.486	130	82.76 3.258	82.25 3.238	160	101.86 4.010	101.35 3.990
41	26.10 1.028	25.59 1.008	71	45.20 1.780	44.69 1.760	101	64.30 2.531	63.79 2.511	131	83.40 3.283	82.89 3.263			

See Page 74 for sprocket O.D. tolerances.

Synchronous Belt Drives – Sprocket Specifications

Sprocket Specifications — continued

				3mm Pit	h Sproc	cket Dia	meters –	PowerGr	ip® GT®2	2 and HTD)®			
No. of	Diameters	mm (in)	No. of	Diameters	mm (in)	No. of	Diameters	mm (in)	No. of	Diameters	mm (in)	No. of	Diameters	mm (in)
Grooves	P.D.	0.D.	Grooves	P.D.	0.D.	Grooves	P.D.	0.D.	Grooves	P.D.	0.D.	Grooves	P.D.	0.D.
*12	11.46 .451	10.70 .421	42	40.11 1.579	39.35 1.549	72	68.75 2.707	67.99 2.677	102	97.40 3.835	96.64 3.805	132	126.05 4.963	125.29 4.933
*13	12.41 .489	11.65 .459	43	41.06 1.617	40.30 1.587	73	69.71 2.744	68.95 2.714	103	98.36 3.872	97.60 3.842	133	127.01 5.000	126.25 4.970
*14	13.37 .526	12.61 .496	44	42.02 1.654	41.26 1.624	74	70.66 2.782	69.90 2.752	104	99.31 3.910	98.55 3.880	134	127.96 5.038	127.20 5.008
*15	14.32 .564	13.56 .534	45	42.97 1.692	42.21 1.662	75	71.62 2.820	70.86 2.790	105	100.27 3.948	99.51 3.918	135	128.92 5.075	128.16 5.045
16	15.28 .602	14.52 .572	46	43.93 1.729	43.17 1.699	76	72.57 2.857	71.81 2.827	106	101.22 3.985	100.46 3.955	136	129.87 5.113	129.11 5.083
17	16.23 .639	15.47 .609	47	44.88 1.767	44.12 1.737	77	73.53 2.895	72.77 2.865	107	102.18 4.023	101.42 3.993	137	130.83 5.151	130.07 5.121
18	17.19 .677	16.43 .647	48	45.84 1.805	45.08 1.775	78	74.48 2.932	73.72 2.902	108	103.13 4.060	102.37 4.030	138	131.78 5.188	131.02 5.158
19	18.14 .714	17.38 .684	49	46.79 1.842	46.03 1.812	79	75.44 2.970	74.68 2.940	109	104.09 4.098	103.33 4.068	139	132.74 5.226	131.98 5.196
20	19.10 .752	18.34 .722	50	47.75 1.880	46.99 1.850	80	76.39 3.008	75.63 2.978	110	105.04 4.136	104.28 4.106	140	133.69 5.263	132.93 5.233
21	20.05	19.29 .760	51	48.70 1.917	47.94 1.887	81	77.35 3.045	76.59 3.015	111	106.00 4.173	105.24	141	134.65 5.301	133.89 5.271
22	21.01 .827	20.25 . 7 97	52	49.66 1.955	48.90 1.925	82	78.30 3.083	77.54 3.053	112	106.95 4.211	106.19 4.181	142	135.60 5.339	134.84 5.309
23	21.96 .865	21.20 .835	53	50.61 1.993	49.85 1.963	83	79.26 3.120	78.50 3.090	113	107.91 4.248	107.15 4.218	143	136.55 5.376	135.79 5.346
24	22.92 .902	22.16 .872	54	51.57 2.030	50.81 2.000	84	80.21 3.158	79.45 3.128	114	108.86 4.286	108.10 4.256	144	137.51 5.414	136.75 5.384
25	23.87 .940	23.11 .910	55	52.52 2.068	51.76 2.038	85	81.17 3.196	80.41 3.166	115	109.82 4.324	109.06 4.294	145	138.46 5.451	137.70 5.421
26	24.83 .977	24.07 .947	56	53.48 2.105	52.72 2.075	86	82.12 3.233	81.36 3.203	116	110.77 4.361	110.01 4.331	146	139.42 5.489	138.66 5.459
27	25.78 1.015	25.02 .985	57	54.43 2.143	53.67 2.113	87	83.08 3.271	82.32 3.241	117	111.73 4.399	110.97 4.369	147	140.37 5.527	139.61 5.497
28	26.74 1.053	25.98 1.023	58	55.39 2.181	54.63 2.151	88	84.03 3.308	83.27 3.278	118	112.68 4.436	111.92 4.406	148	141.33 5.564	140.57 5.534
29	27.69 1.090	26.93 1.060	59	56.34 2.218	55.58 2.188	89	84.99 3.346	84.23 3.316	119	113.64 4.474	112.88 4.444	149	142.28 5.602	141.52 5.572
30	28.65 1.128	27.89 1.098	60	57.30 2.256	56.54 2.226	90	85.94 3.384	85.18 3.354	120	114.59 4.511	113.83 4.481	150	143.24 5.639	142.48 5.609
31	29.60 1.165	28.84 1.135	61	58.25 2.293	57.49 2.263	91	86.90 3.421	86.14 3.391	121	115.55 4.549	114.79 4.519	151	144.19 5.677	143.43 5.647
32	30.56 1.203	29.80 1.173	62	59.21 2.331	58.45 2.301	92	87.85 3.459	87.09 3.429	122	116.50 4.587	115.74 4.557	152	145.15 5.715	144.39 5.685
33	31.51 1.241	30.75 1.211	63	60.16 2.369	59.40 2.339	93	88.81 3.496	88.05 3.462	123	117.46 4.624	116.70 4.594	153	146.10 5.752	145.34 5.722
34	32.47 1.278	31.71 1.248	64	61.12 2.406	60.36 2.376	94	89.76 3.534	89.00 3.504	124	118.41 4.662	117.65 4.632	154	147.06 5.790	146.30 5.760
35	33.42 1.316	32.66 1.286	65	62.07 2.444	61.31 2.414	95	90.72 3.572	89.96 3.542	125	119.37 4.699	118.61 4.669	155	148.01 5.827	147.25 5.797
36	34.38 1.353	33.62 1.323	66	63.03 2.481	62.27 2.451	96	91.67 3.609	90.91 3.579	126	120.32 4.737	119.56 4.707	156	148.97 5.865	148.21 5.835
37	35.33 1.391	34.57 1.361	67	63.98 2.519	63.22 2.489	97	92.63 3.647	91.87 3.617	127	121.28 4.775	120.52 4.745	157	149.92 5.903	149.16 5.873
38	36.29 1.429	35.53 1.399	68	64.94 2.557	64.18 2.527	98	93.58 3.684	92.82 3.654	128	122.23 4.812	121.47 4.782	158	150.88 5.940	150.12 5.910
39	37.24 1.466	36.48 1.436	69	65.89 2.594	65.13 2.564	99	94.54 3.722	93.78 3.692	129	123.19 4.850	122.43 4.820	159	151.83 5.978	151.07 5.948
40	38.20 1.504	37.44 1.474	70	66.85 2.632	66.09 2.602	100	95.49 3.760	94.73 3.730	130	124.14 4.887	123.38 4.857	160	152.79 6.015	152.03 5.985
41	39.15 1.541	38.39 1.511	71	67.80 2.669	67.04 2.639	101	96.45 3.797	95.69 3.767	131	125.10 4.925	124.34 4.895			

*Denotes subminimal diameters not recommended for PowerGrip® GT®2.

NOTE: See Page 74 for sprocket O.D. tolerances.

NOTE: PowerGrip® GT®2 and PowerGrip HTD sprockets are incompatible.

Sprocket Specifications — continued

				5mm Pit	ch Sproc	ket Dia	meters –	PowerGr	ip® GT®2	2 and HTD)®			
No. of	Diameters	mm (in)	No. of	Diameters	mm (in)	No. of	Diameters	mm (in)	No. of	Diameters	mm (in)	No. of	Diameters	mm (in)
Grooves	P.D.	0.D.	Grooves	P.D.	0.D.	Grooves	P.D.	0.D.	Grooves	P.D.	0.D.	Grooves	P.D.	0.D.
*14	22.28 .877	21.14 .832	44	70.03 2.757	68.89 2.712	74	117.77 4.637	116.63 4.592	104	165.52 6.517	164.38 6.472	134	213.27 8.396	212.13 8.351
*15	23.87 .940	22.73 .895	45	71.62 2.820	70.48 2.775	75	119.37 4.699	118.23 4.654	105	167.11 6.579	165.97 6.534	135	214.86 8.459	213.72 8.414
*16	25.46 1.003	24.32 .958	46	73.21 2.882	72.07 2.837	76	120.96 4.762	119.82 4.717	106	168.70 6.642	167.56 6.597	136	216.45 8.522	215.31 8.477
*17	27.06 1.065	25.92 1.020	47	74.80 2.945	73.66 2.900	77	122.55 4.825	121.41 4.780	107	170.30 6.705	169.16 6.660	137	218.04 8.584	216.90 8.539
18	28.65 1.128	27.51 1.083	48	76.39 3.008	75.25 2.963	78	124.14 4.887	123.00 4.842	108	171.89 6.767	170.75 6.722	138	219.63 8.647	218.49 8.602
19	30.24 1.191	29.10 1.146	49	77.99 3.070	76.85 3.025	79	125.73 4.950	124.59 4.905	109	173.48 6.830	172.34 6.785	139	221.23 8.710	220.09 8.665
20	31.83 1.253	30.69 1.208	50	79.58 3.133	78.44 3.088	80	127.32 5.013	126.18 4.968	110	175.07 6.893	173.93 6.848	140	222.82 8.772	221.68 8.727
21	33.42 1.316	32.28 1.271	51	81.17 3.196	80.03 3.151	81	128.92 5.075	127.78 5.030	111	176.66 6.955	175.52 6.910	141	224.41 8.835	223.27 8.790
22	35.01 1.379	33.87 1.334	52	82.76 3.258	81.62 3.213	82	130.51 5.138	129.37 5.093	112	178.25 7.018	177.11 6.973	142	226.00 8.898	224.86 8.853
23	36.61 1.441	35.47 1.396	53	84.35 3.321	83.21 3.276	83	132.10 5.201	130.96 5.156	113	179.85 7.081	178.71 7.036	143	227.59 8.960	226.45 8.915
24	38.20 1.504	37.06 1.459	54	85.94 3.384	84.80 3.339	84	133.69 5.263	132.55 5.218	114	181.44 7.143	180.30 7.098	144	229.18 9.023	228.04 8.978
25	39.79 1.566	38.65 1.521	55	87.54 3.446	86.40 3.401	85	135.28 5.326	134.14 5.281	115	183.03 7.206	181.89 7.161	145	230.77 9.086	229.63 9.041
26	41.38 1.629	40.24 1.584	56	89.13 3.509	87.99 3.464	86	136.87 5.389	135.73 5.344	116	184.62 7.268	183.48 7.223	146	232.37 9.148	231.23 9.103
27	42.97 1.692	41.83 1.647	57	90.72 3.572	89.58 3.527	87	138.46 5.451	137.32 5.406	117	186.21 7.331	185.07 7.286	147	233.96 9.211	232.82 9.166
28	44.56 1.754	43.42 1.709	58	92.31 3.634	91.17 3.589	88	140.06 5.514	138.92 5.469	118	187.80 7.394	186.66 7.349	148	235.55 9.274	234.41 9.229
29	46.15 1.817	45.01 1.772	59	93.90 3.697	92.76 3.652	89	141.65 5.577	140.51 5.532	119	189.39 7.456	188.25 7.411	149	237.14 9.336	236.00 9.291
30	47.75 1.880	46.61 1.835	60	95.49 3.760	94.35 3.715	90	143.24 5.639	142.10 5.594	120	190.99 7.519	189.85 7.474	150	238.73 9.399	237.59 9.354
31	49.34 1.942	48.20 1.897	61	97.08 3.822	95.94 3.777	91	144.83 5.702	143.69 5.657	121	192.58 7.582	191.44 7.537	151	240.32 9.462	239.18 9.417
32	50.93 2.005	49.79 1.960	62	98.68 3.885	97.54 3.840	92	146.42 5.765	145.28 5.720	122	194.17 7.644	193.03 7.599	152	241.92 9.524	240.78 9.479
33	52.52 2.068	51.38 2.023	63	100.27 3.948	99.13 3.903	93	148.01 5.827	146.87 5.782	123	195.76 7.707	194.62 7.662	153	243.51 9.587	242.37 9.542
34	54.11 2.130	52.97 2.085	64	101.86 4.010	100.72 3.965	94	149.61 5.890	148.47 5.845	124	197.35 7.770	196.21 7.725	154	245.10 9.650	243.96 9.605
35	55.70 2.193	54.56 2.148	65	103.45 4.073	102.31 4.028	95	151.20 5.953	150.06 5.908	125	198.94 7.832	197.80 7.787	155	246.69 9.712	245.55 9.667
36	57.30 2.256	56.16 2.211	66	105.04 4.136	103.90 4.091	96	152.79 6.015	151.65 5.970	126	200.54 7.895	199.40 7.850	156	248.28 9.775	247.14 9.730
37	58.89 2.318	57.75 2.273	67	106.63 4.198	105.49 4.153	97	154.38 6.078	153.24 6.033	127	202.13 7.958	200.99 7.913	157	249.87 9.838	248.73 9.793
38	60.48 2.381	59.34 2.336	68	108.23 4.261	107.09 4.216	98	155.97 6.141	154.83 6.096	128	203.72 8.020	202.58 7.975	158	251.46 9.900	250.32 9.855
39	62.07 2.444	60.93 2.399	69	109.82 4.324	108.68 4.279	99	157.56 6.203	156.42 6.158	129	205.31 8.083	204.17 8.038	159	253.06 9.963	251.92 9.918
40	63.66 2.506	62.52 2.461	70	111.41 4.386	110.27 4.341	100	159.15 6.266	158.01 6.221	130	206.90 8.146	205.76 8.101	160	254.65 10.026	253.51 9.981
41	65.25 2.569	64.11 2.524	71	113.00 4.449	111.86 4.404	101	160.75 6.329	159.61 6.284	131	208.49 8.208	207.35 8.163			
42	66.85 2.632	65.71 2.587	72	114.59 4.511	113.45 4.466	102	162.34 6.391	161.20 6.346	132	210.08 8.271	208.94 8.226			
43	68.44 2.694	67.30 2.649	73	116.18 4.574	115.04 4.529	103	163.93 6.454	162.79 6.409	133	211.68 8.334	210.54 8.289			

*Denotes subminimal diameters not recommended for PowerGrip® GT®2.

NOTE: See Page 74 for sprocket O.D. tolerances.

Sprocket Specifications — continued

					MXL	(.080 in	Pitch P	ulley Dia	meters					
No. of	Dimer (iı		No. of		nsions n)	No. of		nsions n)	No. of	Dimer (ii		No. of		nsions in)
Grooves	P.D.	0.D.	Grooves	P.D.	0.D.	Grooves	P.D.	0.D.	Grooves	P.D.	0.D.	Grooves	P.D.	0.D.
10	.255	.235	39	.993	.973	68	1.731	1.711	97	2.470	2.450	126	3.209	3.189
11	.280	.260	40	1.019	.999	69	1.757	1.737	98	2.496	2.476	127	3.234	3.214
12	.306	.286	41	1.044	1.024	70	1.783	1.763	99	2.521	2.501	128	3.259	3.239
13	.331	.311	42	1.070	1.050	71	1.808	1.788	100	2.546	2.526	129	3.285	3.265
14	.357	.337	43	1.095	1.075	72	1.833	1.813	101	2.572	2.552	130	3.310	3.290
15	.382	.362	44	1.120	1.100	73	1.859	1.839	102	2.597	2.577	131	3.336	3.316
16	.407	.387	45	1.146	1.126	74	1.884	1.864	103	2.623	2.603	132	3.361	3.341
17	.433	.413	46	1.171	1.151	75	1.910	1.890	104	2.648	2.628	133	3.387	3.367
18	.458	.438	47	1.197	1.177	76	1.935	1.915	105	2.674	2.654	134	3.412	3.392
19	.484	.464	48	1.222	1.202	77	1.961	1.941	106	2.699	2.679	135	3.438	3.418
20	.509	.489	49	1.248	1.228	78	1.986	1.966	107	2.725	2.705	136	3.463	3.443
21	.535	.515	50	1.273	1.253	79	2.012	1.992	108	2.750	2.730	137	3.489	3.469
22	.560	.540	51	1.299	1.279	80	2.037	2.017	109	2.776	2.756	138	3.514	3.494
23	.586	.566	52	1.324	1.304	81	2.063	2.043	110	2.801	2.781	139	3.540	3.520
24	.611	.591	53	1.350	1.330	82	2.088	2.068	111	2.827	2.807	140	3.565	3.545
25	.637	.617	54	1.375	1.355	83	2.114	2.094	112	2.852	2.832	141	3.591	3.571
26	.662	.642	55	1.401	1.381	84	2.139	2.119	113	2.878	2.858	142	3.616	3.596
27	.687	.667	56	1.426	1.406	85	2.165	2.145	114	2.903	2.887	143	3.641	3.621
28	.713	.693	57	1.451	1.431	86	2.190	2.170	115	2.928	2.908	144	3.667	3.647
29	.738	.718	58	1.477	1.457	87	2.215	2.195	116	2.954	2.934	145	3.692	3.672
30	.764	.744	59	1.502	1.482	88	2.241	2.221	117	2.979	2.959	146	3.718	3.698
31	.789	.769	60	1.528	1.508	89	2.266	2.246	118	3.005	2.985	147	3.743	3.723
32	.815	.795	61	1.553	1.533	90	2.292	2.272	119	3.030	3.010	148	3.769	3.749
33	.840	.820	62	1.579	1.559	91	2.317	2.297	120	3.056	3.036	149	3.794	3.774
34	.866	.846	63	1.604	1.584	92	2.343	2.323	121	3.081	3.061	150	3.820	3.800
35 36 37 38	.891 .917 .942 .968	.871 .897 .922 .948	64 65 66 67	1.630 1.655 1.681 1.706	1.610 1.635 1.661 1.686	93 94 95 96	2.368 2.394 2.419 2.445	2.348 2.374 2.399 2.425	122 123 124 125	3.107 3.132 3.158 3.183	3.087 3.112 3.138 3.163			

NOTE: See Page 74 for sprocket O.D. tolerances.

					XL (.200 in)	Pitch Pu	lley Diam	eters					
No. of	Dimer (i	nsions n)	No. of	Dimei (i	nsions n)	No. of		nsions n)	No. of	Dimer (iı		No. of		nsions n)
Grooves	P.D.	0.D.	Grooves	P.D.	0.D.									
10 11 12 13 14	.637 .700 .764 .828 .891	.617 .680 .744 .808 .871	33 34 35 36 37	2.101 2.165 2.228 2.292 2.355	2.081 2.145 2.208 2.272 2.335	56 57 58 59 60	3.565 3.629 3.692 3.756 3.820	3.545 3.609 3.672 3.736 3.800	79 80 81 82 83	5.029 5.093 5.157 5.220 5.284	5.009 5.073 5.137 5.200 5.264	102 103 104 105 106	6.494 6.557 6.621 6.685 6.748	6.474 6.537 6.601 6.665 6.728
15 16 17 18 19	.955 1.019 1.082 1.146 1.210	.935 .999 1.062 1.126 1.190	38 39 40 41 42	2.419 2.483 2.546 2.610 2.674	2.399 2.463 2.526 2.590 2.654	61 62 63 64 65	3.883 3.947 4.011 4.074 4.138	3.863 3.927 3.991 4.054 4.118	84 85 86 87 88	5.348 5.411 5.475 5.539 5.602	5.328 5.391 5.455 5.519 5.582	107 108 109 110 111	6.812 6.875 6.939 7.003 7.066	6.792 6.855 6.919 6.983 7.046
20 21 22 23 24	1.273 1.337 1.401 1.464 1.528	1.253 1.317 1.331 1.444 1.508	43 44 45 46 47	2.737 2.801 2.865 2.928 2.992	2.717 2.781 2.845 2.908 2.972	66 67 68 69 70	4.202 4.265 4.329 4.393 4.456	4.182 4.245 4.309 4.373 4.436	89 90 91 92 93	5.666 5.730 5.793 5.857 5.921	5.646 5.710 5.773 5.837 5.901	112 113 114 115 116	7.130 7.194 7.257 7.321 7.385	7.110 7.174 7.237 7.301 7.365
25 26 27 28 29	1.592 1.655 1.719 1.783 1.846	1.572 1.635 1.699 1.763 1.826	48 49 50 51 52	3.056 3.119 3.183 3.247 3.310	3.086 3.099 3.163 3.227 3.290	71 72 73 74 75	4.520 4.584 4.647 4.711 4.775	4.500 4.564 4.627 4.691 4.755	94 95 96 97 98	5.984 6.048 6.112 6.175 6.239	5.964 6.028 6.092 6.155 6.219	117 118 119 120	7.448 7.512 7.576 7.639	7.428 7.492 7.556 7.619
30 31 32	1.910 1.974 2.037	1.890 1.954 2.017	53 54 55	3.474 3.438 3.501	3.354 3.418 3.481	76 77 78	4.838 4.902 4.966	4.818 4.882 4.946	99 100 101	6.303 6.366 6.430	6.283 6.346 6.410			

NOTE: See Page 74 for sprocket O.D. tolerances.



Sprocket Specifications — continued

The drive selection procedure for .0816 in. pitch drives is the same as for MXL (0.080 in.) pitch drives and uses the MXL torque ratings.

				.081	in. Pitc	h Pulley	Diamete	ers (For I	leoprene	Belts)				
No. of		nsions n)	No. of	Dimer (i	nsions n)	No. of		nsions n)	No. of		nsions n)	No. of		nsions in)
Grooves	P.D.	0.D.	Grooves	P.D.	0.D.	Grooves	P.D.	0.D.	Grooves	P.D.	0.D.	Grooves	P.D.	0.D.
10	.260	.240	39	1.013	.993	68	1.766	1.746	97	2.519	2.499	126	3.273	3.253
11	.286	.266	40	1.039	1.019	69	1.792	1.772	98	2.546	2.526	127	3.299	3.279
12	.312	.292	41	1.065	1.045	70	1.819	1.799	99	2.571	2.551	128	3.324	3.304
13	.338	.318	42	1.091	1.071	71	1.845	1.825	100	2.597	2.577	129	3.351	3.331
14	.364	.344	43	1.117	1.097	72	1.870	1.850	101	2.623	2.603	130	3.376	3.346
15	.390	.370	44	1.142	1.122	73	1.896	1.876	102	2.649	2.629	131	3.403	3.383
16	.415	.395	45	1.169	1.149	74	1.922	1.902	103	2.675	2.655	132	3.428	3.408
17	.442	.422	46	1.194	1.174	75	1.948	1.928	104	2.701	2.681	133	3.455	3.435
18	.467	.447	47	1.221	1.201	76	1.974	1.954	105	2.727	2.707	134	3.480	3.460
19	.494	.474	48	1.246	1.226	77	2.000	1.980	106	2.753	2.733	135	3.507	3.487
20	.519	.499	49	1.273	1.253	78	2.026	2.006	107	2.780	2.760	136	3.532	3.512
21	.546	.526	50	1.298	1.278	79	2.052	2.032	108	2.805	2.785	137	3.559	3.539
22	.571	.551	51	1.325	1.305	80	2.078	2.058	109	2.832	2.812	138	3.584	3.564
23	.598	.578	52	1.350	1.330	81	2.104	2.084	110	2.857	2.837	139	3.611	3.591
24	.623	.603	53	1.377	1.357	82	2.130	2.110	111	2.884	2.864	140	3.636	3.616
25	.650	.630	54	1.403	1.383	83	2.156	2.136	112	2.909	2.889	141	3.663	3.643
26	.675	.655	55	1.429	1.409	84	2.182	2.162	113	2.936	2.916	142	3.688	3.643
27	.701	.681	56	1.455	1.435	85	2.208	2.188	114	2.961	2.941	143	3.714	3.694
28	.727	.707	57	1.480	1.460	86	2.234	2.214	115	2.987	2.967	144	3.740	3.720
29	.753	.733	58	1.506	1.486	87	2.259	2.239	116	3.013	3.993	145	3.766	3.746
30	.779	.759	59	1.532	1.512	88	2.286	2.266	117	3.039	3.019	146	3.792	3.772
31	.805	.785	60	1.559	1.539	89	2.311	2.291	118	3.065	3.045	147	3.818	3.798
32	.831	.811	61	1.584	1.564	90	2.338	2.318	119	3.091	3.071	148	3.844	3.824
33	.857	.837	62	1.611	1.591	91	2.363	2.343	120	3.117	3.097	149	3.870	3.850
34	.883	.863	63	1.636	1.616	92	2.390	2.370	121	3.143	3.123	150	3.896	3.876
35 36 37 38	.909 .935 .961 .987	.889 .915 .941 .967	64 65 66 67	1.663 1.688 1.715 1.740	1.643 1.668 1.695 1.720	93 94 95 96	2.415 2.442 2.467 2.494	2.395 2.422 2.447 2.474	122 123 124 125	3.169 3.195 3.221 3.247	3.149 3.175 3.201 3.227			

NOTE: .0816 pitch belt drives are not a direct replacement for urethane 40 diametral pitch (40DP) drives. Pulley 0.D.'s must be in accordance with the above dimensions for proper belt-to-pulley fit with neoprene belts.

NOTE: See Page 74 for Pulley O.D. tolerances.

Sprocket Specifications — continued

B. General Tolerances

Gates sprockets are precision made to close tolerances for the best possible performance. Sprockets and bar stock included in this catalog are intended to be used primarily for prototype work. Gates can supply made to order sprockets in a wide range of materials. Gates Application Engineering is able to assist in sprocket design. General tolerances are included in the following tables to assist the designer.

Table 18 – Sprocket O.D. Tol	OKOHOOO

5	Sprocket O	.D.	Sprocket OD.	Tolerances
(in)	(mm)	(in)	(mm)
Up to	1.000	25.4	+.002000	+.0500
Over To	1.000 2.000	25.4 50.8	+.003000	+.0800
Over To	2.000 4.000	50.8 101.6	+.004000	+.1000
Over To	4.000 7.000	101.6 177.8	+.005000	+.1300
Over To	7.000 12.000	177.8 304.8	+.006000	+.1500
Over To	12.000 20.000	304.8 508.0	+.007000	+.1800
Over	20.000	508.0	+.008000	+.2000

Eccentricity: The allowable amount of radial runout from the sprocket bore to the O.D. is shown in Table 19.

Table 19 – Sprocket Run Out

	side neter	Total Run Out Total Indicator Reading				
(in)	(mm)	(in)	(mm)			
Up to 2	50	0.0025	0.06			
Over 2 To 4	50 100	0.003	0.08			
Over 4 To 8	100 200	0.004	0.10			
Over 8	200	.005 per inch 0.D. over 8 "	.013 per mm 0.D. over 200 mm			
		, ,	eed face diameter erance)			

Table 20 – Bore Tolerance for MPB Sprockets

Bore)	Bore To	lerance
(in)	(mm)	(in)	(mm)
Up to 1.000	25.4	+.0010000	+.025000
Over 1.000		+.0015000	+.038000
To 2.000	50.8		

Pitch Accuracy: Adequate pitch to pitch accuracy (center of one groove to center of adjacent groove) is generally more difficult to achieve with molded sprockets than with machined sprockets. Recommended tolerances are listed in Table 21.

lal	pie 21	– Spr	ocker	Pitch	ACCU	racy	
F	Pulley O.I	D.		to Pitch iation	Accumulative over 90°		
(r	nm)	(in)	(in)	(mm)	(in)	(mm)	
Jp to	25.40	1.000	±.001	±0.025	±.0025	±0.064	
Over To	25.40 50.80	1.000 2.000	±.001	±0.025	±.0035	±0.081	

64 50.80 2.000 ±.001 ±0.025 | ±.0045 ±0.114 Over 101.60 4.000 To Over 101.60 4 000 ±.001 ±0.025 ±.0050 ± 0.127 177.80 7.000 Over 177 80 7.000 $\pm .001$ ±0.025 $\pm .0060$ ± 0.152 304.80 12.000 304.80 12.000 ±0.025 ±0.165 Over 508.00 20.000 Over 508.00 20.000 ±.001 ±0.025 | ±.0075 ±0.191

Helix Angle: Grooves should be parallel to the axis of the bore within 0.001 (0.025mm) per inch (25.4mm) of sprocket groove face width.

Draft: The maximum permissible draft on the groove form is 0.001 (0.025mm) per inch (25.4mm) of face width and must not exceed the 0.D. tolerance.

Parallelism: The bore of the sprocket is to be perpendicular to the vertical faces of the sprocket within 0.001 (0.025mm) per inch (25.4mm) of diameter with a maximum of 0.020 (0.51mm) total indicator reading.

Balancing: Balancing is often not required on machined metal sprockets. All sprockets should be statically balanced to 1/8 oz. (3.5 grams) in all sizes. Drives exceeding 6500 ft./min. (33 m/s) may require special materials, and should be dynamically balanced to 1/4 oz-in. (1.78 newton millimeters)

Production sprockets should be produced as closely to these tolerances as possible to maximize drive performance.

Sprocket Specifications — continued

C. Groove Specifications

Accurate reproduction of the correct sprocket groove profile in production sprockets is essential in obtaining the full performance capabilities of the drive system. The correct groove profile for a sprocket changes as the number of grooves changes. Gates can assist the designer with sprocket groove profile data. Data can be furnished in the following forms:

Master Profile: A scaled line drawing of the ideal groove profile with tolerance bands plotted on dimensionally stable translucent material. Suitable for groove inspection purposes on an optical comparitor.

Dimensioned Profile Drawing: A line drawing of the ideal groove profile with all arcs and radii defined. Suitable for mold design.

Digitized Points: A series of X and Y coordinates defining the ideal groove profile. Available in printed form or in a data file. Suitable for mold design.

Some sprocket groove profile data is proprietary and can be furnished only to Gates licensees. Check with Gates Application Engineering for availability.

Tolerancing/Inspection Procedure: A typical sprocket groove tolerance band is illustrated in Fig. 13. Groove inspections must by made on an optical comparitor at a specified magnification. The actual sprocket groove profile must fit within the specified tolerance bands without any sharp transitions or under cuts.






Figure 13

D. Flange Design and Face Width Guidelines

Flanging Guidelines



Face Width Guidelines






Table 22 Nominal Flange Dimensions for Molding, Sintering, Casting, etc.

Belt		mum Height	Nominal Flange Height			
Section	(in)	(mm)	(in)	(mm)		
MXL	0.040	_	0.050	-		
XL	0.060	_	0.080	-		
2MR	0.043	1.10	0.059	1.50		
3M&3MR	0.067	1.70	0.098	2.50		
5M&5MR	0.091	2.30	0.150	3.80		

Table 23

Additional amount of Face Width recommended over Nominal Belt Width (Add Table Values to Nominal Belt Width for Nominal Face Width)

Belt		Face Width Inged	Nominal Face Width Flanged			
Section	(in)	(mm)	(in)	(mm)		
MXL	+0.125	-	+0.040	_		
XL	+0.190	_	+0.060	_		
2MR	+0.118	+3.00	+0.039	+1.00		
3M&3MR 5M&5MR	+0.157 +0.197	+4.00 +5.00	+0.049 +0.059	+1.25 +1.50		

Sprocket Materials

There are a wide variety of materials and manufacturing processes available for the manufacture of synchronous belt sprockets. In selecting an appropriate material and production process, the designer should consider dimensional accuracy, material strength, durability and production quantity. Some broad guidelines and recommendations are as follows:

A. Machining:

Excellent dimensional accuracy. Economical for low to moderate production quantities.

Typical Materials:

Steel - Excellent Wear Resistance

Aluminum – Good Wear Resistance; sprockets for power transmission drives should be hard anodized

B. Powdered Metal And Die Casting:

Good dimensional accuracy. Economical for moderate to high production quantities.

Typical Materials:

Sintered Iron – Excellent Wear Resistance

Sintered Aluminum – Good Wear Resistance; Light Weight and Corrosion Resistant

Zinc Die Cast – Good Wear Resistance

C. Plastic Molding:

Good dimensional accuracy. Economical for high production quantities. Best suited for light to moderate torque loads. Fiber loading improves overall material strength and dimensional stability. However, increased belt wear can result from the presence of sharp abrasive fiber ends on the finished surfaces.

Assistance with total drive system design is available. Contact Gates Application Engineering for assistance with sprocket design, material selection, manufacturing and sourcing, etc.

Note: For non-standard sprocket designs, contact Gates Made-To-Order Metals Team at (800)709-6001.



For information on additional Polyflex JB cross sections, see the Heavy Duty Drive Design Manual 14995-A.

An innovative product developed by Gates, Polyflex JB Belts provide more load-carrying capacity at higher speeds on precision applications than any other V-belt drive. "High power density" puts more power in small spaces.

- Unique construction and 60° angle combine to make Polyflex JB the highest capacity V-belt drive available on comparable diameters
- High modulus, high coefficient of friction polyurethane compound resists fatigue, wear, ozone and most environmental conditions.
- Superior adhesion of tensile cords and specially compounded polyurethane for high fatigue resistance and long belt life
- Precision cast and ground profile for dimensional accuracy and extremely smooth operation
- 60° angle provides greater undercord support to the tensile cord and distributes the load more evenly
- Small mass and large power capacity make Polyflex JB ideal for high speed drives
- Individual belts are joined for greater stability
- Ribbed construction to relieve bending stress on small sheaves and provide lateral rigidity



Polyflex JB Belts




Figure 14

Table 24 — 3M & 5M Polyflex JB Reference Dimensions

Cross	Nomi Stra Spacin	nd	Nomina Wid (b _b	th	Nominal Thickness (h _g)		
Section	(mm)	(in)	(mm)	(in)	(mm)	(in)	
3M							
2 Belt Strands	3.3	0.13	6.4	0.25	2.3	0.09	
3 Belt Strands	3.3	0.13	9.7	0.38	2.3	0.09	
5M							
2 Belt Strands 3 Belt Strands	5.3 5.3	0.21	9.9 15.2	0.39	3.30	0.13	
Strailus	0.5	0.21	10.2	0.00	3.30	0.13	

The Polyflex JB Belt is designated by a four-part symbol consisting of: (1) the number of belt strands; (2) the cross section; (3) the effective belt length, and (4) the JB or joined band belt construction.

For example, the belt designation 3/5M1000JB represents:

- 1. A belt consisting of 3 individual belt strands joined together
- 2. A 5mm top width for each belt strand
- 3. An effective length of 1000 mm
- 4. A Joined Band (JB) belt construction

Polyurethane Construction

Gates Polyflex JB V-belts are manufactured using specially formulated polyurethane compounds which have a higher coefficient of friction than rubber compounds. Because of the higher coefficient of friction, less wedging action between the belt and the sheave is required. This increased tractive action permits the sheave angle to be increased. The benefits of this feature are discussed in the 60° Angle section on the next page.

Polyurethane has excellent abrasion resistance. As the sheave and belt wear, the belt seats deeper into the sheave groove, contributing to tension decay. This high abrasion resistance feature can mean less frequent belt retensioning. Additional information on abrasion resistance and drives operating in hostile surroundings is provided in the 60° Angle section below and section E. Operating Environments on Page 91.

Polyflex JB belts provide excellent resistance to many chemicals, including some acids and petroleum distillates. However, any chemical or liquid can reduce the coefficient of friction, resulting in excessive belt slipping. Liquids act as lubricants that "grease" the belt, reducing the friction needed for power transmission. Do not use Polyflex JB belts in an environment where the belt is submerged or where liquid in any form can get into the drive.

Polyurethane Construction – continued

If the Polyflex JB belt drive is exposed to liquids that can reduce the coefficient of friction, the drive should be completely enclosed or shielded to prevent slipping problems.

Polyurethane also has a much higher compression modulus (i.e., ability to withstand high compressive forces), which permits it to effectively support the tensile cord even when the amount of material is reduced. This allows use of the 60° angle which has 30% less material in the bottom (or compression) part of the belt, compared to a conventional 36° angle belt of the same top width. See Fig. 15.




Figure 15 - 36° and 60° Systems

Benefits of 60° Design Angle

Fig. 16 shows the 60° angle sheave groove provides more support to the tensile cord than the 36° angle sheave groove. This additional undercord support reduces differential tensile cord tension caused when the center tensile cords relax due to the belt collapsing under heavy loading. Differential tensile cord tension means that the cords located at the belt edge have a higher tension than the cords in the belt center, as illustrated in Fig. 17. Tension variation reduces belt performance and horsepower capacity, since all the tensile cords do not share the applied load equally. Therefore, the 60° Polyflex JB system permits overall higher horsepower load carrying capability.




Figure 16 – Increase in cordline support in 60° sheave




Figure 17 – Differential tensile cord tension

The reduced cross-sectional area and lighter polyurethane material combine together to help reduce both bending and centrifugal tension. Bending and centrifugal tension decrease the allowable working tension. Since bending and centrifugal tension are lower for Polyflex JB belts, more effective tension is available for useful work, resulting in higher horsepower ratings.


Initial reduction of operating tension in a V-belt is the result of the belt seating in the sheave groove while operating under a load. The belt effectively runs on a smaller diameter because of seating in and results in a tension loss that requires belt takeup or retensioning. With the 60° Polyflex JB system, longer running time is possible before takeup is required.

The amount a V-belt can seat in the sheave and lose operating tension depends on these factors:

- (1) Abrasion resistance of the belt.
- (2) Abrasive effect of dust or dirt on the sheave groove sidewall.
- (3) Compression modulus (permanent compression set, a stress/time phenomenon, causes tension decay).

Items (1) and (3) above were discussed in the first part of this section under the Polyurethane heading. To briefly review, a high abrasion-resistant material in the belt and a high compression modulus mean less belt tension deterioration.

However, if some belt and sheave wear does occur, the effect on seating in the groove is less for the 60° angle compared to the 36° angle. Any seating due to wear is only 2/3 as great in the Polyflex JB 60° angle as the same wear in a conventional 36° sheave angle. This is illustrated in Fig. 18.



- A Equal wear on 36° and 60° Sheave Groove
- a Distance Belt Seats in 60° Groove Because of Wear A

Figure 18 – Seating in 60° and 36° Sheave Grooves

In summary, three characteristics of the Polyflex JB belt in the 60° angle sheave -- abrasion resistance, high compression modulus and less movement in the sheave groove (if wear does occur) -- all mean less tension decay. For a Polyflex JB drive, the result is a reduced frequency of retensioning.

Advantages of Joined Construction

The actual size of a Polyflex JB belt is relatively small when compared to a conventional V-belt. Small belts, just by their nature, have a slightly lower torsional and lateral rigidity. Subsequently, there is a possibility of turning over (Fig. 19) when subjected to a misalignment, power surge or vibrations at or near its natural frequency. To prevent such stability problems, the belt is constructed with the overcord connected or "joined" together as shown in Fig. 20. Joining the strands limits the possibility of a belt turning over on properly maintained drives when subjected to various types of load fluctuations and vibrations. The ribbed overcord of the belt also helps increase torsional and lateral rigidity and increases belt flexibility.




Figure 19 — Turned Over Belt




Figure 20 - Polyflex JB

Polyflex JB belts are manufactured with either two, three, four or five belt strands joined together. Any combination of Polyflex JB belts can be used on a single drive in matched sets. For example, if six belts are needed to transmit a load, matched sets of two joined belts with three strands in each belt would work as well as matched sets of three belts with two strands in each belt (see Fig. 21).




Figure 21 - Joined Belt Combinations

Matched Sets

When a Polyflex JB drive requires more than 5 strands, matched sets of belts must be used. A matched set of Polyflex JB belts is factory measured and tied together. The belts are measured and grouped within various length ranges. On multiple belt drives (more than 5 strands) this assures that each belt shares its proportion of the load being transmitted. Contact Gates Customer Service for availability.

Standard Polyflex JB Belt Lengths

Below are the standard belt lengths, with each belt length available in both two, three, four or five strands.

Any combination of Polyflex JB belts can be used on a single drive in matched sets. For example, if six belts are needed to transmit a load, matched sets of two joined belts with three strands in each belt would work as well as matched sets of three belts with two strands in each belt (see Fig. 21).

Tal	ble 25 — Sta	andard Polyfle	x JB Belt Length	s 3M and 5I	N
*Designation	Effective	Length	*Designation	Effective	l enath
No.	(mm)	(in)	No.	(mm)	(in)
3M175JB	171.2	6.74	5M280JB	280	11.0
3M180JB	176.3	6.94	5M290JB	290	11.4
3M185JB	181.1	7.13	5M300JB	300	11.8
3M190JB	186.2	7.33	5M307JB	307	12.1
3M195JB	191.3	7.53	5M315JB	315	12.4
3M200JB	196.1	7.72	5M325JB 5M335JB	325 335	12.8 13.2
3M206JB	202.2	7.96	5M345JB	345	13.6
3M212JB	208.3	8.2	5M355JB	355	14.0
	214.1	8.43	5M365JB	365	14.4
3M218JB			5M375JB	375	14.8
3M224JB	220.2	8.67	5M387JB	387	15.2
3M230JB	226.3	8.91	5M400JB	400	15.7
3M236JB	232.2	9.14	5M412JB 5M425JB	412 425	16.2 16.7
3M243JB	239.3	9.42	5M437JB	437	17.2
3M250JB	246.1	9.69	5M450JB	450	17.7
3M258JB	254.3	10.01	5M462JB	462	18.2
3M265JB	261.1	10.28	5M475JB	475	18.7
3M272JB 3M280JB	268.2 276.1	10.56 10.87	5M487JB	487	19.2
3M290JB	286.3	11.27	5M500JB	500	19.7
3M300JB	296.2	11.66	5M515JB 5M530JB	515 530	20.3 20.9
3M307JB	303.3	11.94	5M545JB	545	21.5
3M315JB	311.2	12.25	5M560JB	560	22.0
3M325JB	321.3	12.65	5M580JB	580	22.8
3M335JB 3M345JB	331.2 341.1	13.04 13.43	5M600JB	600	23.6
3M350JB	346.2	13.63	5M615JB	615	24.2
3M355JB	351.3	13.83	5M630JB 5M650JB	630 650	24.8 25.6
3M365JB	361.2	14.22	5M670JB	670	26.4
3M375JB	371.1	14.61	5M690JB	690	27.2
3M387JB	383.3	15.09	5M710JB	710	28.0
3M400JB 3M412JB	396.2 408.2	15.6 16.07	5M730JB	730	28.7
3M425JB	421.1	16.58	5M750JB	750	29.5
3M437JB	433.3	17.06	5M775JB 5M800JB	775 800	30.5 31.5
3M450JB	446.3	17.57	5M825JB	825	32.5
3M462JB	458.2	18.04	5M850JB	850	33.5
3M475JB	471.2	18.55	5M875JB	875	34.4
3M487JB 3M500JB	483.1 496.3	19.02 19.54	5M900JB	900	35.4
3M515JB	511.3	20.13	5M925JB	925	36.4
3M530JB	526.3	20.72	5M950JB 5M975JB	950 975	37.4 38.4
3M545JB	541.3	21.31	5M1000JB	1000	39.4
3M560JB	556.3	21.9	5M1030JB	1030	40.6
3M580JB	576.3	22.69	5M1060JB	1060	41.7
3M600JB 3M615JB	596.1 611.1	23.47 24.06	5M1090JB	1090	42.9
3M630JB	626.1	24.65	5M1120JB	1120	44.1
3M650JB	646.2	25.44	5M1150JB 5M1180JB	1150 1180	45.3 46.5
3M670JB	666.2	26.23	5M11220JB	1220	48.0
3M690JB	660.9	26.02	5M1250JB	1250	49.2
3M710JB	706.1	27.8	5M1280JB	1280	50.4
3M730JB 3M750JB	726.2 746.3	28.59 29.38	5M1320JB	1320	52.0
31917 30313	740.5	25.00	5M1360JB	1360	53.5 55.1
			5M1400JB 5M1450JB	1400 1450	55.1
			5M1500JB	1500	59.1

^{*}Designation No. may not necessarily agree with actual Effective Length.



Polyflex Sheave Specification Tables




	Table 26 – 3M Polyflex Sheaves: 3 Groove										
			Nominal Dimensions (in)								
Outside		В	D F				Plain B	ore (in)	Set		
Diameter	Туре			М	Bushing	Min.	Max.	Screws			
0.67	6	0.400	0.840	0.440	0.400	MPB	0.125	0.125	4-40		
0.71	6	0.450	0.840	0.440	0.400	MPB	0.125	0.188	4-40		
0.75	6	0.490	0.840	0.440	0.400	MPB	0.125	0.250	4-40		
0.79	6	0.530	0.840	0.440	0.400	MPB	0.125	0.250	4-40		
0.83	6	0.570	0.840	0.440	0.400	MPB	0.125	0.313	4-40		
0.88	6	0.620	0.840	0.440	0.400	MPB	0.125	0.375	6-40		
0.93	6	0.670	0.840	0.440	0.400	MPB	0.125	0.375	6-40		
0.98	6	0.720	0.840	0.440	0.400	MPB	0.125	0.438	6-40		
1.04	6	0.780	0.840	0.440	0.400	MPB	0.125	0.500	6-40		
1.10	6	0.840	0.940	0.440	0.500	MPB	0.125	0.563	8-32		
1.17	6	0.910	0.940	0.440	0.500	MPB	0.125	0.625	8-32		
1.24	6	0.980	0.940	0.440	0.500	MPB	0.125	0.750	8-32		
1.57	6	1.250	0.940	0.440	0.500	MPB	0.125	1.000	8-32		
1.97	6	1.500	0.940	0.440	0.500	MPB	0.125	1.250	8-32		




Table 27 - 5M Polyflex Sheaves: 3 Groove										
					Nominal Din	nensions (in)			
Outside								Plain Bore (in)		Set
Diameter	Туре	Α	В	D	F	М	Bushing	Min.	Max.	Screws
1.04	6	-	0.690	1.090	0.690	0.400	MPB	0.375	0.406	6-40
1.10	6	-	0.750	1.090	0.690	0.400	MPB	0.375	0.469	6-40
1.17	6	-	0.820	1.190	0.690	0.500	MPB	0.375	0.500	8-32
1.24	6	-	0.890	1.190	0.690	0.500	MPB	0.375	0.563	8-32
1.32	6	-	0.970	1.190	0.690	0.500	MPB	0.375	0.625	8-32
1.40	6	-	1.050	1.190	0.690	0.500	MPB	0.375	0.688	8-32
1.48	6	-	1.130	1.190	0.690	0.500	MPB	0.375	0.750	8-32
1.57	6	-	1.220	1.190	0.690	0.500	MPB	0.375	0.875	8-32
1.67	6	-	1.320	1.190	0.690	0.500	MPB	0.375	0.938	8-32
1.77	6	-	1.420	1.190	0.690	0.500	MPB	0.375	1.063	8-32
1.87	6	-	1.520	1.190	0.690	0.500	MPB	0.375	1.125	8-32
1.97	6	-	1.620	1.190	0.690	0.500	MPB	0.375	1.250	8-32
2.48	B-1	-	2.380	0.880	0.690	0.190	1108	0.500	1.125	-
3.15	B-1	-	2.380	0.880	0.690	0.190	1108	0.500	1.125	-
3.94	B-1	-	2.750	1.000	0.690	0.310	1610	0.500	1.688	-
4.92	B-1	-	3.760	1.250	0.690	0.560	2012	0.500	2.125	-
6.30	C-1	5.400	4.000	1.250	0.690	0.560	2012	0.500	2.125	-
7.87	C-1	6.900	4.000	1.250	0.690	0.560	2012	0.500	2.125	-
9.84	C-2	9.000	4.000	1.250	0.690	0.560	2012	0.500	2.125	-
12.40	C-2	11.400	4.000	1.250	0.690	0.560	2012	0.500	2.125	-
15.70	C-2	13.700	4.380	1.250	0.690	0.560	2012	0.500	2.125	-

Design Type Suffix: 1 - Solid 2 - Web



^{*}Plain bore style stocked in smallest bore.

^{** 2} ea. set screws at 90 degrees.

Polyflex Sheave Specification Tables




Table 28 - 5M Polyflex Sheaves: 5 Groove										
Nominal Dimensions (in)										
Outside								Plain Bore (in)		Set
Diameter	Туре	Α	В	D	F	М	Bushing	Min.	Max.	Screws
1.04	6	-	0.690	1.508	1.108	0.400	MPB	0.375	0.406	6-40
1.10	6	-	0.750	1.508	1.108	0.400	MPB	0.375	0.469	6-40
1.17	6	-	0.820	1.608	1.108	0.500	MPB	0.375	0.500	8-32
1.24	6	-	0.890	1.608	1.108	0.500	MPB	0.375	0.563	8-32
1.32	6	-	0.970	1.608	1.108	0.500	MPB	0.375	0.625	8-32
1.40	6	-	1.050	1.608	1.108	0.500	MPB	0.375	0.688	8-32
1.48	6	-	1.130	1.608	1.108	0.500	MPB	0.375	0.750	8-32
1.57	6	-	1.220	1.608	1.108	0.500	MPB	0.375	0.875	8-32
1.67	6	-	1.320	1.608	1.108	0.500	MPB	0.375	0.938	8-32
1.77	6	-	1.420	1.608	1.108	0.500	MPB	0.375	1.063	8-32
1.87	6	-	1.520	1.608	1.108	0.500	MPB	0.375	1.125	8-32
1.97	6	-	1.620	1.608	1.108	0.500	MPB	0.375	1.250	8-32
2.48	A-1	1.920	-	0.880	1.108	0.228	1108	0.500	1.125	-
3.15	A-1	2.380	-	0.880	1.108	0.228	1108	0.500	1.125	-
3.94	A-1	2.750	-	1.000	1.108	0.108	1610	0.500	1.688	-
4.92	B-1	-	3.760	1.250	1.108	0.142	2012	0.500	2.125	_
6.30	C-1	5.400	3.760	1.250	1.108	0.142	2012	0.500	2.125	_
7.87	C-1	6.900	4.500	1.750	1.108	0.642	2517	0.500	2.688	_
9.84	C-2	9.000	4.500	1.750	1.108	0.642	2517	0.500	2.688	_
12.40	C-2	11.400	4.500	1.750	1.108	0.642	2517	0.500	2.688	_
15.70	C-2	13.700	4.880	1.750	1.108	0.642	2517	0.500	2.688	_

Design Type Suffix: 1 - Solid 2 - Web

^{*}Plain bore style stocked in smallest bore.

^{** 2} ea. set screws at 90 degrees.

Micro-V® Belt Drives

For information on additional Micro-V cross sections, see the Heavy Duty V-Belt Drive Design Manual 19995-A.

Gates Micro-V Belts are superior to other V-ribbed belts. The reason is the shorter truncated V-rib design coupled with its premium construction.

The truncated rib profile adds these performance qualities:

- Crack resistant ribs
- · Higher load-carrying capacity
- Reduced flex fatigue
- Increased performance on small diameter sheaves allows smaller design packages
- Cool running
- · Greater tolerance to sheave groove debris
- Improved resistance to back bending from tensioning idlers

Gates Micro-V Belts offer 80% higher horsepower capacity than RMA standards. Extra load-carrying capacity means extra long life.

No other V-ribbed belts are built as well as Micro-V Belts, and the Gates belts provide you with the long and improved service life required in the industry today.




Micro-V® Belts

Construction

Gates Micro-V belts feature a smooth-running nylon cross-cord overcord and high modulus, low-stretch polyester tensile cord for added strength and dependability. An optional aramid tensile cord is available on a made-to-order basis.

A specially formulated polychloroprene rubber compound resists oil, heat and cracking. Micro-V belts are static dissipating for added safety.



Nominal Top Width, $b_b = N_r \times S_g$ Where: $N_r = Number of ribs$, $S_g = Pulley groove spacing$

Figure 22 - Micro-V Cross Section

Table 29 - Reference Standard Micro-V **Dimensions Nominal Rib** Nominal Width **Thickness Cross Section** (Sq) (in) (hb) (in) 0.100 0.063 0.092 0.128 K 0.140 0.209

Standard Belt Nomenclature

The Micro-V Belt is correctly identified by a threepart symbol consisting of: (1) a standard length designation; (2) cross section, and (3) number of ribs.

For example: The belt designation "420J6" represents:

- 1. An effective length of 42.0 inches
- 2. J Cross Section
- 3. 6 ribs wide.

Cross Sections

Light Duty Industrial Micro-V Belts are available from stock in a J Cross Section. H and K Cross Sections are available on a made-to-order basis. Fig. 22 shows a cross-sectional view and illustrates the nominal belt dimensions — rib width and belt thickness — for H, J and K cross sections. These belts will operate in pulleys that are manufactured to the RMA standard for the specific cross section.

Micro-V Belt Drives

Standard Micro-V Belt Lengths and Widths

Stock belts are defined by the number of ribs and belt effective lengths specified in Tables 30 and 31, respectively. The line of stock belts available in this manual were chosen specifically to cover the widest possible range of applications.

Table 30 – Stock Rib Widths – J Cross Section							
No. Ribs (b _b)	Nom. Width (in)	No. Ribs (b _b)	Nom. Width (in)				
4	0.368	16	1.472				
6	0.552	20	1.840				
10	0.920						

Tal	Table 31 – Standard Belt Effective Lengths – J Cros							
Standard Length Designation	Effective Length (in)	Permissible Deviation From Standard Length (in)	Standard Length Designation	Effective Length (in)	Permissible Deviation From Standard Length (in)			
180** 190** 200** 220 230	18.0 19.0 20.0 22.0 23.0	+0.2 -0.2 +0.2 -0.2 +0.2 -0.2 +0.2 -0.2 +0.2 -0.2	420 430 440 460 480	42.0 43.0 44.0 46.0 48.0	+0.2 -0.4 +0.2 -0.4 +0.2 -0.4 +0.2 -0.4 +0.2 -0.4			
240 250 260 280 300 320	24.0 25.0 26.0 28.0 30.0 32.0	+0.2 -0.2 +0.2 -0.2 +0.2 -0.2 +0.2 -0.2 +0.2 -0.3 +0.2 -0.3	490 500 520 550 580 610	49.0 50.0 52.0 55.0 58.0 61.0	+0.2 -0.4 +0.2 -0.4 +0.2 -0.4 +0.2 -0.4 +0.2 -0.5 +0.2 -0.5			
330 340 360 380 400 410	33.0 34.0 36.0 38.0 40.0 41.0	+0.2 -0.3 +0.2 -0.3 +0.2 -0.3 +0.2 -0.3 +0.2 -0.4 +0.2 -0.4	650 730 870 920*** 980***	65.0 73.0 87.0 92.0 98.0	+0.2 -0.5 +0.3 -0.6 +0.3 -0.7 +0.4 -0.7 +0.4 -0.8			

^{**}Available in 4 or 6 rib combinations only.

^{***}Available up to 10 ribs only.

Outside Diameter		o. of Grooves		No. of Grooves		Outside Diameter	No	o. of Grooves	
(in)	6	10	16	(in)	6	10	16		
1.50	Χ	-	-	2.80	Х	Х	Х		
1.60	X	-	-	3.00	X	Χ	X		
1.70	Χ	-	-	3.15	X	X	X		
1.80	X	-	-	3.35	X	Χ	X		
1.90	X	-	-	4.50	X	X	X		
2.00	Χ	Х	-	6.00	X	X	X		
2.12	X	X	-	8.00	X	Χ	X		
2.24	Χ	X	-	10.60	X	X	X		
2.36	X	X	-	14.00	X	Χ	X		
2.50	X	X	X	19.00	X	X	X		
2.65	X	X	X						

NOTE: Check with Customer Service for availability. Additional sizes available on a made-to-order basis.

How to Design Polyflex JB and Micro-V Belt Drives

Note: The upcoming drive selection and engineering sections provide information for Polyflex JB and Micro-V belts and sheaves (or pulleys). Where we refer to sheaves (for Polyflex JB belts), you can substitute pulleys for Micro-V belts. If you need additional information, contact Gates Application Engineering, Denver.

This section describes how to design standard two-sheave Polyflex JB and Micro-V drives.

To select either a Gates Polyflex JB and Micro-V Belt drive, you need to know these five facts:

- Horsepower or kilowatt rating of the driveR machine
- 2. rpm of the driveR machine
- 3. rpm of the driveN machine
- 4. Approximate center distance required
- 5. Hours per day operation.

Follow these seven steps to design a drive:

Step 1 Find the Design Horsepower (Design kw)

Design Horsepower =

(Service Factor) x (Horsepower Requirement)

- A. Select the proper service factor from Table 37 on Page 86. If your driveN machine is not listed, find a machine with comparable starting, running and shock load characteristics.
- **B.** The horsepower requirement of the drive usually is taken as the nameplate rating of the driveR. The actual requirement of the driveN machine may be used as the horsepower requirement, if it is known. This type of load approximation is used in those applications where a small auxiliary machine is being driven from a large motor or engine.

Step 2 Find the Speed Ratio

Use Formula 7 on this page to calculate the desired speed ratio for your drive. The speed ratio can be determined from either the shaft speeds or the sheave pitch diameters. To determine the pitch diameter of a sheave, measure the outside diameter and add the appropriate add-on factor from Table 33.

Formula 7

Speed Ratio = RPM of Faster Shaft RPM of Slower Shaft = Pitch Dia. of Larger Sheave Pitch Dia. of Smaller Sheave

Step 3 Choose the Sheave Diameters

Standard sheave diameters for Polyflex JB and Micro-V belts are listed in Tables 26-28 and 32 on Page 80-81 and 83.

A. The drive can be designed around a known sheave diameter. For example, if you have one sheave available, or if a minimum or maximum sheave diameter is known, use Formula 7 in conjunction with Table 26-28 or Table 32 to determine the other sheave diameter. To calculate the pitch diameter of the larger sheave, multiply the pitch diameter of the smaller sheave by the speed ratio, or divide the pitch diameter of the smaller sheave. To convert the pitch diameter to outside diameters, subtract the values in Table 33 from the pitch diameters.

Table 33 – Factors to Calculate Polyflex JB and Micro-V Pitch Diameters

	O.D. to P.D. Value				
Cross Section	(in)	(mm)			
3M Polyflex JB	+0.023	+0.58			
5M Polyflex JB	+0.050	+1.27			
J Micro-V	+0.030	+0.76			

NOTE: Pitch diameters are always used in speed ratio calculations. If your drive uses an electric motor, the minimum selected sheave 0.D. should be at least as large as the sheave outside diameters specified in Table 38 on Page 86.

B. Calculate the sheave rim speed for your drive using Formula 8 below:

Formula 8

Sheave Rim Speed (ft/min) = $\frac{(0.D. \text{ of either sheave}) \times (\text{rpm of same sheave})}{3.82^*}$

*This constant is derived from $12/\pi$.

For standard Polyflex JB and Micro-V sheaves the rim speeds should not exceed 6,500 feet per minute. If the rim speeds exceed this figure, special sheave materials and dynamic balancing are usually required. If possible, redesign the drive using smaller diameter sheaves so that the rim speed is between 4,000 and 6,000 fpm.

- **C.** When designing a drive, consider these factors:
 - 1. Advantages of Larger Diameter Sheaves:

Cost Considerations:

Since sheave diameter and rated horsepower per belt or rib are proportional, larger diameter drives will usually require fewer belts or ribs to transmit a specific load. This generally results in a more cost effective drive.

Space Limitations:

In addition to being more cost effective, large diameter sheaves will result in a "narrower" drive. Therefore, to minimize the sheave face width, select the largest diameter drive from the group of drives being considered.

However, if there are space restrictions and larger diameter sheaves cannot be used, consider using a smaller diameter drive from the group of drives being considered. If the driveR is an electric motor, the smallest sheave must be at least as large as the Minimum Recommended Sheave O.D. specified in Table 38 on Page 86.

Component Life:

As sheave diameters are increased, the required drive tensions and shaft pulls are decreased. By lowering the forces on the bearings, belts and sheaves, component wear is reduced and component service life is extended.

NOTE: On some lightly-loaded drives, the cost of the larger sheave (to obtain belt speed between 4,000 and 6,000 feet per minute) may result in a less economical drive. For high horsepower drives, it is usually best to check several designs for economics before making a final choice.

D. If the drive requires an idler, refer to Table 43 on Page 95 for recommended idler diameters.



How to Design Polyflex JB and Micro-V Belt Drives - continued

Step 4 Determine the Belt Length **Designation and Actual Center Distance**

A. For a two-sheave drive, calculate the belt effective length from Formula 9. If your drive requires an idler, determine the belt effective length from Engineering Section VII. Design of Drives With Idlers on Page 96.

Formula 9

Belt Effective Length (in) = $2CD + 1.57(D + d) + \frac{(D - d)2}{d}$

Where: d = Small sheave outside diameter, inches D = Large sheave outside diameter, inches

CD = Desired center distance, inches.

Compare the calculated belt effective length from Formula 9 to the standard belt effective lengths given in Table 25 or Table 31 on Pages 79 or 83. Find the closest standard belt effective length in Table 25 or Table 31 and calculate the actual center distance using Formula 10 below.

B. The approximate nominal center distance for the drive can be calculated using the following formula:

Formula 10

Center Distance =
$$\frac{K + \sqrt{K2 - 32 (D - d)^2}}{16}$$

$$K = 4EL - 6.28 (D + d)$$

Where: d = Small sheave outside diameter, inches

D = Large sheave outside diameter, inches

EL = Belt effective length, inches

Step 5 Calculate the Number of Strands/Ribs Required

- **A.** From the tables on Page 87, 88, or 89 find the basic horsepower rating based on the small sheave diameter and rpm of the faster shaft. Add the 'additional horsepower per strand or rib for speed ratio' from the right of the table to find the rated horsepower per strand or rib. Interpolate if necessary.
- **B.** From Table 34, find the Arc of Contact Correction Factor (G) based on the quantity (D - d)/C. (D and d are large and small sheave outside diameters and C is the actual center distance. All values are in inches.)

- **C.** Based on the belt length and cross section that you selected, determine the Belt Length Correction Factor from Table 35 or Table 36 on this page.
- **D.** From Steps B and C, multiply the Arc of Contact Correction Factor (G) and the Belt Length Correction Factor (KL) to get the Horsepower Correction Factor.
- **E.** Multiply the rated horsepower per strand or rib by the Horsepower Correction Factor to obtain the Horsepower Per Strand or Rib.
- F. Divide the design horsepower from Step 1 by the horsepower per strand or rib to find the number of strands or ribs required. The answer may be a fraction, so always round to the next larger whole number.

Factor									
		Arc of Contact On Small	Ard Correct Factor	tion					
	D-d C	Sheave (degrees)	Polyflex JB	Micro-V					
	0.00	180	1.00	1.00					

	Contact On Small	Correction Factor (G)				
D-d C	Sheave (degrees)	Polyflex JB	Micro-V			
0.00	180	1.00	1.00			
0.10	174	0.99	0.98			
0.20	169	0.97	0.97			
0.30	163	0.96	0.95			
0.40	157	0.94	0.94			
0.50	151	0.93	0.92			
0.60	145	0.91	0.90			
0.70	139	0.89	0.88			
0.80	133	0.87	0.85			
0.90	127	0.85	0.83			
1.00	120	0.82	0.80			
1.10	113	0.79	0.77			
1.20	106	0.77	0.74			
1.30	99	0.73	0.71			
1.40	91	0.70	0.67			
1.50	83	0.65	0.63			

	the same of the contract of th		
Table 25 - Pol	utley IR length	Correction Factors ("
IGDIC JJ — FUI	VIIGA JD EGIIGUI	UVITGGUUH TAGUNƏ I	1.1

	10.010	00 . 0.,	HOA OF LOIL	g an Ooi 100	dioni i diotoi	~ (D)	
3M Belt Length Designation	3M Belt Length Correction Factor	3M Belt Length Designation	3M Belt Length Correction Factor	5M Belt Length Designation	5M Belt Length Correction Factor	5M Belt Length Designation	5M Belt Length Correction Factor
175	0.82	365	1.08	280	0.83	670	1.09
180	0.83	375	1.09	290	0.84	690	1.10
185	0.84	387	1.10	300	0.85	710	1.10
190	0.85	400	1.11	307	0.86	730	1.11
195	0.86	412	1.12	315	0.87	750	1.12
200	0.87	425	1.13	325	0.88	775	1.13
206	0.88	437	1.14	335	0.89	800	1.14
212	0.89	450	1.15	345	0.89	825	1.15
218	0.90	462	1.16	355	0.90	850	1.16
224	0.91	475	1.17	365	0.91	875	1.17
230	0.92	487	1.18	375	0.92	900	1.17
236	0.93	500	1.19	387	0.93	925	1.18
243	0.94	515	1.20	400	0.94	950	1.19
250	0.95	530	1.21	412	0.95	975	1.20
258	0.96	545	1.22	425	0.96	1000	1.20
265	0.97	560	1.23	437	0.96	1030	1.21
272	0.98	580	1.24	450	0.97	1060	1.22
280	0.99	600	1.25	462	0.98	1090	1.23
290	1.00	615	1.26	475	0.99	1120	1.24
300	1.01	630	1.27	487	1.00	1150	1.25
307	1.02	650	1.28	500	1.00	1180	1.25
315	1.03	670	1.29	515	1.01	1220	1.26
325	1.04	690	1.30	530	1.02	1250	1.27
335	1.05	710	1.31	545	1.03	1280	1.28
345	1.06	730	1.32	560	1.04	1320	1.29
350	1.07	750	1.33	580	1.05	1360	1.29
355	1.07			600	1.06	1400	1.30
				615	1.06	1450	1.31
				630	1.07	1500	1.32
				650	1.08		

Tahla "	16 - Micro-	V annth Carror	tion Factors (K.)
	1711.01.0-	V EGILLE DULLED	aun auaus m

Belt	Length	Belt	Length	Belt	Length
Length	Correction	Length	Correction	Length	Correction
Designation	Factor	Designation	Factor	Designation	Factor
180	0.76	360	0.97	580	1.11
190	0.78	380	0.98	610	1.13
200	0.79	400	1.00	650	1.15
220	0.82	420	1.01	730	1.18
240	0.85	430	1.02	870	1.23
260 280 300 320 340	0.87 0.89 0.91 0.93 0.95	440 460 490 520 550	1.03 1.04 1.06 1.08 1.10	920 980	1.25 1.27

How to Design Polyflex JB and Micro-V Belt Drives - continued

Step 6 Determine the Minimum Installation and Takeup Allowances

- **A.** Find the recommended installation and takeup allowance in Engineering, Section V. Installation and Takeup Table 41 or Table 42 on Page 94.
- **B.** For optimum belt performance, the drive must have sufficient belt installation and takeup allowance. Tables 41 and 42 on Page 94 show

the required center distance movement to provide proper installation and takeup. However, if you have a fixed center drive, it also must have provisions for belt length adjustment. Use of idlers is the most common method to provide belt length adjustment with fixed center drives. See Engineering Section VI: Idler Usage on Page 94 and Section VII. Design of Drives With Idlers on Page 96.

DriveN Machine			Dri	veR		
The machines listed below are representative samples only. Select the group listed below	Synchronous Split F DC Motors: Shunt			Synchronous Split F DC Motors: Shunt		•
whose load characteristics most closely approximate those of the machine being considered.	Intermittent Service 3-5 Hours Daily or Seasonal	Normal Service 8-10 Hours Daily	Continuous Service 16-24 Hours Daily	Intermittent Service 3-5 Hours Daily or Seasonal	Normal Service 8-10 Hours Daily	Continuous Service 16-24 Hours Daily
Agitators for Liquids Blowers and Exhausters Centrifugal Pumps & Compressors Display Equipment Dispensing Equipment Fans up to 10 Horsepower Instrumentation Light Duty conveyors Office Equipment	1.0	1.1	1.2	1.1	1.2	1.3
Belt conveyors for Sand, Grain, Etc. Dough Mixers Fans - Over 10 Horsepower Generators Line Shafts Laundry Machinery Machine Tools Punches - Presses - Shears Printing Machinery Positive Displacement Rotary Pumps	1.1	1.2	1.3	1.2	1.3	1.4
Brick Machinery Bucket Elevators Exciters Piston Compressors Conveyors (Drag-Pan-Screw) Piston Pumps Positive Displacement Blowers Textile Machinery	1.2	1.3	1.4	1.4	1.5	1.6
Hoists	1.3	1.4	1.5	1.5	1.6	1.8

	Table	38 – Mir	imum R	ecomme	nded She	ave Outsi	de Diameters	for Gen	eral Pur	pose Ele	ctric Mo	tors	
	Moto	or rpm (60	Cycle and §	50 Cycle Ele	ectric Motor	s		Moto	r rpm (60 C	cycle and 5	O Cycle Ele	ctric Motors	;
Motor	575	690	870	1160	1750	3450	Motor	575	690	870	1160	1750	3450
Horsepower	485*	575*	725*	950*	1425*	2850*	Horsepower	485*	575*	725*	950*	1425*	2850*
1/2	-	-	2.4	-	-	-	3	4.8	4.1	3.2	3.2	2.6	2.6
3/4	-	-	2.6	2.4	-	-	5	4.8	4.8	4.1	3.2	3.2	2.6
1	3.2	2.7	2.6	2.6	2.4	-	7 1/2	5.6	4.8	4.7	4.1	3.2	3.2
1 1/2	3.2	3.2	2.6	2.6	2.6	2.4	10	6.4	5.6	4.7	4.7	4.1	3.2
2	4.1	3.2	3.2	2.6	2.6	2.6	15	7.3	6.4	5.6	4.7	4.7	4.1

^{*}These speed values are for 50 Cycle electric motors.

Rubber Calendars - Extruders - Mills



										3M P	olyfle	x JB	Powe	er Rat	ings										
			Basi	c Horse	power	per Stra	and for	Small 0									A	ddition	al Hors	epower	per St	rand fo	r Speed	Ratio	
	(in) (mm)	0.67 17	0.71 18	0.75 19	0.79 20		0.88	0.93 24	0.98 25	1.04 26	1.10 28	1.17 30	1.24 31	1.57 40	1.97 50	1.00 to 1.01	1.02 to 1.03	1.04 to 1.05	1.06 to 1.08	1.09 to 1.11	1.12 to 1.15	1.16 to 1.21	1.22 to 1.29	1.30 to 1.46	1.47 and over
	0.18 690	0.24	575	0.000	0.001 0.057	0.002	0.003	0.004	-	0.005	0.006	0.007	0.008	575 0.21	0.029	0.043	0.050	0.056	0.065	0.073	0.082	0.092	0.10	0.11	0.12
	725 870 950	0.036	0.046	0.056	0.058 0.066 0.070	0.076	0.077 0.089 0.094	1	0.098 0.11 0.12	0.11 0.13 0.14	0.12 0.14 0.15	0.14 0.16 0.17	0.15 0.18 0.19	0.22 0.25 0.27	0.34	0.000	0.001 0.001 0.002	0.003	0.004	0.006	0.007	0.008	0.010	0.009 0.011 0.012	0.012
	1160 1425	0.041 0.045	0.054 0.060	0.067 0.076	0.080 0.091	0.093 0.11	0.11 0.13	0.12 0.14	0.14 0.16	0.16 0.19	0.18 0.21	0.20 0.23	0.22 0.26	0.32 0.38	0.44 0.52	0.000 0.000	0.002 0.002	0.004 0.005	0.006 0.007	0.007 0.009	0.009 0.011	0.011 0.014	0.013 0.016	0.015 0.018	0.017 0.020
	1750 2850 3450	0.047	0.066	0.085 0.11 0.11		0.16	0.14 0.20 0.22	0.23	0.19 0.27 0.30	0.22 0.31 0.35	0.24 0.35 0.40	0.27 0.40 0.46	0.31 0.44 0.51	0.45 0.66 0.77	0.62 0.92 1.07	0.000	0.003 0.005 0.005	0.009	0.014	0.018	0.023	0.027	0.032	0.022 0.036 0.044	0.041
	500 600 700	0.030		0.044	0.045 0.051 0.057	0.058	0.067	0.066 0.076 0.085	0.073 0.085 0.095	0.082 0.095 0.11	0.091 0.11 0.12	0.10 0.12 0.13	0.11 0.13 0.15	0.16 0.18 0.21		0.000	0.001 0.001 0.001	0.002	0.003	0.004	0.005	0.006	0.007	0.006 0.008 0.009	0.009
	800 900	0.035 0.037	0.044 0.047	0.053 0.058	0.063 0.068	0.072 0.078	0.083 0.091	0.095 0.10	0.11 0.12	0.12 0.13	0.13 0.15	0.15 0.16	0.16 0.18	0.24 0.26	0.32 0.35	0.000	0.001 0.001	0.003 0.003	0.004 0.004	0.005 0.006	0.006 0.007	0.008	0.009 0.010	0.010 0.011	0.011 0.013
	1000 1200 1400	0.042	0.055	0.069	0.073 0.082 0.090	0.095	0.098 0.11 0.12	0.11 0.13 0.14	0.13 0.14 0.16	0.14 0.16 0.18	0.16 0.18 0.21	0.18 0.20 0.23	0.20 0.23 0.26	0.28 0.33 0.37	0.45 0.51	0.000 0.000	0.002 0.002 0.002	0.004 0.004	0.006 0.007	0.008 0.009	0.010 0.011	0.011 0.013	0.013 0.016	0.015 0.018	0.017 0.020
	1600 1800 2000	0.046	0.064 0.067 0.070	0.081 0.086 0.091		1	0.14 0.15 0.16	0.17	0.18 0.19 0.21	0.20 0.22 0.24	0.23 0.25 0.27	0.26 0.28 0.30	0.28 0.31 0.34	0.42 0.46 0.50	0.63	0.000	0.003 0.003 0.003	0.006	0.009	0.011	0.014	0.017	0.020	0.023	0.026
	3000 4000 5000			0.11		0.17	0.20 0.24 0.27	0.24	0.28 0.33 0.38	0.32 0.39 0.45	0.36 0.44 0.51	0.41 0.51 0.59	0.46 0.57	0.69 0.86 1.02	0.95 1.20	0.000	0.005 0.006 0.008	0.010 0.013	0.014 0.019	0.019 0.026	0.024 0.032	0.029 0.038	0.033 0.045	0.038 0.051	0.043 0.057
	6000 7000					0.21	0.27 0.29 0.31	0.36 0.38	0.42 0.46	0.50 0.55	0.58 0.63	0.67 0.74	0.67 0.76 0.84	1.16 1.29	1.63 1.81	0.000	0.010 0.011	0.019 0.022	0.029 0.033	0.038 0.045	0.048 0.056	0.057 0.067	0.067 0.078	0.076 0.089	0.086 0.100
Shaft	8000 9000 10000							0.40 0.42	0.49 0.51 0.53	0.59 0.62 0.65	0.68 0.73 0.77	0.80 0.85 0.90	0.91 0.97 1.03	1.41 1.52 1.62	2.13	0.000	0.013 0.014 0.016	0.029	0.043	0.057	0.072	0.086	0.100	0.115	0.129
er St	12000		Rasio	Kilov	ratt ne	r Reit	for Sm	all She	ave O	0.69	0.83	0.98 ter	1.13	1.78	2.48	0.000	0.019							0.153 d Ratio	
of Faster	575		0.027	0.032	0.037	0.042	0.048	0.055	0.061	0.069	0.076	0.085	0.093	0.13			0.001	0.001	0.002	0.003	0.003	0.004	0.005	0.005	0.006
rpm of	690 725				0.042	0.048			0.070 0.073		0.088	0.098	0.11	0.15 0.16			0.001								
므	870	0.027	0.035	0.042	0.049	0.057	0.066	0.075	0.084	0.095	0.11	0.12	0.13	0.19	0.26	0.000	0.001	0.002	0.003	0.004	0.005	0.006	0.007	0.008	0.009
	950 1160				0.052			0.080	0.090	0.10	0.11 0.13	0.13	0.14	0.20 0.24			0.001							0.009	
	1425		0.045		0.068		0.094		0.12	0.14	0.16	0.17	0.19	0.28	0.39	0.000	0.002	0.003	0.005	0.007	0.008	0.010	0.012	0.014	0.015
	1750	0.035	0.049		0.077		0.11	1	0.14	0.16	0.18	0.20	0.23	0.33			0.002								
	2850 3450			0.079			0.15 0.16	1	0.20	0.23	0.26 0.30	0.30	0.33	0.49 0.57			0.003							0.027	
	500			0.029	0.033	0.038	0.044	0.049	0.055	0.061	0.068	0.075	0.083	0.12			0.001					0.004	0.004	0.005	0.005
	600					0.043			0.063		0.079	0.088	0.096	0.14 0.16			0.001								
	700 800					0.049			0.071			0.099	0.11	0.10	0.24	0.000	0.001	0.002	0.003	0.004	0.005	0.006	0.007	0.008	0.009
	900					0.058			0.086		0.11	0.12	0.13	0.19	0.26	0.000	0.001	0.002	0.003	0.004	0.005	0.006	0.007	0.009	0.010
	1000 1200					0.063	0.073	0.083	0.094	0.11	0.12 0.14	0.13	0.15	0.21 0.25	0.29	0.000	0.001 0.001	0.002	0.004	0.005	0.006	0.007	0.008	0.010	0.011
	1400	0.033	0.045	0.056	0.067	0.079	0.093		0.12	0.14	0.15	0.17	0.19	0.28	0.38	0.000	0.002	0.003	0.005	0.007	0.008	0.010	0.012	0.013	0.015
	1600	0.034				0.086	0.10		0.13	0.15	0.17	0.19	0.21	0.31	0.43	0.000	0.002	0.004	0.006	0.008	0.010	0.011	0.013	0.015	0.017
	1800 2000				0.078		0.11		0.14	0.17 0.18	0.19	0.21 0.23	0.23	0.34 0.37	0.47	0.000	0.002 0.002	0.004	0.006	0.009	0.011	0.013	0.015	0.017	0.019 0.021
	3000		0.002	0.080			0.15	1	0.21	0.24	0.27	0.31	0.34	0.51	0.71	0.000	0.004	0.007	0.011	0.014	0.018	0.021	0.025	0.029	0.032
	4000				0.12	1	0.18		0.25	0.29	0.33	0.38	0.42	0.64	0.89	0.000	0.005	0.010	0.014	0.019	0.024	0.029	0.033	0.038	0.043
	5000 6000					0.16	0.20		0.28	0.33	0.38	0.44	0.50	0.76 0.86	1.00	0.000	0.006 0.007	0.012	0.018	0.024	0.030	0.030	0.042	0.048	0.064
	7000						0.23	0.29	0.34	0.41	0.47	0.55	0.62	0.96	1.35	0.000	0.008	0.017	0.025	0.033	0.042	0.050	0.058	0.067	0.075
	8000 9000							0.30	0.36 0.38	0.44	0.51 0.54	0.59 0.63	0.68	1.05 1.13	1.48	0.000	0.009 0.011	0.019	0.028	0.038	0.048	0.057	0.067	0.076	0.085
	10000							0.31	0.40	0.48	0.54	0.63	0.73	1.13	1.69	0.000	0.012	0.024	0.036	0.048	0.059	0.071	0.083	0.095	0.107
	12000									0.52	0.62	0.73		1.33	1.85	0.000	0.014	0.029	0.043	0.057	0.071	0.086	0.100	0.114	0.128

									5M P	olyfle	х ЈВ	Powe	r Rat	ings									
				Basic	Horsepo	wer per	Strand 1	for Smal	II Outsid	le Diam	eter				Ado	litional	Horsepo	ower pe	r Strand	for Sp	eed Ra	tio	
	(in) mm	1.04 26	1.10 28	1.17 30	1.24 32	1.32 34	1.40 36	1.48 38	1.57 40	1.67 42	1.77 45	1.87 48	1.97 50	1.00 to 1.01	1.02 to 1.03	1.04 to 1.05	1.06 to 1.08	1.09 to 1.11	1.12 to 1.15	1.16 to 1.21	1.22 to 1.29	1.30 to 1.46	1.47 and over
	575 690 725 870 950	0.11 0.12 0.12 0.14 0.15	0.13 0.14 0.15 0.17 0.18	0.15 0.17 0.18 0.20 0.22	0.17 0.20 0.21 0.24 0.26	0.20 0.23 0.24 0.28 0.30	0.23 0.26 0.27 0.32 0.34	0.25 0.29 0.31 0.36 0.38	0.28 0.33 0.34 0.40 0.43	0.32 0.37 0.38 0.45 0.48	0.35 0.41 0.42 0.49 0.53	0.38 0.44 0.46 0.54 0.58	0.41 0.48 0.50 0.59 0.63	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00	0.01 0.01 0.01 0.01 0.01	0.01 0.01 0.01 0.01 0.01	0.01 0.01 0.01 0.02 0.02	0.01 0.02 0.02 0.02 0.02 0.02	0.02 0.02 0.02 0.02 0.02 0.03	0.02 0.02 0.02 0.03 0.03	0.02 0.02 0.03 0.03 0.03	0.02 0.03 0.03 0.04 0.04
1	1160 1425 1750 2850 3450	0.17 0.19 0.22	0.21 0.24 0.27 0.36	0.25 0.29 0.34 0.46 0.52	0.30 0.35 0.40 0.56 0.64	0.35 0.41 0.47 0.68 0.77	0.40 0.47 0.55 0.79 0.91	0.45 0.53 0.62 0.90 1.04	0.50 0.60 0.70 1.03 1.19	0.57 0.67 0.79 1.17 1.36	0.63 0.74 0.88 1.31 1.52	0.69 0.82 0.97 1.44 1.68	0.75 0.89 1.06 1.58 1.84	0.00 0.00 0.00 0.00 0.00	0.01 0.01 0.01 0.01 0.02	0.01 0.01 0.02 0.03 0.03	0.02 0.02 0.02 0.04 0.05	0.02 0.03 0.03 0.05 0.06	0.03 0.03 0.04 0.06 0.08	0.03 0.04 0.05 0.08 0.09	0.04 0.04 0.06 0.09 0.11	0.04 0.05 0.06 0.10 0.12	0.05 0.06 0.07 0.12 0.14
	500 600 700 800 900	0.10 0.11 0.12 0.13 0.14	0.11 0.13 0.15 0.16 0.17	0.13 0.15 0.17 0.19 0.21	0.15 0.18 0.20 0.22 0.24	0.18 0.21 0.23 0.26 0.29	0.20 0.23 0.27 0.30 0.33	0.23 0.26 0.30 0.33 0.36	0.25 0.29 0.33 0.37 0.41	0.28 0.33 0.37 0.42 0.46	0.31 0.36 0.41 0.46 0.51	0.34 0.39 0.45 0.50 0.56	0.37 0.43 0.49 0.55 0.61	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00	0.00 0.01 0.01 0.01 0.01	0.01 0.01 0.01 0.01 0.01	0.01 0.01 0.01 0.01 0.02	0.01 0.01 0.02 0.02 0.02	0.01 0.02 0.02 0.02 0.02	0.02 0.02 0.02 0.03 0.03	0.02 0.02 0.03 0.03 0.03	0.02 0.02 0.03 0.03 0.04
1 1 1	1000 1200 1400 1600 1800	0.15 0.17 0.19 0.20 0.22	0.19 0.21 0.23 0.26 0.28	0.23 0.26 0.29 0.32 0.34	0.27 0.30 0.34 0.38 0.41	0.31 0.36 0.40 0.44 0.48	0.35 0.41 0.46 0.51 0.56	0.40 0.46 0.52 0.58 0.63	0.45 0.52 0.59 0.65 0.72	0.50 0.58 0.66 0.74 0.81	0.55 0.65 0.73 0.82 0.90	0.61 0.71 0.81 0.90 0.99	0.66 0.77 0.88 0.98 1.08	0.00 0.00 0.00 0.00 0.00	0.00 0.01 0.01 0.01 0.01	0.01 0.01 0.01 0.01 0.02	0.01 0.02 0.02 0.02 0.02	0.02 0.02 0.03 0.03 0.03	0.02 0.03 0.03 0.04 0.04	0.03 0.03 0.04 0.04 0.05	0.03 0.04 0.04 0.05 0.06	0.04 0.04 0.05 0.06 0.06	0.04 0.05 0.06 0.06 0.07
: 2 5 6	2000 3000 4000 5000 6000	0.23	0.29 0.37	0.37 0.48 0.57 0.64	0.44 0.58 0.70 0.80 0.89	0.52 0.70 0.86 0.99 1.11	0.61 0.82 1.01 1.18 1.33	0.69 0.94 1.16 1.36 1.54	0.78 1.07 1.33 1.57 1.78	0.88 1.22 1.52 1.80 2.05	0.98 1.36 1.70 2.02 2.31	1.08 1.50 1.89 2.24 2.57	1.18 1.65 2.07 2.47 2.83	0.00 0.00 0.00 0.00 0.00	0.01 0.01 0.02 0.02 0.03	0.02 0.03 0.04 0.05 0.05	0.03 0.04 0.05 0.07 0.08	0.04 0.05 0.07 0.09 0.11	0.05 0.07 0.09 0.11 0.14	0.05 0.08 0.11 0.14 0.16	0.06 0.09 0.13 0.16 0.19	0.07 0.11 0.14 0.18 0.22	0.08 0.12 0.16 0.20 0.24
Shaft	7000 3000 9000 0000 2000			Dania	0.96	1.21 1.30 1.38 1.45	1.46 1.58 1.69 1.78 1.93	1.71 1.86 1.99 2.11 2.30	1.98 2.16 2.33 2.47 2.72	2.28 2.50 2.70 2.87 3.17	2.58 2.83 3.06 3.27 3.62	2.88 3.16 3.42 3.65 4.06	3.17 3.49 3.77 4.04 4.48	0.00 0.00 0.00 0.00 0.00	0.03 0.04 0.04 0.04 0.05	0.06 0.07 0.08 0.09 0.11	0.09 0.11 0.12 0.13 0.16	0.13 0.14 0.16 0.18 0.22	0.16 0.18 0.20 0.23 0.27	0.19 0.22 0.24 0.27 0.32	0.22 0.25 0.28 0.32 0.38	0.25 0.29 0.32 0.36 0.43	0.28 0.32 0.36 0.40 0.49
of Fa	575	0.07	0.09	0.11	Kilowat 0.13	0.15	urand r 0.17	or Sma 0.19	0.21	0.23	0.26	0.29	0.31	0.00	0.00	0.00	0.01	1tt per 0.01	0.01	0.01	0.01	atto 0.02	0.02
md.	690 725 870 950	0.08 0.09 0.10 0.10	0.11 0.11 0.13 0.14	0.13 0.14 0.16 0.17	0.15 0.16 0.19 0.20	0.18 0.18 0.21 0.23	0.20 0.21 0.24 0.26	0.22 0.23 0.27 0.29	0.25 0.26 0.30 0.32	0.27 0.28 0.33 0.35	0.30 0.32 0.37 0.40	0.34 0.35 0.41 0.44	0.36 0.37 0.44 0.47	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	0.00 0.00 0.01 0.01	0.01 0.01 0.01 0.01	0.01 0.01 0.01 0.01	0.01 0.01 0.01 0.02	0.01 0.01 0.02 0.02	0.02 0.02 0.02 0.02	0.02 0.02 0.02 0.03	0.02 0.02 0.03 0.03
1	1160 1425 1750 2850 3450	0.12 0.13 0.15	0.16 0.18 0.20 0.27	0.19 0.22 0.26 0.36 0.40	0.23 0.27 0.31 0.44 0.50	0.27 0.31 0.37 0.52 0.60	0.30 0.36 0.42 0.61 0.70	0.34 0.40 0.47 0.69 0.80	0.38 0.45 0.53 0.77 0.89	0.41 0.49 0.58 0.85 0.99	0.47 0.56 0.66 0.98 1.14	0.52 0.62 0.74 1.10 1.28	0.56 0.66 0.79 1.18 1.37	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.01 0.01 0.01	0.01 0.01 0.01 0.02 0.02	0.01 0.01 0.02 0.03 0.03	0.02 0.02 0.02 0.04 0.05	0.02 0.02 0.03 0.05 0.06	0.02 0.03 0.04 0.06 0.07	0.03 0.03 0.04 0.07 0.08	0.03 0.04 0.05 0.08 0.09	0.04 0.04 0.05 0.09 0.10
	500 600 700 800 900	0.07 0.08 0.09 0.09 0.10	0.09 0.10 0.11 0.12 0.13	0.10 0.12 0.13 0.15 0.16	0.12 0.14 0.16 0.17 0.19	0.14 0.16 0.18 0.20 0.22	0.15 0.18 0.20 0.23 0.25	0.17 0.20 0.23 0.25 0.28	0.19 0.22 0.25 0.28 0.31	0.21 0.24 0.27 0.30 0.34	0.23 0.27 0.31 0.34 0.38	0.26 0.30 0.34 0.38 0.42	0.27 0.32 0.36 0.41 0.45	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.01 0.01	0.01 0.01 0.01 0.01 0.01	0.01 0.01 0.01 0.01 0.01	0.01 0.01 0.01 0.01 0.02	0.01 0.01 0.01 0.02 0.02	0.01 0.01 0.02 0.02 0.02	0.01 0.02 0.02 0.02 0.02 0.02	0.02 0.02 0.02 0.02 0.03
1 1 1	1000 1200 1400 1600 1800	0.11 0.12 0.13 0.14 0.15	0.14 0.16 0.18 0.19 0.21	0.17 0.20 0.22 0.24 0.26	0.21 0.24 0.27 0.29 0.32	0.24 0.27 0.31 0.34 0.37	0.27 0.31 0.35 0.39 0.43	0.30 0.35 0.40 0.44 0.48	0.33 0.39 0.44 0.49 0.54	0.37 0.43 0.48 0.54 0.59	0.41 0.48 0.55 0.61 0.67	0.46 0.54 0.61 0.68 0.75	0.49 0.58 0.65 0.73 0.81	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.01 0.01	0.01 0.01 0.01 0.01 0.01	0.01 0.01 0.01 0.02 0.02	0.01 0.02 0.02 0.02 0.02	0.02 0.02 0.02 0.03 0.03	0.02 0.02 0.03 0.03 0.04	0.02 0.03 0.03 0.04 0.04	0.03 0.03 0.04 0.04 0.05	0.03 0.04 0.04 0.05 0.05
3 2 5	2000 3000 4000 5000 5000	0.16	0.22 0.28	0.28 0.37 0.44 0.49	0.34 0.46 0.55 0.63 0.70	0.41 0.54 0.66 0.77 0.86	0.47 0.63 0.78 0.91 1.02	0.53 0.72 0.89 1.04 1.18	0.59 0.80 1.00 1.18 1.34	0.65 0.89 1.11 1.31 1.50	0.73 1.02 1.27 1.51 1.73	0.82 1.14 1.44 1.71 1.96	0.88 1.23 1.54 1.84 2.11	0.00 0.00 0.00 0.00 0.00	0.01 0.01 0.01 0.02 0.02	0.01 0.02 0.03 0.03 0.04	0.02 0.03 0.04 0.05 0.06	0.03 0.04 0.05 0.07 0.08	0.03 0.05 0.07 0.08 0.10	0.04 0.06 0.08 0.10 0.12	0.05 0.07 0.09 0.12 0.14		0.06 0.09 0.12 0.15 0.18
8 9 10	7000 3000 9000 0000 2000				0.76	0.95 1.02 1.08 1.14	1.13 1.22 1.31 1.38 1.50	1.31 1.43 1.53 1.62 1.77	1.49 1.62 1.75 1.86 2.05	1.67 1.82 1.97 2.09 2.31	1.93 2.12 2.29 2.44 2.70	2.19 2.40 2.60 2.78 3.09	2.36 2.60 2.81 3.01 3.34	0.00 0.00 0.00 0.00 0.00	0.02 0.03 0.03 0.03 0.04	0.05 0.05 0.06 0.07 0.08	0.07 0.08 0.09 0.10 0.12	0.09 0.11 0.12 0.13 0.16	0.12 0.13 0.15 0.17 0.20	0.14 0.16 0.18 0.20 0.24	0.16 0.19 0.21 0.23 0.28	0.21 0.24 0.27	0.21 0.24 0.27 0.30 0.36

									J	Sect	tion N	/licro	-V Po	wer	Ratin	ıgs										
		J Section Micro-V Power Ratings Basic Horsepower per Rib for Small Outside Diameter												Add	itional	Horsep	ower I	oer Rib	for Sp	eed R	atio					
	(in)	0.80	0.90	1.00	1.10	1.20	1.30	1.40	1.50	1.60	1.70	1.80	1.90	2.00	2.20	2.40	1.00 to	1.03 to	1.07 to	1.11 to	1.17 to	1.24 to	1.34 to	1.48 to	1.72 to	2.32 and
	mm 575	20.3 0.02	22.9 0.03				33.0 0.06	35.6 0.06	38.1 0.07	40.6 0.08	43.1 0.09	45.7 0.09	48.3 0.10	50.8 0.11	55.9 0.12	61.0 0.14	1.02 0.00	1.06	0.00	1.16 0.00	1.23		1.47 0.01	1.71		over 0.01
	690 725 870 950	0.02 0.02 0.02 0.02 0.02	0.03 0.03 0.03 0.04	0.03 0.04 0.04 0.05 0.05	0.04 0.05 0.05 0.06 0.06	0.03 0.06 0.06 0.07 0.07	0.07 0.07 0.08 0.09	0.07 0.08 0.09 0.10	0.07 0.08 0.09 0.10 0.11	0.00 0.09 0.10 0.11 0.12	0.10 0.11 0.12 0.13	0.11 0.12 0.13 0.15	0.10 0.12 0.12 0.15 0.16	0.13 0.13 0.16 0.17	0.15 0.15 0.18 0.19	0.14 0.16 0.17 0.20 0.21	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.01 0.01	0.01 0.01 0.01	0.01 0.01 0.01 0.01 0.01	0.01 0.01 0.01	0.01 0.01 0.01 0.01	0.01 0.01 0.01 0.01 0.01
	1160 1425 1750 2850 3450	0.03 0.03 0.03 0.04 0.04	0.04 0.05 0.06 0.08 0.08	0.06 0.07 0.08 0.11 0.12	0.07 0.08 0.10 0.14 0.16	0.09 0.10 0.12 0.17 0.20	0.10 0.12 0.14 0.21 0.24	0.12 0.14 0.16 0.24 0.28	0.13 0.15 0.18 0.27 0.31	0.14 0.17 0.20 0.30 0.35	0.16 0.19 0.22 0.33 0.39	0.17 0.21 0.24 0.36 0.43	0.19 0.22 0.26 0.40 0.46	0.20 0.24 0.28 0.43 0.50	0.23 0.27 0.32 0.49 0.57	0.26 0.30 0.36 0.55 0.64	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.01	0.00 0.00 0.01 0.01 0.01	0.01 0.01 0.01 0.01 0.02	0.01 0.01 0.01 0.02 0.02	0.01 0.01 0.01 0.02 0.03	0.01 0.02 0.03 0.03	0.02 0.03 0.04	0.02 0.04	0.02 0.02 0.03 0.04 0.05
	500 600 700 800 900	0.02 0.02 0.02 0.02 0.02	0.02 0.03 0.03 0.03 0.04	0.03 0.03 0.04 0.04 0.05	0.04 0.04 0.05 0.05 0.06	0.04 0.05 0.06 0.06 0.07	0.05 0.06 0.07 0.07 0.08	0.06 0.07 0.08 0.08 0.09	0.06 0.07 0.08 0.09 0.10	0.07 0.08 0.09 0.11 0.12	0.08 0.09 0.10 0.12 0.13	0.08 0.10 0.11 0.13 0.14	0.09 0.11 0.12 0.14 0.15	0.10 0.11 0.13 0.15 0.16	0.11 0.13 0.15 0.17 0.18	0.12 0.14 0.16 0.18 0.20	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.01 0.01	0.01	0.01 0.01 0.01	0.01 0.01 0.01 0.01	0.01 0.01	0.01 0.01 0.01 0.01 0.01
	1000 1200 1400 1600 1800	0.02 0.03 0.03 0.03 0.03	0.04 0.04 0.05 0.05 0.06	0.05 0.06 0.07 0.07 0.08	0.06 0.07 0.08 0.09 0.10	0.08 0.09 0.10 0.11 0.12	0.09 0.10 0.12 0.13 0.14	0.10 0.12 0.13 0.15 0.17	0.11 0.13 0.15 0.17 0.19	0.13 0.15 0.17 0.19 0.21	0.14 0.16 0.19 0.21 0.23	0.15 0.18 0.20 0.23 0.25	0.16 0.19 0.22 0.24 0.27	0.18 0.21 0.24 0.26 0.29	0.20 0.23 0.27 0.30 0.33	0.22 0.26 0.30 0.34 0.37	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.01 0.01	0.00 0.01 0.01 0.01 0.01	0.01 0.01 0.01 0.01 0.01	0.01 0.01 0.01 0.01 0.01	0.01 0.02 0.02	0.01 0.02 0.02 0.02	0.02 0.02 0.02	0.01 0.02 0.02 0.02 0.03
	2000 3000 4000 5000 6000	0.04 0.04 0.04 0.04 0.04	0.06 0.08 0.09 0.10 0.11	0.09 0.11 0.13 0.15 0.17		0.13 0.18 0.22 0.26 0.30	0.36	0.18 0.25 0.31 0.37 0.42	0.20 0.28 0.35 0.42 0.48	0.23 0.32 0.40 0.47 0.53	0.25 0.35 0.44 0.52 0.59	0.27 0.38 0.48 0.57 0.65	0.30 0.41 0.52 0.62 0.70	0.32 0.44 0.56 0.66 0.76	0.36 0.51 0.64 0.76 0.87	0.41 0.57 0.72 0.85 0.97	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.01 0.01 0.01	0.01 0.01 0.01 0.02 0.02	0.01 0.01 0.02 0.02 0.03	0.01 0.02 0.03 0.03 0.04	0.02 0.02 0.03 0.04 0.05	0.03 0.04 0.05 0.06	0.03 0.04 0.06 0.07	0.04 0.05 0.06 0.08	0.03 0.04 0.06 0.07 0.09
rpm of Faster Shaft	7000 8000 9000 10000	0.04 0.03 0.02 0.01	0.11 0.11 0.11 0.11		0.30	0.32 0.35 0.37 0.39		0.46 0.50 0.54 0.57	0.53 0.58 0.62 0.65	0.59 0.65 0.69 0.73	0.66 0.72 0.77 0.81	0.72 0.79 0.84 0.89	0.78 0.85 0.91 0.96	0.84 0.92 0.98 1.03	0.96 1.04 1.11 1.16	1.07 1.16 1.23 1.28	0.00 0.00 0.00 0.00	0.01 0.01 0.01 0.02		0.03 0.04 0.04 0.05		0.08	0.08 0.09 0.10	0.09 0.10 0.11	0.10 0.11 0.13	0.10 0.11 0.13 0.14
of Fas	575	0.01	0.02	0.02	0.03	0.04	0.04	Rib for 0.05	0.05	0.06	0.06	0.07	0.08	0.08	0.09	0.10	0.00	Additi 0.00	0.00	0.00	0.00	_				0.01
rbm	690 725 870 950	0.01 0.01 0.02 0.02	0.02 0.02 0.03 0.03	0.03 0.03 0.03 0.04		0.04 0.04 0.05 0.05	0.05 0.05 0.06 0.06	0.06 0.06 0.07 0.07	0.06 0.06 0.08 0.08	0.07 0.07 0.09 0.09	0.08 0.08 0.09 0.10	0.08 0.09 0.10 0.11	0.09 0.09 0.11 0.12	0.10 0.10 0.12 0.13	0.11 0.11 0.13 0.14	0.12 0.13 0.15 0.16	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00		0.01	0.01 0.01 0.01 0.01	0.01	0.01 0.01 0.01 0.01
	1160 1425 1750 2850 3450	0.02 0.02 0.02 0.03 0.03	0.03 0.04 0.04 0.06 0.06	0.04 0.05 0.06 0.08 0.09	0.05 0.06 0.07 0.11 0.12	0.06 0.07 0.09 0.13 0.14	0.08 0.09 0.10 0.15 0.18	0.09 0.10 0.12 0.18 0.21	0.10 0.11 0.14 0.20 0.23	0.11 0.13 0.15 0.23 0.27	0.12 0.14 0.17 0.25 0.29	0.13 0.15 0.18 0.27 0.32	0.14 0.16 0.20 0.29 0.34	0.15 0.18 0.21 0.32 0.37	0.17 0.20 0.24 0.36 0.43	0.19 0.23 0.27 0.41 0.48	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.01 0.01	0.00 0.01 0.01 0.01 0.01	0.01 0.01 0.01 0.01 0.02	0.02	0.01 0.02	0.01 0.01 0.02	0.03	0.01 0.02 0.02 0.03 0.04
	500 600 700 800 900	0.01 0.01 0.01 0.02 0.02	0.02 0.02 0.02 0.02 0.03	0.02 0.02 0.03 0.03 0.03		0.03 0.04 0.04 0.05 0.05		0.04 0.05 0.06 0.06 0.07	0.05 0.06 0.06 0.07 0.08	0.05 0.06 0.07 0.08 0.09	0.06 0.07 0.08 0.09 0.09	0.06 0.07 0.08 0.09 0.10	0.07 0.08 0.09 0.10 0.11	0.11	0.08 0.10 0.11 0.12 0.14	0.09 0.11 0.12 0.14 0.15	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00		0.00 0.00 0.00 0.00 0.00	0.00	0.00 0.00 0.00 0.00 0.01	0.00 0.00 0.01 0.01	0.00 0.01 0.01 0.01	0.01 0.01	0.01
	1000 1200 1400 1600 1800	0.02 0.02 0.02 0.02 0.02	0.03 0.03 0.04 0.04 0.04	0.06	0.06 0.06 0.07 0.08	0.06 0.06 0.07 0.08 0.09	0.08 0.09 0.10 0.11	0.08 0.09 0.10 0.11 0.13	0.09 0.10 0.11 0.13 0.14	0.11 0.13 0.14 0.16	0.10 0.12 0.14 0.15 0.17	0.11 0.13 0.15 0.17 0.19	0.20	0.15 0.18 0.20 0.22	0.15 0.18 0.20 0.22 0.25	0.17 0.20 0.22 0.25 0.28	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.01 0.01	0.01 0.01 0.01 0.01	0.01 0.01 0.01 0.01	0.01 0.01 0.01 0.01	0.01 0.01 0.01 0.01	0.01 0.01 0.01 0.02 0.02	0.01 0.01 0.02 0.02
	2000 3000 4000 5000 6000		0.05 0.06 0.07 0.08 0.08	0.11 0.12	0.11 0.13 0.16 0.17	0.10 0.13 0.16 0.19 0.21	0.20 0.23 0.27	0.14 0.19 0.24 0.28 0.32	0.15 0.21 0.26 0.31 0.35	0.35 0.40	0.18 0.26 0.32 0.38 0.44	0.21 0.29 0.36 0.43 0.49		0.42 0.50 0.57	0.27 0.38 0.48 0.57 0.65	0.30 0.43 0.54 0.64 0.72	0.00 0.00 0.00 0.00 0.00	0.00 0.00 0.00 0.01 0.01	0.00 0.01 0.01 0.01 0.01	0.01 0.01 0.01 0.02 0.02	0.02 0.03	0.02 0.02 0.03 0.04	0.02 0.03 0.04 0.04	0.02 0.03 0.04 0.05	0.05 0.06	0.03 0.04 0.05 0.06
	7000 8000 9000 10000	0.02 0.01 0.01 0.00	0.08 0.09 0.09 0.09	0.14	0.20 0.22	0.23 0.25 0.27 0.28	0.29 0.32 0.34 0.36	0.35 0.38 0.41 0.43		0.45 0.49 0.53 0.56	0.49 0.53 0.57 0.60	0.54 0.59 0.63 0.67	0.58 0.63 0.67 0.71	0.69	0.72 0.78 0.83 0.87	0.80 0.87 0.92 0.95	0.00 0.00 0.00 0.00	0.01 0.01 0.01 0.01	0.02 0.02 0.02 0.02	0.02 0.03 0.03 0.04			0.06 0.06	0.07 0.07		0.09 0.10

I. Operating Characteristics

A. High Speed Drives

One major advantage of Gates Polyflex JB and Micro-V belts is the ability to operate smoothly and efficiently at high belt and shaft speeds. For example, shaft speeds of 30,000 rpm and higher have been achieved with smaller Polyflex JB cross sections. Polyflex JB and Micro-V belts both have the ability to transmit power to shafts turning at high speed mainly because the self-imposed centrifugal force acting on it is low.

Centrifugal tension occurs in a belt because of centrifugal force — the belt is rotating around the drive. Two things govern the magnitude of centrifugal tension acting in a belt drive:

- (1.) The size of the belt (cross-sectional mass).
- (2.) The speed the belt is traveling.

The relationship of these items is expressed in the following formula:

$$T_C = MV^2$$

Where:Tc = Centrifugal tension, (lb)

M = A constant depending on mass of belt

V = Belt speed, (ft/min)

The formula shows, as the size (mass) of the belt increases, centrifugal tension increases. But, more influential is speed, which increases exponentially.

Because a V-belt is basically a tension carrying member, its horsepower rating increases with speed until a maximum value is reached, as illustrated in Fig. 23. As belt speed increases, the increase in centrifugal tension creates a need to increase the installation tension so the desired running tension is obtained. Beyond this point, centrifugal tension increases to such a level it starts to reduce the available working tension, causing the horsepower rating to drop off. (See Fig. 23).




Figure 23 - Available Belt Working Tension

Polyflex JB belts have proportionally higher horsepower ratings than any other conventional type V-belt. This is due mainly to the belt cross-sectional shape and special polyurethane material, as previously described. For high speed drives, this higher horsepower rating is further extended because the rotating mass of Polyflex JB belts is reduced - smaller cross section, lighter material. Because of these unique characteristics, Polyflex JB belts may be applied on high speed drives where other belt types cannot be used.

B. Smooth Running

Gates Polyflex JB and Micro-V belts are the smoothest running V-belt drives available. For most applications, conventional V-belts transmit power from the driveR to driveN shafts very smoothly, with a minimum of vibration. Some high speed, high precision equipment may demand better performance than a conventional V-belt which is designed mainly for heavy duty, industrial power transmission.

Smooth running characteristics of a belt drive are determined by measuring the variation in center distance as the belt slowly rotates around sheaves on a special measuring machine. The machine uses one shaft on a movable base and holds the belt at constant measuring tension. There are no industry standards prescribing levels of smooth running performance. When smooth running is specified as a special requirement, most manufacturers will only supply these belts on a made-to-order basis.

Conventional V-belts are usually manufactured by plying up layers of various rubber stocks, fabric and tensile cord. In most applications, the layers and overlaps do not disturb the drive operation. But, as speeds increase and sheave diameters decrease, or the machinery supporting the drive becomes more sensitive or compliant, the small discontinuities in the layers, coupled with overlaps in fabric, become much more apparent with respect to smooth running.

Due to the special patented manufacturing process, Polyflex JB belts have exceptionally smooth operating characteristics. Belts are cast in polyurethane and precision ground to assure the best possible cross sectional uniformity. The result is low center distance variation and minimal vibration.

Gates Micro-V belts also have excellent smooth running characteristics. Micro-V and Polyflex JB drives have been used extensively on applications such as precision grinders, medical equipment, office equipment, business machines, etc. where smooth running is an essential performance requirement.

C. Noise

Polyflex JB and Micro-V drives generate minimal noise levels when installed and operating properly. They can, however, generate noise in adverse conditions such as misalignment, improper tension, under design, etc.

Since Polyflex JB belts have a polyurethane body with a high coefficient of friction, they may react on a steel surface causing noise, particularly on a misaligned drive. When a drive is misaligned the V-belt will not enter the sheave groove properly. It will stick and rub heavily on the side on the sheave causing noise. (See Fig. 24). Low belt tension can also be a source of noise problems. (See Section *III. Drive Alignment* and Section *IV. Belt Tensioning*, page 92-93.)




Figure 24 - Misaligned Belt Entry

Ribs molded laterally across the top of Polyflex JB belts help to reduce bending stresses and increase torsional stiffness. Because of the ribbed overcord, a backside idler may generate objectionable noise. The sound level produced is usually inversely proportional to the pulley diameter. So, the larger the pulley diameter, the lower the noise level. Backside idlers should be as large as possible. See Table 43, Page 95, Minimum Sheave Diameter for more information on backside idler recommendations.

I. Operating Characteristics - continued

Micro-V belts can be prone to slippage when installed with less than adequate tension, or when operating on a drive system with flexing centers. This potential slippage can result in noise. See Section *IV. Belt Tensioning* on Page 92.

In many cases the belt drive system is not the primary cause of noise. Undersized, poorly lubricated, worn or misaligned bearings can cause significant noise levels. Rotating parts of a total system can create air movement patterns that generate noise. A weak structure could flex under the load and cause misalignment and affect components in the drive system, thereby creating noise. Also, make sure that the total system has not been designed into an echo chamber, amplifying an otherwise insignificant noise.

D. Static Conductivity

Polyflex JB belts do not meet the static-conductive requirements specified in RMA Bulletin IP-3-3. This bulletin describes those belt characteristics necessary for safe operation in potentially explosive or flammable environments. However, laboratory testing confirms that under dynamic operating conditions, Polyflex JB belts are non-static generating. Under normal operating conditions, Polyflex JB belts do not build up significant static charge.

When Polyflex JB belts are used in explosive or flammable environments, additional steps must be taken to protect against accidental static spark discharges:

- (1) The entire system must be properly grounded.
- (2) A static conductive brush or similar device is recommended to bleed off any static buildup on the belt if it should occur.

The nonstatic generating characteristics apply to new, clean belts. It is the user's responsibility to establish an effective preventive maintenance program to monitor equipment and to replace or repair components, as needed, for continued safe operation.

Micro-V belts do meet the static conductive requirements specified in RMA Bulletin IP-3-3 describing the characteristics necessary for safe operation in potentially explosive or flammable environments. This applies to new clean belts. Belt conductivity properties can be influenced by age and environmental debris.

E. Operating Environments

Caution should be used when installing Polyflex JB and Micro-V belt drives where debris is present. Debris can damage belts by becoming wedged between the belt's strands, causing damage or separation. Debris can also cause belts to become unstable and turn over. If the drive must operate in this type of environment, be sure to provide adequate shielding.

Since Polyflex JB belts use a 60° angle system, the coefficient of friction between the belt and sheave is extremely important. Any substance which decreases the coefficient of friction can cause belt slip. If the belt slips excessively, enough heat may be generated to cause catastrophic failure. Environmental contamination can also cause Micro-V belts to slip.

Polyflex JB belt performance is generally unaffected in ambient temperature environments between -65°F and +185°F (-54°C and +85°C). Micro-V belts are capable of operating between -30°F and +180°F (-34°C and +82°C). Contact Gates Application Engineering if the drive must operate in temperatures that exceed these limits.

II. Calculating Speed Ratio

Nominal pitch is satisfactory for use in speed calculations on most drives. Most machines do not require exact driveN speeds to operate efficiently, and speeds vary because the speed of common driveR machines usually varies by several percent. For example, the speed of an ordinary induction type electric motor varies with load and line voltage.

Speed ratio may be determined by the following formula:

 $\mbox{Speed Ratio} = \frac{\mbox{DriveN Pitch Diameter}}{\mbox{DriveR Pitch Diameter}}$

Find the pitch diameters of the sheaves by adding the appropriate factor listed in Table 33 on Page 84 to the sheave outside diameters.

III. Drive Alignment

The "high performance" features (high HP capacity, smooth running, etc.) of Gates Polyflex JB and Micro-V belt drives may be realized on drives where proper sheave alignment is maintained. Polyflex JB and Micro-V belts should not be used on twisted or turned drives, or where shaft misalignment can exceed the amount specified in the following text. Sheave misalignment can cause belt instability, belt and sheave wear, strand separation, noise or excessive machine vibration.

There are two types of misalignment:

- Parallel
- Angular

Parallel misalignment occurs when the driveR and driveN shafts are parallel, but the sheave faces are in different planes. When the two shafts are not parallel the drive is angularly misaligned. Fig. 25 illustrates both parallel and angular misalignment. The fleeting angle is the angle at which the belt enters and exits the sheave and is the sum of parallel and angular misalignment.

Any degree of sheave misalignment will result in a reduction in belt life which is not accounted for in the normal drive design procedure. Misalignment of Polyflex JB and Micro-V belt drives should not exceed 1/4° or about 1/16 inch offset per foot of linear distance.

One easy way to check alignment is to use a straightedge checking alignment in both directions. In other words, lay the straightedge across the face of the driveN sheave and check driveR alignment. Then lay the straightedge across the driveR and check the positioning of the driveN sheave. This procedure will check for both parallel and angular misalignment. (Make sure the groove location from the sheave face is equal for both sheaves. If they are not equal, allow for the difference when measuring alignment.)




Figure 25 – Types of Misalignment

IV. Belt Tensioning

In order to obtain full benefit of all the performance advantages offered by using Polyflex JB and Micro-V drives on various applications, special attention is required for belt tensioning. Excessive belt slip can result from low belt tension or improper drive design. If a Polyflex JB belt slips, enough heat may be generated to cause catastrophic belt failure.

Tensioning Polyflex JB and Micro-V drives by "feel" may result in performance problems unless the installer has extensive experience with the particular drive assembly. The relatively small belts, coupled with proportionally higher horsepower capacity makes the belts "feel" tighter than they actually are. For example, 50 pounds tension in a large industrial V-belt may not remove the sag, whereas 50 pounds in a 5M or J section belt makes them feel quite snug.

It is common practice to measure installation tension. Numerical methods for measuring tension have several advantages. For example, they prevent over or under tensioning a drive, thus preventing possible bearing or belt damage.

The procedures that follow explain how to properly pre-tension a drive when it is stopped (static tension) so belt tension will be correct when the drive is operating. Static tension (sometimes referred to as installation tension) can be measured by the force-deflection method. The amount of force needed to deflect a belt a known amount (see Fig. 26) is measured and compared to the recommended force. Adjustments can then be made as needed.




Figure 26 - Belt Deflection Distance

Step 1. Calculate the required static tension per strand.

Formula 11 - English Units

$$T_{st} = 15 \quad \left(\frac{B-G}{G}\right) \quad \frac{(HP) (10^3)}{(N_b) (V)} + \frac{mV^2}{10^6}$$
, lb.

Where: $T_{st} = Static tension$ (lb), per strand.

B = Belt type (5M Polyflex JB = 2.50, J Micro-V = 2.67)

G = Arc correction factor from Table 34, Page 85

HP = Driver load in horsepower

 $N_b = Number of Belts (This is the total number of strands or ribs on the drive.)$

V = Belt speed (ft/min; Formula 12, page 93)

m = Constant from Table 39.

PD = Pitch Diameter (in) (See Table 33, Page 84.)

Formula 12 - English Units

$$V = \frac{\text{(PD) (rpm)}}{3.82}$$
, ft/min

Table 39 – Factor m, Y and Minimum T_{st} (English)

Cross Section	m	Υ	*Minimum T _{st} (lb)
3M Polyflex JB	0.030	1.00	5.0
5M Polyflex JB	0.050	1.20	8.0
J Micro-V	0.035	0.56	2.8

Formula 13 - Metric Units

$$T_{st} = 450 \quad \left(\frac{B - G}{G}\right) \frac{(kW)}{(N_v)(V)} + (mV^2), N$$

Where: T_{St} = Static tension in Newtons, per strand

 $\label{eq:Belt type (5M Polyflex JB = 2.50,} \ \ J \ \mbox{Micro-V} = 2.67)$

G = Arc correction factor from Table 34, Page 85

KW = DriveR load in kilowatts

 $N_b = Number of Belts (This is the total number of strands or ribs on the drive.)$

V = Belt speed (m/s; Formula 14, Page 93)

m = Constant from Table 40, Page 93

PD = Pitch Diameter (mm) (See Table 33, Page 84.)

IV. Belt Tensioning - continued

Formula 14

$$V = \frac{(PD) (RPM)}{19100}$$
, m/s

Table 40 – Factor m, Y and Minimum T_{st} (Metric)

-5t ()													
Cross Section	m	Υ	*Minimum T _{st} (Newtons)										
3M Polyflex JB	0.005	1.8	20.0										
5M Polyflex JB	0.009	2.2	35.0										
J Micro-V	0.006	1.03	12.5										

Note: *If the value of T_{st} , calculated in Step 1, is less than the Minimum Tst in Table 39 or 40, use the Minimum T_{st} value from the table for T_{st} to calculate Minimum and Maximum deflection forces in Step 2. The minimum value must be used on lightly loaded drives due to belt stiffness so the belt will properly conform to the sheave.

Step 2. Calculate the minimum and maximum recommended deflection forces per strand.

A. Measure the span length (t) on the drive or calculate span length (t) using the formula below:

Formula 15

Where: t = Span length, inches

$$t = CD \left[1 - 0.125 \left(\frac{D - d}{CD} \right)^2 \right]$$

CD = Center distance, inches

D = Large sheave or pulley diameter, inches

d = Small sheave diameter, inches

B. If the drive uses only a single, 2, 3, 4 or 5-strand Polyflex JB belt, calculate the minimum and maximum recommended deflection force using these formulas.

Formula 16 - English Units

Formula 17 – English Units

Deflection Force per strand, Min. =
$$\frac{T_{st} + \left(\frac{t}{Le}\right) \ Y}{16}$$
 , lb.

Where: T_{St} = Static tension per strand from Step 1.

Deflection Force per strand, Max. =
$$\frac{1.5 \, T_{st} + \left(\frac{t}{Le}\right)}{16} \, Y}{16}$$
, lb.

Y = Constant from Table 39, page 92

t = Span length, inches

 $L_e = Effective Belt length, inches$

Formula 18 - Metric Units

Deflection Force per strand, Min. =
$$\frac{T_{st} + \left(\frac{t}{Le}\right) Y}{25}$$
, N

Formula 19 - Metric Units

Deflection Force per strand, Max. =
$$\frac{1.5 \, T_{st} + \left(\frac{t}{Le}\right) \, Y}{25}$$
, N

Where: T_{St} = Static tension per strand from Step 1.

Y = Constant from Table 40

t = Span length, millimeters

Le = Effective Belt length, millimeters

C. If the drive uses two or more Polyflex JB belts (should be matched sets), calculate the minimum and maximum recommended deflection forces using the formula below:

Formula 20 - English Units

Deflection Force per strand, Min. = $\frac{T_{st} + Y}{16}$, Ib.

Formula 21 - English Units

Deflection Force per strand, Max. = $\frac{1.5 T_{st} + Y}{16}$, lb.

Where: T_{St} = Static tension per strand from Step 1.

Y = Constant from Table 39, page 92.

Formula 22 - Metric Units

Deflection Force per strand, Min. =
$$\frac{T_{st} + Y}{25}$$
, N

Formula 23 - Metric Units

Deflection Force per strand, Max. =
$$\frac{1.5 T_{st} + Y}{25}$$
, N

Where: T_{St} = Static tension per strand from Step 1.

Y = Constant from Table 40.

Step 3. Minimum and maximum deflection forces are calculated on a per strand or rib basis. The values in Step 2 should be multiplied by the number of strands in the belt which is being deflected. For example, if a 3-strand Polyflex JB belt is to be deflected, the minimum and maximum deflection forces should be multiplied by 3.

Step 4. Calculate the deflection distance.

The force deflection procedure is based on the following belt span deflection distances:

Formula 24

Deflection distance
$$=\frac{t}{64}$$
, inches; or $=\frac{t}{100}$, mm

Where: t = Span lengths

Step 5. Apply the tension.

- A. Midway between the belt contact points on the two sheaves, apply a force perpendicular to the belt large enough to deflect it from its normal position by the amount calculated in Step 4. Be sure the force is distributed evenly across the belt top width. When pushing on a multiple strand belt, for example, it may be necessary to use a bar under the gauge to distribute the force equally on all strands. (This force can be applied by pushing the belt in or pulling it out.) At least one sheave should be free to rotate.
- **B.** Compare this deflection force with the range of forces calculated in Step 3.
 - 1. If this force is less than the recommended minimum, the belt should be tightened.
 - 2. If this force is more than the recommended maximum, the belt should be loosened.

Ideally, the maximum deflection force should be used when installing the belts and they should be retensioned when the deflection force falls below the minimum value calculated in Step 2.

V. Installation and Takeup Allowances

Like any power transmission belt drive, installation allowance is necessary for Polyflex JB and Micro-V drives to assure the belt can be installed without damage and then tensioned correctly. The standard installation allowance is the minimum decrease in center distance required to install the belt on the sheaves (See Fig. 27).

NOTE: A belt should never be rolled onto a sheave. This can damage tensile cords in the belt resulting in premature failure. The damage may be invisible and difficult to identify as the cause of failure. A rolled on belt, because of cord damage, may also elongate rapidly and run out of takeup.




Figure 27 - Installation and Takeup

Takeup allowance is the increase in center distance which permits retensioning the belt due to wear and elongation. Takeup values lower than standard practice may not permit full belt life and could be a cause for excessive slipping.

Installation and takeup allowances are listed in Tables 41 and 42.

Table 41 – 5M Polyflex JB Installation and takeup Allowances

	Center Distance Allowance for										
Standard	Insta	allation	Tak	eup							
Effective Length	(in)	(mm)	(in)	(mm)							
175 - 300	0.4	10	0.2	5							
307 - 710	0.6	15	0.6	15							
730 - 1090	0.9	25	1.1	30							
1120 - 1500	1.1	30	1.4	35							

Table 42 – J Micro-V Installation and Takeup Allowances

	Center	Distance	Allowa	nce for
Standard	Insta	allation	Tak	eup
Effective Length	(in)	(mm)	(in)	(mm)
Up through 20.0	0.4	10.2	0.3	07.6
20.1 through 40.0	0.5	12.7	0.5	12.7
40.1 through 60.0	0.6	15.2	0.7	17.8
60.1 through 80.0	0.7	17.8	0.9	22.9
80.1 through 100.0	0.8	20.3	1.1	27.9

VI. Idler Usage

Idlers are either grooved sheaves or flat pulleys which do not transmit power. They are used in Polyflex JB and Micro-V drives to perform these functions:

- Provide takeup for fixed center drives.
- Maintain belt tension; i.e., when the idler is spring-loaded or weighted.
- Increase arc of contact on critically-loaded sheaves.
- Break up long spans where span vibration or belt whip may be a problem.
- Clear obstructions.

NOTE: An idler can solve the design problems above. Since an idler always imposes additional bending stresses on the belt, it usually is best to design the drive without idlers if possible. Also, from an economic standpoint, it is generally more cost effective to provide takeup by movement of either the driveR or driveN shaft rather than by inserting an idler.

When using idlers, certain principles should be followed to obtain the best possible drive and to minimize common idler problems. The important design considerations are:

- · Placement in the drive (inside vs. outside).
- · Placement on tight or slack sides.
- · Idler location in span.
- Diameter.
- Grooved or flat.
- Center distance, belt length, installation and takeup.
- Inside or Outside:

Idlers may be placed either inside or outside the drive, as shown in Fig. 28 and Fig. 29.

An inside idler decreases the arc of contact on the adjacent sheaves; whereas, a backside idler increases the arc of contact on the adjacent sheaves. Either may be used, but a backside idler must be larger (See B. *Idler Diameters* on Page 95). If a backside idler is used for belt takeup, the idler penetration (amount of takeup) is limited by the belt span on the opposite side of the drive.




Figure 28 - Inside Idler




Figure 29 - Outside or Backside Idler

Backside idlers are always flat pulleys, since they contact the top of the Polyflex JB or Micro-V Belt. Inside idlers can be either flat or grooved. If they are grooved, the idler sheave must be machined correctly for the specific belt cross section. (See Sections VIII. Polyflex JB Sheave Groove Specifications and IX. Micro-V Pulley Groove Specifications on pages 97 and 98.

A. Idler Placement In the Span

Idler position in the span with respect to other sheaves.

A grooved inside idler may be located at any point in the span, but preferably so that it results in nearly equal arcs of contact on the two adjacent sheaves. See Fig. 30 on Page 95.



VI. Idler Usage - continued




Figure 30 - Equal Arcs

A flat idler pulley (inside or backside) should be positioned in the span so that the distance between the idler and the sheave following the idler (in the direction the belt is traveling) is reasonably large. See Fig. 31 below. In this position, possible misalignment due to belt tracking will be minimized because the increased span length allows the belt to "realign" itself before entering the adjacent sheave. This, however, reduces the amount of idler movement available for belt takeup.




Figure 31 - Locating Flat Idler

In certain applications that have long belt spans and moderate shock loading, span vibration or belt whip may occur. If this happens, span vibration can be minimized by breaking up the long belt spans with contact idlers.

Tight or slack spans

Figs. 32 and 33 show the idler positioned on the tightside and slackside spans of the drive.




Figure 32 - Tightside Idler




Figure 33 - Slackside Idler

If possible, the idler should be placed on the slackside span of the drive (See Fig. 33) rather than on the tightside.

The span tension directly influences the amount of stress on the belt. Since the operating tensions are lower in the slackside span, the belt stresses are significantly reduced when the idler is placed in this span. Reduced belt stresses reduce the amount of belt fatigue, resulting in longer belt life.

Spring-loaded idlers provide belt tension proportional to the load being transmitted. A useful paper, "Spring-Loaded Idler Designs for V-Belt Drives" ASAE Paper No. 75-1524 is available from Gates Application Engineering upon request.

This text describes proper design and analysis procedures, as well as a comparison between the operating characteristics of spring-loaded (automatic) and manual tensioning systems.

Spring-loaded or weighted idlers should always be located on the slackside because the spring force, or weight, can be much less in this position. In addition, these idlers should not be used on a drive where the load can be reversed; i.e., where the slackside can become the tightside.

Contact Gates Application Engineering for assistance in determining the force which idlers must impose on belts. The idler force must be such that the resulting belt tension in the span over the idler is equal to the slack span operating tension. Calculate the span operating tensions using the procedure outlined in *Section X. Belt Pull and Bearing Loads* on Page 99.

B. Idler Diameters

Idler diameters should be at least as large as the recommended sheave diameters in Table 43.

Table 43 – Minimum Recommended Idler
Diameters

Min. O.D. of Min. O.D. Min. O.D. of

Belt Cross Section	Min. O.D. of of Grooved Idler (in)	Min. O.D. of Flat Inside Idler (in)	Min. O.D. of outside or Backside Idler (in)
3M Polyflex JB	0.67	0.49	1.80
5M Polyflex JB	1.04	0.78	2.90
J Micro-V	0.80	0.65	1.25

C. Grooved or Flat

Inside idlers may be either grooved or flat, and backside idlers should always be flat.

It is important to remember an outside idler on the ribbed back of Polyflex JB belts may be noisy. For additional information, refer to Section \emph{I} , Part \emph{C} on Page 90.

D. Idler Details

Flat idlers should not be crowned. However, flanging of idlers is good practice. If flanges are used, the inside bottom corner should not be rounded because this may cause the belts to climb off the pulleys.

Brackets for idlers should be rigid. Drive problems described as "belt stretch," "belt instability," "short belt life," "belt vibration" and others are frequently traced to flimsy idler bracketry. This bracketry must be designed to withstand the forces imposed by the operating belt tensions.

VII. Design of Drives With Idlers

To calculate the proper belt length and required installation and takeup allowances for a drive that uses idlers, follow the procedure below.

Step 1

Use the Drive Selection procedures on Pages 84-89 to determine the service factor, design horsepower proper cross-section and driveR/driveN sheave combination required for your drive. The required center distance between the driveR and driveN shafts should be known.

Step 2

Using the idler guidelines outlined in Section *VI. Idler Usage* on Page 94, select the diameter and placement of the idler(s) needed for the drive.

Step 3

Find a first-trial belt effective length by using the known center distance and selected sheave effective outside diameters (EOD) in Formula 25 below:

Formula 25

Belt Effective Length (in) = $2CD + 1.57(D + d) + \frac{(D - d)^2}{4CD}$

Where: D = Large sheave, outside diameter, inches

d = Small sheave, outside diameter, inches

CD = Center distance, inches

Step 4

Find the appropriate installation allowance for this first-trial belt length from Table 41 or Table 42 on Page 94. Multiply the installation allowance by 2 when working with belt effective length since Tables 41 and 42 are based upon center distance. Add installation allowance to trial length. If this is a nonstandard length, select the next larger standard belt length for the drive.

Step 5

Determine the maximum belt length for takeup. For the standard belt length selected in Step 4, find the takeup allowance in Table 41 or Table 42 on Page 94. Multiply this takeup allowance by 2 and add it to the standard belt effective length to determine the maximum belt effective length for takeup.


Step 6

Lay out the drive to scale using the selected diameters and centers. Using a trial-and-error method, position the idler in several locations until the correct belt effective length is obtained.

There are several methods to calculate belt effective length from a drive layout; i.e. a map-measuring device, or digitizer can be used to trace around the line indicating the belt length.

Another method involves measuring all the span lengths, and adding them to the arc lengths (the length of belt contacting the sheaves). Measure each arc of contact (wrap) with a protractor and calculate each arc length using Formula 26.

Formula 26



Arc Length = π x Arc of Contact x Diameter of Sheave NOTE: $\pi = 3.1416$

Step 7

Using the trial-and-error method, locate the idler in the minimum (belt installation) and maximum (belt takeup) positions. This step assures the idler has adequate movement to provide sufficient installation and takeup allowances. (NOTE: The minimum and maximum idler positions should reflect the actual bracketry design used to support the idler assembly). Measure each arc of contact.

Step 8

From Steps 6 and 7, examine the three drive layouts (installation, nominal and maximum belt lengths) and determine the smallest arc of contact for each loaded sheave or pulley. Find the appropriate Factor G in Table 44 for each of these sheaves.

Table 44 – Arc of Contact Correction Factor (G)

Arc of Contact on Small Sheave	Arc Correction Factor G		Arc of Contact on Small Sheave	Arc Correction Factor G		
(degrees)	Polyflex JB	Micro-V	(degrees)	Polyflex JB	Micro-V	
230	1.09	1.11	160	.95	.94	
220	1.08	1.09	150	.92	.91	
210	1.06	1.07	140	.89	.88	
200	1.04	1.05	130	.86	.84	
190	1.02	1.02	120	.82	.80	
180	1.00	1.00	110	.78	.76	
170	.98	.97	100	.74	.72	

NOTE: Use the smallest Factor G in the following design steps.

Step 9

Find the rated horsepower per strand or rib, using the smallest diameter loaded sheave in the drive, from the tables on Page 87, 88, or 89. Based on the standard belt length selected, determine the belt length correction factor K_L from Table 35 or Table 36 on Page 85. Calculate the corrected horsepower per strand or rib by multiplying the rated horsepower per strand or rib by the factor G and the belt length correction factor KL determined above.

Calculate the horsepower per strand or rib by multiplying the corrected horsepower per strand or rib by the appropriate Idler Correction Factor in Table 45 below.

Table 45 – Idler Correction Factor				
No. of Idlers in Drive	Idler Correction Factor			
0	1.00			
1	0.91			
2	0.86			
3	0.81			

Determine the number of strands or ribs required by dividing the design horsepower by the horsepower per strand or rib. The answer may contain a fraction. Always round to the next larger whole number of strands or ribs.

Subminimal idler diameters (smaller than recommended) are the single largest cause of problems with idler drives. These diameters impose additional stresses in the belt that will result in short belt life even if the number of strands or ribs is determined using the procedure above. Contact Gates Application Engineering for possible recommendations if subminimal sheaves must be used.

VIII. Polyflex JB Sheave Groove Specifications




	Table 46 – 5M Polyflex JB Sheave Groove Specifications										
Cross Section	Minimum Recommended Outside Diameter (in)	2a PD to OD Value (in) (bg)	(b _g) Groove Top Width (in) ±0.002 (S)	(S) Groove Spacing (in) +0.005 -0.002	(S _e) Edge Spacing (in) Minimum	(r _b) Bottom Radius (in) Maximum	Groove Outside Diameter Range (in)	(a) Groove Angle (Degrees) ±1/4°	(hg) Groove Depth (in) Reference**	(2K) Two Times Belt Extension (in) ±0.005	(d) Ball or Rod Diameter (in) ±0.0005
ЗМ	0.67	0.023	0.110	0.132	0.088	0.012	0.67 -0.90 Over 0.90	60 62	0.077 0.074	0.184 0.185	0.1250
5M	1.04	0.050	0.177	0.209	0.136	0.016	1.04 -1.26 1.27 -3.80 Over 3.80	60 62 64	0.129 0.124 0.120	0.209 0.211 0.213	0.1719

NOTES:

- 1. The sides of the groove shall not exceed 125 microinches (RMS) roughness.
- 2. The summation of deviations from S for all grooves and any one sheave shall not exceed ± 0.015 ".
- 3. The variation in diameter over-ball (Outside Diameter + 2K) shall not vary from groove to groove in any one sheave more than 0.002".


Outside Diameter Eccentricity

Radial runout shall not exceed 0.005" TIR for outside diameters up through 10.0". Add 0.0005" TIR* per inch of outside diameter for diameters more than 10.0".

Side Wobble


Axial runout shall not exceed 0.001" TIR for outside diameters up through 20.0". Add 0.0005" TIR* per inch of outside diameter for diameters more than 20.0".

*Total Indicator Reading



IX. Micro-V Pulley Groove Specifications

Pulley Groove Specifications For Gates J Section Micro-V® Drives



Where: Face Width = $S_g(N_g - 1) + 2S_e$ $N_g = Number of grooves$

	Table 47 – Micro-V Pulley Groove Specifications								
Cross Section	Minimum Recommended Outside Diameter (in)	2a PD to OD Value (In)	Sg* (in)	S _e (in)	r _b (in)	r _t +0.005 -0.000 (in)	α Groove Angle (°) (±0.25°)	h _g Minimum (in)	d ₈ ±0.0005 (in)
Н	0.50	0.020	0.063 ±0.001	0.080 +0.020 -0.010	0.013 +0.000 -0.005	0.005	40	0.041	0.0469
J	0.80	0.030	0.092 ±0.001	0.125 +0.030 -0.015	0.015 +0.000 -0.005	0.008	40	0.071	0.0625
К	1.5	0.038	0.140 ±0.002	0.125 +0.050 -0.000	0.020 +0.000 -0.005	0.010	40	0.122	0.1093

^{*}Summations of deviations from Sg for all grooves in any one pulley shall not exceed ± 0.010 .

The variations in pitch diameter between the grooves in any one pulley must be within the following limits:

Up through 2.9 and up through 6 grooves (Add 0.0001" for each additional groove)0.002" Over $2.9 \pm to$ and including 19.9" and up through 10 grooves (Add 0.0002" for each additional groove)0.005" Over 19.9" and up through 10 grooves (Add

0.0005" for each additional groove)0.010"

This variation can be easily obtained by measuring the distance across two measuring balls or rods placed in the grooves diametrically opposite each other. Comparing this "diameter-over-balls or -rods" measurement between grooves will give the variation in pitch diameter.

Other Pulley Tolerances



X. Belt Pull and Bearing Loads

Belt pull is the magnitude of force exerted on the sheaves by the belts. This force is often referred to as side load. Magnitude of the bearing load in driveR or driveN machines depends upon both the side load (shaft load) acting on the shaft and bearing locations with respect to side load. Side load is the combined load created by sheave weight and belt pull. In comparing these force components, the sheave weight is usually much less than belt pull and is typically ignored. However, critical applications requiring exacting shaft loading values should include sheave wieights in the calculations. Belt pull is a function of the following variables:

- Horsepower Transmitted For the following given drive, horsepower is directly proportional to the belt pull; i.e., as the load increases, the belt pull also increases.
- Belt Speed For the same horsepower, higher belt speed (larger sheave diameters) reduces belt pull.
- Arc of Contact Reduced arc of contact (wrap) requires more tension to prevent belt slip.
 This increases the belt pull for the same horsepower load.
- 4. Total Drive Installation Tension Minimum tension is required to keep Polyflex JB and Micro-V belts from slipping. However, if the installation tension is excessively high, the belt pull also will be higher than desired.

NOTE: Required belt pull is *independent of the number of belts or ribs* used on the drive. The number of belts or ribs only affects the amount of overhang from the center of belt pull to the bearings.

After accurately calculating belt pull, the designer can size the shafts and bearings required for the driveR and driveN equipment. It is important that the designer check the capacity of the shafts and bearings on both the driveR and driveN.

The driveR is usually an electric motor or engine. For electric motors, the belt pull is limited to an acceptable amount by either the recommended sheave diameters listed in Table 38 on Page 86 or by the minimum recommended diameters specified by the motor manufacturer.

Many handbooks show belt pull formulas that differ from formulas and procedures described in this section. These differences are the result of shortcuts that either ignore or average factors such as the arc of contact correction factor. The Gates method results in accurate calculations of belt pull for drives operating at design loads and tensions.

Belt tensions are based on a ratio between the tightside and slackside tensions. The design tension ratio for Polyflex JB drives is 5:1, and 4:1 for Micro-V, based upon 180° arc of contact. Design tension ratio is then corrected for the actual arc of contact.

The equipment designer should recognize that belts can be tensioned up to 1.5 times the design tension. (See Section IV. *Belt Tensioning* on Page 92 and 93. This higher tension expedites belt seating, but does not exist for the life of the drive. Shafts and bearings must be designed to tolerate these higher tensions for a reasonable amount of time without sustaining damage.

The following formulas are correct for Polyflex JB and Micro-V belt drives. When shaft load calculations are required, Gates recommends using the following formulas and procedures:

Belt Pull Calculations

Step 1 Calculate the Drive Tensions.

Belt pull is the vector sum of T_T and T_S , the tightside and slackside tensions, respectively. Calculate these tensions using the formulas below.

Formula 27

$$T_T = \frac{41,250 \; (\text{HP})}{\text{GV}} \; \; \text{, lb.} \tag{Polyflex JB} \label{eq:TT}$$

Formula 28

$$T_S = 33,000 \frac{(1.25 - G) (HP)}{GV}$$
, lb. (Polyflex JB)

Formula 29

$$T_T = \frac{44,000 \text{ (HP)}}{\text{GV}} \text{ , lb.} \tag{Micro-V}$$

Formula 30

$$T_S = 33,000 \frac{(1.33 - G) (HP)}{GV}$$
, lb. (Micro-V)

Where: $T_T = Tightside Tension$, pounds

T_S = Slackside Tension, pounds

HP = DriveR load in horsepower

V = Belt Speed (ft/min) = {(Pitch Diameter, in.) (rpm)} over 3.82

G = Arc of contact correction factor, (Table 34, Page 85.)

Step 2 Find the Vector Sum of T_T and T_S.

Calculate the magnitude and direction of the belt pull by summing the T_T and T_S vectors. The simplest method of calculating the belt pull vector is by graphical addition. After determining the belt pull vector, calculate true shaft loads by adding belt pull vectors to sheave weight vectors.

A. If only the magnitude of belt pull is needed, numerical methods for vector additions are faster than the graphical approach. If both magnitude and direction of belt pull are required, the vector sum of T_T and T_S can be calculated by graphical vector addition as shown in Fig. 34. The T_T and T_S vectors are parallel to the tightside and slackside, respectively, and they should be drawn to a convenient scale; i.e. 1 in. = 100 lb.

Fig. 34 shows the vector addition for belt pull on a motor shaft. Use the same procedures to determine the belt pull on the driveN shaft. This graphical illustration method should also be used for drives that have three or more sheaves or idlers.

For two-sheave drives, belt pull on the driveR and driveN shafts is equal but opposite in direction. For drives using idlers, both magnitude and direction may be different.




Figure 34 – Graphical Addition of $T_{T} \ and \ T_{S}$

X. Belt Pull and Bearing Loads - continued

B. For a two-sheave drive that requires only the magnitude of belt pull, use Formula 31 below:

Formula 31

Belt Pull = $\sqrt{\ T_{T}^2 + T_{S}^2 + 2T_{T}\,T_{S}\,Cos\ (180$ - $\varphi)}$, lb.

Where: $T_T = Tightside tension$, lb.

T_S = Slackside tension, pounds

 Φ = Arc of contact on small sheave, degrees

 $\phi = 2 \text{ Cos}^{-1} \left(\frac{D - d}{2CD} \right)$

Where: D = Large Diameter, inches

d = Small Diameter, inches

CD = Center Distance, inches

Belt pull also may be determined by using the alternate procedure as follows:

1. Add T_T and T_S (from Step 1 on Page 97 to find $T_T + T_S$ (arithmetic sum.)

2. Calculate D - CD

Where: D = Large Diameter, inches

d = Small Diameter, inches

CD = Center Distance, inches

Use value calculated above to find the vector sum correction factor from Fig. 35 below.

Multiply $T_T + T_S$ by the vector sum correction factor to find the true vector sum of $T_T + T_S$. This is the belt pull on either the driveR or driveN shaft.

Bearing Load Calculations

In order to find actual bearing loads, it is necessary to know the weights of machine components and the value of all other forces contributing to the load. However, sometimes it helps to know the bearing load contributed by the belt drive alone. The resulting bearing load due to belt pull can be calculated if both bearing spacing with respect to the sheave center and the belt pull are known. For approximate bearing load calculations, machine designers use belt pull and ignore sheave weight forces. If more accurate bearing load calculations are needed, or if the sheave is unusually heavy, the actual shaft load (including sheave weight) should be used.

A. Overhung Sheaves

Formula 32

Load at B =
$$\frac{\text{Shaft Load x (a + b)}}{\text{a}}$$

Formula 33

Load at
$$A = \frac{Shaft Load \times b}{a}$$




Figure 36 – Overhung Sheave

B. Sheave Between Bearings

Formula 34

Load at D =
$$\frac{\text{Shaft Load } \times \text{ c}}{\text{(c + d)}}$$

Formula 35

Load at C =
$$\frac{\text{Shaft Load } \times \text{ d}}{\text{(c + d)}}$$

Where: c and d = spacing (in). See Fig. 37 below.




Fig. 37 – Sheave Between Bearings




Figure 35 - Vector Sum Correction Factor

XI. Belt Storage and Handling

Below is a partial reprint of RMA (Rubber Manufacturers Association) Bulletin Number IP-3-4 which discusses general guidelines for storage of V-belts:

Storage of power transmission belts is of interest to users and distributors as well as manufacturers. Under favorable storage conditions, good quality belts retain their initial serviceability and dimensions. Conversely, unfavorable conditions can adversely affect performance and cause dimensional change. Good storage facilities and practices will allow the user to achieve the most value from belt products.

Power transmission belts should be stored in a cool and dry environment with no direct sunlight. When stacked on shelves, the stacks should be small enough to avoid excess weight on the bottom belts which may cause distortion. When stored in containers, the container size and contents should be sufficiently limited to avoid distortion, particularly to those belts at the bottom of the container.

Some things to avoid:

Do not store belts on floors unless a suitable container is provided. They may be susceptible to water leaks or moisture or otherwise damaged due to traffic.

Do not store belts near windows which may permit exposure to sunlight or moisture. Do not store belts near radiators or heaters or in the air flow from heating devices.

Do not store belts in the vicinity of transformers, electric motors or other electrical devices that may generate ozone. Also avoid areas where evaporating solvents or other chemicals are present in the atmosphere.

Do not store belts in a configuration that would result in bend diameters less than the minimum recommended sheave or pulley diameter for normal bends.

Equipment using belts is sometimes stored for prolonged periods (six months or more) before it is put in service or during other periods when it is idle. It is recommended that tension

on the belts be relaxed during such periods and that equipment storage conditions should be consistent with the guidelines for belt storage. If this is not possible, belts should be removed and stored separately.

Handling of Polyflex JB and Micro-V belts is also important. Belts should not be crimped or tightly bent. Belts should not be bent inside tighter than the smallest recommended sheave diameter for that particular cross section. (See Table 43 on Page 95.) Backside bending should be limited to the values specified in Table 43 on Page 95.

Belts may be cleaned by wiping with a rag slightly dampened with a light nonvolatile solvent. Soaking or brushing on of such solvent is not advisable. The belt must be completely dry before using on the drive. More obviously, sanding or scraping the belt with a sharp object to remove grease or debris is not recommended.

Drive Design

Speed Ratio =
$$\frac{\text{rpm (faster)}}{\text{rpm (slower)}} = \frac{\text{PD}}{\text{pd}} = \frac{\text{N}}{\text{n}}$$

Where:rpm = Revolutions per minute

PD = Larger pitch diameter

pd = Smaller pitch diameter

N = Larger sprocket grooves

n = Smaller sprocket grooves

Horsepower =
$$\frac{(0) (rpm)}{63025}$$

Where: Q = Torque, Ib-in

rpm = Revolutions per minute

Be sure to use torque and rpm values at the same shaft; do not mix torque and rpm values from different shafts.

Horsepower =
$$\frac{(T_e)(V)}{33,000}$$

Where: Te = Effective tension, lb.

V = Belt speed, ft/min

Design Horsepower = $hp \times SF$

Where: hp = Horsepower

SF = Service Factor

Torque (lb-in) =
$$\frac{63025 \text{ (hp)}}{\text{rpm}}$$

Where: hp = Horsepower

rpm = Revolutions per minute

Design Torque = $\mathbf{Q} \times \mathbf{SF}$

Where: T = Torque load

SF = Service factor

Service Factor =
$$\frac{\text{Rated T}_a}{(\text{T}_e + \text{T}_c)}$$

Where: $T_a = Rated belt working tension, lb.$

 T_e = Effective tension, lb.

 T_c = Centrifugal tension, lb.

Belt Speed (V) =
$$\frac{(PD) (rpm)}{3.82}$$

Where: V = Belt speed, ft/min

PD = Pitch diameter, in.

rpm = Revolutions per minute of same pulley

The exact belt pitch length, in inches, can be found as follows:

Pitch Length =
$$2(CD)(Cos \phi) + \frac{(PD + pd)}{2} + \frac{\phi (PD - pd)}{180}$$

$$\phi = Sin^{-1} \left(\frac{PD - pd}{2CD} \right)$$

Where: CD = Drive center distance, in.

PD = Large pitch diameter, in.

pd = Small pitch diameter, in.

The approximate center distance in inches can be found as follows:

Center Distance =
$$\frac{K + \sqrt{K^2 - 32(PD - pd)^2}}{16}$$

$$K = 4PL - 6.28 (PD + pd)$$

Where: PD = Large pitch diameter, in.

pd = Small pitch diameter, in.

PL = Belt pitch length, in.

The exact center distance can be calculated using an iterative process between the center distance and belt length equations above. The exact center distance has been found when the two equations converge.

Span Length =
$$\sqrt{CD^2 - \frac{(PD - pd)^2}{4}}$$

Where: PD = Large pitch diameter, in.

pd = Small pitch diameter, in.

CD = Drive center distance. in.

The arc of contact on the smaller pulley in degrees can be found as follows:

Arc of Contact =
$$180 - \left(\frac{60 \text{ (PD - pd)}}{\text{CD}}\right)$$

Where: PD = Large pitch diameter, in.

pd = Small pitch diameter, in.

CD = Drive center distance, in.

Drive Design - continued

The number of teeth in mesh on the smaller sprocket can be found as follows:

Teeth in Mesh = $\frac{(Arc)(n)}{360}$

Where: Arc $\,=\,$ Arc of contact; small sprocket, degrees

n = number of grooves, small sprocket

Drop any fractional part and use only the whole number as any tooth not fully engaged cannot be considered a working tooth.

If the teeth in mesh is less than 6, correct the belt torque rating with the following multiplication factors:

5 Teeth in Mesh - Multiply by 0.8

4 Teeth in Mesh - Multiply by 0.6

3 Teeth in Mesh - Multiply by 0.4

2 Teeth in Mesh - Suggest Redesign

1 Tooth in Mesh – Suggest Redesign

Torque loading due to flywheel effect (acceleration or deceleration) can be calculated as follows:

Torque (lb-in) = $\frac{0.039(RPM - rpm) (WR^2)}{t}$

Where: RPM = Final revolutions per minute

rpm = Initial revolutions per minute

WR2 = Flywheel effect, pound-feet²

(lb-ft²) (1 ft-lb-sec² is equivalent to 32.2 lb-ft²)

t = time, seconds

The flywheel effect of a sprocket can be estimated as follows:

WR² (lb-ft²) =
$$\frac{(F) (Z) (D^4 - d^4)}{1467}$$

Where: F = Face width of rim, in.

Z = Material density, lb/in³

D = Outside rim diameter, in.

d = Inside rim diameter, in.

Typical Values: 2024 Aluminum - 0.100 lb/in3

6061 Aluminum - 0.098 lb/in3

Iron - 0.284 lb/in3

Synchronous Belt Tension

Effective Pull

$$T_e = T_T - T_S = \frac{2(0)}{1}$$

pd

Where: $T_T = Tight \text{ side tension, lb.}$

 T_S = Slack side tension, lb.

Q = Torque Load, Ib-in

pd = Pitch diameter, in.

 T_e = Effective tension, lb.

Total Tension (8:1)

$$T_T + T_S = \frac{2.571(0)}{1.00}$$

pd

Where: $T_T = Tight side tension, lb.$

 T_S = Slack side tension, lb.

Q = Torque load, lb-in

pd = Pitch diameter, in

Tight Side Tension (8:1)

$T_T = \frac{2.286(0)}{}$

pd

Where: $T_T = Tight side tension, lb.$

Q = Torque load, lb-in

pd = Pitch diameter, in.

Slack Side Tension (8:1)

$T_S = 0.285(Q)$

pd

Where: $T_S = Slack$ side tension, lb.

Q = Torque load, lb-in

pd = Pitch diameter, in.

Working Tension

$T_w = (T_e + T_c)$ (SF)

Where: $T_W = Working tension$, lb.

 T_e = Effective tension, lb.

 T_c = Centrifugal tension, lb.

SF = Service Factor

Centrifugal Belt Tension

$$T_c = \frac{(m) (PD)^2 (rpm)^2}{16.2 \times 10^6}$$

Where: $T_c = Centrifugal tension$, lb.

m = Belt mass constant

PD = Smaller pitch diameter, in. rpm =Smaller sprocket revolutions per minute

Reit Section	Beit Wiath	<u>m</u>
2MR GT2	4mm	0.0234
	6mm	0.0351
	9mm	0.0522
	12mm	0.0693
3MR GT2	6mm	0.0693
	9mm	0.108
	12mm	0.135
	15mm	0.171
5MR GT2	9mm	0.153
	12mm	0.252
	15mm	0.342
	25mm	0.423
Dalt Castion	Dalt Width	
Belt Section	Belt Width	<u>m</u>
Belt Section 3M HTD	6mm	0.0612
	6mm 9mm	0.0612 0.0918
3M HTD	6mm 9mm 15mm	0.0612 0.0918 0.153
	6mm 9mm 15mm 9mm	0.0612 0.0918 0.153 0.1467
3M HTD	6mm 9mm 15mm	0.0612 0.0918 0.153 0.1467 0.2448
3M HTD	6mm 9mm 15mm 9mm	0.0612 0.0918 0.153 0.1467
3M HTD	6mm 9mm 15mm 9mm 15mm	0.0612 0.0918 0.153 0.1467 0.2448
3M HTD 5M HTD	6mm 9mm 15mm 9mm 15mm 25mm	0.0612 0.0918 0.153 0.1467 0.2448 0.4077
3M HTD 5M HTD	6mm 9mm 15mm 9mm 15mm 25mm	0.0612 0.0918 0.153 0.1467 0.2448 0.4077 0.0027
3M HTD 5M HTD	6mm 9mm 15mm 9mm 15mm 25mm 1/8" 3/16"	0.0612 0.0918 0.153 0.1467 0.2448 0.4077 0.0027 0.0036
3M HTD 5M HTD MXL	6mm 9mm 15mm 9mm 15mm 25mm 1/8" 3/16" 1/4"	0.0612 0.0918 0.153 0.1467 0.2448 0.4077 0.0027 0.0036 0.0045

Relt Section Relt Width

Polyflex® JB® Belt Tension

Effective Pull

 $T_T - T_S = 33,000 \left(\frac{hp}{V}\right) = T_e$

Where: $T_T = Tight$ side tension, lb.

 T_S = Slack side tension, lb.

hp = Horsepower

V = Belt speed, ft/min

 T_e = Effective tension, lb.

Total Tension (5:1)

 $T_T + T_S = 33,000 (2.5 - G) \left(\frac{hp}{GV}\right)$

Where: $T_T = Tight$ side tension, lb.

 T_S = Slack side tension, lb.

hp = Horsepower

V = Belt speed, ft/min

G = Arc of contact correction factor (Table 34, Page 85)

Tension Ratio

 $T_T / T_S = 1 \over 1 - 0.8G$ (Also, $T_T / T_S = e^{K \theta}$)

Where: $T_T = Tight$ side tension, lb.

 T_S = Slack side tension, lb.

G = Arc of contact correction factor (Table 34, Page 85)

e = Base of natural logarithms

K = .51230, a constant for V-belt drive design

 $\theta = \text{Arc of contact in radians}$

Tight Side Tension (5:1)

 $T_T = 41,250 \left(\frac{hp}{GV}\right)$

Where: $T_T = Tight$ side tension, lb.

hp = Horsepower

V = Belt speed, ft/min

G = Arc of contact correction factor (Table 34, Page 85)

Slack Side Tension (5:1)

 $T_S = 33,000 (1.25 - G) \frac{hp}{GV}$

Where: $T_S = Slack$ side tension, lb.

hp = Horsepower

V = Belt speed, ft/min

G = Arc of contact correction factor (Table 34, Page 85)

Micro-V® Belt Tension

Effective Pull

 $T_T - T_S = 33,000 \left(\frac{hp}{V}\right) = T_e$

Where: T_T = Tight side tension, lb.

 T_S = Slack side tension, lb.

hp = Horsepower

V = Belt speed, ft/min

 T_e = Effective tension, lb.

Total Tension (4:1)

 $T_T + T_S = 33,000 (2.67 - G) \left(\frac{hp}{GV}\right)$

Where: $T_T = Tight$ side tension, lb.

 T_S = Slack side tension, lb.

hp = Horsepower

V = Belt speed, ft/min

G = Arc of contact correction factor (Table 34, Page 85)

Tension Ratio

 $T_T / T_S = 1$ (Also, $T_T / T_S = e^{K \upsilon}$)

Where: T_T = Tight side tension, lb.

 $T_S = Slack side tension, lb.$

G = Arc of contact correction factor (Table 34, Page 85)

e = Base of natural logarithms

K = .44127, a constant for Micro-V drive design

 $\theta = Arc$ of contact in radians

Tight Side Tension (4:1)

$$T_T = 44,000 \left(\frac{hp}{GV}\right)$$

Where: TT = Tight side tension, lb.

hp = Horsepower

V = Belt speed, ft/min

G = Arc of contact correction factor (Table 34, Page 85)

Slack Side Tension (4:1)

$$T_S = 33,000 (1.33 - G) \left(\frac{hp}{GV}\right)$$

Where: TS = Slack side tension, lb.

hp = Horsepower

V = Belt speed, ft/min

G = Arc of contact correction factor (Table 34, Page 85)

Power Transmission Conversions

I OWCI	ii alioillioololi	OUIIVCI SIUIIS
		Torque Conver
Metric to U.S.		U.S. to Metric

Newton Meters x 141.6119 = Ounce Inches Newton Meters x 8.8508 = Pound Inches Newton Meters x 0.7376 = Pound Feet U.S. to Metric

Ounce Inches x 0.0071 = Newton Meters

Pound Inches x 0.1130 = Newton Meters

Pound Feet x 1.3558 = Newton Meters

sion Constants

Metric to Metric

Newton Meters x 10.1972 = Kilogram
Centimeter

Kilogram Centimeters x 0.0981 = Newton Meters
Newton Meters x 0.1020 = Kilogram Meters
Kilogram Meters x 9.8067 = Newton Meters

Power Conversion Constants

Metric to U.S. U.S. to Metric

Kilowatt x 1.3410 = Horsepower Horsepower x 745.6999 = Watt Watt x 0.0013 = Horsepower Horsepower x 0.7457 = Kilowatt

Velocity Conversion Constants

Metric to U.S. U.S. to Metric Metric to Metric to Metric

Meters/Second x 196.8504 = Feet/Minute Feet/Minute x 0.0051 = Meters/Second Meters/Second x 3.6000 = Kilometers/Hour

Other Conversions

Force Conversion Constants

Metric to U.S. U.S. to Metric Metric to Metric to Metric

Newtons x 3.5969 = Ounces Ounces x 0.2780 = Newtons Kilograms x 9.8067 = Newtons Newtons x 0.2248 = Pounds Pounds x 4.4482 = Newtons Newtons x 0.1020 = Kilograms X 0.2046 = Pounds Pounds x 0.4536 = Kilograms

Length Conversion Constants

Metric to U.S. U.S. to Metric

Millimeters x 0.0394 = Inches Inches x 25.4000 = Millimeters Meters x 39.3701 = Inches Inches x 0.0254 = Meters Meters x 3.2808 = Feet Feet x 0.3048 = Meters Meters x 1.0936 = Yards Yards x 0.9144 = Meters Kilometers x 3280.84 = Feet Feet x 0.0003048 = Kilometersx 0.6214 Statute Miles x 1.6093 Kilometers = Statute Miles = Kilometers x 0.5396 = Nautical Miles Nautical Miles x 1.8532 = Kilometers Kilometers

Area Conversion Constants

Metric to U.S. U.S. to Metric

Square Millimeters $\times 0.0016 = Square Inches$ Square Inches x 645.160 = Square Millimeters Square Centimeters x 0.1550 = Square Inches Square Inches x 6.4516 = Square Centimeters Square Meters x 10.7639 = Square FeetSquare Feet x 0.0929 = Square Meters Square Meters x 1.1960 = Square YardsSquare Yards x 0.8361 = Square Meters Hectares x 2.4711 = AcresAcres x 0.4047 = HectaresSquare Kilometers \times 247.105 = Acres Acres x 0.004047 = Square KilometersSquare Kilometers $\times 0.3861 = \text{Square Miles}$ Square Miles x 2.5900 = Square Kilometers

Weight Conversion Constants

Metric to U.S. Kilograms x 35.2740 = Ounces (Avd.) Metric Tons (1000 Kg)

Grams x 15.4324 = Grains Kilograms x 2.2046 = Pounds (Avd.)

Grams x 0.0353 = Ounces (Avd.)

Grams x 0.0338 = Fluid Ounces (water)

Kilograms x 2.2046 = Pounds (Avd.)

Metric Tons (1000 Kg)

Gross Ton (2240 lbs.)

x 1.1023

= Net

Other Conversions – continued

Weight Conversion Constants – continued

U.S. to Metric

 Grains
 x 0.0648
 = Grams
 Pounds (Avd.)
 x 0.4536
 = Kilograms

 Ounces (Avd.)
 x 28.3495
 = Grams
 Net Ton (2000 lbs.)
 x 0.9072
 = Metric Tons (1000 Kg)

 Fluid Ounces (water)
 x 29.5735
 = Grams
 Gross Ton (2240 lbs.)
 x 1.0160
 = Metric Tons (1000 Kg)

= 2116.3 pounds per square foot = 33.95 feet of water at 62°F

Ounces (Avd.) x 0.0283 = Kilograms

Measures of Pressure

= 144 pounds per square foot
= 0.068 atmosphere
= 2.042 inches of mercury at 62°F
= 27.7 inches of water at 62°F
= 2.31 feet of water at 62°F
= 30 inches of mercury at 62°F
= 30 inches of mercury at 62°F
= 144 pounds per square foot
= 0.433 pounds per square foot
= 0.433 pounds per square inch
= 1.132 feet of water at 62°F
= 13.58 inches of water
= 0.491 pounds per square inch

1 atmosphere Column of water 12 inches high, 1 inch in diameter = 34 lb.

Decimal and Millimeter Equivalents of Fractions						
Inches			Inches			
Fractions	Decimals	Millimeters	Fractions	Decimals	Millimeters	
1/64 —	.015625	.397	33/64 —	.515625	13.097	
1/32	.03125	.794	17/32	.53125	13.494	
3/64	.046875	1.191	35/64	.546875	13.891	
1/16 —	.0625	1.588	9/16 -		14.288	
5/64 ————	.078125	1.984	37/64	.578125	14.684	
3/32 —	.09375	2.381	19/32	.59375	15.081	
7/64	.109375	2.778	39/64	.609375	15.478	
1/8 —	.125	3.175			15.875	
9/64	.140625	3.572	41/64 — 5/8 –	.640625	16.272	
5/32 —	.15625	3.969	21/32 —	.65625	16.669	
1/64	.171875	4.366	43/64	.671875	17.066	
	.1875	4.763			17.463	
3/64 — 3/16 —	.203125	5.159	45/64 — 11/16 –	.703125	17.859	
7/32 —	.21875	5.556	23/32 —	.71875	18.256	
5/64	.234375	5.953	47/64	.734375	18.653	
	.250	6.350		.750	19.050	
7/64 — 1/4 —	.265625	6.747	49/64	.765625	19.447	
9/32 —	.28125	7.144	25/32 —	.78125	19.844	
9/64	.296875	7.541	51/64	.796875	20.241	
	.3125	7.938	10/10	0.10=	20.638	
5/16 —	.328125	8.334	53/64 — 13/16 –	.828125	21.034	
11/32 —	.34375	8.731	27/32 —	.84375	21.431	
23/64	.359375	9.128	55/64	.859375	21.828	
3/8	.375	9.525			22.225	
3/8 —	.390625	9.922	57/64	.890625	22.622	
13/32	.40625	10.319	20/22	.90625	23.019	
7/64	.421875	10.716	59/64	.921875	23.416	
	.4375	11.113	15/16 –		23.813	
7/16 —	.453125	11.509	61/64	.953125	24.209	
15/32	.46875	11.906	31/32	.96875	24.209	
13/32	.484375	12.303	63/64	.984375	25.003	
1/2 —	.500	12.700	1 -		25.400	

Power To or From Machinery

In the absence of accurate data on horsepower requirements for a drive, it is sometimes possible to calculate the power output from a driveN machine or the required power input to a driveN machine. In each formula below, efficiency must be known or estimated. For checking a drive which is providing power to a pump or generator, it is more conservative to estimate a low efficiency for the driveN machine. For power input to a drive from a motor or turbine, is more conservative to estimate high efficiency for the driveR machine. Efficiency is used as a decimal in the formulas. For example, if a pump is 70% efficient, use .70 in the formula.

Hydraulic Machinery

Power required by pumps

Horsepower =
$$\frac{(F) (p)}{(1714) (eff)}$$

Where: F = Flow rate, gallons per minute

P = Discharge pressure for pumps, inlet pressure for turbines, pounds/square inch

eff = Overall mechanical and hydraulic efficiency.

Power from water wheel or turbine

Horsepower =
$$\frac{(F) (p) (eff)}{(1714)}$$

Where: F = Flow rate, gallons per minute

P = Discharge pressure for pumps, inlet pressure for turbines, pounds/square inch

eff = Overall mechanical and hydraulic efficiency.

A.C. Machinery

Kilowatts = $\frac{\text{(volts) (amps) (p.f.)}}{Y}$

Where: p.f. =Power factor

Y = 1000 (Single phase)

Y = 577 (Three phase)

Power required for generator (alternator)

Horsepower =
$$\frac{\text{(volts) (amps) (p.f.)}}{\text{(Z) (eff)}}$$

Where: eff = Overall mechanical and hydraulic efficiency.

p.f. = Power factor

Z = 746 (Single phase)

Z = 431 (Three phase)

Power from motor

Horsepower =
$$\frac{\text{(volts) (amps) (p.f.) (EFF)}}{\text{(Z)}}$$

Where: eff = Overall mechanical and hydraulic efficiency.

p.f. = Power factor

Z = 746 (Single phase)

Z = 431 (Three phase)

D.C. Machinery

$$Kilowatts = \frac{(volts) (amps)}{1000}$$

Power required for generator

Horsepower =
$$\frac{\text{(volts) (amps)}}{\text{(746)(eff)}}$$

Where: eff = Overall mechanical and hydraulic efficiency.

Power from motor

Horsepower =
$$\frac{\text{(volts) (amps) (eff)}}{746}$$

Where: eff = Overall mechanical and hydraulic efficiency.

Gates Application Data Worksheet

Company:	Contact:
Address:	Tu
	Phone: Fax:
	 Email:
Application Summary	
General Description:	
Product Type:	
Prototype Time Schedule:	
Function: Motion Transfer Reversing Ligh	
	Cycle Description:
	,
Design Parameters	
DriveR	
Motor Type & Description (Servo, Stepper, D.C., A.C., etc.):	
	RPM:
	RPM:
Motor Stall Torque (If Applicable):	
DriveN	
Description of DriveN Component::	
	Speed Up/Down:
Additional Details:	
Geometry	
	Point: Are Layout Prints Available?
Center Distance Range: To	•
Type of Adjustment:	
	ack Side
DriveR: Max O.D Max Width	
Max Vidil	WidA O.D WidA Widdi
Special Requirements	
	Usage: Hours/Day: Hours/Year:
•	Usaye, Huurs/Day.
Product Design Life: Belt Design Life:	
Product Design Life: Belt Design Life: Shafts: DriveR DriveN	
Product Design Life: Belt Design Life: Shafts: DriveR DriveN Environmental Conditions:	