



INNOVATORS OF TECHNOLOGY

Android Pie Release Note

VER. 2.10 September 20, 2019



REVISION HISTORY

Revision	Date	Originator	Notes
1.00	March 30, 2019	TechNexion	tn-p9.0.0_1.0.0_8m-ga First public release
2.00	July 30, 2019	TechNexion	tn-p9.0.0_2.0.0_8m-ga First public release
2.10	September 20, 2019	TechNexion	tn-p9.0.0_2.0.1_8m-ga tn-p9.0.0_2.2.0-ga First public release



Table of Contents

1. Overview	4
1.1 Supported Hardware	
1.2 Package Content	
2. Software Difference	5
4. Known Issues	



1. Overview

1.1 Supported Hardware

Following Android Pie distribution is provided for Technexion platforms:

- PICO-IMX8M
 - PI baseboard
- PICO-IMX8MM
 - PI baseboard
- FLEX-IMX8MM
 - PI baseboard
- EDMI-MX8M
 - WIZARD baseboard
- PICO-IMX6
 - DWARF baseboard
 - > HOBBIT baseboard
 - NYMPH baseboard
 - PI baseboard
- PICO-IMX7
 - DWARF baseboard
 - HOBBIT baseboard
 - NYMPH baseboard
 - PI baseboard

Each hardware has its own different functions and features, please refer the specifications first from Technexion official website if possible.

1.2 Package Content

The release package includes the following software and documents:

- Release Notes
- User Manual
- Prebuilt Image
- Installation Tools
- README file



2. Software Difference

Following Android Pie distribution is provided for Technexion platforms:

- IMX8 series:
 - > tn-p9.0.0_2.0.1_8m-ga:
 - 1. Add EDM-IMX8M support
 - 2. Fix 4GB DDR memory only shows 3GB DDR memory information issue
 - 3. Increase BT speed to 3Mbps
 - 4. A2DP audio function support
 - > tn-p9.0.0_2.0.0_8m-ga:
 - 1. Add PICO-IMX8MM support
 - 2. Add FLEX-IMX8MM support
 - 3. Fix camera switch hang issue on two camera case
 - 4. Add 5" ILI9881C MIPI panel support
 - > tn-p9.0.0_1.0.0_8m-ga:

First release

- IMX6/IMX7 series:
 - > tn-p9.0.0_2.2.0-ga: First release



4. Known Issues

The known issues about the hardware and hardware rework instructions are not included in this document.

tn-p9.0.0_2.0.1_8m-ga: No known hardware issues

tn-p9.0.0_2.0.0_8m-ga: No known hardware issues

tn-p9.0.0_1.0.0_8m-ga:

|--|

Items	Issue description	Status
1	Dual mipi camera is not stable in Camera app failed when switching front camera	WIP
	and rear camera.	
2	ILI9881C 5-inch panel is not stable, sometimes appear flicking, wrong color display	WIP