¹ WORK APPROVAL

STATUS: Approved by CSM

Insurer Name	Branch	Insured Name	
Insured Phone	Insured Address	Workshop Name	

Vehicle Number	Registration Date
Chassis Number	Odometer reading
Vehicle Manufacturer	Vehicle Model

Spare Parts (all Replace)

S.No.	Panel	Remarks	HSN Code	Assessed For (in INR)	Rate of GST(%)	Amount of GST Tax	Final Amount
1	Windshield Pasting			1476.56	28	413.44	1890.00
2	PANEL ASSY-UNDER COVER			464.84	28	130.16	595.00
3	PANEL-FENDER,RH			1162.50	28	325.50	1488.00
4	INSULATOR-FENDER RH			104.68	28	29.31	133.99
5	GLASS ASSY-WINDSHIELD			2506.78	28	701.90	3208.68
6	GRILLE ASSY-RADIATOR			3659.37	28	1024.62	4683.99
7	COVER-RADIATOR GRILLE UPR			792.19	28	221.81	1014.00
8	COVER-FR BUMPER			1615.62	28	452.37	2067.99
9	COVER-FR BUMPER,LWR			3421.87	28	958.12	4379.99
10	ABSORBER-FRONT BUMPER ENERGY			1210.93	28	339.06	1549.99
11	BRACKET ASSY-FR BUMPER SD UPR,			49.99	28	14.00	63.99
12	END PIECE-AIR DUCT,RH			39.06	28	10.94	50.00
13	COVER-FR BUMPER FOG LAMP,RH			1425.78	28	399.22	1825.00
14	RETAINER ASSY-BUMPER COVER MT			0.00	28	0.00	0.00
15	LIP-FRONT BUMPER			0.00	28	0.00	0.00
16	COVER-RR BUMPER			0.00	28	0.00	0.00
17	COVER-RR BUMPER LWR			1330.47	28	372.53	1703.00

S.No.	Panel	Remarks	HSN Code	Assessed For (in INR)	Rate of GST(%)	Amount of GST Tax	Final Amount
18	BRACKET-RR BUMPER SIDE LWR,LH			24.22	28	6.78	31.00
19	BRACKET-RR BUMPER SIDE LWR,RH			24.22	28	6.78	31.00
20	BRACKET ASSY-RR BUMPER SIDE,LH			141.40	28	39.59	180.99
21	BRACKET ASSY-RR BUMPER SIDE,RH			141.40	28	39.59	180.99
22	GUARD ASSY-FRONT WHEEL,RH			548.44	28	153.56	702.00
23	LAMP ASSY-OUTSIDE MIRROR,RH			1212.47	28	339.49	1551.96
24	LAMP ASSY-HEAD,RH			3385.13	28	947.84	4332.97
25	LAMP ASSY-FR FOG,RH			1734.75	28	485.73	2220.48
26	LAMP ASSY-DAY RUNNING LIGHT,RH			3890.53	28	1089.35	4979.88
27	LAMP ASSY-REAR COMB OUTSIDE,RH			7801.32	28	2184.37	9985.69
28	LAMP ASSY-REAR COMB INSIDE,RH			0.00	28	0.00	0.00
29	LAMP ASSY-REAR R/REFL,RH			0.00	28	0.00	0.00
30	RESERVOIR & PUMP ASSY-WASHER			0.00	28	0.00	0.00
31	310 MI-sealant Kit-w/s Glass			0.00	28	0.00	0.00
32	32 Denting Painting			0.00	28	0.00	0.00
33	Sensor Module			8438.98	18	1519.02	9958.00
34	Glass Assy Windshield			3667.97	28	1027.03	4695.00
35	Frot Windshield Glass R & R			0.00	18	0.00	0.00
	Total		1	50271.47		13232.11	63503.58

Labour Charges (all Replace + all Repair)

S.No.	Panel	Remarks	Assessed For (in INR)	Rate of GST(%)	Amount of GST Tax	Final Amount
1	Denting Painting		0.00	18	0.00	0.00
2	Frot Windshield Glass R & R		2100.00	18	378.00	2478.00
	Total		2100.00		378.00	2478.00

Assessed For

S.No. Assessed For				
1	Total Labour Charges	2478.00		
2	Total Cost of Parts	63503.58		

3	Less Excess (-)	
4	Less Additional Excess (-)	1
5	Less Salvage cost (-)	
5	Add Towing Charges (+)	1
	Total	

VEHICLE IMAGES

Download link : Click here

Vehicle 1

Download link : Click here

Download link : Click here

Vehicle 3

Vehicle 3

Download link : Click here

Note: Approval subject to policy terms & conditions. Contact support@techkrate.com for Re-inspection.