|	Variance explained per component	Cumulative variance explained

Variance explained per component

Variance explained (%) — y-axis: 0, 20, 40, 60, 80

Principal Component — x-axis: 1 2 3 4 5 6 7 8 9 10 11 12 13 14

Legend: lnX, PCA

Cumulative variance explained

Cumulative variance explained (%) — y-axis: 20, 40, 60, 80, 100

Order means (26.6%)

Principal Component — x-axis: 1 2 3 4 5 6 7 8 9 10 11 12 13 14

Legend: lnX, PCA