Too thin to measure? Measure many and divide!



N = 500 sheets

L = 5.0 cm

✗ One sheet is about 0.1 mm thick: a ruler (sensitivity 1 mm) cannot measure it.

✓ Stack **N** identical sheets, measure the whole pile **L** and divide:

$$e = \frac{L}{N} = \frac{5.0\ \text{cm}}{500}$$

e = 0.01 cm = 0.1 mm