

STAKEDXF

UI & CAPABILITIES · v1.22

Rugged on-device field kit — Civil 3D DWG → Trimble DXF recovery
and scaled staking-plot PDFs on the TSC5 handheld.

ENGINE

LIBREDWG · EZDXF · FLUTTER

OUTPUT

DXF R2010 · PDF

TARGET

TRIMBLE TSC5

AGENDA

- Before / after — visible break from v1.19
- Design system
- Home / operations
- CONVERT · DWG → DXF pipeline
- PLOT · Export points + staking sheet
- Plot customization
- Staking plot examples
- Install on Trimble TSC5
- Field workflow end-to-end

BEFORE · AFTER

v1.19 - retired

StakeDXF

≈ Convert DWG → DXF

Convert for Trimble Access

Soft cards. Rounded chrome. Forest wash. Marketing copy.
Every version prior to v1.22 looked essentially the same.

v1.22 - shipped

STAKEDXF

FIELD-KIT / TSC5 / TRIMBLE

01

CONVERT

DWG → DXF · Civil 3D linework recovery

→

RUN CONVERT

→

Hard 90° corners. Hairline rules. Mono telemetry. Safety-orange reserved for commands.
Corner brackets frame the active field of view. Reads as a piece of ruggedized field kit — not an app.

DESIGN SYSTEM




BG

#07090B




CARD

#10131A




RAIL

#1D212B




BORDER

#252B36




FG

#F1F4F7



DIM

#C6CAD1



MUTED

#798594



ACCENT

#FF5A1F



OK

#7EDF9F



WARN

#F1C15A




DANGER

#E4474D

PRINCIPLES

- Hard 90° corners — no rounded chrome
- Mono telemetry for coordinates, versions, entity counts
- Safety-orange only for active / primary actions
- Hairline rules over cards; content over decoration
- Minimum 44 px tap targets for TSC5 field use

HOME / OPERATIONS



Two ops, one screen: CONVERT and PLOT.

Rugged action rails with a numeric tag, thick left rail, and arrow — reads like a hardware toggle, not a marketing card.

TELEMETRY

- Ribbon: SDX build + ONLINE / LOCAL pills
- Status grid: ENGINE / OUTPUT / MODE readouts
- Footer: TRIO FIELD OPS · NO CLOUD · NO TRACKING

CONVERT · DWG → DXF

SDX · 09:41

ONLINE

CONVERT / DWG → DXF

DRAWING

ALPINE_HILLS.DWG

TRIO/PROJECTS/ALPINE/...

RUN CONVERT

→

CONVERT / OK

RECOVERED 390 ENTITIES · 12 LAYERS

STAKEABLE390

LAYERS12

PROXIES148

FILEALPINE_HILLS_TRIMBLE.DXF

LAYERS3/12ALL

✓

P-CURB

390

✓

P-U-STM

649

✓

P-CL

124

DEFPOINTS

26804

HATCH

33

SAVE DXF · 3 LAYERS

→

- Input slot glows orange when a drawing is loaded
- RUN CONVERT primary button with arrow slot
- Result readout tagged CONVERT / OK with mono KVs
- Layer checklist with hard tick boxes + entity counts
- SAVE DXF button carries the selected-layer count

STAKEDXF / TRIO FIELD OPS

06 / 15

PLOT · EXPORT POINTS — START

SDX · 09:41

ONLINE

PLOT / EXPORT POINTS

JOB

ALPINE_HILLS

IMPORT POINTS CSV

LINK DXF LINEWORK

IMPORT A PNEZD CSV
FROM TRIMBLE ACCESS TO BEGIN.

- Enter a JOB name — becomes the sheet title
- IMPORT POINTS CSV / TXT from Trimble Access
- Optional LINK DXF LINEWORK for on-plot detail
- PNEZD headered or headerless supported

PLOT · CUSTOMIZE + CREATE

SDX · 09:41

ONLINE

PLOT / EXPORT POINTS

JOB

ALPINE_HILLS

IMPORT POINTS CSV

LINK DXF LINEWORK

PLOT OPTIONS

MARKER

LARGE X

LABEL

NUM + ELEV

SCALE

1"=40'

SHEET

ANSI B 17×11 LAND.

LAYERS 3/3

CL

CURB

STRUCT

- MARKER · triangle / X / cross / circle / dot
- LABEL · number / desc / elev combinations
- SCALE · engineering presets or custom 1"=N'
- SHEET · ANSI A–D, portrait or landscape
- LAYERS · tick only the linework you want
- Object library places hydrants / MH / signs
- CREATE STAKING PLOT PDF or EXPORT CSV

PLOT CUSTOMIZATION

MARKERS

- Filled triangle · Triangle outline
- Cross (+) · X · Large X
- Circle · Dot · Large dot


LABELS

- Point number
- Number + description
- Number + elevation
- Number + description + elevation
- No labels


LAYOUT & LINEWORK

- Point list table optional (off by default for staking)
- Linked DXF: LINE / LWPOLYLINE / ARC / CIRCLE by layer
- Auto engineering scale or hard-set 1"=N'
- Layer LOCK column prevents accidental drag-selection
- Full ACI + CTB + true-color HSV picker


STAKING PLOT EXAMPLES




FIELD STAKING · LARGE X + ELEV



CONTROL-NOTE STYLE + TABLE




CIRCLES + CURB LAYER




CROSS (+) NUMBER ONLY


STAKING PLOT EXAMPLES




OVERVIEW · DOTS · NO LABELS



DENSE SET · NUMBER ONLY



GRADE CHECK · ELEV LABELS



FULL SHEET + LINEWORK

INSTALL / TRIMBLE TSC5

- Copy dist/StakeDXF vX.Y.Z.apk onto the TSC5
- Open the APK — allow Install from this source
- Open StakeDXF from the app drawer
- MDM blocked? Ask IT for unknown-source exception
- APK is Android-only — will not install on iPhone

FIELD WORKFLOW

- Office: save Civil 3D DWG with proxies preserved
- TSC5: CONVERT → save DXF into Trimble job folder
- Trimble Access: Map files → selectable → Stakeout
- Export points CSV from Access for shots you need
- StakeDXF PLOT → customize → CREATE staking plot PDF
- Keep PDF open while staking for a scaled field sheet

DOCS & HELP

- [dist/INSTALL_TSC5.md](#) — quick install card
- [dist/StakeDXF_User_Guide.pdf](#) — full usage / help
- [docs/USER_GUIDE.md](#) — same guide in Markdown
- [dist/plot_examples/](#) — sample staking PDFs
- [PR #18](#) — source, APK, release notes

READY FOR THE FIELD.

STAKEDXF · TSC5

RECOVER LINEWORK. PLOT POINTS. STAKE WITH CONFIDENCE.