B. HARGA SATUAN UPAH TENAGA KERJA

No.	Uraian	Sat	Upah (Rp.)	Keterangan		
1	2	3	4	5		
1	Kepala Tukang Batu	hari	75.000,00	Jam Kerja = 7 jam/hari		
2	Tukang Batu	hari	70.000,00			
3	Pembantu Tukang Batu	hari	65.000,00			
4	Kepala Tukang Kayu	hari	75.000,00			
5	Tukang Kayu	hari	70.000,00			
6	Tukang Kayu Halus	hari	55.000,00			
7	Pembantu Tukang Kayu	hari	65.000,00			
8	Kepala Tukang Besi	hari	75.000,00			
9	Tukang Besi	hari	70.000,00			
10	Pembantu Tukang Besi	hari	65.000,00			
11	Kepala Tukang Cat	hari	75.000,00			
12	Tukang Cat	hari	70.000,00			
13	Pembantu Tukang Cat	hari	65.000,00			
14	Sopir/ Operator	hari	70.000,00			
15	Mandor	hari	80.000,00			
16	Penyemprot Aspal	hari	65.000,00			
17	Kernet	hari	60.000,00			
18	Jaga Malam	hari	60.000,00			
19	Tenaga	hari	60.000,00			

C. HARGA SATUAN PEKERJAAN PINTU AIR

T!!4	Cotuon	Daun pintu					Tinggi		Daham	TT	D 111	
Jenis pintu	Satuan	Ting	inggi Lebar		Tebal		gawang		Bahan	Harga	Pemeliharaan	
1	2	3		4		5		6		7	8	9
	Buah	400	mm	400	mm	6	mm	1.600	mm	Besi	4.131.750	413.175
	Buah	500	mm	500	mm	6	mm	1.600	mm	Besi	4.845.750	484.575
Pintu ulir	Buah	600	mm	600	mm	8	mm	1.600	mm	Besi	7.150.500	715.050
	Buah	700	mm	700	mm	8	mm	1.600	mm	Besi	9.030.000	903.000
	Buah	800	mm	800	mm	8	mm	1.600	mm	Besi	11.670.750	1.167.075
	Buah	200	mm	200	mm	6	mm	1.100	mm	Besi	1.317.750	131.775
Pintu tarik	Buah	300	mm	300	mm	6	mm	1.100	mm	Besi	1.506.750	150.675
	Buah	400	mm	400	mm	6	mm	1.100	mm	Besi	1.695.750	169.575
Pintu ulir	Buah	800	mm	1.000	mm	60	mm	2.500	mm	Besi	16.934.400	1.693.440
dengan 1	Buah	900	mm	1.000	mm	60	mm	2.500	mm	Besi	18.816.000	1.881.600
(satu)	Buah	1.000	mm	1.200	mm	60	mm	2.750	mm	Besi	20.475.000	2.047.500
standart	Buah	1.000	mm	1.500	mm	60	mm	2.750	mm	Besi	23.047.500	2.304.750
Pintu ulir	Buah	1.100	mm	1.750	mm	80	mm	3.000	mm	Besi	47.040.000	4.704.000
dengan 2	Buah	1.200	mm	1.800	mm	80	mm	3.000	mm	Besi	56.448.000	5.644.800
(dua)	Buah	1.400	mm	2.000	mm	80	mm	4.000	mm	Besi	63.975.450	6.397.545
standart	Buah	1.500	mm	2.500	mm	80	mm	4.000	mm	Besi	69.055.350	6.905.535

Keterangan:

Harga-harga belum termasuk biaya pemasangan dan transportasi.