V2.3.0

• <u>5d927e27</u> · <u>update 8278 A1 drivers</u> · 21 hours ago

Bug Fixs:

- fix parameter error of queue in USB CDC TX function
- update 8258 ADC driver to avoid ram being flushed by ADC data
- optimize the continuity of the audio waveform by dongle only reporting

Features:

- support 8278 A1 chip
- change the pairing key of 8278 RCU back to sw5
- add frequency hopping function when transmitting voice data

V2.2.0

- 24affa29 · add 8278 chip · 1 month ago

Bug Fixs:

update 826x adc driver to improve the battery detection precision

Features:

- support 8278 A0 chip
- change the 8278 RCU's pairing key to SW23, 8258/826x RCU remain un

v2.1.0

• 407510e7 · add rf4ce sdk · 4 months ago

GitServer: ssh://gitolite@192.168.48.47:222/zigbee branch: telink_zigbee S

Bug Fixs

- fix mac address issue
- fix quick set IR toggle bit issue

Features

- Auto-generated ota file in the proj
- add rsp code in the callback function for pushing attribute response
- add callback for all of the command, optimize the discovery procedure
- change led action for pair, audio issue for 8258
- add demo for rf4ce/ble switch