V2.3.1

◆ <u>a9b3a554</u> · <u>Delete unwanted folders</u> · 2 months ago

Bug Fixs:

• add macros to enable GPIO UART print

Features:

- support 8278 A2 chip
- optimize the voice delivery process and resend voice data at 16K sampling rate

V2.3.0

◆ <u>5d927e27</u> · <u>update 8278 A1 drivers</u> · 2 months ago

Bug Fixs:

- fix parameter error of queue in USB CDC TX function
- update 8258 ADC driver to avoid ram being flushed by ADC data
- · optimize the continuity of the audio waveform by dongle only reporting valid voice data

Features:

- support 8278 A1 chip
- change the pairing key of 8278 RCU back to sw5
- add frequency hopping function when transmitting voice data

V2.2.6

-O <u>24affa29</u> · <u>add 8278 chip</u> · 3 months ago

Bug Fixs:

• update 826x adc driver to improve the battery detection precision

Features:

- support 8278 A0 chip
- change the 8278 RCU's pairing key to SW23, 8258/826x RCU remain unchanged

<u>v2.1.0</u>

◆ 407510e7 · add rf4ce sdk · 6 months ago

 $\label{link_zigbee} \textit{GitServer}: \ \underline{ssh://gitolite@192.168.48.47:222/zigbee} \ branch: \ telink_zigbee \ SHA-1: \ a21ca21bb33a2ac9b6$

Bug Fixs

- fix mac address issue
- fix quick set IR toggle bit issue

Features

- Auto-generated ota file in the proj
- add rsp code in the callback function for pushing attribute response
- add callback for all of the command, optimize the discovery procedure
- change led action for pair, audio issue for 8258
- add demo for rf4ce/ble switch