# QATAR NAVIGATION (QPSC)

## SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH
Cable: "NAVIGATION" Doha
Bank A/c:QNB Main Branch
P.O.Box 1000, Doha - Qatar
Swift Code: QNBAQAQA
QAR A/C No. 0013-000309-060
USD A/C No. 0013-000309-061

Page: 1 / 2

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard WS

PO Box 153, Doha - Qatar

INVOICE NO: SFWK/INV/013069/2021

DATE: 29/11/2021

EXPENSE A/C: 85.901.1434006

W/O NO: 21-011058 / 1

W/O REF: MLO21037

Vessel Name/Description: M.V. "HALUL-29"

| Job No | Description  | Line Amount |
|--------|--|-------------|
|        |  |             |
| 2500   | ANTI-HEELING PUMPS MOTORS END COVER RESLEEVING:-   | 3,600.00    |
|        | Anti-Heeling pump motors following end covers pre machined, new cast iron sleeves manufactured, inserted and fixed each with 2 Nos. stainless steel grub screws. Motor No. 1 DE sleeve size 130mm Od x 40mm long - 1 No.  Motor No. 2 DE & NDE sleeve size 130mm Od x 40mm long - 2 Nos.   |             |
|        | As per our quotation No. EM 15747A, item No. 1.  |             |
| 5600   | ANTI-HEELING PUMPS :-  | 6,960.00    |
|        | Two numbers of anti-keeling pumps received from vessel and bought to workshop and dismantled. Mechanical seal, O-rings and bearings found damage.  No:2 Pump shaft gear found damage. Initial QC report submitted to client. Parts all cleaned, impeller polished. Inspected by client. Pump no:1 & 2 assembled with client supplied spares, witnessed by yard QC and Client.  No:1 Pump shifted to location and installed in position. Pump No:2 shifted to vessel and located as per client instruction. |             |
|        | Based on our quotation No. EM 15747 Revised, item No. 1. (QRs. $3,450.00 + QRs. 3,510.00 = QRs. 6,960.00$ ).   |             |
| 7000   | ANTI-HEELING PUMPS MOTORS:-  | 6,620.00    |
|        | Motors megger test carried out and report to be submitted. 2 Nos. motors (30KW) received in our work shop, motor dismantled winding checked, cleaned, dried, insulation checked and bearing renewed, reassembled and bench tested.   |             |
|        | Motors collected by Client on completion.  |             |

E & O.E

## for QATAR NAVIGATION (Q.S.C)

SHIP REPAIR, FABRICATION & ENGINEERING DIVISION

# QATAR NAVIGATION (QPSC)

## SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

: 4771687



Telex : 4206 DH Cable : "NAVIGATION" Doha Bank A/c:QNB Main Branch P.O.Box 1000, Doha - Qatar Swift Code: QNBAQAQA QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

Page: 2 / 2

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard WS

PO Box 153, Doha - Qatar

INVOICE NO: SFWK/INV/013069/2021

DATE: 29/11/2021

EXPENSE A/C: 85.901.1434006

W/O NO: 21-011058 / 1

W/O REF: MLO21037

Vessel Name/Description : M.V. "HALUL-29"

Job No Description Line Amount

As per our quotation No. EM 15747 Revised, item No. 2.

Encls:-

- Copy of our quotation No. EM 15747 Revised by E-Mail dated 22-02-2021.
- Copy of your mail dated 22-02-2021.
- Copy of our quotation No. EM 15747Ad by E-Mail dated 28-03-2021.
- Copy of your mail dated 28-03-2021.
- Copy of signed work completed reports.

Invoice Amount -->

17,180.00

(QAR - Seventeen Thousand One Hundred Eighty Only)

E & O.E

for QATAR NAVIGATION (Q.S.C) SHIP REPAIR, FABRICATION & ENGINEERING DIVISION