SHIP REPAIR & FABRICATION

Telephones

900001

Office: 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH
Cable: "NAVIGATION" Doha
Bank A/c:QNB Main Branch
P.O.Box 1000, Doha - Qatar
Swift Code: QNBAQAQA
QAR A/C No. 0013-000309-060
USD A/C No. 0013-000309-061

Page: 1 / 4

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard WS

PO Box 153, Doha - Qatar

INVOICE NO: SFWK/INV/012661/2021

DATE: 24/03/2021

EXPENSE A/C: 85.901.1434006

W/O NO: 21-011073 / 1 W/O REF: MDO 21051

Vessel Name/Description : MOORING BOAT "WASSIT-II"

Job No	Description	Line Amount
	BOAT ARRIVED : 08-03-2021. BOAT DOCKED : 08-03-2021. BOAT UNDOCKED : 11-03-2021. BOAT SAILED : 12-03-2021.	
1100	BERTH PREPARATION, DOCKING AND UNDOCKING:-	5,700.00
	Berth prepared, Vessel docked and later undocked.	
	As per our quotation no. EM 15762, item no. A.1.	
1101	DRYBERTH HIRE:-	6,200.00
	Dock hire dated 08-03-2021 and 11-03-2021.	
	Based on our quotation no. EM 15762, item no. A.2. (QRs.1,550.00 per day \times 4 days = QRs. 6,200.00).	
1102	SERVICES:-	3,025.00
	A) Fire and safety watch provided during period of dry docking.	
	Based on our quotation no. EM 15762, item no. A.6 (QRs. 330.00 per day \times 5 days = QRs. 1,650.00).	
	B) Electrical shore power supply (415 V, 3 phase, 50 Hz, up to 150 amps) provided during period of dry docking, including connecting and disconnecting.	
	Based on our quotation no. EM 15762, item no. A-5.	
	$(QRs. 275.00 per day \times 4 days + QRs. 275.00 = QRs. 1,375.00).$	

E & O.E

for QATAR NAVIGATION (Q.S.C)

SHIP REPAIR, FABRICATION & ENGINEERING DIVISION

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

: 4771687



Telex : 4206 DH Cable : "NAVIGATION" Doha Bank A/c:QNB Main Branch P.O.Box 1000, Doha - Qatar Swift Code: QNBAQAQA QAR A/C No. 0013-000309-060

USD A/C No. 0013-000309-061

Page: 2 / 4

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard WS

PO Box 153, Doha - Qatar

INVOICE NO: SFWK/INV/012661/2021

DATE: 24/03/2021

EXPENSE A/C: 85.901.1434006

W/O NO: 21-011073 / 1 W/O REF: MDO 21051

Vessel Name/Description : MOORING BOAT "WASSIT-II"

Job No	Description	Line Amount
1150	WHARFAGE CHARGES:-	770.00
	Wharfage charges of vessel applied whilst alongside shipyard's quay.	
	QRs. 770.00 per day x 1 day = QRs.770.00.	
1200	HULL BOTTOM CLEANING:-	2,100.00
	Hand scraping and removed marine growth. H.P. jet washed using with fresh water.	
	As per our quotation no. EM 15762, item no. 1.	
1400	TAIL SHAFT AND RUDDER CLEARENCE:-	2,500.00
	A) P&S TAILSHAFT CLEARANCES:-	
	Port and stbd. Tail shaftweardown clearance taken and report issued.	
	As per our quotation no. EM $15762B$, item no. 1. (QRs. 1,600.00).	
	B) RUDDER CLEARANCES:-	
	Port and stbd. rudder lower and upper clearance taken and report issued.	
	As per our quotation no. EM 15762B, item no. 2. (QRs. 900.00).	

E & O.E

for QATAR NAVIGATION (Q.S.C)

SHIP REPAIR, FABRICATION & ENGINEERING DIVISION

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH
Cable: "NAVIGATION" Doha
Bank A/c:QNB Main Branch
P.O.Box 1000, Doha - Qatar
Swift Code: QNBAQAQA
QAR A/C No. 0013-000309-060
USD A/C No. 0013-000309-061

Page: 3 / 4

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard WS

PO Box 153, Doha - Qatar

INVOICE NO: SFWK/INV/012661/2021

DATE: 24/03/2021

EXPENSE A/C: 85.901.1434006

W/O NO: 21-011073 / 1 W/O REF: MDO 21051

Vessel Name/Description : MOORING BOAT "WASSIT-II"

Job No Description Line Amount

8000 PORT SIDE PROPELLER CLEANING:-

10,200.00

A) Port & Stbd. side propeller cleaned and polished with cup wire brush.

As per our quotation no. EM 15762, item no. 3.1. (QRs. 2,200.00).

B) Port and stbd. propellers removed entangled port side wire ropes between bracket and propeller cut removed and later propellers refitted.

Based on our quotation no. EM 15762, item no. 3.3. (QRs. $1,800.00 \times 2 \text{ Nos.} = \text{QRs.} 3,600.00$).

C) Aft transom area scaffolding to be arranged for access and later removed on completion of proppeller works.

As per our quotation no. EM 15762, item no. 3.2. (QRs. 1,000.00).

D) Stbd. side propeller brought to work shop, calibrated, found 2 blades out of profile, blade #2 and #4 brought approximate match the profile by heating and hammering process.

Root and tip area DP tested. Static balancing carried out.

As per our quotation no. EM 15762A, item no. 3. (QRs. 3,400.00).

Encl:-

- Copy of our quotation no. EM 15762 by E-mail dated 08-03-2021.
- Copy of our quotation no. EM 15762A by E-mail dated 10-03-2021.

E & O.E

for QATAR NAVIGATION (Q.S.C)

SHIP REPAIR, FABRICATION & ENGINEERING DIVISION

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH
Cable: "NAVIGATION" Doha
Bank A/c:QNB Main Branch
P.O.Box 1000, Doha - Qatar
Swift Code: QNBAQAQA
QAR A/C No. 0013-000309-060
USD A/C No. 0013-000309-061

Page: 4 / 4

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard WS

PO Box 153, Doha - Qatar

INVOICE NO: SFWK/INV/012661/2021

DATE: 24/03/2021

EXPENSE A/C: 85.901.1434006

W/O NO: 21-011073 / 1 W/O REF: MDO 21051

Vessel Name/Description : MOORING BOAT "WASSIT-II"

Job No Description

Line Amount

- Copy of our quotation no. EM 15762B by E-mail dated 11-03-2021.

- Copy of signed work completed reports.

Invoice Amount -->

30,495.00

(QAR - Thirty Thousand Four Hundred Ninety-Five Only)

E & O.E

for QATAR NAVIGATION (Q.S.C)
SHIP REPAIR, FABRICATION & ENGINEERING DIVISION