QATAR NAVIGATION (QPSC)

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH
Cable: "NAVIGATION" Doha
Bank A/c:QNB Main Branch
P.O.Box 1000, Doha - Qatar
Swift Code: QNBAQAQA
QAR A/C No. 0013-000309-060
USD A/C No. 0013-000309-061

Page: 1 / 2

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard WS

PO Box 153, Doha - Qatar

INVOICE NO: SFWK/INV/012841/2021

DATE: 29/06/2021

EXPENSE A/C: 85.901.1434006

W/O NO: 21-011170 / 1 W/O REF: MDO 21139

Vessel Name/Description : PILOT BOAT "ZAKRA-II"

Job No	Description	Line Amount
1100	BERTH PREPARATION, DOCKING AND UNDOCKING:-	5,700.00
1101	Berth prepared, Vessel docked and later undocked. DRY BERTH HIRE :-	C 200 00
1101	Dated from 03-06-2021 to 06-06-2021.	6,200.00
	Based on our quotation No.: EM 15746, item No. A-2. (QRs.1,550.00 per day x 4days = QRs.6,200.00)	
1102	SERVICES :-	2,695.00
	A) Fire and safety watch provided dated from $03-06-2021$ to $06-06-2021$. (QRs.330.00 per day x 4 days = QRs. 1,320.00).	
	B)Electrical shore power supplied dated from 03-06-2021 to 06-06-2021. including connection and disconnection.	
	(QRs. 275.00 per day x 4 days + QRs. 275.00 = QRs.1,375.00).	
1200	UNDERWATER AREA CLEANING :-	2,310.00
	Underwater area treated and painted as follows. Hand scraped to remove marine growth. H.P. jet washed using fresh water.	

E & O.E

for QATAR NAVIGATION (Q.S.C)

SHIP REPAIR, FABRICATION & ENGINEERING DIVISION

QATAR NAVIGATION (QPSC)

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH
Cable: "NAVIGATION" Doha
Bank A/c:QNB Main Branch
P.O.Box 1000, Doha - Qatar
Swift Code: QNBAQAQA
QAR A/C No. 0013-000309-060
USD A/C No. 0013-000309-061

Page: 2 / 2

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard WS

PO Box 153, Doha - Qatar

INVOICE NO: SFWK/INV/012841/2021

DATE: 29/06/2021

EXPENSE A/C: 85.901.1434006

W/O NO: 21-011170 / 1 W/O REF: MDO 21139

Vessel Name/Description : PILOT BOAT "ZAKRA-II"

Job No	Description	Line Amount
1800	INSTALLATION OF D FENDER :-	
	Job has been cancelled.	
2250	REPAIR OF DAMAGED FIBER AREA :-	2,260.00
	Damaged fiber area repaired 5 location Sanding and Cleaned with Actone Applied GRP mate 5 layer Sanding and cleaned Applied filler Smooth sanding and applied one coat primer and one top coat Yard Supplied GRP materials and filler	
	Invoice Amount>	19,165.00

(QAR - Nineteen Thousand One Hundred Sixty-Five Only)

E & O.E

for QATAR NAVIGATION (Q.S.C)
SHIP REPAIR, FABRICATION & ENGINEERING DIVISION