QATAR NAVIGATION (QPSC)

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

: 4771687



Telex : 4206 DH Cable : "NAVIGATION" Doha Bank A/c:QNB Main Branch P.O.Box 1000, Doha - Qatar Swift Code : QNBAQAQA QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

Page: 1 / 1

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard WS

PO Box 153, Doha - Qatar

INVOICE NO: SFWK/INV/012808/2021

DATE: 31/05/2021

EXPENSE A/C: 85.901.1434006

W/O NO: 21-011087 / 1 W/O REF: MLO21065

Vessel Name/Description : TUG "SODANATHEEL"

Job No Description Line Amount

5800 FWD WINCH BRAKE BAND :- 2,450.00

Forward winch brake lining 1 set disconnected and removed from location. Brought to workshop removed old brake liner and chipping, grinding and cleaning done. Client supplied new liners and new brass counter sunk crews installed on the brake bends. Pins and holes are cleaned and polished. Brake bend shifted to on-board vessel and fitted back on position. Witnessed by client.

5801 ANCHOR WINDLASS BRAKE BAND WORKS :- 15,850.00

Remove anchor windlass brake band from vessel. Transfer to shipyard workshop. Cut and remove existing liner from brake band. Renew brake liner 12 mm x 100 mm x 4 mtr approx Carry out ovality check for drum and brake liner. Carried out insitu machining of drum. Carried out skimming of brake band and sleeve fabricated -2 pc

Based on our quotation EM 15825 A

Invoice Amount -->

18,300.00

(QAR - Eighteen Thousand Three Hundred Only)

E & O.E

for QATAR NAVIGATION (Q.S.C)

SHIP REPAIR, FABRICATION & ENGINEERING DIVISION