QATAR NAVIGATION (QPSC)

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

: 4771687



Telex : 4206 DH Cable : "NAVIGATION" Doha Bank A/c:QNB Main Branch P.O.Box 1000, Doha - Qatar Swift Code: QNBAQAQA QAR A/C No. 0013-000309-060

USD A/C No. 0013-000309-061

Page: 1 / 3

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard WS

PO Box 153, Doha - Qatar

INVOICE NO: SFWK/INV/012729/2021

DATE: 30/04/2021

EXPENSE A/C: 85.901.1434006

W/O NO: 21-011063 / 1

W/O REF: MLO21042

Vessel Name/Description : M.V. "HALUL-61"

Job No	Description	Line Amount
1150	BERTHING CERWS:- Berthing crew provided whilst vessel at alongside dated 25.02.2021	1,000.00
1151	WHARFAGE CHARGES:- Wharfage charges from 25.02.2021 to 09.03.2021	14,547.00
1152	QRs 1,119 per day x 13 days = QRs 14,547.00 FIRE AND SAFETY WATCH:- Fire and safety watch provided whilst alogside.	4,290.00
1153	QRs 330 per day x 13 days = QRs 4,290.00 GALLEY GARBAGE SKIP:- Galley garbage skip provided x 14 days.	3,575.00
1154	QRs 275 per day x 13 days = QRs 3,575.00 MAST AREA SCAFFOLDING:- Arranged scaffolding and removed after completion of work. As per our quotation EM 15729 A	1,520.00
	<u>. </u>	

E & O.E

for QATAR NAVIGATION (Q.S.C)

SHIP REPAIR, FABRICATION & ENGINEERING DIVISION

QATAR NAVIGATION (QPSC)

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH
Cable: "NAVIGATION" Doha
Bank A/c:QNB Main Branch
P.O.Box 1000, Doha - Qatar
Swift Code: QNBAQAQA
QAR A/C No. 0013-000309-060
USD A/C No. 0013-000309-061

VOICE

Page: 2 / 3

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard WS

PO Box 153, Doha - Qatar

INVOICE NO: SFWK/INV/012729/2021

DATE: 30/04/2021

EXPENSE A/C: 85.901.1434006

W/O NO: 21-011063 / 1

W/O REF: MLO21042

Vessel Name/Description : M.V. "HALUL-61"

Job No	Description	Line Amount
1155	INSTALLATION OF SAUSAGE FENDERS - 1 NO:-	10,565.00
	Shifting and Installation of client supplied sausage fender (in 3 Pieces).	
	11 Nos. pad eyes to be fabricated and welded for SPM hose fitting.	
	50 Ton Crane arranged for 2 days.	
	As per our quotation EM 15729 B, item 1	
1156	NDT (DP AND MPI) TEST:-	1,050.00
	NDT (DP and MPI) test carried out for ${\tt H61}$ gangway and crane (hook and pedestal).	
1800	FIRE RENEWAL OF STERNROLLER AREA DAMAGED DECK PLATE:-	1,500.00
	One no. damaged deck plate to be cut removed, bevel to be prepared and new plate to be fabricated fitted and welded to size $350\mathrm{mm}$ x $200\mathrm{mm}$ x $20\mathrm{mm}$ thickness.	
	As per our quotation EM 15729 B, item 3	
2800	REPAIR OF PORT AND STBD. TYRE FENDERS:-	3,468.00
	Port side 3 Nos. tyre fenders chain to be renewed using client supplied	
	chain and shackles.	
	1 No. pad eye to be fabricated and fitted. 1 No. additional tyre fender to be fitted using client supplied	
	materials.	
	Stbd. side	

E & O.E

for QATAR NAVIGATION (Q.S.C)

SHIP REPAIR, FABRICATION & ENGINEERING DIVISION

QATAR NAVIGATION (QPSC)

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH
Cable: "NAVIGATION" Doha
Bank A/c:QNB Main Branch
P.O.Box 1000, Doha - Qatar
Swift Code: QNBAQAQA
QAR A/C No. 0013-000309-060
USD A/C No. 0013-000309-061

Page: 3 / 3

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard WS

PO Box 153, Doha - Qatar

INVOICE NO: SFWK/INV/012729/2021

DATE: 30/04/2021

EXPENSE A/C: 85.901.1434006

W/O NO: 21-011063 / 1

W/O REF: MLO21042

Vessel Name/Description : M.V. "HALUL-61"

Job No Description

Line Amount

- 2 Nos. tyre fenders chain to be renewed using client supplied chain and shackles.
- 1 No. pad eye to be fabricated and fitted.
- 2 Nos. additional tyre fender to be fitted using client supplied materials.

As per our quotation EM 15729 B, item 2

Invoice Amount -->

41,515.00

(QAR - Forty-One Thousand Five Hundred Fifteen Only)

E & O.E

for QATAR NAVIGATION (Q.S.C)
SHIP REPAIR, FABRICATION & ENGINEERING DIVISION