QATAR NAVIGATION (QPSC)

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

: 4771687



Telex : 4206 DH Cable : "NAVIGATION" Doha Bank A/c:QNB Main Branch P.O.Box 1000, Doha - Qatar Swift Code : QNBAQAQA QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

Page: 1 / 1

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard WS

PO Box 153, Doha - Qatar

INVOICE NO: SFWK/INV/012704/2021

DATE: 01/04/2021

EXPENSE A/C: 85.901.1434006

W/O NO: 20-010975 / 1 W/O REF: MLO 20280

Vessel Name/Description : M.V. "HALUL-100"

Job No Description Line Amount

1800 FABRICATION OF SEA WATER INJECTION BOX:- 16,820.00

One in no. damaged sea water injection box to be received in work shop, inspected and 1 No. injection box to be fabricated as per sample and client supplied drawing. Box shell thickness (3mm) top rectangle flange (5mm), top cover (5mm), changes in top flange hole to hole distance (76 to 35mm) to overall size 1122mm long x 460mm width provided with jacket cooling section, both end flange, reducing section, square flange and flap. Both end existing loose ring flanges to be reused.

Using SS 316L materials.

Sea water injection box to be hydro tested and report issued.

FABRICATION OF SEA WATER INJECTION BOX COLLAR FLANGE:-Two in no. stainless steel collar flange fabricated for sea water injection box to size 380mm OD x 25mm thickness.

As per our quotation EM 15689 A

Invoice Amount --> 16,820.00

(QAR - Sixteen Thousand Eight Hundred Twenty Only)

E & O.E

for QATAR NAVIGATION (Q.S.C) SHIP REPAIR, FABRICATION & ENGINEERING DIVISION