QATAR NAVIGATION (QPSC)

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH
Cable: "NAVIGATION" Doha
Bank A/c:QNB Main Branch
P.O.Box 1000, Doha - Qatar
Swift Code: QNBAQAQA
QAR A/C No. 0013-000309-060
USD A/C No. 0013-000309-061

Page: 1 / 3

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard WS

PO Box 153, Doha - Qatar

INVOICE NO: SFWK/INV/012840/2021

DATE: 29/06/2021

EXPENSE A/C: 85.901.1434006

W/O NO: 21-011139 / 1

W/O REF: MLO21112

Vessel Name/Description : PILOT BOAT "ZARKA-II"

Job No	Description	Line Amount
1150	OFFLOADING OF MTU ENGINE :-	540.00
1130		540.00
	MTU engine (approx. 3 Ton) offloaded in yellow shed.	
1151	BERTHING CREWS :-	770.00
	Berthing crews provided during berthing alongside shipyard's quay dated 25-05-2021.	
	As per our quotation No. EM 15844, item No.A.1.	
1152	WHARFAGE CHARGE :-	6,930.00
	Dated from 25-05-2021 to 02-06-2021.	
	Based on our quotation No. EM 15844, item No.A.2. (QRs.770.00 per day \times 9 days = QRs. 6,930.00)	
1153	FIRE AND SAFETY WATCH :-	2,970.00
	Dated from 25-05-2021 to 02-06-2021.	
	Based on our quotation No. EM 15844, item No.A.2. (QRs.330.00 per day \times 9 day = QRs. 2,970.00).	
1154	PROVIDING OF GANGWAY :-	400.00
	Gangway provided dated from 26-05-2021 to 02-06-2021.	

E & O.E

for QATAR NAVIGATION (Q.S.C)

SHIP REPAIR, FABRICATION & ENGINEERING DIVISION

QATAR NAVIGATION (QPSC)

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

: 4771687



Telex : 4206 DH Cable : "NAVIGATION" Doha Bank A/c:QNB Main Branch P.O.Box 1000, Doha - Qatar Swift Code : QNBAQAQA QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

Page: 2 / 3

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard WS

PO Box 153, Doha - Qatar

INVOICE NO: SFWK/INV/012840/2021

DATE: 29/06/2021

EXPENSE A/C: 85.901.1434006

W/O NO: 21-011139 / 1

W/O REF: MLO21112

Vessel Name/Description : PILOT BOAT "ZARKA-II"

Job No Description Line Amount

(QRs. 50.00 per day x 8 days = QRs. 400.00.

5050 INSTALLATION OF ENGINE :- 11,452.00

Port Side Main engine Cardan shaft removed from location and shifted to side. Engine foundation bolts removed. And engine lifted out and kept on wooden blocks. Vulcan coupling and cover removed from old engine.

Client supplied new engine shifted to jetty side nearby vessel. New engine does not have the Vulcan coupling. Old engine's Vulcan coupling and cover installed to new engine.

New engine lifted by yard crane and kept on position in engine room. Alignment carriedout with yard fabricated special tool, micrometer, feeler gauge and vernier caliper . Reports submitted to client. Engine foundation bolts tightened at 350Nm torque, Rubber mounting tightened with 330Nm torque, cardan shaft flange bolts tightened with 300Nm torque and Flywheel housing tightened with 74Nm. Inspected and witnessed by Client.

As per our quotation No. EM 15844, item No. 1.

7000 ELECTRICAL SHORE POWER :- 2,750.00

Electrical shore power to be provided dated from 25-05-2021 to 02-06-2021.

 $(QRs. 275.00. per day \times 9 days + QRs. 275.00 = QRs. 2,750.00.$

E & O.E

for QATAR NAVIGATION (Q.S.C)

SHIP REPAIR, FABRICATION & ENGINEERING DIVISION

QATAR NAVIGATION (QPSC)

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

: 4771687



Telex : 4206 DH Cable : "NAVIGATION" Doha Bank A/c:QNB Main Branch P.O.Box 1000, Doha - Qatar Swift Code: QNBAQAQA QAR A/C No. 0013-000309-060 USD A/C No. 0013-000309-061

Page: 3 / 3

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard WS

PO Box 153, Doha - Qatar

INVOICE NO: SFWK/INV/012840/2021

DATE: 29/06/2021

EXPENSE A/C: 85.901.1434006

W/O NO: 21-011139 / 1

W/O REF: MLO21112

Vessel Name/Description : PILOT BOAT "ZARKA-II"

Job No Description Line Amount

25,812.00 Invoice Amount -->

(QAR - Twenty-Five Thousand Eight Hundred Twelve Only)

E & O.E

for QATAR NAVIGATION (Q.S.C) SHIP REPAIR, FABRICATION & ENGINEERING DIVISION