QATAR NAVIGATION (QPSC)

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH
Cable: "NAVIGATION" Doha
Bank A/c:QNB Main Branch
P.O.Box 1000, Doha - Qatar
Swift Code: QNBAQAQA
QAR A/C No. 0013-000309-060
USD A/C No. 0013-000309-061

Page: 1 / 1

106734

ALFARDAN MARINE SERVICES

Al Funduq Street, West Bay, Doha

Doha QA 9948

INVOICE NO: SFWK/INV/013115/2021

DATE: 26/12/2021

EXPENSE A/C:

W/O NO: 21-011209 / 1

W/O REF: MLY21171

Vessel Name/Description : "YACHT " ONE MORE TOY

Job No Description

Line Amount

5050 PORT AND STB SIDES MAIN ENGINES EXHAUST PIPES REPAIR:-

9,050.00

Port side engine exhaust pipe leak inspection and repair.

Removal of port and stb exhaust bellows and have them sent to shipyard $-4~\mathrm{pcs}$

Replaced exhaust gasket between main engine expansion below and exhaust pipe flanges.

Cleaning and skimming of flanges between main engine expansion below and exhaust pipe.

Remove and replace of pipe exhaust insulation with ceramic 50 mm secured with bands one layer of Kevlar cloth. Replacement of 8 carbon steel bolts and nuts. Deliver the exhaust bellows and install the same onboard.

As per our quotation EM 15917

Note:-

Payment within 7 working days after that 1% interest shall be applied every month.

Encl:-

Copy of quotation.

Invoice Amount -->

9,050.00

(QAR - Nine Thousand Fifty Only)

E & O.E

for QATAR NAVIGATION (Q.S.C)

SHIP REPAIR, FABRICATION & ENGINEERING DIVISION