## QATAR NAVIGATION (QPSC)

## SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH
Cable: "NAVIGATION" Doha
Bank A/c:QNB Main Branch
P.O.Box 1000, Doha - Qatar
Swift Code: QNBAQAQA
QAR A/C No. 0013-000309-060
USD A/C No. 0013-000309-061

Page: 1 / 1

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard WS

PO Box 153, Doha - Qatar

111101

INVOICE NO: SFWK/INV/012777/2021

DATE: 31/05/2021

EXPENSE A/C: 85.901.1434006

W/O NO: 21-011105 / 1 W/O REF: MLO21081

Vessel Name/Description : TUG "GHASHAM"

Job No

Description

Line Amount

5800

RENEWAL OF ANCHOR WINDLASS BRAKE LINER: (PORT & STBD)

2,900.00

2Sets brake bands each approx. 400mm dia. received in work shop.

Cut and remove the brake lining. Brake band blasted and applied with 1 coat shop primer.

New bralke liner supplied (80mm x 10mm brass woven brake band material) fitted to each brake band and locked with yard supplied brass countersunk bolts and nuts. brake bands collected by you on completion.

As per our quotation EM 15768 Revised

Invoice Amount -->

2,900.00

(QAR - Two Thousand Nine Hundred Only)

E & O.E

for QATAR NAVIGATION (Q.S.C)
SHIP REPAIR, FABRICATION & ENGINEERING DIVISION