QATAR NAVIGATION (QPSC)

SHIP REPAIR & FABRICATION

Telephones

Office: 4771690 / 4771695

Fax : 4771687



Telex: 4206 DH
Cable: "NAVIGATION" Doha
Bank A/c:QNB Main Branch
P.O.Box 1000, Doha - Qatar
Swift Code: QNBAQAQA
QAR A/C No. 0013-000309-060

USD A/C No. 0013-000309-060

Page: 1 / 1

900001

SHIP MANAGEMENT - SHIPYARD INTERCO Shipyard WS

PO Box 153, Doha - Qatar

INVOICE NO: SFWK/INV/012732/2021

DATE: 30/04/2021

EXPENSE A/C: 85.901.1434006

W/O NO: 21-011068 / 1

W/O REF: MLO21047

Vessel Name/Description : M.V. "HALUL-101"

Job No Description Line Amount

1800 REPAIR OF SEA WATER INJECTION BOX (EXHAUST HOUSING):-

12,200.00

One in no. damaged sea water injection box to be received in work shop, inspected and injection box to be repaired using following new sections.

Outer box section with rectangular flange and cover.

Internal taper cut piece.

Flap to be repaired.

Based on client supplied drawing No. SEAS66-10600-04-A along with modification as per your instruction in box shell thickness (3mm) top rectangle flange (5mm), top cover (5mm), changes in top flange hole to hole distance (76 to 35mm) to overall size 1122mm long x 460mm width.

Using 316L materials.

Sea water injection box to be hydro tested and report issued.

As per our quotation EM 15742 (PO: H 101-21-5016)

Invoice Amount --> 12,200.00

(QAR - Twelve Thousand Two Hundred Only)

E & O.E

for QATAR NAVIGATION (Q.S.C)
SHIP REPAIR, FABRICATION & ENGINEERING DIVISION